MILLS OF CO OFFALY: AN INDUSTRIAL HERITAGE SURVEY



Part 2 Site Gazetteer

Fred Hamond

An Action of the Offaly Heritage Plan 2002 – 2006



for
Offaly County Council
May 2009



Cover: Belmont Mill (OFIAR-014-004)

CONTENTS

PREFACE

INTRODUCTION

MILL LOCATION MAPS

SITE GAZETTEER

SITE INDEXES

PREFACE

This gazetteer of mills in Co Offaly accompanies the general site overview presented in Part 1 of this report.

The introduction explains the various attributes recorded for each mill site in the county. Maps showing the mills' locations are then presented, followed by a gazetteer detailing each site's location, function, history, upstanding remains and industrial heritage significance. Indexes to the gazetteer form the remainder of the volume.

The report is accompanied by a DVD which reiterates the texts of both Parts 1 and 2 in PDF format. This disc also contains an *Access* database of all the mills included in the gazetteer, a *MapInfo* database of their locations, and photographs in JPEG format. The appropriate computer software will be necessary in order to utilize the databases. However, a free PDF reader - *Adobe Acrobat* - is downloadable on the internet and will also enable the user to search for any text within both parts of the report without recourse to the indexes.

Fred Hamond
Industrial Archaeologist
75 Locksley Pk.
Belfast BT10 0AS

14 May 2009

INTRODUCTION

All the data collected during the course of this project has been transferred to the Offaly Industrial Archaeology Record (OFIAR). This is in the form of a Microsoft *Access* database and contains records for a wide variety of industrial sites throughout the county. Each site is uniquely identified by its OFIAR number and has a corresponding record in the database. Each record contains information on the site's location, history, physical remains and heritage significance. Selected data for all sites are also held in *MapInfo* format and can be superimposed on maps at various scales.

Site gazetteer fields

The key features of each site are printed out in hard-copy format in this volume. The fields within each site record are as follows:

tieias within e	each site record are as follows:
Site no	This is the Offaly Industrial Archaeology Record number (OFIAR). It comprises two sets of three digits. The first set denotes the Ordnance Survey County Series six-inch map on which the site is depicted. The second set denotes the number of the site within that particular sheet. For example OFIAR-045-015 denotes site 15 on sheet 45 of the Co Offaly six-inch maps.
Name	This is the name by which the site is officially or commonly known (usually derived from the OS maps). Mills sometimes have several different names (often their present or past owner), each of which is listed, where known. Defunct names are given in curly brackets.
County	The county within which the site lies, here Co Offaly.
Townland	This is the townland where the site is located. Sometimes its townland boundary will have changed so that the site was previously in a neighbouring townland. Past names are given in curly brackets. Where different townlands share the same name, they are distinguished by barony and/or parish.
Town	This is given in those instances where the site is located within a town or large village. The settlements thus differentiated are: Ballyboy Ballycumber Banagher Birr Clonbulloge Daingean Edenderry Ferbane Kilcormac Killeigh Portarlington Shinrone Tullamore
Planning	This is the Planning Authority responsible for that site. There are three such authorities in Co Offaly:
	Birr Urban District Council

Offaly County Council

Tullamore Urban District Council
 OS 1:50,000 Discovery Series map sheet.

Six-inch map

OS 1:10,560 County Series map sheet.

Summary

This briefly outlines the site's function, historical development and what now remains.

History

This is an overview of the site's development based primarily on depictions on past editions of the OS six-inch maps, supplemented by published information where available.

Each site component is now detailed:

Component	The OFIAR site number followed by component number, e.g. OFIAR-008-028.2 is
	component 2 at site 008-028.

Type Seventy-one different types of mill-related site were encountered in Co Offaly:

- Bleach works
- Bleach works (water)
- Blue mill
- Bonded warehouse
- Bone mill (water)
- Bottling works
- Brewery
- Brewery (water)
- Brewery house
- Chimney
- Chop mill
- Distillery
- Distillery (steam)
- Distillery (steam; water)
- Distillery office
- Electricity generating station (water)
- Engine house (steam)
- Factory canteen
- Factory garage
- Factory house
- Factory office
- Flax mill (water)
- Flax mill?
- Footwear factory
- Grain kiln
- Grain mill
- Grain mill (electric; water)
- Grain mill (steam)
- Grain mill (steam; water)
- Grain mill (water)
- Grain mill (water; steam)
- Grain mill (wind)
- Grain silo
- Grain store
- Hydraulic ram
- Jute factory (electricity; steam)
- Jute factory (electricity; steam; water)

- Jute store
- Kiln
- Malt house
- Malt kiln
- Malt silo
- Malt store
- Maltings office
- Mill
- Mill (water)
- Mill (wind)
- Mill building
- Mill chimney
- Mill house
- Mill race
- Mill weir
- Mill?
- Millstone quarry
- Newspaper printing works
- Oilseed mill (water)
- Quay
- Railway siding
- Saw mill
- Saw mill (steam)
- Saw mill (water)
- Smithy
- Spinning mill
- Starch house
- Tannery
- Threshing mill (horse)
- Threshing mill (water)
- Tobacco factory
- Tuck mill (water)
- Water pump (water)
- Weaving factory

Function

Offaly's mills have one several of 22 functional associations:

- Agricultural engineering
- Bone and fat products
- Brewing
- Cotton
- Distilling
- Electricity
- Flax & linen
- Footwear manufacture
- Grain milling
- Grain processing
- Inland waterway
- Jute
- Leather products
- Malting
- Oilseed milling

- Printing & publishing
- Stone
- Timber processing & products
- Tobacco processing & products
- Unknown
- Water supply
- Wool

Category

This field denotes the **industrial categories** with which the mill is associated. Offaly's mills fall into one or several of 13 categories:

- Animal-based products
- Drink processing & products
- Engineering
- Farming production
- Food processing & products
- Fuel & power production
- Mineral extraction, processing & products
- Other industry
- Textile manufacture & products
- Timber processing & products
- Transport
- Unknown
- Water supply & related processes

Context

This field denotes the **built heritage context** within which the mill operates. There are four such contexts:

- Agriculture & fishing
- Industry
- Infrastructure
- Settlement

Irish Grid

This gives the component's easting and northing, each to six figures (i.e. to 1m).

Accuracy

This gives the accuracy to which the component has been plotted on the *MapInfo* base map. In most cases, the six-inch map has been used as the basis of the plot. These may differ slightly from those generated using modern base maps and aerial photos on account of their differing projections. The grid coordinates given for each site component are reckoned to be within about 10m of their position on the ground. Sometimes it was only possible to locate a site to within 100m or 1km of its location.

Survey date

The day, month and year in which the site component was surveyed. A blank field denotes that it was not surveyed.

Surveyor

Name of surveyor (where surveyed).

Building remains

This denotes the degree of survival of the mill building:

- Complete
- Substantial remains
- Some remains
- Traces
- No visible remains

Building condition

This describes the condition of the buildings' remains:

- Excellent = virtually as new.
- Good = maintained in good condition.
- Fair = not maintained but in reasonable condition.
- Poor = not maintained and derelict.
- N/A = not applicable (in the case of sites with no upstanding remains).

Building use	The current use of the surviving building.
Waterworks remains	The degree of survival of the waterworks (weir, headrace and tailrace) associated with water-powered sites. For categories, see under 'Building remains'. N/A denotes water power not used.
Waterworks condition	The condition of the waterworks; see under 'Building condition' for categories.
Waterworks use	The current use of the waterworks, where surviving.
Plant remains	The degree of survival of the plant which drove the mill -generally waterwheels, turbines, and steam engines. For categories, see under 'Building remains'. N/A denotes no significant items of plant used.
Plant condition	The condition of the surviving plant; see under 'Building condition' for categories.
Plant use	The current use of the plant, where surviving.
Machinery remains	The degree of survival of the machinery - power transmission shafts/gears and primary items of machinery. For categories, see under 'Building remains'. N/A denotes no significant items of machinery used.
Machinery condition	The condition of the surviving machinery; see under 'Building condition' for categories.
Machinery use	The current use of the machinery, where surviving.
Description	A description of the physical elements which make up each site component. The buildings are described first, then waterworks, plant and machinery.

The record return	ns to the overall site:				
Interest	National Inventory of Architectural Heritage evaluation categories relevant to this particular site. Those particularly relevant to mill sites are: - Archaeological - Architectural - Group value - Historical - Rarity - Setting - Technical				
Evaluation	This is an evaluation of the industrial heritage significance of the overall site, including all its components.				
Rating	This denotes whether the site's industrial heritage significance: Record Only Local Regional National International				
Protection	 This denotes whether the site has any form of statutory protection: Birr RPS = Record of Protected Structures as listed in the Draft Birr Development Plan, 2010-16 Offaly RPS = Record of Protected Structures as listed in the Co Offaly 				

Development Plan, 2009-15

Action

Development Plan, 2010-16

Noted where the site is of regional or national significance. If the site is already

Tullamore RPS = Record of Protected Structures as listed in the Draft Tullamore

RMP = Record of Monuments & Places (Archaeological Survey Ireland)

	protected, no action is required. Otherwise a recommendation is given for inclusion in the RPS and/or RMP.
Associated with	Other sites within the OFIAR database with which the site is associated.
Other dbase	 Other databases containing additional details of this particular site. They are: NIAH = National Inventory Architectural Heritage Heritage rating is given in brackets: L = local; R = regional; N = national SMR = Sites & Monuments Record (Archaeological Survey Ireland)
References	This lists all published and unpublished references uncovered during the course of the 'paper survey' phase of the project. Photocopies of the actual material referenced will be found in the OFIAR files.
Photographs	For each image the following details are given: Number: OFIAR-002-006_03 denotes image 3 of site-002-006 Photographer: initials of photographer (FWH = Fred Hamond) Date: day/ month/ year Caption: what the image shows

Site indexes


The easiest way to find a particular site or set of sites matching particular criteria is to use the 'Find' facility on the PDF version of the Site Gazetteer. To find sites in the printed-out version of the gazetteer, six indexes are given at the back this volume. They are arranged as follows:

- 1. Name Townland Type Site component no
- 2. Townland Type Function Site component no
- 3. Town Type Function Site component no
- 4. Grid easting Grid northing Type Site component no
- 5. Type Function Townland Site component no
- 6. Statutory Protection Site component no

MapInfo data

Selected data fields are also held in *MapInfo* format. This requires the user to have access to this particular software (*MapInfo Professional* version 7.5 was used here) as well as base maps over which to overlay the site distributions (e.g. OS Discovery and six-inch maps).


The following figure shows an example of the MapInfo data for a mill in south Co Offaly. The cursor has been clicked over site OFIAR-045-015 to reveal the data relating to it. Additional details will also be found in the gazetteer contained in this volume.





Example of map and data generated using *MapInfo* for site 15 on map sheet 45. Clicking on the arrowed site brings up the 'Info Tool' table which gives basic details that particular mill.


MILL LOCATION MAPS


Ordered by OS six-inch map sheets






























Clara































Tullamore


























































Birr






























SITE GAZETTEER

Ordered by OFIAR number

0:4	OFIAD 004 000
Site no	OFIAR-001-002

County Planning	Offaly Offaly CC	Townland Moyally; {F	Parkwood}	Town Six-inch map 1
Summary	Site of 18th/ea Gageborough	ırly 19th century water-pow River.	rered grain mill and	kiln on tributary of the
History	described as a Byrne. It had a the 1854 Griffi	d kiln are explicitly cited or corn mill in the 1840s Mill 16ft x 3ft 10in waterwhee th Valuation under Samue not cited on the 1884 or 19	Valuation book and to two pairs of stor Collins. It probably	was worked by Daniel nes. The mill is cited in stopped in the later

Component OFIAR-001-002 1

Type Grain kiln; Grain mill (water) Function Grain milling

associated with the flour mill to the west (OFIAR/001/003).

Category Food processing & products Context Industry

Irish Grid 221788 238617 +/- 10m

Survey date 10/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Use N/A Condition N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill and kiln on minor tributary of the Gageborough River. It stood in

what is now a car park east of 'The Well' public house, on the north side of main Moate-Kilbeggan road. The watercourse to the headrace is canalised hereabouts and its sides are lined with stones. The actual head and tail races are both infilled and

there is no plant or machinery.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-001-003?

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-001-0	003		Marchbrook Mill
County	Offaly	Townland Moya	ally; {Parkwood	d} Town
Planning	Offaly CC	Discovery map	48	Six-inch map 1
Summary				oowered grain mill to rear of The On tributary of Gageborough River.
History	Marshbrook Mill is explicitly cited at this location on the 1838 OS six-inch map. It may have been associated with a corn mill a short distance to its east (OFIAR/001/002). It appears to have stopped soon afterwards as it not cited in the 1840s Mill Valuation Book or in the 1854 Griffith Valuation. It is shown but not captioned on the 1884 and 1909 maps.			
Component	OFIAR-001-003	1		
Туре	Grain mill (wate	r)	Function	Grain milling
Category	Food processing	g & products	Context	Industry

Irish Grid 221725 238627 +/- 10m

Survey date 10/06/2003 Surveyor Fred Hamond

Condition Poor Use Disused Building Remains Some remains Use N/A Waterworks Remains No visible remains Condition N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Ruinous remains of 18th/19th century grain mill on minor tributary of the

Gageborough River, behind 'The Well' public house, on the north side of main Moate-

Kilbeggan road.

Buildings

The mill is of L-plan, two storeys high at NW but generally reduced to a single storey; its original height and number of bays are now indeterminate. The walls are of random rubble. No original openings survive apart from an infilled semi-elliptical brick-headed doorway in an internal party wall.

The adjacent Well public house was formerly Marshbrook House. It is a four-storey/ three-bay building with hipped replacement artificial slate roof, painted rendered walls and 6/6 sash windows. Later extensions abut its west, north and east elevations.

Waterworks, plant and machinery

The watercourse which supplied the headrace is canalised hereabouts and its sides are lined with stones. There is now no visible evidence of the head and tail races, or of any plant or machinery.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-001-002?

Other dbase

References

OFIAR-001-003_01 FWH 10/06/2003 Looking west up canalised section of river to north of mill.



OFIAR-001-003_02 FWH 10/06/2003 Marchbrook House from south-east.



0 14	0 = 1 4 D 000 000	_
Site no	OFIAR-002-006	j

County	Offaly	Townland Cappydonnell Little	Town
Planning	Offaly CC	Discovery map 48	Six-inch map 2
Summary		s of 18th/early 19th water-powered co loat-Kilbeggan Road. On Gageborou	
History	A corn mill and kiln are cited at this location in the 1838, 1884 and 1910 OS six-inch maps. It is described as a corn mill in the 1840s Mill Valuation book and was operate by Timothy Buckley. It had a 10ft x 3ft waterwheel to two sets of stones. In 1854 it		

Component OFIAR-002-006 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 227523 238255 +/- 10m

Survey date 10/06/2003 Surveyor Fred Hamond

was worked by Joseph Hackett.

Building Remains Some remains Condition Poor Use Disused Waterworks Remains Substantial remains Condition Fair Use Disused Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains Traces Condition Fair Use Disused

Description Ruinous remains of 18th/19th century corn mill and kiln on minor tributary of the Gageborough River, just north of farmhouse down a laneway off main Moate-

Kilbeggan road immediately west of Horseleap.

Buildings

The remains comprise a multi-bay range aligned NW-SE on a south-facing slope. The mill itself has been reduced to foundation level except for the waterwheel section, enclosed in a partly truncated two-storey/single-bay section with random rubble walls. The east wall of the waterwheel section is abutted by a two-storey store with replacement pitched corrugated metal roof. The kiln was probably incorporated in this block, but has also been reduced to foundation level. Square-headed window and door openings, where they exist. Immediately south of the mill complex is a refurbished two-storey farmhouse (undoubtedly the former mill house) with artificial slate roof, rendered walls and uPVC windows.

Waterworks, plant and machinery

Water still flows through the waterwheel pit and bypass channel to east. The tailrace is culverted under the yard between the mill and house. The waterwheel does not survive but a one-piece conglomerate runner stone 107cm diameter (3ft 6in) lies against a nearby outbuilding.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-002-006_01 FWH 10/06/2003 General view from south-west. The waterwheel was housed in the overgrown section left of the roofed store at right.



 $OFIAR-002-006_02 \quad FWH \quad 10/06/2003 \qquad South-east \ gable \ of \ mill-related \ store; \ refurbished \ farmhouse \ at \ left.$



 $OFIAR-002-006_03 \quad FWH \quad 10/06/2003 \qquad One-piece \ conglomerate \ millstone \ (30cm \ scale).$



C:4	OFIAD 000 040	•
Site no	OFIAR-002-010	J

County	Offaly	Townland	Ballicknahee	Town
--------	--------	----------	--------------	------

Planning Offaly CC Discovery map 48 Six-inch map 2

Summary Possible site of late 19th/early 20th century windmill of unknown function.

History Cited in the 1910 OS six-inch map as The Windmill, but not shown or captioned on earlier editions. The absence of this mill from the 19th century OS maps and Griffith

valuation suggests that it is a early 20th century erection or a fanciful local place

name.

Component OFIAR-002-010 1

Type Mill (wind) Function Unknown

Category Unknown Context Industry

Irish Grid 228677 234792 +/- 10m

Survey date 10/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A

Waterworks Remains N/A Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Possible site of 19th century windmill in middle of an Early Christian ringfort on a

south facing slope a short distance south of summit of Ballard Hill; it is approached via a lane from a farm at Cappanamorath, 1km to the SW. No trace of any structure

is now evident.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

OFIAR-002-010_01 FWH 10/06/2003 Looking north to tree ring around perimeter of ring fort.



 $OFIAR-002-010_02 \quad FWH \quad 10/06/2003 \qquad Looking \ north \ across \ interior \ of \ ring \ fort.$



Site no OFIAR-002-014

County Offaly Townland Tully (Kilcoursey By, Town

Ardarcher or Horseleap Par); {Tully (Kilcoursey By, Kilmanagh Parish)}

Planning Offaly CC Discovery map 48 Six-inch map 2

Summary Substantial remains of 18th/early 19th century tuck mill, now converted into a house

and outbuilding. On tributary of Gageborough River.

History A woollen factory is cited at this location in the 1838 and 1884 and OS six-inch maps.

It is described as a woollen factory in the 1840s Mill Valuation book and was operated by John Gibbons. It had a massive 30ft x 6ft high breastshot waterwheel. Along with the wheel at Garrycastle Mill (OFIAR-029-011), this was the largest diameter wheel in the county at this time. The wheel powered six fulling stocks used to shrink and wash

the cloth after it was woven.

In 1854 the factory was still operated by John Gibbons and had a relatively high rateable valuation of £60 (including a house and offices). Gibbons also ran a corn mill

in Newtown townland at this time (OFIAR-002-015).

Component OFIAR-002-014 1

Type Tuck mill (water) Function Wool

Category Textile manufacture & products Context Industry

Irish Grid 224181 237331 +/- 10m

Survey date 10/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Good Use Dwelling

Waterworks Remains Some remains Condition Fair Use Disused

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description A two-storey/six-bay 18th/19th century woollen mill on a tributary of the Gageborough

River. This site is approached down a lane running south of a minor road off the main

Moate-Kilbeggan road.

Buildings

The mill is aligned east-west and its western half has been converted to a dwelling. The mill and house are each three bays wide and two storeys high. They share a common pitched natural slate roof. The house has a rendered chimney at each end and rainwater goods. Both sections have rendered random rubble walls and square-headed openings.

The north elevation of the unconverted section is blank. Its south elevation has replacement timber windows and loading door to first floor. The ground floor doorway on this elevation is distinguished by a finely dressed flat stone head and jambs. The east gable is abutted by a one-storey former stable block, now with a monopitched roof and south elevation rebuilt in concrete blocks. The converted section has replacement uPVC windows and a relatively modern single-bay/ single-storey lean-to extension a south. There was formerly another section abutting at west, long demolished (the 1838 OS map suggests that this may have been the actual mill).

Waterworks, plant and machinery

The now-dry pond is NW of the mill, but there is now no indication of the head and tail races. Water still flows along a by-pass channel around and to the south of the pond. Just before it reaches Tully House, the water is turned east, the channel being enclosed to both sides by rubble stone walls, under which is a narrow tunnel to facilitate access to both banks. The water then spills over a waterfall and is culverted under the farmyard east of the house, eventually to return to the stream running around the east side of the complex.

No plant or machinery survives.

Interest Historical

Evaluation The industrial integrity of this mill is diminished by later conversion to a dwelling. It is

now primarily of local historical interest, being one of the few surviving wool-related

mills in Co Offaly.

Rating Local Protection Action

Associated with OFIAR-002-015

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 75 of Ireland c.1850 (Dublin, 2000).

OFIAR-002-014_01 FWH 10/06/2003 General view from north-west.



OFIAR-002-014_02 FWH 10/06/2003 North elevation, from north-west.



OFIAR-002-014_03 FWH 10/06/2003 General view from south-east.



OFIAR-002-014_04 FWH 10/06/2003 Dressed surround to door on south elevation.



OFIAR-002-014_05 FWH 10/06/2003 Aerial view of site (in possession of owner).



OFIAR-002-014_06 FWH 10/06/2003 Pond overspill tunnel under building.



OFIAR-002-014_07 FWH 10/06/2003 Waterfall on pond overspill.



OFIAR-002-014_08 FWH 10/06/2003 Culverted section of pond overspill at foot of waterfall.



OFIAR-002-014_09 FWH 10/06/2003 Tully House from north-west.



Site no	OFIAR-002-015
---------	---------------

County Offaly Townland Newtown (Kilcoursey By, Town

Kilcumreragh Par)

Planning Offaly CC Discovery map 48 Six-inch map 2

Summary Ruinous shell of mid 19th century water-powered corn mill, subsequently converted

to saw mill. On tributary of Gageborough River.

History Nothing is shown at this site on the 1838 OS six-inch map, nor is a mill cited in the

1840s Mill Valuation book. A corn mill operated by John Gibbons is cited in the 1854 Griffith valuation. Gibbons also operated a woollen mill in Tully townland at this time (OFIAR-002-014). A saw mill is cited here on the 1884 OS map. Operations may have

ceased by 1910 as no mill is explicitly cited on the six-inch map.

Component OFIAR-002-015 1

Type Grain mill (water); Saw mill (water) Function Grain milling; Timber processing &

products

Industry

Category Food processing & products; Context

Timber processing & products

Irish Grid 225014 238416 +/- 10m

Survey date 10/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Poor Use Disused

Waterworks Remains Some remains Condition Poor Use Disused

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains Traces Condition Fair Use Disused

Description Ruinous remains of 18th/19th century corn on tributary of Gageborough River;

accessed down a lane running south from a minor road to the south of the main Moate-Kilbeggan road. A saw mill was set up in the corn mill in the late 19th century

and probably shared the same power source.

Buildings

The complex comprises the roofless remains of a three-storey mill aligned east-west and of L plan. The walls are of random rubble with brick trim to the openings. The walls have mostly been reduced in height and all internal floors are gone.

Waterworks, plant and machinery

The head and tail races are still evident but are infilled in the immediate vicinity of the mill. The waterwheel pit on the outside of the east gable is also infilled and the waterwheel is long removed.

The only machinery to survive is the pitwheel and a cast-iron spur gear. These were probably part of a two-step transmission system which also drove the later saw mill.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Other dbase

References

OFIAR-002-015_01 FWH 10/06/2003 General view from south-west.



OFIAR-002-015_02 FWH 10/06/2003 General view from south-east.



OFIAR-002-015_03 FWH 10/06/2003 Pitwheel.



Site no	OFIAR-002-0	17				
County	Offaly	Townland E	,	Kilcou	rsey By)	Town
Planning	Offaly CC	Discovery m	ap 48			Six-inch map 2
Summary						nage works in 1955. tributary of Gageborough
History	This mill was ex dated to 636 AD			955 ar	nd its timbe	ers dendrochronologically
Component	OFIAR-002-017	1				
Туре	Grain mill (wate	r)	Fun	ction	Grain mil	ling
Category	Food processing	g & products	Con	text	Industry	
Irish Grid	225849 237230	+/- 10m				
Survey date	10/06/2003	Surve	yor Fre	d Han	nond	
Building	Remains No vi	sible remains	Condition	N/A	Use	N/A
Waterworks	Remains No vi	sible remains	Condition	N/A	Use	N/A
Plant	Remains No vi	sible remains	Condition	N/A	Use	N/A
Machinery	Remains No vi	sible remains	Condition	N/A	Use	N/A
Description	Site of horizontal watermill.					
Interest	Archaeological					
Evaluation		MP OF002-01	9), the pre	sent s		ord of Monuments & industrial heritage

Rating Record only Protection RMP OF002-019---**Action**

Associated with

Other dbase SMR OF002-019---

References

Archaeological Survey of Ireland record. Page(s)

Lucas, A.T. A horizontal mill at Ballykilleen, Co Offaly. In Journal Royal Page(s) 100-113

Society of Antiquaries of Ireland, vol. 85 (1955).

O'Brien, C. & Sweetman, P.D. Archaeological Inventory of County Offaly Page(s) 50

(Dublin: Stationery Office, 1997).

Site no	OFIAR-002-019

County Offaly Townland Gorteen (Kilcoursey By) Town

Planning Offaly CC Discovery map 48 Six-inch map 2

Summary Site of unlocated 17th century mill in Gorteen townland.

History Mill of unknown function shown in Gorteen townland in 17th century document.

Component OFIAR-002-019 1

Type Mill Function Unknown

Category Unknown Context Industry

Irish Grid 223344 235657 +/- 1000m

Survey date Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of unlocated mill within townland.

Interest Archaeological

Evaluation No industrial heritage interest.

Rating Record only Protection Action

Associated with

Other dbase SMR OF002-041---

References

Archaeological Survey of Ireland record.

Page(s)

C:40 100	OFIAD 004 044
Site no	OFIAR-004-011

County	Offaly	Townland Derryiron	Town
Planning	Offaly CC	Discovery map 49	Six-inch map 4
Summary	Site of 18th/ea	arly 19th century water-powered co	orn mill and kiln on Yellow River.
History	map, it was ex 1838 and 188 and was opera	ctant before then as a mill race and 4 maps. It is described as a corn mated by John and Thomas Mooney . The Mooneys are also cited in the	location until the 1910 OS six-inch d corn kiln are both captioned on the nill in the 1840s Mill Valuation book. An 8ft x 3ft waterwheel drove two e 1853 Griffith valuation as operating

Component OFIAR-004-011 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 253190 236202 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Use N/A Waterworks Remains No visible remains Condition N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of 18th/19th century corn mill and kiln on the Yellow River, on the west side of

minor road north of the main Rochfortbridge – Rhode road. The headrace appears to have been of some length and passed through what is now part of Rhode power

station. It has been subsumed by land reclamation.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-003-002

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 71 of Ireland c.1850 (Dublin, 2000).

C:40 mg	OFIAD AND	- 004
Site no	OFIAR-005	ว-บบ เ

County	Offaly	Townland Clonmacnoise	Town
Planning	Offaly CC	Discovery map 47	Six-inch map 5
Summary		rly 19th century water-powered corn mill a present dwelling may incorporate fabric o val mill.	

History

A corn mill is explicitly cited at this location on the 1838 OS six-inch map. The 1840s Mill Valuation notes John Connor as the operator of an oat and wheat mill. A 10ft x 2ft wheel drove a single set of stones but was "old and broken" at the time of valuation. A corn mill and kiln are noted in the 1854 Griffith Valuation under Thomas Connor. A Thomas Connor was also operating a corn mill elsewhere in the county at the same time (OFIAR-026-015), but whether they are the same person is uncertain. The mill had probably stopped by 1885 as it is not cited on the six-inch map of this date, or the 1909 map.

Component OFIAR-005-001 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 201529 230469 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Remains No visible remains Condition N/A Use N/A Building Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Condition N/A Machinery Remains No visible remains Use N/A

Description Site of 18th/19th century corn mill and kiln on small stream discharging into the River

Shannon, on the west side of a minor road running north from the main

Shannonbridge-Moate road. A single-storey/four-bay farmhouse now occupies the

site. No evident traces of former mill in wall fabric.

Interest Archaeological

Evaluation Although the site is of archaeological interest and included in the Record of

Monuments & Places (Offaly RMP OF005-067---), the absence of obvious upstanding

mill remains makes this site of no industrial heritage significance.

Rating Record only Protection RMP OF005-067--- Action

Associated with OFIAR-026-015?

Other dbase SMR OF005-067---

References

Archaeological Survey of Ireland record.

Page(s)

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills of Ireland c.1850 (Dublin, 2000).

Page(s) 72

0:4	OFIAD 000 000
Site no	OFIAR-006-003

County Planning	Offaly Offaly CC	Townland Door	n Demesne 47	Town Six-inch map 6
Summary			n century water-powered c re was formerly also a tucl	
History	inch maps. It is operated by Joh An old tuck mill waterwheel, ind	described as an oa nn Lyons. It had a 1 is also cited in this licating that it was n	nis location on the 1838, 1 t mill in the 1840s Mill Val 2ft x 1ft 11in waterwheel t valuation; it had a dilapid o longer operational. The /aluation); there is no mer	luation book and was to a single set of stones. ated 12ft x 1ft corn mill was still being

Component OFIAR-006-003 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 211513 232142 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Poor Use Disused Waterworks Remains Some remains Condition Poor Use Disused Remains No visible remains Condition N/A Use N/A **Plant** Machinery Remains No visible remains Condition N/A Use N/A

Description

Ruinous remains of corn mill on west side of The Brook (a tributary of the Boor River), behind a bungalow on the east side of the Athlone-Ferbane road. It is aligned north-south and consists of three random rubble walls, none of which are now to their original heights. There is one small square-headed window opening to the south gable.

The head and tailraces are still evident as overgrown ditches on the west side of the building, but the waterwheel pit is infilled. There are no evidence of plant or machinery.

Component OFIAR-006-003 2

Type Grain kiln Function Grain milling

Category Food processing & products Context Industry

Irish Grid 211525 232141 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A Use N/A Condition N/A Plant Remains N/A Use N/A Machinery Remains N/A Condition N/A Use N/A

Description The drying kiln lay just east of the corn mill but does not survive.

Component OFIAR-006-003 3

Type Tuck mill (water) Function Wool

Category Textile manufacture & products Context Industry

Irish Grid 211516 232131 +/- 100m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description No trace of the tuck mill survives.

Interest None

Evaluation No special industrial heritage significance.

Rating Local Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-006-003_01 FWH 24/06/2003 General view of mill from east.



Site no OFIAR-007-008		Grogan Mill	
County	Offaly	Townland Ballycumber	Town
Planning	Offaly CC	Discovery map 48	Six-inch map 7
Summary		ains of 18th/early 19th century water-po converted to corn mill and kiln in mid	
History	A linen factory is explicitly cited on the 1838 OS six-inch map together with a bleach green to its immediate west. This is probably the Blue mill cited in the 1840s Mill Valuation book. It belonged to Dr Thomas Molly and a 14ft x 4ft 3in wheel drove the machinery. The building had been converted to a corn mill by 1854 (Griffith Valuation), under Patrick Robins. This corn mill is cited on the 1884 map and named as Grogan corn		ue mill cited in the 1840s Mill I a 14ft x 4ft 3in wheel drove the 854 (Griffith Valuation), under

Component	OFIAR-007-008	1
-----------	---------------	---

Type Bleach works (water); Grain kiln; Function Flax & linen; Grain milling

Grain mill (water)

mill on the 1910 map.

Category Textile manufacture & products; Context Industry

Food processing & products

Irish Grid 220258 230653 +/- 10m

Survey date 10/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Poor Use Disused Waterworks Remains Some remains Condition Poor Use Drainage Plant Use Disused Remains Complete Condition Poor Machinery Remains Traces Condition Poor Use Disused

Description

Ruinous remains of 18th/19th century linen mill on minor tributary of the Brosna River, a short distance north of a house on the north side of main Ferbane-Clara road. It was converted into a grain mill and kiln during the 19th century and utilized the existing waterworks.

Buildings

The mill is a 2½ -storey/three-bay building aligned east-west. Now roofless, only the random rubble walls survive, collapsed at the east end. Square headed window openings and segmental-headed door openings, the latter with brick heads. It incorporates a kiln at its west end; neither its floor or firehole survive.

Waterworks, plant and machinery

The headrace supplying the mill from the north is still clearly evident, along with a bypass channel to the east. The tailrace has been infilled.

There was originally an internal waterwheel, the wheelpit of which is 1.2m (4ft) wide. The present turbine is a later insertion into this pit and was supplied from a mass-concrete cistern constructed therein. A rack-and-pinion operated sluice gate controlled the flow from the base of the cistern to the turbine. An upright drive shaft projects from the turbine, with a pulley at its top end.

The only surviving equipment is a lineshaft with two pulleys, undoubtedly related to the corn mill. It is uncertain whether this shaft was driven by the turbine or an external power source. Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-007-008_01 FWH 10/06/2003 General view from south.



OFIAR-007-008_02 FWH 10/06/2003 Interior showing penstock and pulley at top of turbine shaft.



OFIAR-007-008_03 FWH 10/06/2003 Sluice gate at exit from mill pond.



0:4	OFIAD 007 040
Site no	OFIAR-007-016

County	Offaly	Townland Castlearmstrong	Town
Planning	Offaly CC	Discovery map 48	Six-inch map 7
Summary	Site of 18th/early 19th century water-powered corn mill and kiln on tributary of River Brosna.		
History		mill and kiln are cited here on the 1838 40s or 1850s valuation books, or on su	. ,

Component OFIAR-007-016 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 217594 229936 +/- 10m

Survey date 10/06/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains No visible remains Condition N/A Use N/A Use N/A **Plant** Remains No visible remains Condition N/A Machinery Remains No visible remains Use N/A Condition N/A

Description Site of 18th/19th century corn mill and kiln on minor tributary of the River Brosna, a

short distance NW of Castle Armstrong. Just south of the mill are the remains of what was probably an ancillary building (shown on the 1838 map). This single bay, single storey building is aligned north-south and is now a roofless random rubble shell.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

OFIAR-007-016_01 FWH 10/06/2003 Ancillary building from south-west.



Site no	OFIAR-007-0	017				
County	Offaly	Townland (Cornafurrish	and C	orrabeg	Town
Planning	Offaly CC	Discovery m	ap 48			Six-inch map 7
Summary	Site of 18th/ear Brosna.	ly 19th century	water-powei	ed co	rn mill and k	kiln on tributary of River
History		An Old corn mill and kiln are cited on the 1838 OS six-inch map. They are not cited in the 1840s Mill Valuation book, nor in the 1850s Griffith valuation or subsequent OS maps.				
Component	OFIAR-007-017	7 1				
Туре	Grain kiln; Grai	n mill (water)	Fun	ction	Grain mill	ing
Category	Food processin	g & products	Con	itext	Industry	
Irish Grid	219560 22949	3 +/- 10m				
Survey date	10/06/2003	Surve	or Fre	d Han	nond	
Building	Remains No v	isible remains	Condition	N/A	Use I	N/A
Waterworks	Remains No v	isible remains	Condition	N/A	Use I	N/A
Plant	Remains No v	isible remains	Condition	N/A	Use I	N/A
Machinery	Remains No v	isible remains	Condition	N/A	Use I	N/A
Description	Site of 18th/19t immediately ea					of the River Brosna,
Interest	None					
Evaluation	No industrial he	ritage significa	nce.			

Rating Record only Protection Action

Associated with

Other dbase

References

Site no	OFIAR-007-0)18		
County	Offaly	Townland Ballyd	umber	Town Ballycumber
Planning	Offaly CC	Discovery map	48	Six-inch map 7
Summary	Site of 18th/ear	ly 19th century corn	and tuck mills o	n River Brosna.
History	occupied one of river was dredge	f the arches of the med and a new bridge re, as they are not c	ulti-span Ballyco erected. The m	six-inch map. They appear to hav umber Bridge. In the 1840s, the ills probably disappeared at this s or 1850s valuations or on
Component	OFIAR-007-018	3 1		
Туре	Grain mill (wate	er); Tuck mill (water)	Function G	rain milling; Wool
Category	Food processing Textile manufact	g & products; cture & products	Context In	ndustry
Irish Grid	221094 230614	4 +/- 10m		
Survey date	10/06/2003	Surveyor	Fred Hamor	nd
Building	Remains No v	isible remains Co	ndition N/A	Use N/A
Waterworks	Remains No v	isible remains Co	ndition N/A	Use N/A
Plant	Remains No v	isible remains Co	ndition N/A	Use N/A
Machinery	Remains No v	isible remains Co	ndition N/A	Use N/A
Description	Site of 18th/19th of Ballycumber		uck mills on righ	t bank of River Brosna in vicinity
Interest	None			
Evaluation	No industrial he	ritage significance.		

Action

Associated with

Record only Protection

Other dbase

Rating

References

Site no	OFIAR-007-019
OILE IIU	OI IAIN-001-013

County	Offaly	Townland Cranasallagh	Town
Planning	Offaly CC	Discovery map 48	Six-inch map 7
Summary	Site of 18th/early 19th century corn mill and kiln on tributary of River Brosna.		
History	An Old corn mill and kiln are cited here on the 1838 OS six-inch map. They are not cited in the 1840s or 1850s valuations, nor on subsequent OS maps.		

Component OFIAR-007-019 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 220609 231618 +/- 10m

Survey date 10/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A

Waterworks Remains Some remains Condition Fair Use Drainage

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Site of 18th/19th century corn mill and kiln on minor tributary of the River Brosna, just

south of a minor road 1km north of Ballycumber. The head and tailraces are now

utilized for land drainage purposes.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Site no	OFIAR-007	Blue House			
County	Offaly	Townland Ballycumber	Town Ballycumber		
Planning	Offaly CC	Discovery map 48	Six-inch map 7		
Summary	Ruinous two-storey building said to be connected with the processing of linen during 18th century.				
History	Although a building is shown at this location on the 1838, 1884 and 1910 OS six-inch maps, it is not captioned. Nothing is recorded in the 1840s Mill Valuation book. A blue mill and drying house are recorded in the 1854 Griffith valuation, under Dr Thomas H. Molloy. There is a reference to a Blue mill in 1840s Mill Valuation book, but this probably refers to Grogan Mill (OFIAR-007-008), in the same townland.				
Component	OEIAB 007.0				

Component OFIAR-007-021 1

Type Blue mill Function Flax & linen

Category Textile manufacture & products Context Industry

Irish Grid 220994 230567 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Use Disused Building Remains Substantial remains Condition Poor

Waterworks Condition N/A Use N/A Remains No visible remains **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description

This building, known locally as the Blue House, is located on the north side of the Brosna River, just downstream from the road bridge into the village.

It comprises a detached two-storey/three-bay symmetrical building, now disused. It is aligned east-west, with its principal façade facing south. It has a hipped natural slate roof (mostly gone), with remains of chimneys on its east and west gables. The walls are of random rubble (formerly rendered), with a moulded stone eaves course. The windows have flat voussoired head and finely dressed cills. At ground floor centre on the ground floor is a doorway with semicircular head and dressed stone jambs. The other elevations are blank. There are indications of infilled voussoired windows on the west elevation, subsequently blocked by the internal chimney breast. The north side is abutted by a modern Dutch barn. Internally, the first floor is now missing.

There was originally a staircase in the central bay.

There are no traces of any waterworks, plant or machinery.

Interest None

Evaluation In its present form, this building appears to be a house. However, it may originally

have been for some other purpose as there are indications of internal modification. It is locally said to have been connected with the linen industry. Its name suggests bleaching ('blue' was used to whiten cloth), but its industrial associations await documentary confirmation. Possibly of local industrial heritage significance.

Rating Local **Protection** Action

Other dbase

References

OFIAR-007-021_01 FWH 24/06/2003 General view from south-west.



OFIAR-007-021_02 FWH 24/06/2003 General view from south-east.



0:1	OFIAD 007 000
Site no	OFIAR-007-022

County Planning	Offaly Offaly CC	Townland Bohe	ernagrisna 48	Town Six-inch map 7
Summary	Unlocated mill o Brosna.	cited in 1854 Griffith	n Valuation. Probably wate	er powered off River
History	the 1840s Mill V a sizeable wate	/aluation book as a rwheel measuring 1	ix-inch map, nor is any ra corn mill belonging to The 5ft x 8ft to three sets of s on and had probably ceas	omas Molloy. It then had tones. It was vacant by

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 222023 230359 +/- 1000m

Survey date 10/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Use N/A Remains No visible remains Condition N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Unlocated corn mill on River Brosna. Its precise location within the townland is

uncertain, and there are no obvious remains.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-007-032
---------	---------------

County	/ Offal	v Townland	Ballybruncullin	Town
O Garrey	, Oliai,	, i o i i i i i i i i i i i i i i i i i	Banyoranoanin	

Planning Offaly CC Discovery map 48 Six-inch map 7

Summary Site of unlocated 17th century mill in Ballybruncullin townland.

History Mill of unknown function cited in 17th century document in Ballybruncullin townland.

Component OFIAR-007-032 1

Type Mill Function Unknown

Category Unknown Context Industry

Irish Grid 221740 229634 +/- 1000m

Survey date Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of unlocated mill within townland.

Interest Archaeological

Evaluation No industrial heritage interest.

Rating Record only Protection Action

Associated with

Other dbase SMR OF008-063---

References

Archaeological Survey of Ireland record.

Page(s)

Site no	OFIAR-008-0	001				
County	Offaly	Townland (Cloghatanny		Town	
Planning	Offaly CC	Discovery m	ap 48		Six-inch map	8
Summary	Derelict remain	s of water-powe	ered corn/tud	ck mill and	d kiln on Clonghatanny Riv	ver.
History	the 1884 and 19	910 maps. Noth	ning is cited i	in the 184	h map and a corn mill and 0s Mill Valuation book. A ion, under John Walton.	
Component	OFIAR-008-001	l 1				
Туре	Grain kiln; Grai mill (water)	n mill (water); T	Tuck Fun	ction G	rain milling; Wool	
Category	Food processin Textile manufac	•		ntext Ir	dustry	
Irish Grid	222173 23363	9 +/- 10m				
Survey date	10/06/2003	Surve	yor Fre	ed Hamon	d	
Building	Remains Som	e remains	Condition	Poor	Use Disused	
Waterworks	Remains No v	isible remains	Condition	N/A	Use N/A	
Plant	Remains No v	isible remains	Condition	N/A	Use N/A	
Machinery	Remains No v	isible remains	Condition	N/A	Use N/A	
Description	the west and so and devoid of o Internally, there	outh random rub penings. A late is a fireplace in gle-storey/two-b walls.	oble walls of r single-stor n the SW co pay house, w	the buildi ey agricul rner of th rith pitche	ank of Clonghatanny Riveing survive, 2½-3 storeys tural shed abuts at west. e building. d corrugated metal roof al	high
Interest	None					
Evaluation	No special indu	strial heritage s	significance.			
Rating	Record only	Protection			Action	

Associated with

Other dbase

References

OFIAR-008-001_01 FWH 10/06/2003 General view of kiln from north. Mill house at background left.



Site no	OFIAR-008	-009	Charlestown no.1 Mill
County	Offaly	Townland Kilcoursey	Town Clara
Planning	Offaly CC	Discovery map 48	Six-inch map 8
Summary	Brosna. Estab	ins of water-powered flour mill and ki lished by Goodbody family in 1839 a 118. Some remains of paddle wheel a	nd augmented by steam in 1843.

History

Established as a water-powered mill by Robert Goodbody & Sons in 1839. A flour mill and kiln are explicitly cited in the 1884 OS six-inch map (not shown on 1838 edition). Old photographs show it to have been a substantial six-storey block. It was known as Charlestown no.1 Mill (to distinguish it from its adjoining sister mill, OFIAR-008-042). It is described as a flour mill in the 1840s Mill Valuation book and was operated by Robert Goodbody. The waterwheel measured 13ft 6in x 10ft and drove five pairs of stones. It had the third highest valuation rating in the county - £75. Goodbody was also operating an adjoining flour mill at this time as well (OFIAR-008-042). Water power was supplemented by a steam engine in 1843. The engine was supplied by Roberts Brothers of Mountmellick and was peat fired. An extension of 1851 apparently collapsed into the yard. In the 1854 Griffith Valuation, the mill, kilns, offices and yard belonged to L.M. & J. Goodbody and were rated at £135 (the fourth highest rated industrial buildings in the entire county). The Goodbodys also operated the adjoining flour mill and cotton factory at the same time (OFIAR-008-042 and 008-054 respectively). The mill was totally destroyed by an accidental fire in 1918 and never reopened.

Component OFIAR-008-009 1

Type Engine house (steam); Grain kiln; Function Grain milling

Grain mill (water; steam)

Category Food processing & products Context Industry

Irish Grid 226148 232267 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused Waterworks Remains Substantial remains Condition Poor Use Disused Plant Remains Traces Condition Poor Use Disused

Machinery Remains No visible remains Condition N/A Use N/A

Description Derelict remains of mid 19th century flour mill and kiln situated off right bank of River Brosna at east end of Clara.

Buildings

The mill was originally a double-pile/six-storey/ten-bay building, but has been lowered to three storeys. It is aligned east-west and survives as a very overgrown ruinous random rubble shell. Most of the openings have square-heads; there is a semi-elliptical brick headed doorway on the west gable of the south pile. The building probably incorporates the former kiln, of which there is no trace. The shell of the engine house and vestiges of its associated chimney are at its east end. A wall break along this elevation confirms that the engine house and chimney are later additions (1843).

Immediately SW of the mill is a double-pile/two-storey store. It was probably connected with the mill and is of mid 20th century date. Now disused and in separate

ownership to the mill, this structure is clad in corrugated metal and has a curved metal roof and mass concrete ground-floor walls. There is a canopy to the south gable of the west pile.

Waterworks, plant and machinery

The long headrace off the Brosna is still clearly evident, as is the external waterwheel pit on the east gable of the north pile, and partly-culverted tailrace. Immediately east of the wheelpit area is a stone-lined bypass channel. There are also remains of a hydraulic ram.

The wheel pit contains the partly-buried remains of cast-iron starts and timber floats; these indicate a paddle wheel (as opposed to bucket wheel). The cill level of the water intake indicates a low breastshot feed thereto. The wheelpit is 3.20m (10ft 6in) wide and the radius of its curved cast-iron apron is 1.98-2.13m (6ft 6in - 7ft). This suggests a wheel at least 3.96m (13ft) in diameter by 3.05m (10ft wide). No machinery survives.

Interest Architectural; Group; Historical; Technical

Evaluation

Although approximately half its original height, this is mill is still of interest on account of its size, associated races, waterwheel remains, and historical links with the Goodbody family. It also has group value on account of its proximity to another flour mill owned by the Goodbodys - OFIAR-008-042. The wheel pit merits archaeological excavation, should the opportunity arise, in order to record and salvage what remains of the waterwheel. Overall, it is of local industrial heritage merit.

Rating Local Protection Action

OFIAR-008-042; OFIAR-008-054; OFIAR-Associated with 008-064

Other dbase

References

Lawrence, W. Miscellaneous photographs of Ireland. National Photographic Page(s) Royal 8322 Archive.

Quinn, D.B. 'Clara: a Midland Industrial Town'. In Nolan W. and O'Neill, T.P. Page(s) 802-803 (eds), Offaly: History and Society (Dublin: Geography Publications, 1998).

Quinn, D.B. 'Clara: a Midland Industrial Town'. In Nolan W. and O'Neill, T.P. Page(s) 809-810 (eds), Offaly: History and Society (Dublin: Geography Publications, 1998).

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills

of Ireland c.1850 (Dublin, 2000).

Page(s) 74

OFIAR-008-009_01 FWH 23/06/2003 General view of north elevation, from north-west.



OFIAR-008-009_02 FWH 23/06/2003 Curved metal apron at intake to waterwheel pit.



OFIAR-008-009_03 FWH 23/06/2003 Remains of waterwheel starts and floats.



OFIAR-008-009_04 FWH 23/06/2003 Looking towards tailrace culvert from waterwheel pit.



 $OFIAR-008-009_05 \quad FWH \quad 23/06/2003 \quad \quad Corrugated \ metal \ store, \ from \ south-west.$



Site no OFIAR-008-012

County Offaly; Townland Kilclare; Co Westmeath Town

Westmeath

Planning Offaly CC; Discovery map 48 Six-inch map 8

Westmeath CC

Summary 18th/early 19th century tailrace associated with bleach mill in Ballycahan townland,

Co Westmeath.

History An Old bleach green is recorded in an adjoining townland in Co Westmeath on the

1837 OS six-inch map (sheet 37).

Component OFIAR-008-012 1

Type Mill race Function Flax & linen

Category Textile manufacture & products Context Industry

Irish Grid 229360 233062 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Building Remains N/A Condition N/A Use N/A

Waterworks Remains Some remains Condition Poor Use Disused

Plant Remains N/A Condition N/A Use N/A Machinery Remains N/A Condition N/A Use N/A

Description Remains of tailrace running parallel with River Brosna, to west of Lismoyne Bridge.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Kinahan, R, Kenny, B., English, P. & Clyne, O. Clara: a Pictorial Record

Page(s) 33

(Tullamore, 1992).

Site no	OFIAR-008	-016	Coleraine flour mill
County	Offaly	Townland Loughaun	Town
Planning	Offaly CC	Discovery map 48	Six-inch map 8
Summary		mains of 18th/early 19th century wate lver River. In use as corn mill in 1850	
History	mill in the 184 waterwheel to valuation, und	or mill is explicitly cited in the 1838 OS 10s Mill Valuation book, under Philip E two sets of stones. A corn mill and ki der Robert B. Slater. They were in ruir ned on the 1910 edition.	Bolton; it had a 13ft x 4ft In are noted in the 1854 Griffith

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 230256 228981 +/- 10m

Survey date 09/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused

Waterworks Remains No visible remains Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description

Substantial derelict remains of 18th/19th century flour mill on right bank of tributary of Silver River, east of the main Tullamore-Clara road. It comprises a detached two-storey (+ attic)/ six-bay building aligned north-south with its principal elevation to west. Its pitched natural slate roof is now missing. There is a chimney to centre. The walls are of rendered random rubble, with a projecting dressed stone eaves. The openings are mostly square-headed, with voussoired lintels, brick jambs and dressed cills. There is a loading door to the first floor. The north gable is abutted by a two-storey/single-bay lean-to. The rear elevation is abutted by two two-storey/single-bay returns (probably once kilns) and a single-storey/single-bay return. All internal fixtures and fittings are missing save for a ground floor fireplace. On the south gable is an infilled brick-trimmed opening for the former waterwheel axle.

No traces of waterworks, plant or machinery.

Interest Historical; Setting

Evaluation This substantial building incorporates the mill, kiln(s) and house. Although ruinous, it

is of historical and landscape interest. It is also noted in the Sites & Monuments Record because of its proximity to an ecclesiastical site (SMR OF008-043---). It is of

local industrial heritage merit in its own right.

Rating Local Protection Action

Associated with

Other dbase SMR OF008-043---

References

Archaeological Survey of Ireland record.

Page(s)

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills of Ireland c.1850 (Dublin, 2000).

Page(s)

OFIAR-008-016_01 FWH 09/06/2003 General view from south-west.



OFIAR-008-016_02 FWH 09/06/2003 General view from north-west.



AR-008-025

County	Offaly	Townland Kilcoursey	Town
Planning	Offaly CC	Discovery map 48	Six-inch map 8
Summary	Site of 18th/ea	arly 19th century bleachworks on nort	th bank of River Brosna.
History	defunct by the	en is cited on the 1838 OS six-inch ma e mid 1800s as it is not cited in the 18 ion. Uncertain if water power ever us	340s Mill Valuation book or the 1854

Type Bleach works Function Flax & linen

Category Textile manufacture & products Context Industry

Irish Grid 227187 232302 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A
Waterworks Remains No visible remains Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Site of bleachworks on the right bank of the River Brosna, on a gentle south-facing

slope.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Site no	o OFIAR-008-028		Clashawaun Works	
County	Offaly	Townland Erry (Armstrong)	Town Clara	
Planning	Offaly CC	Discovery map 48	Six-inch map 8	
Summary	Extensive jute	e spinning and weaving complex establis	hed by Jonathan and Lewis	

Frederic Goodbody in 1865. Expanded to south side of road by Robert Goodbody in 1873. Powered by water, steam and electricity. The first steam engine was installed in 1870. Concrete chimney erected 1884. Rope walk cited in 1884 OS map. The complex was electrified in 1951. Goodbodys ceased production in 1984. The premises are now used for storage and distribution of synthetic yarns. Also incorporates two steam engine houses, water turbine, mill-related offices and housing, and siding off former Great Southern & Western Railway.

History

Ireland's first jute factory was established on the north side of the Clara road in 1865 by Jonathan and Lewis Frederic Goodbody. Here jute was spun and woven, the power being supplied by a waterwheel off the River Brosna. The wheel, which came from the Hibernia Foundry, Mountmellick, was supplemented by a steam engine in 1870. The latter was replaced by a larger engine in 1884, the same year in which the circular concrete chimney was built by Robert Goodbody (third son of Jonathan). The wheel was eventually superseded by a turbine. This complex also had a gas works which apparently supplied both it and Clara.

In 1873, Robert Goodbody transferred spinning operations to a new site on the south side of the main road. Houses for the staff were also constructed here, and a goods siding off the main Portarlington-Athlone railway. This side of the premises was powered by a purpose-built steam engine.

Over succeeding decades, new, more automated machinery was added. In the 1950s, steam power was superseded by electricity. In 1960, an extension was added to the weaving factory on the north side of the road.

The jute mill ceased production in the 1970s and Goodbodys went into receivership in 1984. The premises are now occupied by Synthetic Packaging Ltd and the buildings are used as warehouses.

Component OFIAR-008-028 1

Type	Chimney	Function	Jute

Category Textile manufacture & products Context Industry

Irish Grid 224937 232215 +/- 10m

Fred Hamond Survey date 11/09/2003 Surveyor

Building Remains Substantial remains Condition Fair Use Disused

Waterworks Use N/A Remains N/A Condition N/A **Plant** Remains N/A Condition N/A Use N/A Machinery Remains N/A Condition N/A Use N/A

Description

Freestanding reinforced-concrete chimney on north side of road at west end of site. It is of circular cross-section and slightly tapered profile and sits on an octagonal concrete base. Tie straps around upper section and lighting conductor. The top-most section fell off when it struck by lighting in 1962. What survives is in fair condition, but is no longer in use.

Type Jute store Function Jute

Category Textile manufacture & products Context Industry

Irish Grid 224950 232219 +/- 10m

Survey date 11/09/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A
Use N/A

Description A single-storey/six-bay jute store aligned north-south, with its south gable on to the

north side of the road. Pitched corrugated roof with circular ridge vents and rainwater goods, all in asbestos fibre cement. Cement-dashed brick walls with exposed dressed limestone quoins. Square-headed window openings with metal casement windows and concrete cills. A door in south gable is linked to the main road by a metal girder/concrete slab footbridge. Survives in good condition but seemingly disused.

Component OFIAR-008-028 3

Type Factory canteen Function Jute

Category Textile manufacture & products Context Industry

Irish Grid 224979 232223 +/- 10m

Survey date 11/09/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description A two-storey/four-bay former workers' canteen aligned east-west on north side of

road towards west end of site. Curved corrugated metal roof with slightly raised ridge vent. No rainwater goods. Cement-rendered random rubble walls. Large double- and tripartite square headed windows to first floor, some with concrete cills; all now sheeted over. A metal girder/concrete slab footbridge over the tailrace links a door at

SE corner of ground floor with main road.

Type Electricity generating station Function Jute

(water)

Category Textile manufacture & products Context Industry

Irish Grid 224995 232233 +/- 10m

Survey date 11/09/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Electricity generation Waterworks Remains Complete Condition Good Use Electricity generation Condition Good Plant Remains Complete Use Electricity generation Machinery Remains Complete Condition Good Use Electricity generation

Description Small turbine house aligned north-south on north side of road at east end of former

canteen. Generates electricity for the factory, with excess to ESB grid. Generator manufactured by British Thomson Houston (Rugby) and dates from 1936. The water for the turbine is diverted off the river directly to the headrace, the pond on the other side of the river now being defunct. The cement-lined tailrace is evident along the

south side of the canteen.

Component OFIAR-008-028 5

Type Engine house (steam) Function Jute

Category Textile manufacture & products Context Industry

Irish Grid 225004 232233 +/- 10m

Survey date 11/09/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Disused

Waterworks Remains N/A Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains N/A Condition N/A Use N/A

Description Two-storey engine house aligned north-south with south gable fronting north side of

road. May date from 1884 when the original steam engine was superseded by a larger model. Pitched corrugated metal roof, plain timber bargeboards (with finials), and galvanised metal trough gutters. Lined cement-rendered walls with brick dressings to quoins and openings; the upper sections are slightly advanced. Double-

height semicircular headed window and triangular apex window to south gable, both

sheeted over. Plant long removed.

Type Jute factory (electricity; steam; Function Jute

water)

Category Textile manufacture & products Context Industry

Irish Grid 225022 232258 +/- 10m

Survey date 11/09/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Warehouse

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

Description A single-storey multi-bay weaving shed behind the office block fronting the north side

of the road. This section is almost certainly of 1865 date, when the complex was established. Each bay has a sawtooth-profiled roof clad in corrugated metal; glazing

to the east pitch. Walls are cement rendered.

Component OFIAR-008-028 7

Type Factory office Function Jute

Category Textile manufacture & products Context Industry

Irish Grid 225035 232236 +/- 10m

Survey date 11/09/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Offices

Waterworks Remains N/A Condition N/A Use N/A

Plant Remains N/A Condition N/A Use N/A

Machinery Remains N/A Condition N/A Use N/A

Description

Three factory office buildings along north side of main road. At west is a single-storey/four-bay office aligned east-west. May date to 1865. Hipped corrugated metal roof, tall rendered chimneys to rear eaves, and ogee cast-iron rainwater goods. Lined cement rendered walls. Square-headed openings. Paired 1/1 sliding sash windows and stone cills. Panelled entrance door with overlight. In good condition, but possibly disused.

To its east is a two-storey/three-bay office aligned north-south. Possibly dates to 1865. Hipped corrugated metal roof with soffited brick eaves and ogee cast-iron rainwater goods. Lined cement-rendered walls with square-headed openings. Those to the windows have shallow segmental brick heads and jambs (stepped and chamfered), and stone cills. All windows are 1/1 sliding sashes. Those to the ground floor may be set in what was formerly a segmental arched doorway. Decorative wrought-iron railings on low plinth to street frontage.

East again is a two-storey/eight-bay office block aligned east-west and the most prominent feature on this side of the road. Probably of later 19th century date. Hipped corrugated metal roof with circular metal ridge vents, timber bargeboards and soffited eaves carrying ogee cast-iron rainwater goods. Lined cement-rendered walls with square-headed openings. The window openings, which are generally paired, have 1/1 sliding sash windows and concrete cills. Two doorways to ground floor, both with double-leaf timber doors and overlights.

Type Factory garage Function Jute

Category Textile manufacture & products Context Industry

Irish Grid 225077 232261 +/- 10m

Survey date 11/09/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Good Use Warehouse

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A
Condition N/A Use N/A

Description At the east end of the block along the north side of the road is a large single-

storey/single-bay mid 20th century factory-related garage aligned north-south. Pitched corrugated asbestos roof with asbestos rainwater goods. Cement-rendered walls. South gable to road has a pair of sliding timber doors. North gable opens into

former weaving sheds.

Component OFIAR-008-028 9

Type Factory house Function Jute

Category Textile manufacture & products Context Industry

Irish Grid 224967 232184 +/- 10m

Survey date 11/09/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description At the west end of the block on the south side of the main road is a pair of semi-

detached two-storey/three-bay factory-related houses. Probably erected in 1870s. Pitched natural slate roof with brick chimneys (one rendered), plain bargeboards, and half-round metal rainwater goods. Cement-harled walls. Window openings are square-headed and have 1/1 sashes and stone cills. Symmetrically placed semicircular

doorway to each house with panelled timber door and overlight.

There was a terrace of 12 workers' houses to the west of this house, all now

demolished.

Type Factory house Function Jute

Category Textile manufacture & products Context Industry

Irish Grid 224993 232191 +/- 10m

Survey date 11/09/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A
Condition N/A Use N/A

Description A two-storey/three-bay factory-related dwelling detailed and dated as the pair of

houses to its west (component 9).

Component OFIAR-008-028 11

Type Engine house (steam) Function Jute

Category Textile manufacture & products Context Industry

Irish Grid 225037 232166 +/- 10m

Survey date 11/09/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description Towards the west end of the factory block on the south side of the road, a second

engine house rises above the saw-tooth roofs. Aligned north-south, it has a pitched corrugated asbestos roof over angle-iron trusses. The upper sections of the walls are also clad in corrugated metal; the lower sections are of mass concrete. The steam

engine was on the upper floor but is long removed.

Type Jute factory (electricity; steam) Function Jute

Category Textile manufacture & products Context Industry

Irish Grid 225050 232187 +/- 10m

Survey date 11/09/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Warehouse

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

Description A single-storey/18-bay former spinning mill of 1873 aligned east-west along the south

side of the road. Excepting the street frontage, it has saw-tooth roofs clad in natural and artificial slate, with continuous skylights to their north pitches. Metal rainwater goods. The wall of the street elevation is of random rubble limestone (brought to courses), and has vee-jointed quoins. A low stone parapet runs its entire length over advanced dressed stone eaves; there are two small rendered chimneys towards its west end. This building may be of two phases as it has an advanced basal course of stone on its west half, and of concrete to its east half. All 16 window openings to this elevation have segmental heads and contain 2/2 sash windows, trimmed in slightly-projecting stepped brickwork and with stone cills. There are two semicircular-headed dressed-stone entrances, one for pedestrians, the other for vehicles; the keystone of the latter is inscribed "Clashawaun Works/ 1873". The gables of all the bays are rendered with cement and most have circular apex vents. An Edward VII letterbox is set into the front wall at the west end of the mill.

Internally, the roof is supported on perforated cast-iron trusses (designed by Robert Goodbody); their supporing cast-iron columns double as rainwater downpipes. Immediately east of this block were 44 workers' houses arranged in 16 blocks; all have been demolished.

Component OFIAR-008-028 13

Type Railway siding Function Jute

Category Textile manufacture & products Context Industry

Irish Grid 225180 232103 +/- 10m

Survey date 11/09/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A
Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A

Machinery Remains N/A Condition N/A Use N/A

Description Along the SE side of the premises was a siding off the Clara-Athlone railway line, no

tracres of which survive. A conveyor transferred the bales of jute into a goods sheds,

also long gone.

Interest Architectural; Historical; Rarity, Setting; Technical

Evaluation This complex is of architectural interest on account of its massing, use of various

materials and range of functional forms (e.g. the two engine houses). The saw tooth roof forms are unusual in the context of Co Offaly; there are only two other instances in the county and both date from the 1930s - Tullamore (OFIAR-017-085) and Birr (OFIAR-035-053). The tall chimney is one of the few such examples in the county and an early example of the structural use of reinforced concrete. The vestiges of the former workers' houses are also of note (one of the few factory sites in Offaly to have associated houses). The complex is also of historical interest in being the first of only a few jute mills to be established in Ireland. Its association with the Goodbodys, prominent local industrialists, is also of note. The range of different materials (stone, brick and concrete) incorporated in the buildings also illustrate the site's spatial evolution during the later 19th century. The turbine and the waterworks are also of technical interest. Both roadside blocks and the tall concrete chimney are prominent landmarks on entering Clara from the west. At a smaller scale, the Edward VII letter box also enhances the streetscape.

The complex is of regional industrial heritage interest and merits its inclusion as a Protected Structure in the Co Offaly County Development Plan 2009-15.

Rating Regional Protection Offaly RPS 12-37; Action None (in RPS)
Offaly RPS 12-39

Associated with OFIAR-008-030

Other dbase NIAH 14802033 (R); NIAH 14802035 (R)

References		
Cox, R.C. & Gould, M.H. Civil Engineering Heritage Ireland (London: Thomas Telford, 1998).	Page(s)	84
Kinahan, R, Kenny, B., English, P. & Clyne, O. Clara: a Pictorial Record (Tullamore, 1992).	Page(s)	151
Kinahan, R, Kenny, B., English, P. & Clyne, O. Clara: a Pictorial Record (Tullamore, 1992).	Page(s)	157
Kinahan, R, Kenny, B., English, P. & Clyne, O. Clara: a Pictorial Record (Tullamore, 1992).	Page(s)	162
Kinahan, R, Kenny, B., English, P. & Clyne, O. Clara: a Pictorial Record (Tullamore, 1992).	Page(s)	164
Kinahan, R, Kenny, B., English, P. & Clyne, O. Clara: a Pictorial Record (Tullamore, 1992).	Page(s)	165
Neame, N. Goodbodys of Clara (Clara: J. & L.F. Goodbody Ltd, 1965).	Page(s)	
Quinn, D.B. 'Clara: a Midland Industrial Town'. In Nolan W. and O'Neill, T.P. (eds), Offaly: History and Society (Dublin: Geography Publications, 1998).	Page(s)	800
Quinn, D.B. 'Clara: a Midland Industrial Town'. In Nolan W. and O'Neill, T.P. (eds), Offaly: History and Society (Dublin: Geography Publications, 1998).	Page(s)	808-809
Tullamore Tribune, 24 Nov 1984.	Page(s)	

OFIAR-008-028_01 FWH 11/09/2003 General view of complex from west.



OFIAR-008-028_02 FWH 11/09/2003 1884 concrete chimney, from south.



OFIAR-008-028_03 FWH 11/09/2003 Chimney (left), store (middle) and canteen (right), from west.



OFIAR-008-028_04 FWH 11/09/2003 South elevation of canteen and tailrace, from west.



 $OFIAR-008-028_05 \quad FWH \quad 11/09/2003 \qquad South \ gable \ of \ engine \ house \ on \ north \ side \ of \ road.$





OFIAR-008-028_07 FWH 11/09/2003 Garage at east end of north block, from east.



 $OFIAR-008-028_08 \quad FWH \quad 11/09/2003 \qquad Dwellings \ at \ west \ end \ of \ south \ block, \ from \ west.$



 $OFIAR-008-028_09 \quad FWH \quad 11/09/2003 \qquad Spinning factory on south side of road, from east.$



OFIAR-008-028_10 FWH 11/09/2003 Datestone on vehicular entrance to spinning factory.



OFIAR-008-028_11 FWH 11/09/2003 Window detailing on street elevation of spinning factory.



 $OFIAR-008-028_12 \quad FWH \quad 11/09/2003 \qquad Edward \ VII \ letter \ box \ at \ west \ end \ of \ spinning \ mill \ wall.$



0 14	0 = 1 4 D 000 000
Site no	OFIAR-008-029

County	Offaly	Townland Lehinch	Town		
Planning	Offaly CC	Discovery map 48	Six-inch map 8		
Summary	Site of 18th/early 19th century water-powered corn mill on tributary of River Brosna.				
History	A corn mill is explicitly cited on the 1838 OS six-inch map. It is described as a corn mill in the 1840s Mill Valuation book and was operated by John Hackett. It had a 10ft x 4ft waterwheel to two sets of stones. It was defunct soon afterwards as it is not cited on the 1854 Griffith Valuation book, or on subsequent OS maps.				

Grain mill (water) **Function** Grain milling Type

Category Food processing & products Context Industry

Irish Grid 228891 233001 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Condition N/A Use N/A Building Remains No visible remains Waterworks Use N/A Remains No visible remains Condition N/A Remains No visible remains Plant Condition N/A Use N/A Machinery Remains No visible remains Use N/A Condition N/A

Description Site of corn mill on right bank of a tributary of the River Brosna, immediately south of

> the main Clara-Kilbeggan road. There are no evident traces of the mill, waterworks, plant or machinery. A ruinous single-storey random rubble building may have been

associated.

Interest None

Evaluation No industrial heritage merit.

Action Record only **Protection** Rating

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-008-029_01 FWH 23/06/2003 General view of ancillary building, from east.



Site no OFIAR-008-038 Erry Mill

County	Offaly	Townland Erry (Maryborough)	Town Clara
Planning	Offaly CC	Discovery map 48	Six-inch map 8

Summary

Substantial remains of late 18th/early 19th century water-powered grain mill in centre of Clara on River Brosna. Acquired by Goodbody family around 1850. Remodelled c.1920, when steam engines and turbines (for electricity) also installed. Acquired by Messrs Ranks c.1930. New generator installed in late 1900s to supply electricity to ESB grid. Flour milling equipment, engine house, chimney and hydro-electric plant survive.

History

A flour mill and kiln are cited on the 1838 and 1884 OS six-inch maps. It is described as a flour mill in the 1840s Mill Valuation book and was operated by John Dugdale & Co. The mill then contained nine sets of stones. Only one other mill in the county (Manor Mill, Birr - OFIAR-035-009) had this number of stones at this time (the average was two or three sets). These were powered by a massive breastshot 28ft x 7ft waterwheel - the third biggest diameter wheel in the county at that time. The property's valuation was over £68, making it the fifth most valuable industrial site in the county in the 1840s.

By the 1854 Griffith Valuation, Erry Mill was in the hands of Robert Perry & Co and now had the highest of any industrial premises in the county - £180. During the mid 1860s, the mill came into the possession of the Goodbody family; their name appears in the 1866 valuation revision book.

The mill was re-equipped in 1919-1922 to produce 10 sacks of flour per hour (equivalent to a throughput of one ton of wheat per hour at 75% extraction rate). The floor levels inside the mill were reconfigured to accommodate this and ancillary equipment for cleaning and conditioning the grain, and grading and packing the flour, pollard and bran. Animal feedstuffs were also produced in the screen house side of the mill. The waterwheel was replaced by one or more Gilkes turbines and by a steam engine; the millstones were superseded by roller mills. Silos and a spur from the railway were also constructed on the opposite side of the road (OFIAR-008-053). Ranks (Ireland) Ltd acquired the mill from the Goodbodys around 1930. In the 1950s, the mill was connected up to an ESB mains supply. In the late 1950s, second-hand turbines from Quarterstown Mill, Mallow were installed. These generated electricity for motors inside the mill, the ESB supply acting as a back-up. The steam engine was probably discontinued at the same time.

Ranks continued to operate the mill until its closure around 1969. A new generator was subsequently installed and the existing turbines used to generate electricity which was exported to the ESB.

Component OFIAR-008-038 1

Туре	Grain kiln; Grain mill (water)	Function	Grain milling
Category	Food processing & products	Context	Industry

Irish Grid 225666 232461 +/- 10m

Survey date 15/10/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Fair Use Disused Waterworks Remains Complete Condition Good Use Disused Plant Remains Complete Condition Fair Use Disused Machinery Remains Substantial remains Condition Good Use Disused

Description

Substantial remains of an extensive 18th/19th century flour milling complex on left bank of River Brosna at the corner of Bridge St and Frederick St (at south end of Clara). The site comprises the flour mill and ancillary buildings (including houses, engine house and chimney), waterworks, and 20th century turbines and machinery.

Building

Six storey/seven-bay former flour mill aligned north-south in middle of complex. Half-hipped natural slate roof, eaves chimney on west elevation, and half-round metal rainwater goods. Painted harled-cement walls with advanced eaves over rubble masonry; evidence of stone quoins (rendered over). Square-headed openings with brick dressings (also rendered over), 2x2 timber casement windows and stone cills. The window levels relate to the internal floors before they were reconfigured with the remodelling of the mill c.1920. There is some leakage to the roof, but it is otherwise in fair condition and stands unused.

Internally, a longitudinal wall runs down the centre of the building and divides it into two sections. The west section contains the screening (cleaning) and preparing machinery over five floors and the east section the flour milling and purifying equipment over four floors; only the ground and top floors of each section are level with one another. All floors are of timber over joists resting on transverse beams supported on timber uprights (but RSJ columns to the ground floor). At the south end of the west section, there are vestiges of the original flooring supported on cast-iron columns. Ladder stairs connect all floors. The walls are painted and plastered. The roof is internally plastered and rests on common rafters over double purlins on queenpost trusses. Skylights to north and south pitches.

The west elevation of the mill is abutted by a two-storey/two-bay return. The latter is abutted at south by a two-storey/two-bay lean-to. Both buildings share a corrugated metal roof. Walls harled as main block; the lean-to may be of brick underneath. Square-headed openings with 6/6 sliding sash windows and stone cills; security bars to ground floor. This section houses an office, now dilapidated. One of these returns was probably a grain drying kiln originally, but was subsequently converted to other uses when the mill was remodelled.

The mill's east elevation is abutted by three returns, all now dilapidated. At south is a small single-storey/two-bay building with flat concrete roof, and harled walls. Two heavy steel entrance doors. Contains traces of flour bleaching gas plant (Dyox) by Wallace and Tiernan. At middle is a two-storey/four-bay building with corrugated metal monopitched roof, harled walls and square-headed openings; stone cills to windows (now sheeted over). At north is a three-storey/single-bay building with flat concrete roof, harled random rubble walls and square-headed openings; no cills to windows. Original interior has been gutted to accommodate textile dust collectors, many of which survive.

The site is bounded along Bridge St and Frederick St by a high random rubble wall with chamfered ashlar copings. At the south end of Bridge St is the main entrance to the site. It comprises a dressed limestone semi-elliptical archway (with keystone) with a replacement pair of timber gates.

Waterworks

Water is diverted off the Brosna at a vee weir a short distance upstream to the east. There are two headraces from this weir, one on either bank. That on the south bank runs to this mill and that on the north bank formerly supplied mill OFIAR-008-045. A concrete aqueduct now conveys water from the latter across the river and into the headrace to Erry Mill. At the moment, the water is returned to the river via a modern sluice emplacement before it reaches the turbines (which are no longer in use). The tailrace passes under the road and has recently been piped thereafter. There are concrete footbridges over the river, head- and tailraces; that over the river is a modern rebuild of an earlier one.

Plant

The waterwheel was mounted externally on the north gable but has been superseded by turbines linked to electricity generators in the engine house (described under component 7). The west and east section of the mill contains grain screening/preparing and milling machinery, arranged over five and four floors respectively. The ground floor of the west section contains a whizzer scourer, elevator intakes and discharge from a conditioner-dryer. There was formerly also a grinder for animal feedstuffs on this floor. The first floor of this section contains a rubble separator and 50hp electric motor (powered by the turbine generator). The second floor contains a scourer (by Samuelson of Banbury). Grain was conveyed into this level via an overhead bridge from silos on the opposite side of Frederick St (OFIAR-008-053); sacks of flour were also conveyed from the mill across to the railway spur beside the silos. The third floor contains packing spouts towards it south end. The fourth floor houses an entoleter, screw conveyors and the feed to the conditioner-dryer.

The ground floor of the east section contains elevator intakes (from the first floor), electrical switch room and principal electric motor (fed via the turbine generator and ESB mains supply). The first floor formerly contained the roller mills, arranged according to the gradual reduction process; they were removed when the mill closed c.1969. There are remains of dust extraction trucking in the ceiling. The second floor contains four double purifiers (by Robinson; probably mid 20th century replacements of earlier ones) and screw conveyors. The third floor (which is level with the west section's fourth floor) has eight centrifugal sifters and two reel sifters (ally by Samuelson). The roofspace accommodates a centrifugal sifter (by Samuelson), elevator heads and a sack hoist. All the equipment is driven by overhead lineshafts, many of which survive.

Component OFIAR-008-038 2

Type Mill building Function Grain milling

Category Food processing & products Context Industry

Irish Grid 225648 232472 +/- 10m

Survey date 15/10/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Good Use Store Waterworks Remains N/A Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description

Just west of the west return to the main mill building is a three-storey/three-bay store where animal feedstuffs were mixed. Pitched roof reclad in profiled metal sheeting, with concrete verges. Harled walls. Square-headed openings with 2x2 casement windows and stone cills. First floor loading door. Internal walls are painted and plastered. The first floor comprises timber joists over steel beams and columns. Ladder stairs to upper floors. Disused mixer on first floor, supplied from top floor and discharging to ground floor.

Type Mill house Function Grain milling

Category Food processing & products Context Industry

Irish Grid 225637 232479 +/- 10m

Survey date 15/10/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Dwelling

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description Fronting Bridge Street, along the west side of the premises, is a two-storey/four bay

mill house, still occupied but in separate ownership. Hipped natural slate roof, with rendered chimneys and half-round metal rainwater goods. Harled walls. Square-headed windows with 1/1 sliding sash windows and stone cills. Front door (to street) is set in segmental-headed recess. Two-storey monopitched return to rear (east)

elevation.

Component OFIAR-008-038 4

Type Mill house Function Grain milling

Category Food processing & products Context Industry

Irish Grid 225635 232458 +/- 10m

Survey date 15/10/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Dwelling

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description At the west end of the Frederick St end of the premises is a second mill house,

currently occupied by the owner. It comprises a two-storey/three-bay dwelling with pitched natural slate roof, rendered chimneys, bracketed barge boards, and ogee cast-iron rainwater goods. Square-headed openings with 2/2 sliding sash windows and stone cills. Multi-panel door set into semicircular headed doorway to street.

Type Mill building Function Grain milling

Category Food processing & products Context Industry

Irish Grid 225651 232448 +/- 10m

Survey date 15/10/2003 Surveyor Fred Hamond

Building Remains Complete Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description To the east of the house fronting Frederick St is a single-storey/single-bay toilet block

with pitched corrugated asbestos roof, harled walls and square-headed openings with

concrete cills to the windows. It is now disused and in a poor state.

Component OFIAR-008-038 6

Type Mill building Function Grain milling

Category Food processing & products Context Industry

Irish Grid 225683 232451 +/- 10m

Survey date 15/10/2003 Surveyor Fred Hamond

Building Remains Complete Condition Fair Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

Description East of the main mill block is a single-storey/three-bay workshop. It has a pitched

natural slate roof and half-round asbestos rainwater goods. The walls are unusual in being of unrendered mass concrete. Square-headed openings with assorted windows and concrete cills. The sarked roof is carried on tied common timber rafters. The building is abutted at east by a large single-storey/single-bay monopitched shed clad

in corrugated metal.

Type Electricity generating station Function Grain milling

(water); Engine house (steam)

Category Food processing & products Context Industry

Irish Grid 225681 232484 +/- 10m

Survey date 15/10/2003 Surveyor Fred Hamond

Building Remains Complete Condition Poor Use Disused Waterworks Remains Complete Condition Good Use Disused Plant Remains Complete Condition Fair Use Disused Machinery Remains Substantial remains Condition Fair Use Disused

Description

North of the turbine emplacement on the north gable of the mill is a double-pile/single-storey building which houses an electricity generator and formerly also a steam engine and Lancashire boiler. Aligned east-west, the pitched roofs are clad in corrugated metal, and have plain timber bargeboards and eaves. Harled mass concrete walls. Both gables are partly glazed; the north and south elevations are largely devoid of openings. The sarked roofs, both of which are in poor condition, are carried on steel trusses.

The south pile contains a 75hp electricity generator in a basement to its west end, a late 20th century replacement of the original. This is linked to the three external turbines via a flywheel and vee-pulley (belts disconnected) and generated electricity for the ESB until recently. The other end of this pile formerly contained a steam engine, and there was a Lancashire boiler in the north pile. The only surviving machinery is an electrically-powered fan which ducted steam from the boiler along a lagged pipe into the mill.

Four turbines are mounted externally in a concrete cistern at the end of the headrace, between the engine house and north end of the mill. The top of the race hereabouts is bridged with a large concrete slab. Three of the turbines are mounted in line and drove the generator inside the engine house. The fourth was linked to a lineshaft driving ancillary equipment inside the mill. One or more of these turbines were installed second-hand c.1959 and it is uncertain whether any original 1919 turbines survive.

Component OFIAR-008-038 8

Type Mill chimney Function Grain milling

Category Food processing & products Context Industry

Irish Grid 225674 232488 +/- 10m

Survey date 15/10/2003 Surveyor Fred Hamond

Building Remains Complete Condition Fair Use Disused Waterworks Remains N/A Condition N/A Use N/A Plant Remains N/A Condition N/A Use N/A

Machinery Remains N/A Condition N/A Use N/A

Description
Just west of the engine house is an octagonal brick chimney standing to its full

height. It sits on a square mass concrete base and is slightly tapered in profile. The

top courses are corbelled outwards.

Type Mill building Function Grain milling

Category Food processing & products Context Industry

Irish Grid 225717 232451 +/- 10m

Survey date 15/10/2003 Surveyor Fred Hamond

Building Remains Complete Condition Fair Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description East of the boiler house is a single-storey/single-bay shed aligned east-west with

curved corrugated Belfast truss roof clad in corrugated metal. Its walls are of mass

concrete and concrete blockwork.

Interest Architectural; Historical; Technical; Setting

machinery (but not the rollers).

Evaluation The main block is a substantial architectural form, typical of late 18th/early 19th

century purpose-built flour mills. Along with the chimney, it is a prominent landscape feature hereabouts. The complex is of historical interest in illustrating the switch from traditional stone grinding to roller reduction milling in the earlier 20th century. The mass-concrete engine house and chimney are also of historical interest in signifying the inception of steam power and water turbines around the same time. In the context of Co Offaly, Erry Mill is unique in being the only roller mill in the county. Its association with the Goodbody family, prominent industrialists in this town, is also of note. The complex is also of considerable technical interest on account of the survival of its waterworks, turbines and much of its grain handling and flour dressing

The complex is of regional industrial heritage significance and merits its inclusion as

a Protected Structure in the Co Offaly County Development Plan 2009-15.

Rating Regional Protection Offaly RPS 12-25: Action None (in RPS)

Offaly RPS 12-26; Offaly RPS 12-40; Offaly RPS 12-41

Associated with OFIAR-008-053

Other dbase NIAH 14802020 (R); NIAH 14802021(R); NIAH 14802036 (R); NIAH 14802037 (R)

References

Hamond, F. A Survey of Clara Mill, Co Offaly. Unpublished report for Offaly Page(s) County Council, 2005.

Quinn, D.B. 'Clara: a Midland Industrial Town'. In Nolan W. and O'Neill, T.P. Page(s) 810-811 (eds), Offaly: History and Society (Dublin: Geography Publications, 1998).

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 73 of Ireland c.1850 (Dublin, 2000).

OFIAR-008-038_01 FWH 15/10/2003 General view of complex from south-west.



OFIAR-008-038_02 FWH 15/10/2003 General view of complex from south. Note mill house 2 at left.



OFIAR-008-038_03 FWH 15/10/2003 Mill from south-west.



 $OFIAR-008-038_04 \quad FWH \quad 15/10/2003 \qquad \mbox{Mill from south-east}.$



OFIAR-008-038_05 FWH 15/10/2003 Mill from north-east.



OFIAR-008-038_06 FWH 15/10/2003 Three-storey feedstuffs mixing unit (left) and mill (right), from south-west.



OFIAR-008-038_07 FWH 15/10/2003 Mill house 1 fronting Bridge St, from west.



 $OFIAR-008-038_08 \quad FWH \quad 15/10/2003 \qquad Workshop, from south-west.$



OFIAR-008-038_09 FWH 15/10/2003 Boiler/generator house, from south-east.



 $OFIAR-008-038_10 \quad FWH \quad 15/10/2003 \qquad \text{Vee pulley at end of turbine lineshaft in basement of boiler/generator house}.$



OFIAR-008-038_11 FWH 15/10/2003 Generator in boiler/generator house.



OFIAR-008-038_12 FWH 15/10/2003 Interior of south bay of boiler house.



OFIAR-008-038_13 FWH 15/10/2003 Chimney, from west.



OFIAR-008-038_14 FWH 15/10/2003 Shed at north-west corner of site, from north-west.



OFIAR-008-038_15 FWH 15/10/2003 Belfast truss room in shed.



 $OFIAR-008-038_16 \quad FWH \quad 15/10/2003 \qquad \text{Main entrance to mill on Bridge St.}$



Looking east along River Brosna. Headrace to Erry Mill on left bank (at right), and aqueduct from headrace on right bank (at left).



 $OFIAR-008-038_18 \quad FWH \quad 15/10/2003 \qquad Turbine \ guide \ vane \ control \ shaft.$



OFIAR-008-038_19 FWH 15/10/2003 Looking down into turbine emplacement. Note turbine guide vanes at right.



OFIAR-008-038_20 FWH 15/10/2003 Whizzer (left) and conditioner-dryer on ground floor of west section of mill.





OFIAR-008-038_22 FWH 15/10/2003 Scourer on second floor of west section of mill.



OFIAR-008-038_23 FWH 15/10/2003 Third floor of west section of mill, looking north. Note packing spouts along party wall at right.



 $OFIAR-008-038_24 \quad FWH \quad 15/10/2003 \qquad Elevators \ on \ ground \ floor \ of \ east \ section \ of \ mill, \ looking \ north.$





OFIAR-008-038_26 FWH 15/10/2003 First floor of east section of mill, looking south (former roller floor). Note duct trunking in ceiling.



 $OFIAR-008-038_27 \quad FWH \quad 15/10/2003 \qquad Second floor of east section of mill, looking north. \ Note purifiers.$



OFIAR-008-038_28 FWH 15/10/2003 Semolina purifier on second floor of east section of mill.



OFIAR-008-038_29 FWH 15/10/2003 Top floor of mill, looking north-west. Note roof trusses.



OFIAR-008-038_30 FWH 15/10/2003 Centrifugal sifter on third floor of east section of mill.



OFIAR-008-038_31 FWH 15/10/2003 Roofspace gallery, looking south.



Site no	OFIAR-008	3-042	Charlestown no.2 Mill
County	Offaly	Townland Kilcoursey	Town Clara
Planning	Offaly CC	Discovery map 48	Six-inch map 8
Summary		ns of 18th/early 19th century water- ed by the Goodbody family since 1	powered flour mill and kiln on River 826. Burnt down 1967.
History	cited in the 18 large five-store (to distinguish It is described Robert Goodle stones. It was rating of £50. (OFIAR-008-0 In the 1854 GL.M. & J. Goodlill (OFIAR-008-0 Mill (O	338 and 1884 OS six-inch maps. Of ey L-plan block. It was known as the it from its adjoining sister mill OF as a flour mill in the 1840s Mill Valody. The waterwheel measured 15 the seventh most valuable proper Goodbody was also operating an a 209). Tififth Valuation, the mill, kiln and of	aluation book and was operated by 5ft x 11ft and drove six pairs of ties in the county at that time, with a adjoining flour mill at this time as well offices are recorded as belonging to is rating is equalled by Drumakeenan by Mill (OFIAR-008-038). The

The mill was burnt down in 1967; most of its remains were subsequently removed.

Component OFIAR-008-042 1

Type	Grain kiln: Grain mill (water)	Function	Grain milling
IVDE	Giaili Kiili. Giaili Illiii (Water)	Function	Giain illilling

well (OFIAR-008-009 and 008-054 respectively).

Category Food processing & products Context Industry

Irish Grid 226088 232309 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Fair Use Store
Waterworks Remains Traces Condition Poor Use Disused
Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Partial remains of 18th/19th century flour mill, kiln and ancillary buildings and waterworks situated off right bank of River Brosna at east end of Clara.

Buildinas

The main section of the mill and related kiln were demolished following a fire in 1967. All that survives is a two-bay/two-storey former office block on its east side. This building has a hipped natural slate roof, cement-rendered rubble masonry walls and square-headed openings.

Fronting the road immediately west of the mill is a single-storey/three-bay building, presumed to have been a former mill office. It has since been used as a court house and library, and is now an Offaly County Council depot. It has a hipped natural slate roof, brick chimney (with bracketed coping), ogee aluminium rainwater goods, and painted/rendered walls with projecting dressed stone eaves. All openings have shallow segmental heads (with stucco keystones) and moulded architraves; the windows have stone cills (bracketed to front).

North-east of the mill is the mill owner's house - Charlestown House and ancillary building (OFIAR-008-064).

Waterworks, plant and machinery.

The headrace is shared with site OFIAR-008-009 and is open save for the last 100m, which are infilled. The tailrace is culverted under the road and open to the river. No plant or machinery survives.

Component OFIAR-008-042 2

Type Mill building Function Grain milling

Category Food processing & products Context Industry

Irish Grid 226064 232311 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Council depot

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A
Condition N/A Use N/A

Description This single-storey/three-bay building fronts the road immediately west of the mill and

is presumed to have been a former mill office. It has since been used as a court

house and library, and is now an Offaly County Council depot.

It has a hipped natural slate roof, brick chimney (with bracketed coping), ogee aluminium rainwater goods, and painted/rendered walls with projecting dressed stone eaves. All openings have shallow segmental heads (with stucco keystones) and moulded architraves; the windows have stone cills (bracketed to front). No plant or

machinery survives.

Interest Group; Historical

Evaluation This was once a significant mill on account of its size and Goodbody associations. Its

interest is enhanced by the adjoining buildings, notably Charlestown House (OFIAR-008-064) and another flour mill owned by the Goodbodys (OFIAR-008-009).

Unfortunately little now survives above ground and for this reason the site as a whole is of no special industrial heritage significance except for the former mill office along the road which is of local industrial heritage interest and also a Protected Structure in

the Co Offaly Development Plan 2009-15.

Rating Local Protection Offaly RPS 12-18 Action

Associated with OFIAR-008-009; OFIAR-008-054; OFIAR-

008-064

Other dbase NIAH 14802014 (R)

References

Kinahan, R, Kenny, B., English, P. & Clyne, O. Clara: a Pictorial Record Page(s) (Tullamore, 1992).

Quinn, D.B. 'Clara: a Midland Industrial Town'. In Nolan W. and O'Neill, T.P. Page(s) 810

(eds), Offaly: History and Society (Dublin: Geography Publications, 1998).

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 74

of Ireland c.1850 (Dublin, 2000).

OFIAR-008-042_01 FWH 23/06/2003 General view of mill remains, from south-east.



OFIAR-008-042_02 FWH 23/06/2003 Mill office, from west.



OFIAR-008-042_03 FWH 23/06/2003 Mill office, from east.



Site no	OFIAR-008-045
Site IIO	UTIAN-000-043

County	Offaly	Townland	Clara	Town	Clara

Planning Offaly CC Discovery map 48 Six-inch map 8

Summary Site of 18th/early 19th century water-powered flour, corn and bone mills on River

Brosna.

History A corn mill and flour mill are cited on the 1838 OS six-inch map. A flour mill, two corn

mills and a bone mill are cited in the 1840s Mill Valuation book, all worked by Samuel Robinson. They were driven by 16ft x 2ft 6in, 16ft x 3ft 6in, 14ft x 4ft and 16ft x 4ft waterwheels respectively and each. The three grain mills (where were probably under the one roof) each had two sets of stones.

Corn mills are recorded in the 1854 Griffith Valuation, also under Samuel Robinson; they have the relatively high rating of £98 (the seventh highest in Co Offaly). No mills are explicitly cited in the 1884 or 1910 OS maps, implying that they were probably defunct in the later 1800s.

Component OFIAR-008-045 1

Type Bone mill (water); Grain mill (water) Function Bone and fat products; Grain

milling

Category Animal-based products; Food

processing & products

Context Industry

Irish Grid 225742 232473 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A

Waterworks Remains Substantial remains Condition Fair Use Disused

Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of 18th/19th century flour, corn and bone mills on the right bank of River Brosna,

immediately south of Main St. Nothing survives except for the vee-weir (shared with Erry Mill) and headrace. The tailrace has been infilled, but the culvert under the main

road survives.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-008-045_01 FWH 23/06/2003 Looking west to weir. Headrace at right (left race supplies Erry Mill).



0 14	OFIAD 000 050
Site no	OFIAR-008-053

County Planning	Offaly Offaly CC	Townland Erry Discovery map	(Maryborough) 48	Town Clara Six-inch map 8
Summary		ncrete grain silo ass ly by a siding. Demo	sociated with Erry Mill. Lin olished 2001.	ked to Great Southern &
History	metal silos were	e erected at this located in 193	ne last manager of Erry M ation when the mill was re 5, and a further set (using	emodelled in 1919-22.

Component OFIAR-008-053 1

Type Grain silo Function Grain milling

Category Food processing & products Context Industry

Irish Grid 225669 232387 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Use N/A Remains N/A Condition N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of reinforced-concrete grain silo associated with Erry Mill (OFIAR-008-038, to its

north). This plot has recently been redeveloped for housing.

Component OFIAR-008-053 2

Type Railway siding Function Grain milling

Category Food processing & products Context Industry

Irish Grid 225737 232318 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A Use N/A **Plant** Remains N/A Condition N/A Use N/A Machinery Remains N/A Condition N/A Use N/A

Description All traces of the siding have been removed.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-008-038

Other dbase

References

K. Corrigan, 2001. 'Historic Clara landmark comes tumbling down'. In Offaly Page(s) Express, 10 Feb 2001.

Kinahan, R, Kenny, B., English, P. & Clyne, O. Clara: a Pictorial Record Page(s) 158 (Tullamore, 1992).

Quinn, D.B. 'Clara: a Midland Industrial Town'. In Nolan W. and O'Neill, T.P. Page(s) 805 (eds), Offaly: History and Society (Dublin: Geography Publications, 1998).

Site no	OFIAR-008-054			Old Factory	
County	Offaly	Townland	Kilcoursey	Town	Clara

48

Discovery map

Summary

Planning

Large 18th/early 19th century building on north side of River Brosna. Original function uncertain. Used as cotton weaving factory by Goodbody family in 1850s and subsequently as a grain store for adjoining mills. No water power despite proximity to river.

Six-inch map 8

History

An uncaptioned building is shown here on the 1838 OS six-inch map. Hand looms were installed by the Goodbodys in 1853 for the production of sacks for use in their flour mills. Premises described in 1854 Griffith Valuation as a cotton factory, offices and yard, all rated at £45. The factory was presumably where cotton sacks were manufactured. The Goodbodys also operated two adjoining flour mills at this time (OFIAR-008-009 and 008-042). Fell into disuse after a purpose-built jute mill opened in 1865 (OFIAR-008-028). In later years used as a grain store for the above mills.

Component OFIAR-008-054 1

Offaly CC

Type Weaving factory Function Cotton

Category Textile manufacture & products Context Industry

Irish Grid 226076 232244 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Fair Use Disused Waterworks Remains N/A Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains Traces Condition Fair Use Disused

Description

Substantial disused mid 19th century textile mill and ancillary buildings just NE of the road bridge over the River Brosna at the east end of Clara. This three-storey (+ attic)/eight-bay building is aligned north-south. It has a pitched natural slate roof with an ashlar chimney and coped verges to each gable. Half-round metal rainwater goods. Rendered rubble stone walls and projecting dressed eaves. All openings have segmental heads and stone cills; all have been infilled with concrete blocks. Wrought-iron railings and random rubble wall delineate the property along the main road. The north gable has loading doors at first and second floor levels and is abutted by a two-storey lean-to (a later infill). The rear (east) elevation has a sliding timber door to centre, with corrugated-metal canopy over.

Internally, all floors survive (although most of the attic floor has been removed). The upper floors are of timber over joists and transoms supported by cast-iron and timber uprights. Timber stairs at NE connect the floors. The walls are painted and plastered. The inside surface of the roof is plastered and rests on common rafters over triple purlins; the latter are supported at intervals by braced timber uprights. There are the remains of a bucket elevator at the north end, a sack hoist at the north end of the top, and belt-driven screw conveyor along the roof apex.

Immediately north of the mill and aligned along the street is the ruinous shell of a two-storey random rubble building. There was once a clock on the apex of its north gable. Abutting this gable is the ruinous shell of a one-storey building. Just NE of the latter is a ruinous overgrown two-storey dwelling. Just east of the mill is a random rubble wall, along which open-sided outbuildings formerly abutted to both sides. There was no internal access to any of these ancillary buildings.

p hgu h

Interest Architectural; Group; Historical; Setting

Evaluation Architecturally, this building is of significance on account of its completeness, scale,

and prominent position on the eastern approach to Clara. Although its historical development is vague, its attested link with the Goodbody family is of interest. It has group value due to its proximity to two Goodbody flour mills - OFIAR-008-009 and OFIAR-008-042. It merits its inclusion as a Protected Structure in the Co Offaly

County Development Plan 2009-15.

Rating Regional Protection Offaly RPS 12-20 Action None (in RPS)

Associated with OFIAR-008-009; OFIAR-008-042

Other dbase NIAH 14802016 (R)

References

Kinahan, R, Kenny, B., English, P. & Clyne, O. Clara: a Pictorial Record Page(s) (Tullamore, 1992).

Quinn, D.B. 'Clara: a Midland Industrial Town'. In Nolan W. and O'Neill, T.P. Page(s) 800 (eds), Offaly: History and Society (Dublin: Geography Publications, 1998).

OFIAR-008-054_01 FWH 23/06/2003 General view from south-west.



OFIAR-008-054_02 FWH 23/06/2003 General view from south-west.



OFIAR-008-054_03 FWH 23/06/2003 West elevation.



OFIAR-008-054_04 FWH 23/06/2003 General view from north-east.



OFIAR-008-054_05 FWH 23/06/2003 Looking north-east across ground floor.



OFIAR-008-054_06 FWH 23/06/2003 Looking south along attic.



OFIAR-008-054_07 FWH 23/06/2003 Sack hoist in attic space.



OFIAR-008-054_08 FWH 23/06/2003 Buildings to north of mill, from north-west.



OFIAR-008-054_09 FWH 23/06/2003 Rubble wall to east of mill, from north-west.



OFIAR-008-054_10 FWH 23/06/2003 Mill-related house, from south.



Site no OFIAR-008-064			Charlestown House	
County	Offaly	Townland Kilcoursey	Town Clara	
Planning	Offaly CC	Discovery map 48	Six-inch map 8	
Summary	Late 18th/ early 19th century house occupied by Goodbody family, owners of a number of mills in Clara. Enlarged and remodelled in 1853.			
History	century date.	rlestown House on 1838 OS map. Pro Occupied by Robert Goodbody until 1 odbody. The drawing room and dining	1843 when it was taken over by	

Component O	FIAR-008-064 1
-------------	----------------

Type Mill house Function Grain milling

Category Food processing & products Context Industry

Irish Grid 226103 232336 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Dwelling Waterworks Remains N/A Condition N/A Use N/A

Plant Remains N/A Condition N/A Use N/A

Machinery Remains N/A Condition N/A Use N/A

Description A two-storey over basement/four-bay house with hipped natural slate roof, rendered

chimneys and cast-iron balustrade around its projecting bracketed eaves. The walls are painted and rendered. The principal elevation faces east on to a landscaped garden. The end bays to this side have curved projecting bays to their ground- and first floors. All openings are square-headed and have moulded architraves. The

windows are variously 1/1, 2/2 and 6/3 sliding sashes.

Aligned along Kilbeggan Road, at the NW corner of the premises, is a multi-bay/two-storey block of outbuildings now used primarily as a garage and office. It has a pitched artificial slate roof, plastic rainwater goods on advanced eaves, painted rendered walls and square-headed openings; the first floor windows are of diminished size. Some of the openings have been enlarged and some also have later

replacement fittings. Original 4x12-paned window frames survive on the ground floor.

Interest Architectural; Group; Historical

Evaluation This house is of architectural character and is of historical interest on account of its

links with the Goodbodys. It also has a group association with the adjoining Charlestown mills (OFIAR-008-009 and 008-042). It is of regional industrial heritage merit and warrants its inclusion as a Protected Structure in the Co Offaly County

Development Plan 2009-15.

Rating Regional Protection Offaly RPS 12-13 Action None (in RPS)

Associated with OFIAR-008-009; OFIAR-008-042

Other dbase NIAH 14802006 (R)

References

OFIAR-008-064_01 FWH 23/06/2003 East façade of Charlestown House.



OFIAR-008-064_02 FWH 23/06/2003 Mr & Mrs Payne, owners of Charlestown House.



 $OFIAR-008-064_03 \quad FWH \quad 23/06/2003 \qquad Outbuilding \ on \ Kilbeggan \ Road, \ from \ north-west.$



Site no	OFIAR-008-065
OILE IIU	

County Offaly Townland Erry (Marlborough) Town

Planning Offaly CC Discovery map 48 Six-inch map 8

Summary Site of unlocated mid 17th century mill in Erry townland.

History Mill of unknown function cited in 1655 Down Survey in Erry townland.

Component OFIAR-008-065 1

Type Mill Function Unknown

Category Unknown Context Industry

Irish Grid 226646 230923 +/- 1000m

Survey date Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of unlocated mill in Erry townland.

Interest Archaeological

Evaluation No industrial heritage interest.

Rating Record only Protection Action

Associated with

Other dbase SMR OF008-052---

References

Archaeological Survey of Ireland record.

Page(s)

Site no OFIAR-009-005

County	Offaly	Townland Acantha	Town
Planning	Offaly CC	Discovery map 48	Six-inch map 9
Summary	Substantially	complete 18th/early 19th century water-	nowered corn mill and kiln on

Summary

Substantially complete 18th/early 19th century water-powered corn mill and kiln on Silver River, and remains of a distillery of c.1782. A second kiln was added in 1954. Distilling had ceased by 1884, but corn milling continued until 1978. Corn mill retains its waterwheel, transmission gearing, millstones and ancillary equipment.

History

A corn mill and distillery are cited here on the 1838 OS six-inch map. The distillery was established by John Green in 1782 and the corn mill possibly dates from around then as well.

The site is described as a corn mill in the 1840s Mill Valuation book and was operated by Edward Woods at that time. It had two sets of stones, driven by a 12ft x 3ft 6in waterwheel.

The 1854 Griffith Valuation notes Edward Scully as the occupier. The house, offices, corn mill, kiln were rated at £18.

The present owner states that the Cobbes took over this site from the Greens in the 1850s. According to family legend, they closed the distillery because they were teetotallers. However, the absence of the distillery from the valuation books suggests that it was already closed.

The mill was possibly heightened to its present form in 1904, at the same time as the three-storey store was re-roofed. Its capacity may well have been enlarged from oneto three sets of stones at the same time.

A cascade-type grain dryer was erected in 1954. Water power was discontinued around 1968 and an oil engine was used thereafter. Pinhead and flaked oatmeal production for human consumption ceased around 1978 but animal feed was produced using this engine until 1990. Oats are still rolled using a modern roller and diesel engine.

Component OFIAR-009-005 1

Type	Grain kiln; Grain mill (water)	Function	Grain milling

Category Food processing & products Context Industry

Irish Grid 234484 228899 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Use Agricultural building Building Remains Complete Condition Fair

Waterworks Use Disused Remains Complete Condition Poor **Plant** Remains Substantial remains Condition Fair Use Disused Machinery Remains Complete Condition Fair Use Disused

Description A well-preserved 18th/19th century corn mill and kiln with mid 20th century kiln

addition and ancillary buildings.

Corn mill

This three-storey/single-bay building is aligned approximately north-south on the east side of the road and now used as an agricultural outbuilding. Pitched corrugated metal roof, plastic rainwater goods on boarded projecting brick eaves, and rendered random rubble walls. The north gable shows evidence of heightening by upwards of 1.8m (6ft). There are small square-headed openings to all floors, with timber heads, 2x2 frames and no cills.

Internally, the walls are painted and some are also plastered. The upper floors are carried on joists over timber transoms supported on intermediate uprights. The roof rests on single purlins over timber A- trusses; the rafters were removed when the metal sheeting was put on.

Store 1

A three-storey/single-bay building abuts the south gable of the mill and shares the same roofline. It is slightly wider than the mill, projecting into the yard at west. Unlike the mill, it retains its natural slate roof, complete with cement coped brick verges, but is without rainwater goods. The walls are detailed as the mill. The square-headed openings are trimmed in brick and have relieving arches over. The apex of the south gable is built up in brick and may have been half-hipped originally. The kneeler stone at the SW corner of the store roof carries the date 1904 (commemorating its reroofing).

Internally, the wall finishes and floors are similar to the mill and the roof retains its tied common rafters. The only equipment is a sack hoist on the top floor, driven off a lineshaft linked to an engine in the cascade dryer room.

Kiln 1

This two-storey/two-bay former grain drying kiln abuts the middle of the east side of the mill and store. It carries a pitched corrugated metal replacement roof. The eaves have been raised slightly using pieces of broken perforated ceramic tile (originally on the drying floor). The walls are of random rubble. There is a small square-headed window to the top floor, with brick trim. Internally, the hearth and drying floor have been removed. According to the owner, this floor was removed in the 1980s and the kiln tiles were reused at Newmills, a corn mill restored by the Office of Public Works near Letterkenny, Co Donegal.

Seed house

Abutting the north end of the east wall of the mill/store is a small single-storey/single-bay seed house. It has a monopitched corrugated-metal roof, no rainwater goods and random rubble walls. It has two square-headed doorways, but no windows. It contains a reciprocating sieve and fans for sifting and winnowing shelled oats; this machinery was driven by a belt from within the mill proper.

Kiln 2

A four-storey high/single-bay 20th century grain drying room about the east wall of store 1 and the south wall of the original kiln. This structure has a pitched corrugated asbestos roof, mass-concrete walls and square-headed openings. The original ridge vent is now covered with corrugated metal sheeting.

Internally, this room contains a cascade dryer heated from below by a small furnace fired with peat briquettes. Grain was fed into the top of the dryer using a bucket elevator driven by a small TVO stationary engine on the ground floor. This engine also powered the sack hoist on the top floor of the store and still drives a elevator which raises grain up to the top floor of the store to feed the Suitor roller on the ground floor of the mill.

Store 2

This single-bay building abuts the west side of the mill and store 1. Originally 1½ storeys high, it has been raised in mass concrete to two storeys to accommodate a shallow monopitched corrugated metal roof which continues south over an open-sided shed partly clad in corrugated metal. Asbestos rainwater goods. The original walls are of random rubble. Internally, the ground floor houses a turnip cutter, now driven by an electric motor but originally by the waterwheel via a lineshaft which still survives. The first floor has been removed. This building is abutted at north by a lower mass-concrete lean-to.

Waterworks

The mill is water powered off the Silver River. The weir is intact, as is the headrace and overgrown tailrace.

Plant

A high breastshot waterwheel sits on the mill's north gable. It measures 4.57m in diameter by 1.45m wide (15ft x 4ft 9in) and is of timber construction save for its castiron hubs and tie rods between its rims. It has eight arms and 48 buckets, most of which are missing, as is the sole plate. According to the owner, this wheel was constructed by Mr Jim Hefferman in 1952.

Machinery

All the machinery inside the corn mill survives intact. The shafts and gears are arranged in a great spurwheel configuration, and are of cast-iron throughout save for the wooden coas to the great spurwheel. The entire transmission system and stones on the floor above are supported on a robust timber frame. The great spurwheel also drives a fourth nut (small spur gear) to ancillary machinery on the upper floors. Besides the power transmission gearing, the ground floor also houses three bucket elevators, a small vertical plate 'Briton' grinder (driven from an external tractor), and a modern oat roller (by Suitor Engineering, Newbliss) which is still in use (it is also driven from a tractor PTO). According to the owner, the wheel also drove a small electricity dynamo until the arrival of mains electricity in the 1960s.

The first floor was originally higher (as evidenced by joist sockets on the north gable), but was lowered when the mill was reconfigured. It contains two pairs of conglomerate millstones (for shelling and grinding) and a pair of French burrs (for grinding). The associated millstone furniture - tun, hopper, shoe and damsel - survive on two sets, and but only the tun remains on the burrs. Each stone has an axial tentering screw (to adjust the gap between them) and a jack ring (to disconnect their stone nut from the spurwheel). This floor also contains two small reciprocating oatmeal sieves.

The second floor has two sets of elevators, two reciprocating sieves and a set of fans. A third elevator, driven off a lineshaft running through from the adjoining store, feeds the Suitor roller on the ground floor.

Component OFIAR-009-005 2

Function Type Distillery Distilling

Category Drink processing & products Context Industry

Irish Grid 234464 228906 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Building Condition Fair Use Agricultural building Remains Some remains

Remains N/A Waterworks Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description The former distillery is also on the east side of the road. It was originally two storeys

high, but has been reduced to one and is now in use as an agricultural shed. It has a pitched corrugated metal roof, random rubble walls and yellow brick trim to its squareheaded openings. A datestone reading JG 1782 [= John Green] which is now set in concrete above a modern metal door on the south wall of a small 11/2 storey/singlebay outbuilding on the mill side of the road may be related.

Acontha House, the mill owner's house, was on the west side of the road. It was

demolished c.1990 and replaced by the present dwelling.

Architectural; Historical; Technical Interest

Technically, the corn mill is a very significant building, being one of only four grain **Evaluation** mills in Co Offaly to retain its waterwheel, power transmission system, millstones and ancillary equipment. The great spurwheel configuration which it contains typifies most rural Irish mills. The mill's physical remains also indicates its development: its refurbishment in 1904, new grain dryer in 1954, and oil engine which enabled it to operate until 1990.

The ancillary kilns, stores and seed house are also an important part of the group. The mid 1900s kiln is of historical interest in demonstrating the site's continuing development through to the mid 20th century. Technically it is also of merit owing to its completeness and is an interesting contrast with the earlier, more traditional, kiln. Mr Cobbe, the owner and third generation miller at this site, also has a collection of documents relating to the mill.

The entire block and associated waterworks are of regional industrial heritage significance. It merits its inclusion as a Protected Structure in the Co Offaly County Development Plan 2009-15.

Rating Regional Protection Offaly RPS 23-01 Action None (in RPS)

Associated with OFIAR-009-021?

Other dbase NIAH 14909004 (R)

References

Abbott, V. A Place Called Durrow. 1999.

Page(s) 80

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-009-005_01 FWH 11/06/2003 General view of corn mill from north.



OFIAR-009-005_02 FWH 11/06/2003 General view of site from west. The building at left has a 1782 datestone over the



OFIAR-009-005_03 FWH 11/06/2003 Mill (left) and store (middle), from west.



OFIAR-009-005_04 FWH 11/06/2003 Store and cascade drying room, from south.



OFIAR-009-005_05 FWH 11/06/2003 Original kiln (foreground) and modern cascade kiln (background), from north. Note perforated tiles on kiln eaves.



OFIAR-009-005_06 FWH 11/06/2003 Waterwheel.





OFIAR-009-005_08 FWH 11/06/2003 Modern roller on ground floor.



OFIAR-009-005_09 FWH 11/06/2003 General view of first (stone) floor.



OFIAR-009-005_10 FWH 11/06/2003 Sheller stone detail.



OFIAR-009-005_11 FWH 11/06/2003 Sieves and fans on top floor of mill.



OFIAR-009-005_12 FWH 11/06/2003 First floor of store, looking north.



OFIAR-009-005_13 FWH 11/06/2003 Lineshaft drive and sack hoist on top floor of store.



OFIAR-009-005_14 FWH 11/06/2003 Cascade dryer, looking to top.



OFIAR-009-005_15 FWH 11/06/2003 Furnace at bottom of dryer.



OFIAR-009-005_16 FWH 11/06/2003 TVO engine in cascade dryer room.



OFIAR-009-005_17 FWH 11/06/2003 Sieve and fans in seed house.



OFIAR-009-005_18 FWH 11/06/2003 Turnip cutter in shed on west side of mill/store.



Site no OFIAR-009-006

County	Offaly	Townland Ballynasrah or Tinnycross	Town
Planning	Offaly CC	Discovery map 48	Six-inch map 9

Summary

18th/early 19th century water-powered corn mill and detached corn kiln on Silver River. Mill retains its waterwheel, power transmission gearing, millstones and ancillary equipment.

History

Cited on 1838, 1884 and 1910 OS six-inch maps. According to the 1840s Mill Valuation book, it was operated by Thomas Kelly. A 10ft x 6ft waterwheel drove two sets of stones. The 1854 Griffith Valuation notes the operator as Daniel Bryan. The mill and kiln were rated at £6. According to the Mrs Gavagan (the owner's mother), the mill produced pinhead and flaked oatmeal. Its water-powered machinery stopped c.1980 but the engine-driven roller mill continued until c.1985. Pat Gavagan operated the mill for a short time after his father's death, but found more lucrative employment elsewhere.

Component OFIAR-009-006 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 235945 228909 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Fair Use Disused Waterworks Remains Substantial remains Condition Fair Use Disused Plant Remains Substantial remains Condition Poor Use Disused Machinery Remains Substantial remains Condition Fair Use Disused

Description

Intact 18th/19th century corn mill and separate kiln/store on left bank of Silver River, immediately north of minor road.

Buildings

The corn mill is a 2½ storey/single-bay building, now disused. It is aligned east-west and is cut into the slope so that it can be entered at both ground- and first floor levels. Pitched corrugated metal roof with concrete verges and dressed eaves. No rainwater goods. Rendered random rubble walls. All openings are square headed. The windows are relatively narrow. The first floor doorway on the east gable has a voussoired head. There is two single-storey lean-tos along its north wall with corrugated metal roofs, random rubble walls and brick trim to its square-headed openings. There is also a seed house lean-to on the west gable, detailed as the other lean-tos. Internally, the walls are painted and the first floor rests on joists over transoms.

A short distance east is the still-occupied mill house, a 1½ storey vernacular building.

Waterworks

The line of the headrace is still clearly evident contouring along the slope and also the overgrown tailrace.

Plant

The waterwheel is located on the south wall of the mill. It is of timber construction save for the cast-iron hubs. The wheel measures 4.27m in diameter by c.1.52m wide (14ft x c.5ft). It originally had eight arms and 40 buckets. The wheel is now in a decayed and derelict state.

Machinery

The milling machinery is arranged against the south wall of the building in a great spurwheel configuration. All the shafts and gears are of timber except for two of the three stone nuts and the stone spindles; cast-iron teeth segments have also been bolted on to the timber pitwheel. There is also a fourth nut off the great spurwheel (also timber) to ancillary machinery. There are also two bucket elevators, and a cylindrical sieve and fan (for processing the shelled oats) on this floor.

There are three sets of millstones on the first floor: one-piece shelling stone (the runner is missing) and two French burrs (one pair by Kay & Hilton, Liverpool). The millstone furniture is incomplete; only one octagonal tun, hopper, horse, shoe and three damsels survive. Each pair of stones has bridge tree tentering (to adjust the gap between the runner and bedstone) and a jack rings (to disconnect its stone nuts from the great spurwheel drive). A workbench is set against the west side of this floor. The top floor contains oatmeal sieves and fans, elevator discharges, and a manual sack hoist.

The smaller of the two lean-tos on the north wall of the mill houses a roller/plate mill mounted on a concrete base. It was belt driven from a small portable engine sitting outside (but now gone).

Component OFIAR-009-006 2

Type Grain kiln Function Grain milling

Category Food processing & products Context Industry

Irish Grid 235970 228890 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Poor Use Disused Waterworks Remains N/A Condition N/A Use N/A

Plant Remains N/A Condition N/A Use N/A

Machinery Remains Substantial remains Condition Fair Use Disused

Description

This building is locate along the roadside, SE of the mill. It is a detached three-bay, two storey building with a later store abutting its road elevation. Pitched natural slate roof with two fixed timber ventilators clad in corrugated metal (one per kiln floor). Random rubble walls brought to courses. Square-headed openings with brick jambs and heads; no cills.

Internally, the building is divided into three sections. The entrance door in the middle of its north elevation leads into a brick vaulted middle section with kilns to left (east) and right (west). The fire hole and drying floor of the left-hand kiln have been removed to accommodate a small oil-fired dryer (with forced-air draught). It was fed by an auger from the adjoining store and belt driven from an external tractor PTO. The right-hand kiln retains its vaulted fire hole (stoked from the middle bay) and metal floor sub-structure. However, its 12-inch perforated clay floor tiles are now piled to one side. Dogleg stairs at the end of the middle bay lead up to the first floor of each kiln.

Abutting the middle of the south elevation of the kiln block is a single-bay, single-storey store aligned at right angles and fronting the road. Double-pile pitched natural slate roof on common rafters. Random rubble walls with brick gable apexes. Accessed from the road by a double-door in square headed opening (with timber head and dressed stone jambs), but no internal link with kiln save for grain feed openings to kiln floors.

Evaluation

The mill is technically significant, being one of only four complete grain mills in Co Offaly. The extensive use of timber is of particular note and contrasts with the nearby Acantha Mill (OFIAR-009-005) which is mostly of cast-iron. The kiln/store is of architectural interest on account of its double-pile construction and internal plan form. It is a prominent roadside feature which is of historical and technical interest in having had two drying floors, one of which was superseded by a more modern dryer. It has group value in the context of the corn mill. The site is of regional industrial heritage signficance and merits inclusion in the Record of Protected Structures.

Rating Regional Protection Action RPS

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 73 of Ireland c.1850 (Dublin, 2000).

OFIAR-009-006_01 FWH 11/06/2003 General view of mill (right) and kiln (background left), from north.



OFIAR-009-006_02 FWH 11/06/2003 Mill from north-east.



OFIAR-009-006_03 FWH 11/06/2003 Waterwheel.



 $OFIAR-009-006_04 \quad FWH \quad 11/06/2003 \qquad \text{Mill: power transmission shafts and gears on ground floor.}$



OFIAR-009-006_05 FWH 11/06/2003 Mill: ground floor shelling stone sieve.



OFIAR-009-006_06 FWH 11/06/2003 Mill: first (stone) floor.



OFIAR-009-006_07 FWH 11/06/2003 Mill: first floor workbench.



OFIAR-009-006_08 FWH 11/06/2003 Mill: top floor with sack hoist at left and oatmeal sieves/fans at right.



OFIAR-009-006_09 FWH 11/06/2003 Mill: roller/grinder in lean-to.



OFIAR-009-006_10 FWH 11/06/2003 Kiln from north.



OFIAR-009-006_11 FWH 11/06/2003 Roadside elevation of kiln store.



 $OFIAR-009-006_12 \quad FWH \quad 11/06/2003 \qquad \text{Kiln: ground floor entrance passage.}$



OFIAR-009-006_13 FWH 11/06/2003 Kiln: right-hand kiln furnace.



OFIAR-009-006_14 FWH 11/06/2003 Kiln: oil-fired dryer in left-hand kiln.



C:40 mg	\sim		В	^^	Λ.	Λ 4	E
Site no	U	FΙΑ	\ K -	UU) -	υı	J

County Planning	Offaly Offaly CC	Townland Bracklin Big Discovery map 48	Town Six-inch map 9
Summary	Site of 18th/early 19th century water-powered corn mill on tributary of Silver River and traces of associated kiln.		
History	This corn mill and kiln are cited on opposite sides of the mill race on the 1838, 1884 and 1910 OS six-inch maps. Cited in the 1840s Mill Valuation book as a corn mill belonging to James Mulloy. A 10ft x 2ft wheel drove two sets of stones. It is noted in the 1854 Griffith Valuation as being operated by Terence McAlroy. The house, offices and corn mill were rated at £6.10s.0d.		

Component OFIAR-009-015 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 238827 230620 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A

Waterworks Remains Traces Condition Fair Use Disused

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains Traces Condition Poor Use Disused

Description No traces of this water-powered corn mill survive. To the south of its former location

is a single-storey random rubble building probably once associated with it. The races have been infilled in the vicinity of the mill but the tailrace culvert under the road is

still open as a slightly skew dressed stone arch.

Component OFIAR-009-015 2

Type Grain kiln Function Grain milling

Category Food processing & products Context Industry

Irish Grid 238852 230624 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Building Remains Traces Condition Fair Use Agricultural building

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A
Condition N/A Use N/A

Description North-east of the mill site are vestiges of random rubble walling which may once

have possibly been the detached kiln. The walls have been incorporated into a later one-storey concrete block agricultural outbuilding. Beside its doorway are fragments

of two one-piece shelling stones; one is a 1.2m (4ft) diameter runner.

Interest None

Evaluation The kiln remains are of no special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-009-015_01 FWH 11/06/2003 Fragment of runner shelling stone.



OFIAR-009-015_02 FWH 11/06/2003 Tailrace culvert under road to west.



Site no OFIAR-009-018

County	v Offal	v Townland	Bracklin Little	Town
County	y Ollai	y rowilianu	Diackiiii Littie	IOW

Planning Offaly CC Discovery map 48 Six-inch map 9

Summary Site of 18th/early 19th century water-powered corn mill on Silver River.

History A ruined corn mill is cited on the 1838 and 1884 OS six-inch maps. Not cited in 1840s

or 1850s valuations.

Component OFIAR-009-018 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 238303 231579 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill on left bank of Silver River a short distance west of New Mill Bridge.

This site has been completely cleared and there are no traces of any building,

waterworks, plant or machinery.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

OFIAR-009-018_01 FWH 11/06/2003 General view of site from south.



Site no	OFIAR-009-021
Site IIO	OFIAN-UU3-UZ I

County	Offaly	Townland Acantha	Town
Planning	Offaly CC	Discovery map 48	Six-inch map 9
Summary	Unlocated site of water-powered tuck mill cited in 1854 Griffith Valuation book in Acantha townland. On Silver River.		
History	Noted in 1854 Griffith Valuation as vacant. Site belonged to Christopher Woods. House, offices, tuck mill rated at £5.		

Component OFIAR-009-021 1

Type Tuck mill (water) Function Wool

Category Textile manufacture & products Context Industry

Irish Grid 234085 229238 +/- 1000m

Survey date 11/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description There is no local knowledge of this water-powered tuck mill.

Interest None

Evaluation No industrial heritage signficance.

Rating Record only Protection Action

Associated with OFIAR-009-005?

Other dbase

References

Site no	OFIAR-010-010
Site no	OFIAK-UIU-UIU

County	Offaly	Townland	Down (Lower Philipstown By)	Town
--------	--------	----------	-----------------------------	------

Planning Offaly CC Discovery map 48 Six-inch map 10

Summary Ruinous remains of 18th/early 19th century water-powered corn mill and kiln on Esker

Stream.

History This corn mill is cited on the 1838 and recorded in the 1840s Mill Valuation book as

belonging to James Mulligan. It had a 13ft x 1ft 8in waterwheel driving two pairs of stones. The machinery classification suggests that it was antiquated by this time. The mill is not cited in the 1854 Griffith Valuation. However, it is explicitly captioned on the 1884 OS map. It may have gone out of use shortly thereafter as it is not captioned on the 1910 map.

Component OFIAR-010-010 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 249046 231162 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Poor Use Disused Waterworks Remains Traces Condition Poor Use Disused

Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

Description Overgrown remains of 18th/19th century corn mill on right bank of Esker Stream. It is

a 2½-3-storey/three-bay building aligned approximately east-west. It may incorporate a kiln aligned north-south at its east end. The roof is now missing. The walls are of random rubble, now partly collapsed at north and east. Square-headed openings. Of the waterworks, only the overgrown tailrace is now visible. The waterwheel may have been internal at the west end of the building, but there is now no trace of it or of

any machinery.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 73 of Ireland c.1850 (Dublin, 2000).

OFIAR-010-010_01 FWH 11/06/2003 General view from south.



Site no	OFIAR-010-012
SILE IIU	OFIAN-UIU-UIZ

County	Offaly	Townland Croghan Demesne	Town
Planning	Offaly CC	Discovery map 48	Six-inch map 10
Summary	Site of 18th/early 19th century water-powered corn mill on Esker Stream.		
History	Cited on 1838 OS six-inch map, but not recorded on the 1840s Mill Valuation or 1850s Griffith Valuation. Possibly associated with a kiln to its east (OFIAR-010-013).		

Component OFIAR-010-012 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 248221 231437 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Condition N/A Use N/A Building Remains No visible remains Use N/A Waterworks Remains No visible remains Condition N/A Plant Remains No visible remains Condition N/A Use N/A Remains No visible remains Condition N/A Use N/A Machinery

Description Site of 18th/19th century corn mill on left bank of Esker Stream at west side of road

junction. No traces of the building, waterworks, plant or machinery survive.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-010-013?

Other dbase

Site no	OF	IAR-	010-	013
OILE HO	OI.	1717-	-טוע	UIJ

County	Offaly	Townland Croghan Demesne	Town
Planning	Offaly CC	Discovery map 48	Six-inch map 10
Summary	Site of 18th/early 19th century corn kiln.		
History	Marked on the 1838 OS six-inch map only, this kiln may have been associated with a corn mill to its west (OFIAR-010-012).		

Component OFIAR-010-013 1

Type Grain kiln Function Grain milling

Category Food processing & products Context Industry

Irish Grid 248250 231443 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A Use N/A Plant Remains N/A Condition N/A Use N/A Machinery Remains N/A Condition N/A Use N/A

Description Site of 18th/19th century corn kiln immediately north of fork in road.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-010-012?

Other dbase

Site no	OFIAR-010-014

Townland Aghamore (Lower Philipstown Town County Offaly

By)

Offaly CC **Planning** Discovery map 48 Six-inch map 10

Site of 18th/early 19th century water-powered corn mill and kiln on Esker Stream. Summary

The mill and kiln are cited on the 1838 OS six-inch map. Cited in the 1840s Mill **History**

> Valuation book as a corn mill belonging to Lawrence Kearney. A 10ft x 2ft 6in wheel drove two sets of stones. The 1853 Griffith Valuation notes the house, offices, corn mill under Patrick Kearney, all rated at £5. Possibly disused by later 1800s as not

explicitly cited on the 1884 or 1910 OS maps.

Component OFIAR-010-014 1

Grain kiln; Grain mill (water) Grain milling Type Function

Category Food processing & products Context Industry

Irish Grid 248232 231382 +/- 10m

Fred Hamond Survey date 11/06/2003 Surveyor

Condition N/A Use N/A **Building** Remains No visible remains Waterworks Remains No visible remains Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A Remains No visible remains Use N/A Machinery Condition N/A

Description Site of 18th/19th century corn mill and kiln on left bank of Esker Stream at west side

of road. Site now occupied by modern bungalow. No traces of the mill, waterworks,

plant or machinery survive.

Interest None

Evaluation No industrial heritage significance.

Action Record only **Protection** Rating

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-010-016
OILE IIO	

CountyOffalyTownlandBarnanTown

Planning Offaly CC Discovery map 48 Six-inch map 10

Summary Site of mid 17th century wind-powered mill in Barnan townland.

History An unlocated windmill is cited in 1655 Down Survey in Barnan townland.

Component OFIAR-010-016 1

Type Grain mill (wind) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 245428 231421 +/- 1000m

Survey date 11/06/2003 Surveyor Fred Hamond

Remains No visible remains Use N/A Building Condition N/A Remains N/A Waterworks Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of unlocated windmill.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase SMR OF010-044--

Site no OFIAR-011-001

County Offaly Townland Fahy Town

Planning Offaly CC Discovery map 49 Six-inch map 11

Summary Shell of 18th/early 19th century wind-powered corn mill.

History Cited on the 1838 and 1884 OS six-inch maps but captioned as disused on the 1910 edition. It is uncertain whether it was still in use in the mid 1800s as it is not recorded

in the 1840s Mill Valuation book or in the 1854 Griffith Valuation.

Component OFIAR-011-001 1

Type Grain mill (wind) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 254967 233816 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Disused shell of 18th century windmill atop a flattish hill east of Rhode. It is of

cylindrical profile and stands to its full height of three storeys. It measures 5.50m (18ft) externally and has 90cm (3ft) thick walls. The latter are of random rubble and have a dressed stone curb around the top (the cap is long gone). There are opposite doors to the ground floor, both with voussoired heads. Above the north door is a small square recess which may once have housed an inscribed plaque. There are small slit windows to each of the upper floors - four to the first floor and two to the top (cap) floor. Although the internal floors are now missing, their positions are evident from the in-stepping of the walls at each level. Sockets for the stairs to the first floor

are also visible. No machinery survives.

Interest Architectural; Rarity; Setting

Evaluation Compared to watermills, windmills are rare in Co Offaly; this is one of six attested

sites, and one of only two surviving windmills (the other is OFIAR-029-008). It is of architectural interest, its cylindrical shell and narrow slit windows being typical of 18th century windmill construction. The shell also has several slightly unusual features - the voussoired door heads (normally flat timber lintels are used), and dressed curb. It is a prominent landmark hereabouts and is undoubtedly of regional interest. Although it is a Protected Structure in the Co Offaly County Development Plan 2009-15, it also

merits inclusion in the Record of Monuments & Places.

Rating Regional Protection Offaly RPS 16-14 Action RMP

Associated with

Other dbase NIAH 14911014 (R)

References

OFIAR-011-001_01 FWH 13/06/2003 General view from north.



 $OFIAR-011-001_02 \quad FWH \quad 13/06/2003 \qquad \mbox{View from south-east}.$



OFIAR-011-001_03 FWH 13/06/2003 View from north-west.



OFIAR-011-001_04 FWH 13/06/2003 Door head and recess at north side.



Site no	OFIAR-011-021
---------	---------------

County Planning	Offaly Offaly CC	Townland Ballyhugh	Town Six-inch map 11
Summary		d corn mill and kiln dating porates a late19th/early 2	
History	The datestone attests to the mill's construction by Samuel Lucas in 1762. It is cited or the 1838, 1884 and 1910 OS six-inch maps; a saw mill is also captioned on the 1910 map. Noted in 1840s Mill Valuation book as belonging to George Gillard. A 10ft x 3ft wheel drove two sets of stones. In the 1853 Griffith Valuation book, the house, office, corn mill and kiln are recorded under Richard Gillard and rated at £20 (the lease is		

Component OFIAR-011-021 1

Type Grain kiln; Grain mill (water); Saw Function Grain milling; Timber processing &

mill (water) products

Category Food processing & products; Context Industry

Timber processing & products

Irish Grid 252860 228651 +/- 10m

from Robert Lucas).

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Good Use Agricultural building

Waterworks Remains No visible remains Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains Traces Condition Fair Use Disused

Description Substantial remains of 18th/19th century corn mill and kiln on Esker Stream, NW of Newtown Bridge; also site of former saw mill. Now in use as agricultural outbuildings.

Buildings

The mill is aligned NE/SW and is a three-storey/two-bay building with shell of two-storey/one-bay kiln on its NE gable. It has a pitched natural slate roof with concrete verges; metal rainwater goods. Random rubble walls (painted and rendered to the east elevation) and dressed stone eaves. Square-headed openings, mostly infilled on east side. A large door has been inserted on west side. The south gable has an infilled doorway with voussoired head, over which is a carved stone reading "SL/1762" [= Samuel Lucas]. There is no obvious evidence of the saw mill which was presumably housed in the corn mill.

The two-storey/one-bay kiln abuts the NE gable of the mill. Its east wall has been slightly lowered to accommodate a new monopitched corrugated metal roof. The walls are of random rubble. There is a large modern doorway to its east wall. Internally, there are traces of brick vaulting.

The mill house at NE is a two-storey/three-bay building, now refurbished. Its only distinguishing feature is a Gibbsian surround to it front entrance.

Waterworks, plant and machinery

The mill pond at west has been infilled and there is no visible evidence of any races. The OS maps show the headrace entering the mill towards its SW end; this indicates an internal wheelwheel of which nothing now survives. The only surviving machinery

d d f f

Interest Historical

Evaluation This is one of the few mill sites in Co Offaly to have an attested construction date.

However, the building is otherwise of no particular merit and is now primarily of local

historical interes because of its datestone.

Rating Local Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-011-021_01 FWH 13/06/2003 General view of site from south-east. Mill at left and house at right.



OFIAR-011-021_02 FWH 13/06/2003 Mill and kiln from north.



OFIAR-011-021_03 FWH 13/06/2003 Datestone on south-west gable of mill.



OFIAR-011-021_04 FWH 13/06/2003 Sack hoist on top floor of mill.



Site no	OFIAR-011-030		
County	Offaly	Townland Clonin	Town
Planning	Offaly CC	Discovery map 49	Six-inch map 11
Summary	Site of 18th/early 19th century horse-powered threshing mill in farmyard of Clonin House.		
History	Cited in 1838	and 1884 OS six-inch maps. A circula	ar building, undoubtedly a horse-

Type Threshing mill (horse) Function Grain processing

walk, is shown on the 1910 six-inch and 25-inch maps.

Category Farming production Context Agriculture & fishing

Irish Grid 253050 234124 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A Use N/A Plant Remains N/A Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Site of 19th century threshing mill in farmyard south of Clonin House. The house has

been replaced by a modern bungalow.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

Site no OFIAR-011-031

County	Offaly	Townland Toberdaly	Town
Planning	Offaly CC	Discovery map 49	Six-inch map 11
Summary	Site of 18th/early 19th century threshing mill in farmyard of Killure House. Probably horse-powered.		
History		and 1884 OS six-inch maps. The building is shown on any maps	here may have been an open horsewalk

Component OFIAR-011-031 1

Type Threshing mill (horse) Function Grain processing

Category Farming production Context Agriculture & fishing

Irish Grid 252484 233169 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Condition N/A Use N/A Building Remains No visible remains Waterworks Remains N/A Condition N/A Use N/A Condition N/A **Plant** Remains N/A Use N/A Use N/A Remains No visible remains Condition N/A Machinery

Description Site of 19th century threshing mill in farmyard east of Killure House. The farmyard is

arranged around a courtyard and comprises miscellaneous two-storey buildings (one of which may originally have been the threshing mill). Killure House is a double-pile/

two-storey/three-bay building; recently refurbished.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

OFIAR-011-031_01 FWH 23/06/2003 Farmyard behind house, from north.



OFIAR-011-031_02 FWH 23/06/2003 Killure House from east.



Site no OFIAR-011-032

County	Offaly	Townland Toberdaly	Town	
Planning	Offaly CC	Discovery map 49	Six-inch map 11	
Summary	18th/early 19th century kiln of unknown function in grounds of Toberdaly House.			
History	Captioned on 1838 OS six-inch map, but not shown on subsequent maps. Probably a grain kiln rather than a lime kiln as explicitly captioned.			

Component OFIAR-011-032 1

Type Kiln Function Unknown

Category Unknown Context Settlement

Irish Grid 252005 232009 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A
Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description No traces of this structure survive.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

Site no	OFIAR-011-035				
County	Offaly	Townland Mountwilson	Town		
Planning	Offaly CC	Discovery map 49	Six-inch map 11		
Summary	Site of 18th/early 19th century threshing mill in farmyard of Mountwilson House. Probably horse-powered.				
History	Cited in 1838 a		tly-roofed circular walk is shown, but		

Component OFIAR-011-035 1

Type Threshing mill (horse) Function Grain processing

Category Farming production Context Agriculture & fishing

Irish Grid 259321 234086 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Remains No visible remains Condition N/A Use N/A Building Waterworks Remains N/A Condition N/A Use N/A Condition N/A Plant Remains N/A Use N/A Remains No visible remains Machinery Condition N/A Use N/A

Description Site of 19th century threshing mill in farmyard behind Mountwilson House. The

original farm outbuildings are generally two storeys high and have random rubble walls with brick trim to the openings. Mountwilson House is a two-storey (+ attic)/five-

bay building, now re-roofed.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

0:4	OFIAD 040 004
Site no	OFIAR-012-001

County Planning	Offaly Offaly CC	Townland Mona	asteroris 49	Town Six-inch map 12
Summary				d corn mill and kiln on tributary of River he 1655 Down Survey.
History	A mill is marked hereabouts on the 1655 Down Survey. A corn mill and kiln are marked on the 1838 and 1884 OS six-inch maps. The site is recorded in the 1840s Mill Valuation book as belonging to W. and J. Jackson. A 14ft x 4ft wheel drove three sets of stones. The 1853 Griffith Valuation notes Robert Jackson as the occupier of the house, offices and corn mill; they are rated at £16. This site may have been functionally associated with the nearby windmill (OFIAR-012-002). A disused mill race is captioned on the 1910 map.			

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 261681 233710 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A

Waterworks Remains Some remains Condition Poor Use Disused

Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of 18th/19th century corn mill and kiln on a minor tributary of River Boyne just

north of Mill Mount House. Only the dried-up and overgrown tailrace is now

discernible.

The nearby Mill Mount House comprises the ruinous shell of a two-storey over

basement building.

Interest Archaeological

Evaluation Although this site is of archaeological interest and in the Record of Monuments &

Places (OF012-016---), the absence of upstanding remains makes it of no industrial

heritage significance.

Rating Record only Protection RMP OF012-016--- Action

Associated with OFIAR-012-002?

Other dbase SMR OF012-016---

References

Archaeological Survey of Ireland record.

Page(s)

Evans, M. & Whelan, N. Edenderry through the Ages (Edenderry: Edenderry

Page(s) 39

Historical Society).

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills of Ireland c.1850 (Dublin, 2000).

Page(s)

OFIAR-012-001_01 FWH 23/06/2003 Mill Mount House, from north-west.



Site no	OFIAR-012-002
OILE IIU	

County	Offaly	Townland Monasteroris	Town	
Planning	Offaly CC	Discovery map 49	Six-inch map 12	
Summary	Site of 18th/early 19th century wind-powered corn mill.			
History		nill is marked on the 1838 OS six-inch ma	ap. May have been associated	

Type Grain mill (wind) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 261737 233449 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of windmill on low hillock south of lane to Mill Mount.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-012-001?

Other dbase

Site no) ()FI	۸R-	012-	024
OILE III	, (JI 11	¬ ı, '-'	U I Z-	VET

County	Offaly	Townland Edenderry	Town Edenderry
Planning	Offaly CC	Discovery map 49	Six-inch map 12

Summary Site of 18th/early 19th century wind-powered corn mill.

History A ruined windmill is cited on the 1838 OS six-inch map.

Component OFIAR-012-024 1

Type Grain mill (wind) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 262180 232177 +/- 10m

Survey date 23/06/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains N/A Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of windmill on ridge to west of Edenderry. This locality is now occupied by

modern housing.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

Site no	OFIAR-012	2-027	Edenderry Saw Mill	
County	Offaly	Townland Edenderry	Town Edenderry	
Planning	Offaly CC	Discovery map 49	Six-inch map 12	
Summary	Remains of steam-powered coach and furniture factory, in operation from 1888 to 1932. Part of the site was developed by the Edenderry Shoe Co in 1935. Shoe production ceased in 1991.			
History	Saw mill is part of furniture factory established in 1888 near terminus of Edenderry Branch of Grand Canal. They produced household furniture and horse traps, carts and motor bodies (all in wood). The saw mill is explicitly captioned on the 1910 OS sixinch map. The factory closed in 1932. The Edenderry Shoe Company started up in part of the site in 1935 and operated until 1991.			

Component OFIAR-012-027 1

Type Saw mill (steam) Function Timber processing & products

Category Timber processing & products Context Industry

Irish Grid 262883 232523 +/- 10m

Survey date 31/07/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Good Use Offices/Retail outlet

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

Description

This site, near the terminus of the Edenderry Branch of the Grand Canal, comprises buildings of 19th and 20th century date, in various states of completeness. It has been redeveloped as Edenderry Business Park for light industrial, commercial and office uses.

Aligned on the street frontage at NW is a long two-storey later 19th century block associated with the former saw mill. It has recently been refurbished as shops and offices. It now has a pitched artificial slate roof; the ghost line of the former roof shows the new one to have a slightly steeper pitch. At centre is an eaves gable (in place of an earlier clock tower). The walls are cement rendered (possibly over stone), with moulded brick string courses at first floor and eaves levels. New shop fronts have been inserted on the ground floor. There are original small sub-rectangular windows with concrete cills to the first floor.

Immediately south of this building is the left half of the main entrance gate screen to the site. It is concave, of random rubble and has been heightened over its original brick coping in rendered concrete blockwork. An ashlar stone gate pillar also survives

In the yard behind is a double-pile/single-storey building aligned north-south. Its pitched roofs are of corrugated asbestos and profiled metal (with skylights); the rainwater goods are also of asbestos fibre cement. The walls are of mass concrete; parts may also be of brick (now obscured by cement render). All openings have square heads and there are large doorways to the south gables. There is a lower similarly detailed extension to the north gable of the west pile.

Aligned along the canal towpath is part of the wall to a two-storey building. It is of brick with concrete cills to the window openings (now infilled with concrete blocks). There is no obvious trace of the former chimney.

Component OFIAR-012-027 2

Type Footwear factory Function Footwear manufacture

Category Other industry Context Industry

Irish Grid 262907 232456 +/- 10m

Survey date 31/07/2003 Surveyor Fred Hamond

Use Offices Building Remains Complete Condition Good Use N/A Waterworks Remains N/A Condition N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Along the street frontage SE of the former sawmill office is a two-storey/multi-bay

concrete-framed office block. It was undoubtedly erected by the Edenderry Shoe Company, probably in the 1930s, and is still used as offices. It has a flat concrete roof and painted/cement-rendered brick walls. All window openings are square headed and have aluminium/uPVC frames and concrete cills. The south end of this

building was originally one storey high but has been raised to two.

Interest Historical

Evaluation The furniture factory/saw mill component of this site is of little architectural interest

and few original features survive. The former Shoe Company office block typifies its period of construction but cannot be said to be of special architectural merit. Overall,

the site is of local industrial heritage significance.

Rating Local Protection Action

Associated with

Other dbase

Edenderry Chamber of Commerce. Edenderry: a Signposted Walking Tour Page(s) 13 (Edenderry: Edenderry Chamber of Commerce, 1989).

Evans, M. & Abbott, T. Safe Harbour: the Grand Canal at Edenderry Page(s) 22 (Edenderry: Edenderry Historical Society).

Evans, M. & Whelan, N. Edenderry through the Ages (Edenderry: Edenderry Page(s) 39 Historical Society).

Evans, M. & Whelan, N. Edenderry through the Ages (Edenderry: Edenderry Page(s) 45 Historical Society).

Evans, M. & Whelan, N. Edenderry through the Ages (Edenderry: Edenderry Page(s) 50 Historical Society).

Offaly Express, 12 Oct 1991. Page(s)

OFIAR-012-027_01 FWH 31/07/2003 Street frontage, from south.



OFIAR-012-027_02 FWH 31/07/2003 Shoe Company block, from south-west.



OFIAR-012-027_03 FWH 31/07/2003 Yard buildings, from north.



OFIAR-012-027_04 FWH 31/07/2003 Looking south to site along canal.



C:4	OFIAD 042 000
Site no	OFIAR-013-006

County	Offaly	Townland Annaghmore (Garrycastle By)	Town		
Planning	Offaly CC	Discovery map 47	Six-inch map 13		
Summary	Site of 18th/early 19th century water-powered corn mill on River Blackwater.				
History	1840s Mill Valua	mill on 1838 OS six-inch map. It is described ation book, operated by Thomas Seale. A 14 of stones. Not cited in 1854 Valuation or 1885	ft x 2ft 3in waterwheel		

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 202430 223715 +/- 10m

implying that out of use.

Survey date 24/06/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains No visible remains Use N/A Condition N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Use N/A Condition N/A

Description Site of corn mill on River Blackwater.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-014-001
---------	----------------------

County	Offaly	Townland Corbane	Town
Planning	Offaly CC	Discovery map 47	Six-inch map 14
Summary	Site of 18th century water-powered corn mill on tributary of River Blackwater.		
History	1830s as not c	orn mill" in 1838 and 1884 OS six- cited in 1840s Mill valuation book, c captioned on the 1910 OS map.	

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 211479 228031 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill on tributary of Blackwater River, immediately south of minor road. A

two-storey/three-bay house stands hereabouts.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

Site no	OFIAR-014-004		Belmont Mills
County	Offaly	Townland Bellmount or Lisderg	Town
Planning	Offaly CC	Discovery map 47	Six-inch map 14
Summary	south of Belmo 20th century h stables). The c	n/19th century grain mill complex on right ont village. Site encompasses oat mill, flo ydro-electricity stations, and ancillary buil oat mill retains its waterwheel and all its mons is operational.	our mill, grain/meal stores, two ldings (houses, offices,

History

Belmont Mills originated in the 1760s with the construction of a water-powered mill, probably for grinding grain (primarily oats). In the later 1700s or early 1880s, a tuck mill (for fulling woollen cloth) and a rape mill (for the production of vegetable oil) were also erected.

The complex is described as encompassing a flour/oat mill and tuck mill in the 1840s Mill Valuation book, operated by Charles Atkinson. The grain mill had a 15ft x 4ft 8in wheel, and the tuck mill one measuring 12ft x 3ft. Both mills are described as old and the grain mill was out of repair.

In the early 1850s, Captain John Collins built a large flour mill beside the earlier mill complex; it was rated at £55 in the 1854 Griffith Valuation (which also notes the corn mill as dilapidated at this time).

In 1859 the flour mill and nearby Belmont House were bought by Henry Robert Perry of Clara, Co Offaly (Robert Perry & Co are noted as the operators of Erry Mill, Clara (OFIAR-008-038) in the 1854 Valuation). In the 1860s, the operation of the flour mill was in the hands of Thomas and James Perry. In 1866, Thomas leased the adjoining derelict corn and rape mills. The following year, the corn mill was enlarged and converted to a grain store. The rape mill was likewise enlarged and converted to an oat mill. A drying kiln was also erected.

Thomas Perry acquired outright ownership of the flour mill in 1878 and made a number of additions to it and the site in general (e.g. the mill house and mill office). The flour mill was gutted by fire in the following year but was quickly rebuilt. Roller mills (an innovation at that time) were installed in addition to conventional millstones. The machinery in the oat mill was probably upgraded at the same time. Both mills were powered by water.

In 1893, the business was restructured as Robert Perry & Co Ltd. Upgrading of the flour mill continued and a new maize mill was added in 1906-09. Another disastrous fire in 1925 resulted in the destruction of the flour/maize mill. Again the mill was rebuilt and operations recommenced in 1928 under Robert Perry & Co (1927) Ltd. A turbine also produced electricity for the mill.

The oat mill functioned until the mid 1970s. The maize mill continued to produce animal feed until it was once again gutted by fire in 1982. It was demolished, leaving only its associated grain store. The generation of hydro-electricity for the national grid also began in that year. The installation of a small hammer mill and two mixing plants enabled its then owner, Mr David Perry, to continue producing animal feed until 1997 when the site was purchased by Mr Tom Dolan, its present owner.

Component	OFIAR-014-004 1				
Туре	Grain kiln; Grain mill (water); Oilseed mill (water)		Function	Grain milling; Oilseed milling	
Category	Food processing &	products	Context	Industry	
Irish Grid	207218 222174	+/- 10m			
Survey date	24/06/2003	Surveyor	Fred Ham	nond	

Building	Remains	Complete	Condition	Fair	Use Disused
Waterworks	Remains	Complete	Condition	Fair	Use Disused
Plant	Remains	Complete	Condition	Fair	Use Disused
Machinery	Remains	Complete	Condition	Fair	Use Disused

Description

The complex comprises a corn mill, kiln, stores, houses, the remains of a flour mill, and two hydro-electric stations. The buildings are in various states of use and repair. Some are undergoing or are earmarked for adaptive reuse, and others are disused but in reasonable repair. Excepting the headrace to the corn mill, the waterworks are complete and still supply a hydro-electric power station. For a detailed description, see references.

Buildings

This block encompasses a corn mill (complete with waterwheel and machinery), kiln, grain store and screen room.

Oat mill

A five-storey/ single-bay block aligned north-south. This was originally the oilseed rape mill, erected in the late 1700s/early 1800s and was heightened by two floors when converted to a corn mill in 1867. Natural slate roof, hipped at its north end and continuous with the grain store at south but separated from it by a raised firewall. Slates mostly gone. Walls of lime-rendered random rubble brought to courses with advanced brick eaves. Square headed openings with brick heads and jambs (rendered over). Windows are 3/3 and 6/6 sliding sashes with stone cills. Internally, the upper floors are of timber boards directly laid on transoms without joists. Timber stairs connect all floors. The walls are plastered. The plant and most of the machinery survive (described below).

Kiln

A two-storey/single-bay grain drying kiln in the corner formed by the mill and grain store. It is aligned north-south and was built in 1867. This building is now in poor repair. Originally it had a pitched natural slate roof, hipped to its north end. This roof was superseded by a shallow monopitched corrugated iron roof, the north gable being built up in concrete blockwork to accommodate its profile. This later roof has also disappeared. The walls are detailed as the mill but are rendered with cement. Squareheaded openings. Windows are 6/6 sashes trimmed in brick. Internally, the ground floor is flagged with stones, with timber boards over the headrace. The walls are lime plastered and the ceiling is of brick jack arch construction. Against the east wall are two brick and rubble masonry fireholes for the drying floor above. There is a French burr stone set against one corner. The drying floor is accessed from the mill's first floor. Its walls are cement rendered. There are grain intake chutes from the adjoining grain store. The floor comprised 305mm (12in) square perforated ceramic tiles resting on cast-iron beams which slot over heavier longitudinal beams. Only c.20 tiles now remain and part of the supporting framework has disappeared. Directly underneath is a hot-air chamber, with ducts across the jack arches from the two fireholes on the ground floor.

Grain store

This double-pile/five-storey/four-bay store abuts the south ends of the mill and kiln and is aligned east-west. This building was originally an oat mill, erected in 1769, but was raised by two floors when converted to its present form in 1867. It is in reasonable repair, apart from a section of its roof, and is disused. This building has a double-pile natural slate roof, hipped at west and half-hipped at east. The west gable incorporates the remains of the original oat mill, evident as unrendered random rubble walling which extends to the third floor and terminates in the eaves line of the former hipped roof. This wall was subsequently raised by 1½ storeys in rendered random rubble brought to courses. Square headed openings. The window openings are trimmed with brick, but have no cills; only one 6/6 sash window survives. Two square-headed doorways to the ground floor gable. One is infilled and the other is an enlargement of an original window. The infilled doorway has dressed stone jambs and

an entabulated head inscribed: "Gilbert Holmes & Thos L'Estrange Esqr. May ye 21/1769/ Erected/ by John Clifford/ mill wright". Over the eaves on the south gable is a projecting timber lucum with pitched natural slate roof, decorative bargeboards and timber walls. It originally contained a sack hoist and then a bell (now removed). Halfway along the base of the south elevation is what appears to be the emplacement to the waterwheel of the former oat mill.

Internally, the ground floor is variously flagged, boarded and concreted. The upper floors are of timber over transverse beams with intermediate timber uprights (but brick piers to the ground floor). Parts of the flooring is in poor repair. Ladders connect all floors. The walls are lime plastered. The roof is of common rafters, without purlins or trusses. The valley between each pitch is carried on a line of timber uprights down the middle of the floor. The undersides of the slates are lime plastered. This building contains the remains of three elevators, screw conveyor, and sack hoist driven by an electric motor. A French burr stone lies against the wall at SE on the first floor.

Screen room

A two-storey/single-bay building abuts the east gable of the grain store. Its triangular plan is shown on the 1838 map. Now roofless and derelict, it contains the remains of 20th century grain cleaning equipment. The roof was originally pitched, with its ridge sloping down to the east. The walls are detailed as the mill but are cement dashed. Square-headed openings.

Inside, the ground floor is of concrete and the first floor of boards over beams (no joists); the latter has mostly collapsed. Cement rendered walls The ground floor contains an intake to a bucket grain elevator, a circular steel cyclone, and cockler (by E.R & F. Turner Ltd, Ipswich) for removing weed seeds from the grain. The first floor contains the remains of a screw conveyor and cleaner, also by Turner. A lineshaft along the party wall with the grain store drove the elevator, cleaner and cockler and was in turn driven by a belt off an electric motor, now removed. Although the building is of 18th or 19th century date, its equipment appears to be of the 20th century. All the grain was cleaned here before moving to the adjoining kiln.

Waterworks

These comprise an impressive weir across the Brosna River and several head- and tailraces. One of the headraces is still live, supplying water to the hydro-electricity generating station; the other, to the oat mill, has been infilled.

Weir

A vee-shaped weir some 3.6m (12ft) high runs diagonally across the river immediately upstream of Belmont Bridge. It has a steeply sloped face of squared limestone rubble, fish pass to centre, and apron below. There is an inscribed limestone plaque at the top of the pass which reads: "VR/ Board of Public Works/ Drainage/ Belmont Mill Weir/ 18[?]1/ [???]. The weir is aligned such that the water is directed through the two arches at the NW end of the bridge and into the headrace. The level of the water in this race could be controlled by two sluice gates set into a concrete emplacement on the downstream side of the bridge, any excess water being returned to the river. A short distance further on, the headrace bifurcated, with a race going to the corn mill and former flour mill.

Headrace 1

This fed the corn mill, but has been infilled. The feed to the waterwheel ran along the north side of the screen room and grain store and then passed through the kiln. It is only now visible where it enters the kiln.

Headrace 2

This channel formerly fed the flour mill. It has been widened in the recent past to supply the new hydro-electricity station. There is a modern sluice emplacement just above the latter.

Tailrace 1

Once the water had passed through the waterwheel in the oat mill and/or along the spillway, it was discharged along this tailrace back into the river.

Tailrace 2

This race returned the water from the waterwheel/turbine in the flour mill back to the river.

Tailrace 3

This race was probably originally a spillway for excess water along headrace 2. It now acts as the tailrace for the turbine in the modern hydro-electric power station.

Plant

The corn mill still retains its internal waterwheel, fed from headrace 1 running below the ground floor of the kiln. It measures 4.27m x 1.37m (14ft x 4ft 6in) and has a breastshot feed. It is of cast-iron throughout except for the timber soleplates and floats. Its two rims each have eight arms affixed to the axle hubs. Thirty-two floats, each 50cm (20in) deep, are affixed to pairs of angled starts mortised through the rims and additionally secured with metal side rings. Although long disused, the wheel is complete and in reasonable condition, albeit with some floats and sole plates missing or loose. Just behind the wheel is an inclined timber sluice gate, manually operated through a two-step rack-and-pinion mechanism.

Machinery

The corn mill contains virtually all its machinery - shafts and gears, millstones, roller mill, and ancillary devices for screening/processing oats and grading oatmeal. The power transmission system is of conventional great spurwheel arrangement to three sets of millstones. There was also a fourth drive off the great spurwheel to the ancillary machinery. All components are of cast iron save the stone nut cogs, which are of wood. The gap between the millstones was altered by means of a screw adjuster underneath each footstep bearing. Each nut could be disconnected from the spurwheel by a jack ring.

Three sets of millstones are located at the east end of the first floor. One was for shelling and the other two (both French burrs) for grinding groats (i.e. shelled oats) and wheat. The burrs carry maker's plates, both reading "Kay & Hilton, Bank Hall Bridge, Liverpool, 1880". The stone spindles to the burrs are now missing, perhaps because the stones were superseded by a small belt-driven roller mill on the first floor (by Buhler, Switzerland).

The mill also retains equipment for handling the grain and meal, for cleaning the grain, separating the shells from the groats, and grading the meal - elevators, screw conveyors, rotary and reciprocating sieves, and fans. The waterwheel drove all this equipment via the auxiliary drive nut off the great spurwheel to lineshafts, pulleys and belts on the floors above.

Type Grain mill (electric; water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 207213 222131 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Fair Use Disused

Waterworks Remains Complete Condition Excellent Use Disused

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description

The five-storey/single-bay store is all that now remains of the 1850s flour mill. It has a hipped corrugated iron roof and lime-rendered random rubble walls. All openings are trimmed in yellow brick (rendered over). Where not infilled, the windows mostly have 4/4 top-hung cast-iron frames. A mass-concrete elevator shaft of c.1908 projects from the middle of the north façade. It rises above eaves level to terminate in a gable with a pitched corrugated iron roof. A corrugated iron awning envelopes the bottom two floors of the north and east elevations.

A triple-pile, five-storey flour mill was formerly attached to the south elevation of this block but was demolished in 1982 after a fire.

Internally, the timber floors rest directly on steel beams. These date from the mill's refurbishment in the 1920s. There are the remnants of equipment for mixing animal compounds (dating from the 1980s). The mass-concrete section to front contains a bucket elevator which supplies a screw conveyor on the top floor. There is also a sack hoist in the roofspace. The elevators and hoist were driven by electric motors. This building is in fair condition. When surveyed, part of the ground floor was in use as a craft studio.

Component OFIAR-014-004 3

Type Mill house Function Grain milling

Category Food processing & products Context Industry

Irish Grid 207221 222262 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Dwelling

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A
Condition N/A Use N/A

Description

A two-storey mill owner's dwelling of 1860s date formerly known as Belmont Cottage, situated at the north end of the site. The front section faces south and has a hipped natural slate roof and boxed bracketed eaves; only the upper floor is visible to this elevation. A pitched roof section abuts the rear of the front block and there is also a return at NW. The eaves are boxed and carried on paired brackets. The walls are of random rubble brought to courses, but all openings are trimmed in brick. The main entrance, in the middle of the first floor of the south elevation, has sidelights and a segmental margined transom light over. All the windows are 2/2 sliding sashes. This building is in excellent condition and occupied by the site owner.

Type Mill building Function Grain milling

Category Food processing & products Context Industry

Irish Grid 207204 222216 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Fair Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description Between the oat mill block and mill house is an L-shaped block comprising a two-

storey stable block to south and a two-storey stable block/coach house to west, both facing into a small yard bounded by a rubble stone wall. This block is abutted at north east by a small one-storey stable and house, only the partial shell of which survives. The south block has a pitched natural slate roof and random rubble walls. Some original 6/6 sliding sash windows survive. There are stables to the ground floor and offices and hayloft to the first floor. The west block has a curved corrugated iron roof and random rubble walls. It has stables on the ground floor and a hayloft over. At its

east end is a coach house.

At the time of survey this derelict block was in the process of being converted into

craft studios and accommodation.

Component OFIAR-014-004 5

Type Mill building Function Grain milling

Category Food processing & products Context Industry

Irish Grid 207187 222168 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Dwelling

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description A one-storey former office of L-plan, built 1880. It has a hipped natural slate roof,

lined cement-rendered walls and stucco quoins. There is an entrance porch to its east elevation. A painted timber fascia board across the east side of the north bay reads "Robt Perry & Co (1927) Ltd Belmont Mills". The windows are 2/2 sliding sashes and originally had metal security bars, since removed. This building has been refurbished

internally as a dwelling.

Type Mill house Function Grain milling

Category Food processing & products Context Industry

Irish Grid 207190 222124 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A
Condition N/A Use N/A

Description

A two-storey/four-bay dwelling formerly occupied by the miller stands towards the SW corner of the site. It has a half-hipped natural slate roof with a pair of yellow brick chimneys towards the centre. The walls are of lime-rendered random rubble. The principal façade faces east and is four openings wide. Square-headed openings. The windows are 6/6 sliding sashes. The centrally placed fielded-and-panelled entrance door has a radial fanlight over. There is a slightly lower two-storey return at the south end of the rear wall. Occupied until 1996, this building is now in poor condition. In the yard behind the dwelling are several outhouses. Along the yard's west side is a two-storey yellow brick store with curved corrugated iron roof. Along its north side is a range of one-storey random rubble buildings, all now roofless and derelict.

Component OFIAR-014-004 7

Type Electricity generating station Function Grain milling

(water)

Category Food processing & products Context Industry

Irish Grid 207221 222114 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Poor Use Disused Waterworks Remains Complete Condition Excellent Use Disused Plant Remains Complete Condition Poor Use Disused Machinery Remains Complete Condition Fair Use Disused

Description

A short distance SE of the flour mill store is the pit of a Francis-type turbine of c.1928. Although now in separate ownership, it is included here for completeness. The turbine survives in situ but could not be accessed for detailed inspection. The top of its vertical shaft is supported on steel beams set into mass concrete emplacements. The turbine pit undoubtedly once contained a waterwheel which powered the flour mill.

The turbine drive is linked by a crown wheel and two-step pulley arrangement to two electricity generators. The pulleys and generators are enclosed in a relatively modern corrugated iron shed; remnants of the original rubble stone walling to this section of the mill are also still apparent. One of the generators appears to be of relatively modern date. It is by Brook Motors Ltd, rated at 75kW (@ 925rpm), and connected to a modern switch panel. The second generator is of earlier date but is disconnected from its drive. It is wired to a switch panel containing an ammeter and voltmeter.

Type Electricity generating station Function Electricity

(water)

Category Fuel & power production Context Industry

Irish Grid 207243 222090 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Excellent Use Electricity generation
Waterworks Remains Complete Condition Excellent Use Electricity generation
Plant Remains Complete Condition Excellent Use Electricity generation
Machinery Remains Complete Condition Excellent Use Electricity generation

Description A hydro-power station dating from 1982 and now in separate ownership. A one-storey

corrugated iron and concrete block shed encloses a Kaplan turbine (by Dumont, France) with a 2.20m dia runner. It has a rated output of 515kW based on a 3.60m

head and 17cum/sec flow. The electricity is exported to the ESB grid.

Component OFIAR-014-004 9

Type Mill building Function Grain milling

Category Food processing & products Context Industry

Irish Grid 207172 222188 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description A mass-concrete World War II shelter, partly buried in the ground and heavily

overgrown. Its flat concrete roof has been cast in situ over corrugated iron formwork.

The entrance is on the south gable.

Type Tuck mill (water) Function Wool

Category Textile manufacture & products Context Industry

Irish Grid 207274 222154 +/- 10m

Fred Hamond Survey date 24/06/2003 Surveyor

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description The tuck mill was located along the bank of the river, but no traces survive.

Architectural; Historical; Technical; Setting Interest

Evaluation Belmont Mill and its associated weir are Protected Structures (RPS Offaly 035, 037

respectively). The block containing the corn mill, kiln, grain store and screen room, as well as the mill owner's house, office and miller's house are of architectural and historical interest both individually and as a group in reflecting the evolution of a small rural 18th century oatmeal into a sizeable 19th century flour milling enterprise. The oat mill block is of considerable technical interest, retaining virtually all its 19th century machinery. Although of 20th century date, the two hydro-electricity stations are of historical and technical interest, illustrating the progress of hydro generation. The waterworks are also of interest, particularly the well constructed weir. The complex is also of considerable landscape value, particularly the corn mill block, flour mill store, weir and races. Overall, the site is of regional industrial heritage significance and merits its inclusion as a Protected Structure in the Co Offaly County

Development Plan 2009-15.

Protection Offaly RPS 30-11: **Action** None (in RPS) Rating Regional

Offaly RPS 30-12; Offaly RPS 30-13; Offaly RPS 30-14; Offaly RPS 30-15; Offaly RPS 30-17

Associated with

Other dbase NIAH 14824004 (R); NIAH 14824005 (R); NIAH 14824006 (R); NIAH 14824007 (R);

NIAH 14824008 (R); NIAH 14824010 (R)

References

Garner, W. Churches and Houses of Architectural Interest in Co Offaly Page(s) 41

(Tullamore: Offaly Historical Society, 1985).

Hamond, F.W. Belmont Mills, Belmont, Co Offaly: Industrial Heritage Page(s)

Survey (Unpublished typescript for Mr Tom Dolan, 2003).

Photographic Collection in Local Studies section of Offaly County Library

Headquarters, Tullamore.

Photographic Collection in Local Studies section of Offaly County Library

Page(s) Acc no Headquarters, Tullamore.

200; Inv no

83-AV1

199; Inv no 83-AV1

Page(s) Acc no

Photographic Collection in Local Studies section of Offaly County Library Headquarters, Tullamore.	Page(s)	Acc no 216; Inv no 83-AV1
Photographic Collection in Local Studies section of Offaly County Library Headquarters, Tullamore.	Page(s)	Acc no 865; Inv no 83-AV8
Photographic Collection in Local Studies section of Offaly County Library Headquarters, Tullamore.	Page(s)	Acc no 866; Inv no 84-AV8
Photographic Collection in Local Studies section of Offaly County Library Headquarters, Tullamore.	Page(s)	Acc no 867; Inv no 84-AV8
Photographic Collection in Local Studies section of Offaly County Library Headquarters, Tullamore.	Page(s)	Acc no 868; Inv no 84-AV8
Ryan, B. A Land by the River of God: a History of Ferbane Parish from Earliest Times to c.1900 (Ferbane, 1994).	Page(s)	237
Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills of Ireland c.1850 (Dublin, 2000).	Page(s)	

OFIAR-014-004_01 FWH 24/06/2003 General view of site from east. Flour mill granary at left and oat mill block at centre.



 $OFIAR-014-004_02 \quad FWH \quad 24/06/2003 \qquad General \ view \ of \ oat \ mill \ block, \ from \ north-west.$





OFIAR-014-004_04 FWH 24/06/2003 General view of flour mill granary, from north-east.



OFIAR-014-004_05 FWH 24/06/2003 Flour mill granary, from west.



OFIAR-014-004_06 FWH 24/06/2003 Mill house, from south-west.



OFIAR-014-004_07 FWH 24/06/2003 Stable block, from south-west.



OFIAR-014-004_08 FWH 24/06/2003 Mill office, from north-east.



OFIAR-014-004_09 FWH 24/06/2003 Miller's house, from east.



OFIAR-014-004_10 FWH 24/06/2003 Sluice gate emplacement above electricity station 2.



OFIAR-014-004_11 FWH 24/06/2003 Looking east over weir from west end of road bridge.



OFIAR-014-004_12 FWH 24/06/2003 Weir and road bridge from east.



OFIAR-014-004_13 FWH 24/06/2003 Weir and fish pass, from east.



 $OFIAR-014-004_14 \quad FWH \quad 24/06/2003 \qquad Weir \ and \ fish \ pass, \ from \ west. \ Note \ inscribed \ stone \ at \ top \ of \ pass.$



OFIAR-014-004_15 FWH 24/06/2003 Oat mill waterwheel.



OFIAR-014-004_16 FWH 24/06/2003 Oat mill power transmission gearing.



OFIAR-014-004_17 FWH 24/06/2003 Oat mill stone floor.



 $OFIAR-014-004_18 \quad FWH \quad 24/06/2003 \qquad Oat \ mill \ second \ floor. \ Note \ cylindrical \ separators.$



OFIAR-014-004_19 FWH 24/06/2003 Oat mill third floor showing cylindrical separators (left) and rotary sieve (right).



 $OFIAR-014-004_20 \quad FWH \quad 24/06/2003 \qquad Oat \ mill \ fourth \ floor \ showing \ reciprocating \ sieve \ and \ aspirator.$



OFIAR-014-004_21 FWH 24/06/2003 Ground floor of kiln, from north-west. Note brick fireholes along wall.



OFIAR-014-004_22 FWH 24/06/2003 First floor of oat mill granary, looking north.



Site no	OFIAR-014-03	1
Site no	OFIAK-014-03	4

County	Offaly	Townland Agha	ıbov	Town
Planning	Offaly CC	Discovery map	48	Six-inch map 14
Summary	Site of 18th/ea Brosna.	arly 19th century wate	er-powered	I flour mill and kiln on tributary of River
History	Cited as a flour mill on the 1838 OS six-inch map. The 1840s Mill Valuation book notes a flour mill and an oat mill, both operated by Robert Delany. There were two sets of stones in the flour mill, driven by a 14ft x 6ft 4in paddle wheel. In the oat mill were three sets in the oat mill (one for shelling, two for grinding), driven by a 13ft 10ir x 5ft wheel. The 1854 Griffith Valuation records the premises under Robert Delany and rates it at £36. The site is not captioned on the 1884 OS map and had disappeared by the 1910 edition.		ed by Robert Delany. There were two ft x 6ft 4in paddle wheel. In the oat mill g, two for grinding), driven by a 13ft 10in ds the premises under Robert Delany	

Component OFIAR-014-034 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 212223 224210 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Site of 18th/19th century grain mill and kiln on tributary of River Brosna. A two-storey/three-bay house on this site may be related; it was being refurbished at the

time of survey.

Interest None

Description

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

Site no OFIAR	-014-035
---------------	----------

County Planning	Offaly Offaly CC	Townland Gallen Discovery map 47	Tow Six-	n Ferbane
Summary	Site of 18th/ea	arly 19th century water-po	wered grain mill and kiln or	n River Brosna.
History	Cited as flour mill on 1838 OS six-inch map. Recorded in 1840s Mill Valuation book as an oat mill worked by Abraham Bagnall. A 13ft 8in x 4ft wheel drove two sets of stones. Noted as formerly having been a flour mill. Recorded in 1854 Griffith Valuation, again under Abraham Bagnall. The corn mill, kilns (there was more than one by this time), and stores were rated at £33.10s.0d. Not cited in 1884 or 1910 OS maps. Operations possibly curtailed by Brosna drainage scheme in mid 1800s.		Irove two sets of The corn mill, at £33.10s.0d. Not	

Component OFIAR-014-035 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 211539 224338 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A Remains No visible remains **Plant** Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of 18th/19th century flour mill and kiln on left bank of River Brosna at so

Site of 18th/19th century flour mill and kiln on left bank of River Brosna at south end of village. No evident traces of buildings, waterworks, plant or machinery.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

Site no		FΙΔΙ	R_01	4-036
Site no	U	ГІАІ	K-U	I 4-USO

County Planning	Offaly Offaly CC	Townland Skehanagh Discovery map 47	Town Six-inch map 14
Summary	Site of 18th/ea	arly 19th century water-powered	d grain mill, kiln and tuck mill on Brosna
History	Cited as corn mill on 1838 OS six-inch map. Recorded as a flour mill under Bernard Gallagher in 1840s Mill Valuation book, with a 14ft x 3ft 8in waterwheel to two sets of stones. The 1840s valuation also notes a tuck mill under George Bayley & Co, powered by a 12ft 8in x 3ft 4in wheel. Operations were possibly curtailed by Brosna drainage scheme in mid 1800s as the mills are not cited in 1854 Valuation or in 1884 and 1910 OS maps.		

Component OFIAR-014-036 1

Type Grain kiln; Grain mill (water); Tuck Function Grain milling; Wool

mill (water)

Category Food processing & products; Context Industry

Textile manufacture & products

Irish Grid 209190 223222 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of 18th/19th century corn mill, kiln and tuck mill on right bank of River Brosna.

No evident traces of buildings, waterworks, plant or machinery. Derelict farm

outbuildings may possibly incorporate fabric of mill-related buildings.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-014-	039		
County Planning	Offaly Offaly CC	Townland Ferba	ane 47	Town Ferbane Six-inch map 14
Summary	Site of 18th ce	ntury brewery.		
History	A brewery is shown on 1804 map of Ferbane. Although adjacent to River Brosna, it may not necessarily have been water powered. Not recorded in valuation books or captioned on 1838 OS map or subsequent editions.			
Component	OFIAR-014-03	9 1		
Typo	Prowery		Eunction	Proving

Туре	Brewery	Function	Brewing
Category	Drink processing & products	Context	Industry

Irish Grid 211561 224431 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of 18th century brewery on right bank of Brosna River at south end of village. The site has been entirely re-landscaped as a garden to a convent. No trace of the

building is now obvious.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Ryan, B. A Land by the River of God: a History of Ferbane Parish from Earliest Times to c.1900 (Ferbane, 1994).

Page(s) 250-251

Site no OFIAR-015-010

County	Offaly	Townland Leal	More	Town
Planning	Offaly CC	Discovery map	48	Six-inch map 15
Summary	Site of mid 19th Brosna.	century water-pow	ered corn and tuck mill or	n tributary of River
History	Not shown on 1838 OS six-inch map. Cited as in 1840s Mill Valuation book as a tuck mill under William Scott. Its waterwheel apparently measured only 6ft x 3ft 6in (the smallest recorded in the county). A mill, possibly the tuck mill, is rated at £5 in the 1854 Griffith Valuation. Cited in the 1885 and 1910 OS six-inch maps as a corn mill, indicating conversion during mid 1800s. A local informant states that closed in 1950s The site was taken over by Bord na Mona in the 1960s, the mill demolished, and the watercourses redirected in order to drain the bog for peat exploitation.		d only 6ft x 3ft 6in (the III, is rated at £5 in the nch maps as a corn mill, ates that closed in 1950s. mill demolished, and the	

Component OFIAR-015-010 1

Type Grain mill (water); Tuck mill (water) Function Grain milling; Wool

Category Food processing & products; Context Industry

Textile manufacture & products

Irish Grid 220741 222006 +/- 10m

Survey date 12/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of 19th century tuck/corn mill on tributary of River Brosna. According to a local

informant, the mill was two- or three storeys high.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 74 of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-016-002	Ballyduff Mill
---------	---------------	----------------

County	Offaly	Townland Ballyduff (Ballycowan By)	Town
Planning	Offaly CC	Discovery map 48	Six-inch map 1

Summary

18th/early 19th century water-powered grain mill and kiln on Silver River. Substantially rebuilt in 1880s following a fire, and also reequipped in 1960s. Animal feedstuff still produced using tractor power.

History

A corn mill is cited at this location on the 1838 OS six-inch map and subsequent editions. A corn mill is cited in the 1840s Mill Valuation book under Denis Molloy. A 10ft x 4ft waterwheel drove one set of stones. A house, office, corn mill and kiln are noted in the 1854 Griffith Valuation under William Huetson; the complex is rated at £13. Following a fire, the mill was substantially rebuilt and re-equipped with three sets of stones in 1884-85. Around 1967, the waterwheel was replaced by a turbine from Manor Mill, Birr (OFIAR-035-009).

A roller mill was subsequently brought in from Erry Mill, Clara (OFIAR-008-038), in the early 1970s to replace one of the three sets of burr stones. Flaked barley is still produced in an adjoining shed using a tractor linked to free-standing roller mill. The present owner, Mr Henry Joughin, is the fourth generator of his family to have operated the mill. He has a collection of mill-related records dating back to the 1800s.

Component OFIAR-016-002 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 231514 227815 +/- 10m

Survey date 09/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused Waterworks Remains Some remains Condition Fair Use Disused Plant Remains Complete Condition Poor Use Disused Machinery Remains Substantial remains Condition Fair Use Disused

Description

A 19th century corn mill on left bank of Silver River on west side of main Tullamore-Clara road. Although in poor condition, the turbine and milling machinery survive.

Buildings

A double-pile/three-storey mill, complete but in poor repair and now disused. Aligned north-south, the building has a pitched natural slate roof; many slates are missing, particularly from the east pile and it is now in poor repair. No rainwater goods. Rendered random rubble walls. Evidence of heightening (by c.1.2m) on north gable of east pile. Square-headed openings. Window openings are without cills and are now devoid of frames.

The south elevation of both piles is abutted by a 20th century one-storey lean-to. Artificial slate roof and concrete walls. The east gable of this lean-to is abutted by a single-storey add-on with hipped corrugated metal roof and concrete walls. This building houses a turnip cutter and diesel engine; the latter is linked to a three-phase generator which provides electrical power to augers in the modern mill. The north gable of the west pile is also abutted by a single-storey/single-bay random rubble shell. A kiln formerly abutted this pile's west elevation but was demolished c.1980 to make way for a large concrete/steel shed housing a tractor-driven modern roller mill. Internally, the milling equipment is housed in the east pile; the west pile was

principally used as a store. The upper floors have boards directly over the main beams (i.e. no joists) but are now in an extremely poor condition. Painted and plastered walls.

Waterworks

The original weir, upstream on the opposite side of the road, has been demolished. The river has been redirected through the head and tailraces.

Plant

A turbine is set in a concrete-lined chamber at the end of the headrace on the north gable of the east pile. Immediately above is a timber sluice gate. A hole has been cut in the floor of the chamber to allow the river to bypass the turbine. The owner has recently also purchased a turbine from a Co Cork mill; it lies dismantled outside the east side of the mill.

Machinery

A crown wheel on top of the turbine's vertical rotor shaft links with a horizontal bevel wheel and lineshaft to transmit the power into the mill. Flat pulleys on this shaft were formerly linked to the three sets of millstones. When the roller mill was installed in the 1970s, these three pulleys were superseded by a single vee-pulley to the roller. There are also flat pulleys to elevators, and to the turnip cutter in an adjoining building.

The first floor contains a shelling stone, grinding stone, and roller mill. The two sets of stones retain their spindles (with flat pulleys), jack rings, axial tentering, and enclosing tunes; there is also a stone nut on the sheller stone spindle.

The top floor contains grain cleaning machinery (cylindrical separators, now disconnected) and meal fans and sieves. This side of the mill also has a single set of elevators.

The west pile has a small roller mill at the north end of the first floor and a sack hoist on the top floor.

Interest Historical; Technical

Evaluation

Despite the poor condition of this mill, it is of technical interest on account of its turbine and milling machinery. It is one of the few surviving mills in Co Offaly to retain its plant and most of its machinery. The juxtaposition of millstones and roller mill is of historical interest in showing the adaptation to changing circumstances in the mid 20th century. The survival of its business records enhances the mill's historical interest. It is of regional industrial heritage significance and merits inclusion in the Record of Protected Structures.

Rating Regional Protection Action RPS

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 74 of Ireland c.1850 (Dublin, 2000).



OFIAR-016-002_02 FWH 09/06/2003 Turbine pit, from east.



OFIAR-016-002_03 FWH 09/06/2003 Crown wheel on top of turbine rotor shaft.



 $OFIAR-016-002_04 \quad FWH \quad 09/06/2003 \qquad General \ view \ of \ ground \ floor \ of \ east \ pile \ of \ mill, \ looking \ north.$





OFIAR-016-002_06 FWH 09/06/2003 Drive to shelling stone.



OFIAR-016-002_07 FWH 09/06/2003 Stone floor on east pile of mill, looking north.



OFIAR-016-002_08 FWH 09/06/2003 Millstones and roller mill on first floor of mill.



OFIAR-016-002_09 FWH 09/06/2003 Roller mill on first floor of mill.



 $OFIAR-016-002_10 \quad FWH \quad 09/06/2003 \qquad Turnip \ cutter \ and \ diesel \ engine \ in \ adjoining \ shed.$



OFIAR-016-002_11 FWH 09/06/2003 Modern tractor-driven roller mill, from south.



 $OFIAR-016-002_12 \quad FWH \quad 09/06/2003 \qquad Modern \ tractor-driven \ roller \ mill \ in \ adjoining \ shed.$



Site no	OFIAR-016-007
---------	---------------

County Planning	Offaly Offaly CC	Townland Raha Discovery map	an Demesne 48	Town Six-inch map 16
Summary			red grain and tuck mills o buse and now an outbuildi	
History	The corn mill is cited as "old corn mill" on 1838 OS six-inch map. It seems to have restarted as the 1840s Mill Valuation book records a corn and tuck mill under Patrick Cahill. The corn mill was driven by an 8ft x 4ft wheel and had two sets of stones. The tuck mill had an 11ft x 2ft 9in wheel and two beetles (fulling stocks?). The mills were rated at only £5.10s.0d in the 1854 Griffith Valuation. The building was converted to a dwelling in the mid 1800s. No mill is cited on the 1884 or 1910 OS maps.			

Component OFIAR-016-007 1

Type Grain mill (water); Tuck mill (water) Function Grain milling; Wool

Category Food processing & products; Context Industry

Textile manufacture & products

Irish Grid 225416 225821 +/- 10m

Survey date 10/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Fair Use Store Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description

A 2½ storey/three-bay corn mill on left bank of Clodiagh River/ north side of minor road. Pitched natural slate roof, two rendered chimneys, raised brick verge to west end, and half-round metal rainwater goods. Partly rendered random rubble walls with advanced brick eaves. Square-headed openings. Window openings have rendered brick jambs and stone cills. 6/6 sash windows to road elevation and smaller fixed windows to rear elevation. West gable is abutted by single-storey extension with pitched corrugated asbestos roof; otherwise detailed as mill. The tuck mill was probably part of the corn mill, but no evident traces survive.

Internally there is no obvious evidence of the building's former use as a mill. According to the owner, it had an internal waterwheel, but there are now no traces of any waterworks.

Interest Setting

Evaluation This mill is of some landscape interest due to its proximity to the road. Its conversion

to a dwelling has diminished its industrial integrity and it is now of local heritage significance only. It is also a Protected Structure in the Co Offaly County

Development Plan 2009-15.

Rating Local Protection Offaly RPS 22-08 Action

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-016-007_01 FWH 10/06/2003 Mill (at right) from south-west. Edward Grennon (owner) in foreground.



OFIAR-016-007_02 FWH 10/06/2003 Mill from north-west.



Site no	OFIAR-016-031

County	Offaly Townland Charleville Demes	ne Town
Planning	Offaly CC Discovery map 48	Six-inch map 16
Summary	Derelict remains of 1850s water-powered saw min Demesne.	Il associated with Charleville
History	Workshops are marked hereabouts on the 1838 document of 1863 notes that a waterwheel had re and frame saws, a lathe, grindstone, threshing mone crusher. The mill was probably built by the saw mill is captioned in the 1884 map. According owner, the saw milling equipment was supersedent.	ecently been installed to drive circular lachine, grain bruiser, chaff cutter and 3rd Earl of Charleville (died 1859). A g to Mr James Hutton-Bury, the site's
Component	t OFIAR-016-031 1	
Туре	Bone mill (water); Saw mill (water); Function Threshing mill (water); Water pump (water)	Bone and fat products; Grain processing; Timber processing & products; Water supply
Category	Animal-based products; Farming production; Timber processing & products; Water supply & related processes	Industry; Agriculture & fishing; Settl
Irish Grid	231287 223323 +/-10m	
Survey date	10/06/2003 Surveyor Fred Har	nond
Building	Remains Traces Condition Pool	r Use Disused
Waterworks	Remains Substantial remains Condition Fair	Use Disused
Plant	Remains No visible remains Condition N/A	Use N/A
Machinery	Remains Some remains Condition Poor	r Use Disused
Description	Fragmentary remains of a mid 19th century saw Charleville Estate. Only the west wall of what ap storey/single-bay building survives. It is aligned a towards its north end. On its external (west) face pit with a curved sluice rack at its intake end. The replaced by a turbine in the 20th century, but the On the wall's internal face is a small belt-driven a turbine). On the floor is a large pit which may man A derelict building adjoins to east. It contains fragand a notice board detailing the operation of a stexisted hereabouts. There is a brick chimney on The water supply originated in the large lake at the first of the main Tullamore road. Towards the mill, the tailrace is likewise culverted. For the culvert carrisee bridge site OFIAR-016-054.	pears to have been a single- north-south, and has been truncated is a 1.30m (4ft 3in) wide waterwheel e waterwheel may have been re is now no trace of either. water pump (probably driven off the ark the site of the saw frame. gments of an electrical switchboard eam boiler which presumably once its east wall. he south end of the demesne, south e open headrace was culverted. The

Interest Historical

Evaluation This building and its associated waterworks are of local historical interest.

Rating Local Protection Action

Associated with OFIAR-016-054

Other dbase

References

Batchen, P. Charleville Estate, Tullamore. Unpublished MS, 1971 (copy in Page(s) 19-20 Offaly Historical Society Archive, Tullamore).

OFIAR-016-031_01 FWH 10/06/2003 Sawmill (middle left) and workshop (right) from south-west.



OFIAR-016-031_02 FWH 10/06/2003 Interior of sawmill, looking north.



OFIAR-016-031_03 FWH 10/06/2003 Waterwheel pit.



OFIAR-016-031_04 FWH 10/06/2003 Pump inside sawmill.



Site no	OFIAR-016-034
OILE IIO	OI IAIN-0 I 0-03 -

County Planning	Offaly Offaly CC	Townland Mucklagh Discovery map 48	Town Six-inch map 16		
Summary	Site of 18th/ea	arly 19th century water-powered co	orn and tuck mills on tributary of		
	Clodiagh River, to south of main road. Traces of tailrace only.				
History	book as belon of stones, and Valuation, onl	Cited as corn and tuck mill on 1838 OS six-inch map. Noted in 1840s Mill Valuation book as belonging to John Molloy and containing an 11ft x 3ft waterwheel to two sets of stones, and a 10ft x 2ft 6in wheel to two beetles (?fulling stocks). By 1854 Griffith Valuation, only the corn mill was working, under Edward Mulloy; rated at £6. Probably stopped in later 1800s. Shown as a partial roofless shell on 1910 OS map.			

Component OFIAR-016-034 1

Type Grain mill (water); Tuck mill (water) Function Grain milling; Wool

Category Food processing & products; Context Industry

Textile manufacture & products

Irish Grid 230746 222516 +/- 10m

Survey date 10/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A

Waterworks Remains Traces Condition Poor Use Disused

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Site of 18th/19th century corn and tuck mills on tributary of Clodiagh River, to south

of main road. A modern house stands on the site. The tailrace is still discernible,

albeit overgrown and dry.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 75 of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-016-040
Site no	UFIAK-U10-U4U

County	Offaly	Townland Killin	а	Town
Planning	Offaly CC	Discovery map	48	Six-inch map 16
Summary	Derelict remains of 18th/early 19th century water-powered corn mill and kiln on tributary of Clodiagh River, just south of Grand Canal. Store converted to dwelling in mid 20th century.			
History			nch map. The corn mill is l liam Boake. A 9ft x 4ft wa	

sets of stones.

The fact that it is not cited in the 1850s Griffith Valuation, and not captioned on subsequent OS maps suggests that it was out of use by the mid 1800s.

Component OFIAR-016-040 1

Grain kiln; Grain mill (water) **Function** Grain milling Type

Food processing & products Context Category Industry

Irish Grid 227965 224834 +/- 10m

Fred Hamond Survey date 10/06/2003 Surveyor

Building Remains Substantial remains Condition Poor Use Disused

Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Use N/A

Machinery Remains No visible remains Condition N/A

Derelict shell of 18th/19th corn mill, kiln and store on tributary of Clodiagh River, on Description south side of Grand Canal. The store was converted to a dwelling in mid 1900s but is

now disused.

The block is of L plan and two storeys high. The single-bay corn mill is aligned eastwest at north, with a kiln return at SE, and a two-bay dwelling behind the kiln. Only the house retains its pitched roof, clad in artificial slate, and with a rendered chimney to centre. Walls of random rubble with square-headed openings, some with brick dressings. Some window openings to the dwelling are later insertions into the original store and have concrete trim and Georgian-style windows. A small massconcrete toilet abuts the house at SW.

A segmental headed brick opening on the west gable of the mill denotes the external waterwheel pit, now infilled along with the head and tail races (the latter was ducted under the canal). On the inside face of this wall is a curved recess signifying a great spurwheel power transmission system. No plant or machinery survives.

Interest None

Evaluation No special industrial heritage significance.

Rating Local **Protection** Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 75 of Ireland c.1850 (Dublin, 2000).

OFIAR-016-040_01 FWH 10/06/2003 General view of mill complex from north-west. Note Grand Canal at left.



OFIAR-016-040_02 FWH 10/06/2003 East elevation, showing dwelling (left) and overgrown kiln (centre) and mill gable (right).



Site no	OFIAR-017-036			Tullamore Distillery
County Planning	Offaly Tullamore U	Townland Tullam	nore 48	Town Tullamore Six-inch map 17
Summary	A two/three-storey block containing boilers, tanks, steam er associated with the former Tullamore Distillery. Founded by it was operated by Bernard Daly from 1857 and then by Da late 1800s. Distilling ceased in 1954, although Tullamore D produced thereafter. Most of the distillery was demolished in			ded by Michael Mulloy in 1829, by Daniel E. Williams from the ore Dew liquor continued to be

History

Established by Michael Mulloy in 1829. Cited as a distillery on the 1838 OS map (and subsequent editions). Sold by the Court of Chancery to his brother Anthony in 1846. Upon his death in 1857, it was inherited by his nephew Bernard Daly. Alfred Barnard noted in 1886 that Daly employed around 100 people and was producing about 270,000 gallons of whisky per year (higher than at Kilbeggan and Birr distilleries). At that time, the premises comprised eight grain stores, four malting houses and kilns, a grist mill with eight pairs of stones, two mash tuns, and four stills with a combined volume of 48,000 gallons. It was powered by three steam engines, one of which was 200hp.

In 1887, Daly's son (also Bernard) took over operations. Daniel Edmond Williams, an employee who had started with the firm in 1862, was promoted to general manager. Under his direction, the distillery was greatly expanded. He was also responsible for the bottling plant on Patrick Street (OFIAR-017-092) and the bonded warehouse on the canal (OFIAR-017-076). Williams also introduced the Tullamore Dew label, the name of which ingeniously carries his initials. In 1903, the distillery was incorporated as B. Daly & Co Ltd, although the Williams family held the majority shareholding. With the death of Daniel in 1921, the premises passed to his son John. The Williams family acquired the distillery outright in 1931.

Although distilling ceased in 1954, there were sufficient stocks of whiskey left to continue operations as the Irish Mist Liqueur Co Ltd. Production of Irish Mist, a whiskey- and honey-based drink, had started in 1948. The Tullamore Dew brand label was sold to Irish Distillers.

Cantrell & Cochrane acquired the Irish Mist label in 1985, and the Tullamore Dew label in 1994. Much of the distillery was demolished in 1995 to make way for the Bridge Shopping Centre.

Component OFIAR-017-036 1

Type	Distillery: Engine house (steam):	Function	D:-4:11:
IVDA	I ligiliary. Engine holise (steam).	Function	nalilitali
1 4 0 0	Distilici V. Eridiric riodsc (stearii).	i uncuon	

Grain mill (steam)

Category Drink processing & products Context Industry

Irish Grid 233695 225040 +/- 10m

Survey date 16/07/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused Waterworks Remains N/A Condition N/A Use N/A
Plant Remains Substantial remains Condition Poor Use Disused Machinery Remains Substantial remains Condition Poor Use Disused

Description A substantial block comprising five contiguous elements on the right bank of the

Tullamore River opposite the Bridge Shopping Centre.

Building 1

This three-storey building is aligned NE-SW along the NW side of the block. It has a hipped artificial slate roof with slates missing in places. Slightly raised ridge ventilator at NE end. Walls of random rubble with brick eaves and dressed stone quoins. Square-headed openings with brick heads and jambs; no cills to window openings. There are seven openings to the street (NW) elevation, including loading doors. All doorways now infilled with concrete blockwork. Two single-storey modern lean-tos abut north elevation.

Internally, this building is divided into two sections. That at NE contains a horizontally-mounted riveted steel boiler. It was fired from an adjoining building, now gone. Also in this section is a vertically-mounted cylindrical tank made up of bolted together castiron segments and with pipes inside (possibly a condenser). The SW section is empty. All floors are in poor condition.

Building 2

This L-shaped, three-storey building is aligned NE-SW and partly abuts the SE side of building 1. It has a hipped natural slate roof, now partly collapsed. Walls are of random rubble with ashlar eaves and dressed stone quoins. Square-headed openings with stone heads and brick jambs; stone cills to window openings.

Internally divided into two sections. The main section, at NE, contains the grist mill (detailed below under machinery). All the floors in this section are timber boards laid directly over steel joists.

The SW section of this building is aligned at right angles. The flooring is of timber throughout. Its ground floor contains a steam engine (detailed below under plant) which formerly drove the grain mill in the adjoining section. The first and second floors of this section are empty and have partly collapsed. The roof comprises internally plastered common rafters over single purlins on king-post trusses.

Building 3

This two-storey building is aligned NE-SW and abuts the SE side of building 1 and NE gable of building 2. Its roof is now missing. Its walls and openings are detailed as building 2. Miscellaneous metal shafts and gears are scattered about the ground floor internally. The first floor comprises timber boards over steel joists but has largely collapsed.

Building 4

This three-storey building is aligned NW-SE and partly abuts building 1 and the NE gable of building 3. It has a hipped natural slate roof. The walls are of random rubble, with brick and stone eaves and dressed stone quoins. A wall break indicates two phases of construction. The NW section is contemporary with building 1, and the SE portion is a later addition. Square-headed openings with brick heads and jambs. The base of a truncated brick chimney rises from the eaves on the NE elevation. Internally the floors comprise timber boards on steel joists, but all are now in poor condition. The ground floor contains a Lancashire boiler, fired from a now-demolished building which formerly abutted its SW side. The first floor contains the basal remains of two large cylindrical wooden tanks (possibly wash backs), around which the second floor was built.

Chimney

Just beyond the SE gable of the engine room in building 2 is the base of a dressed stone chimney. It is of square cross-section and survives to the height of the adjoining block. The brickwork above has been demolished (shown on old photographs). It formed part of a building which is long demolished.

There was formerly an extensive range of grain stores to the SW and SE of this block, no traces of which survive.

Plant

The SW section of building 2 contains the steam engine which powered the grain mill in the adjoining room. It is a horizontal side-by-side duplex engine with two horizontal pistons, each c.46cm in diameter by 107cm stroke (18in x 42in). Its slide valves, pendulum governor and 14ft diameter flywheel also survive but the steam pipes have

d d

Machinery

Building 2 contains a mill for grinding the malted barley. The ground floor contains the power transmission gearing from the adjoining engine room - pit wheel, wallower, great spurwheel and three stone nuts, all mounted on a cast-iron frame. Also on this floor are two sets of elevators and an electric motor which drives three sets of vertical triple-throw pumps (of which only one set is complete) through various bevel gears and line shafts. There is a cast-iron water tank set into the floor (probably associated with the steam engine).

The first floor contains two in-situ sets of millstones, complete with feed chutes from the top floor, circular timber tuns, metal horses, shoes, damsels and stone crane. The third set of stones and its associated furniture have been dismantled. Two French burr stones lie against the wall; both are 1.52m (5ft) in diameter and have left-hand dresses. A third burr stone has collapsed through the floor and now lies on the ground below. The bevelled crown wheel at the top of the upright shaft on this floor formerly drove the equipment on the floor above.

The second floor contains a hammer mill and sack hoist. The elevators also discharge on this floor.

Interest Architectural; Historical; Technical; Setting

Evaluation

This site is of architectural interest in terms of its scale and composition and is an important feature of the streetscape. It is also of historical interest due to its association with the Tullamore Distillery. The survival of the largely intact steam engine and grain mill is of particular technical note. The block is of regional industrial heritage significance and is a Protected Structure in the Draft Tullamore Development Plan 2010-16.

Rating Regional Protection Tullamore RPS 23-281 Action None (in RPS)

Associated with OFIAR-017-064; -065; -076; -090; -091; -092

Other dbase NIAH 14807086 (R)

Quay, Tullamore, Spring 1999.

References

References		
Barnard, A. The Whisky Distilleries of the United Kingdom. London: Ha Weekly Gazette, 1887. (Reprinted by David & Charles, Newton Abbot,		387-389
Byrne, M. Distilling in Tullamore. In Offaly Independent, 17 Jan 1992.	Page(s)	
Byrne, M. The People of Tullamore in the Twentieth Century (Tullamor Esker Press, 2000).	re: Page(s)	125
Byrne, M. Tullamore Town Album (Tullamore, 1988).	Page(s)	Plate 112
Byrne, M. Tullamore Town Album (Tullamore, 1988).	Page(s)	Plate 113
Byrne, M. Tullamore Town Album (Tullamore, 1988).	Page(s)	Plate 114
Byrne, M. 'Tullamore: the growth process, 1785-1841'. In Nolan W. an O'Neill, T.P. (eds), Offaly: History and Society (Dublin: Geography Publications, 1998).	d Page(s)	591
Cunnane Stratton Reynolds. Waterways Corridor Study 2002 (Kilkenny Heritage Council, 2002).	r: Page(s)	Appendix 3
Irish Architectural Archive, Merion Sq., Dublin.	Page(s)	S-570-7
Magee, M. 1000 Years of Irish Whiskey (Dublin: O'Brien Press, 1980).	Page(s)	129-130
Maguire, E.B. Irish Whiskey: a History of Distilling in Ireland (Dublin: G Macmillan, 1973).	ill and Page(s)	366-368
Offaly Historical Society. Offaly in the Pre-Famine Era: an Exhibition a	t Bury Page(s)	Note 58

Tullamore Dew Heritage Centre. Tullamore: a Short Introduction and Trails Page(s) 15-18 of the Town (Tullamore: Tullamore Dew Heritage Centre, 2000).

Tullamore Junior Chamber. Know your Tullamore (Tullamore: Tullamore Junior Chamber, 1994).

Page(s) 99

OFIAR-017-036_01 FWH 16/07/2003 General view from north. Building 1 in foreground and building 4 at left.



OFIAR-017-036_02 FWH 16/07/2003 General view from south-east. Building 4 in foreground.



OFIAR-017-036_03 FWH 16/07/2003 General view from south. Chimney and building 2 at left.



OFIAR-017-036_04 FWH 16/07/2003 General view from north-west. Building 1 at left and building 2 at right.



OFIAR-017-036_05 FWH 16/07/2003 Building 1: boiler in NW section.



OFIAR-017-036_06 FWH 16/07/2003 Building 1: tank in NW section.



 $OFIAR-017-036_07 \quad FWH \quad 16/07/2003 \quad \quad Building \ 2: internal \ view \ of \ ground \ floor \ of \ NE \ section, \ looking \ SW.$



OFIAR-017-036_08 FWH 16/07/2003 Building 2: power transmission gearing at SW end of ground floor.



OFIAR-017-036_09 FWH 16/07/2003 Building 2: triple-throw pump on ground floor.



OFIAR-017-036_10 FWH 16/07/2003 Building 2: millstones on first floor.



 $OFIAR-017-036_11 \quad FWH \quad 16/07/2003 \qquad \text{Building 2: hammer mill on second floor}.$



OFIAR-017-036_12 FWH 16/07/2003 Building 2: steam engine in SW section of building.



 $OFIAR-017-036_13 \quad FWH \quad 16/07/2003 \qquad \text{Building 2: steam engine detail showing valve box and cylinders.}$



 $OFIAR-017-036_14 \quad FWH \quad 16/07/2003 \qquad \text{Building 3: internal view of ground floor, looking SW to building 2.}$



OFIAR-017-036_15 FWH 16/07/2003 Building 4: exposed end of boiler on SW elevation.



OFIAR-017-036_16 FWH 16/07/2003 Building 4: remains of tanks tuns on first floor



Site no	OFIAR-017-037
SILE IIU	OFIAN-017-037

County	Offaly	Townland Tulla	more	Town	Tullamore
Planning	Tullamore UDC	Discovery map	48	Six-inc	h map 17
Summary	Site of late 19th/early 20th century saw mill in what is now car park to Bridge Shopping Centre. Probably not water powered.				
History	Cited as saw mill on 1910 OS map only.				

Component OFIAR-017-037 1

Type Saw mill Function Timber processing & products

Category Timber processing & products Context Industry

Irish Grid 233682 224959 +/- 10m

Survey date 16/07/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Site of late 19th/early 20th century saw mill in what is now car park to Bridge

Shopping Centre. Probably not water powered despite proximity to mill race

supplying nearby grain mill (OFIAR-017-042).

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Site no OFIAR-017-038

County	Offaly	Townland Tullamore	Town Tullamore
Planning	Tullamore UDC	Discovery map 48	Six-inch map 17

Summary

18th/early 19th century four-storey grain mill on Tullamore River, now converted into apartments. Paddle wheel and waterworks survive.

History

Said to date from the 1780s, this site is captioned as a corn mill on the 1838, 1884 and 1910 OS six-inch maps. The 1840s Mill Valuation book notes two corn mills under Thomas Ryan. One had at 14ft x 3ft 6in waterwheel powering two sets of stones, and the other a 10ft x 3ft 6in wheel, also to two sets of stones. One of these entries undoubtedly refers to this mill, and the other to an adjoining grain mill (OFIAR-017-042). The present waterwheel is much bigger than either of the above two wheels, indicating that it is a mid/late 19th century replacement. Owned by Thomas Roberts in 1854 (Griffith Valuation). A Lawrence photograph of c.1910 shows a tall brick chimney at the east end of the river façade, indicating that steam power was probably also in use.

Component OFIAR-017-038 1

Type Grain mill (steam; water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 233579 224890 +/- 10m

Survey date 16/07/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Good Use Dwelling Waterworks Remains Substantial remains Condition Poor Use Disused Plant Remains Substantial remains Condition Good Use Disused Machinery Remains Traces Condition Good Use Disused

Description

A water-powered corn mill on left bank of Tullamore River, just outside north corner of Town Park, now converted into residential apartments.

Buildings

A four-storey building comprising two parallel but offset piles aligned east-west, with returns to north and east on the north block. The irregularity of its plan suggests that it may have been built in several stages. Pitched artificial slate roofs, timber bargeboards, and aluminium rainwater goods on eaves boards. Walls of random rubble masonry, in part newly built, with dressed stone quoins. Square headed openings (some recent insertions), with yellow brick heads and jambs. Window openings have timber casements and concrete cills. Galvanised metal balconies have been added to some openings.

Waterworks

Immediately upstream of the mill is a weir set diagonally across the river. It has a sloping dressed stone face with a concrete fish pass running across it. There is also a vertical sluice gate emplacement at its east end which enabled the river to by-pass the weir. The top of the weir is now missing and its face is overgrown, the river now flowing through the derelict sluice emplacement. Just upstream of the weir is a twin-arch masonry footbridge (OFIAR-017-089).

The short tailrace is carried under the west end of the south pile of the mill and emerges through a segmental headed arch back into the river.

Plant

The waterwheel sits externally at the NW corner of the building. It is of the low breastshot paddlewheel variety and measures 4.57m (15ft) in diameter. The axle, hubs, arms and 48 angled starts survive; all are of metal and were cleaned and painted when the building was converted to apartments. Although the floats are missing, the starts indicate that they were 60cm deep (2ft). The wheelpit is 2.74m (9ft) wide - this would have been about the width of the paddles. Immediately behind the wheel is a curved cast-iron apron and remains of an inclined timber sluice gate.

Machinery

A bevelled cast-iron gear is affixed to the outer end of the waterwheel axle (i.e. on the side away from the mill). It is uncertain what this drove. At the time of survey, there was no access to the interior of the converted mill, so it is uncertain whether any internal machinery survives.

Interest Architectural; Historical; Technical; Setting

Evaluation Renovation has retained the building's original architectural form despite modern

detailing. It is also of historical interest. The waterworks are clearly visible and survive largely intact; along with the waterwheel, they are of technical interest. The mill also adds interest to the riverscape hereabouts and is the only surviving waterpowered corn mill in Tullamore. It is of regional industrial heritage significance and is

a Protected Structure in the Draft Tullamore Development Plan 2010-16.

Rating Regional Protection Tullamore RPS 23-390 Action None (in RPS)

Associated with OFIAR-017-042

Other dbase

References

Byrne, M. Tullamore Town Album (Tullamore, 1988). Page(s) Plate 21

Offaly Historical Society. Offaly in the Pre-Famine Era: an Exhibition at Bury Page(s) Note 3 Quay, Tullamore, Spring 1999.

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-017-038_01 FWH 16/07/2003 General view from north.



OFIAR-017-038_02 FWH 16/07/2003 General view from east.



OFIAR-017-038_03 FWH 16/07/2003 South elevation, from south-east.



OFIAR-017-038_04 FWH 16/07/2003 South elevation, from south-west.



 $OFIAR-017-038_05 \quad FWH \quad 16/07/2003 \qquad Overgrown \ weir, \ from \ south-west.$



OFIAR-017-038_06 FWH 16/07/2003 Wheel and intake sluice, from upstream.



OFIAR-017-038_07 FWH 16/07/2003 Waterwheel.



OFIAR-017-038_08 FWH 16/07/2003 Curved metal apron at back of waterwheel.



Site no	OFIAR-017-039		Lumley's Warehouse; {Tarleton's Maltings}						
County	Offaly	Townland	Tulla	ımore			Town	Tullamore	
Planning	Tullamore UDC	Discovery	map	48			Six-inc	h map 17	
Summary	Four-storey/nine-bay 19th century malt house with early 20th century grain store at south and mid 20th century malt house to west; all on west side of Tanyard Lane and formerly belonging to Messrs Tarleton.								
History	Uncaptioned buildings matching the footprints of most of the existing buildings are shown on the 1838 and 1884 OS six-inch maps. First explicitly cited as a malt house on the 1910 OS map. Only one building has an attested date - erected in 1901 by Messrs Tarleton. Subsequently owned by Messrs Lumley.								

Component OFIAR-017-039 1

Type Malt house Function Malting

Category Drink processing & products Context Industry

Irish Grid 233985 224891 +/- 10m

Survey date 31/07/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Good Use Retail outlet

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description

Substantial remains of five 20th century maltings, now in retail use, on west side of Tanyard Lane. The complex comprises six interconnect buildings used for malting and grain storage.

Malt house 1

A four-storey/nine-bay 19th century building aligned north-south along the street; at its south end is a two-storey/two-bay section which has been raised in concrete blockwork to the same height as the main section and shares the same roof. Shallow pitched profiled metal roof, troughed metal rainwater goods and boarded eaves. Walls of squared rubble limestone brought to courses and with rock-faced quoins to north gable. Shallow segmental openings with brick heads and jambs, but no cills. Two-pane fixed windows have replaced the original shutters. Ground floor windows have been infilled and those to the top floor are of diminished height. "J.A. Lumley & Son Ltd" is painted on the street elevation between the ground and first floors. There is a row of cast-iron tie plates at second floor and eaves levels. The two storey section at south is contemporary with the main block. It has been raised in concrete blockwork to the same eaves line as the latter, allowing the whole to be re-roofed as one. There are two windows, detailed as the main block, to its middle floor.

At the time of writing, the building was being refurbished for commercial use. Internally, the first and third floors have been removed, such that only the ground and second floors are useable. The latter rests on riveted steel beams and intermediate uprights. The roof is supported on steel truss frames and is undoubtedly a later replacement.

Grain store 1

Aligned east-west at the south end of malt house 1 is a two-storey (+ attic)/five-bay

store, now refurbished for commercial use. Pitched natural slate roof with dormer eaves gable to south elevation. No rainwater goods. Random rubble walls with rockfaced quoins. Windows to ground and attic floors only, detailed as malt house 1 but infilled to ground floor. This building is internally accessible from malt house 1.

Office

Derelict roofless shell of a two-storey/three-bay building aligned north-south at the SW corner of grain store 1. Walls and openings (all infilled) detailed as malt house 1. Semi-elliptical arched entrance to east elevation. Internal floor removed.

Grain store 2

Abutting SE corner of the above office is a two-storey/five bay former grain store of 1901. It is aligned east-west and now partly in retail commercial use. Hipped natural slate roof with half-round metal rainwater goods. Random rubble walls with dressed quoins and brick eaves; walls to north elevation are of squared rubble. Metal ties at first floor and eaves levels. Square-headed openings with brick heads and jambs. Ground floor openings now infilled; timber shutters to first floor. Dressed stone plaque on first floor of east gable reads "J & A Tarleton/ AD 1901". The south elevation was formerly abutted by a lean-to, now demolished.

Inside, the original first floor was replaced in 1972. No original features survive to the ground floor. The walls and ceilings of the first floor retain their timber sheeting (for insulation).

Malt house 2

Abutting the NW corner of grain store 1 is a four-storey/ multi-bay malt house of mid 20th century date, now in use as a furniture warehouse. Pitched corrugated metal roof. Walls comprise a reinforced-concrete frame with mass concrete infill panels. Square-headed openings with two-pane fixed timber windows; those to top floor of diminished height. No openings to south elevation. Abutted to north by a five-storey section with corrugated metal monopitched roof; walls partly clad in profiled metal. The space between this building and grain store 1 has a steel framed corrugated metal canopy over.

Interest Architectural; Historical; Setting

Evaluation

Architecturally, the complex is of interest because of its scale and range of contrasting materials (stone, brick, concrete). It is of historical interest because of its associations with the brewing and distilling industries in Tullamore and also exhibits an evolutionary sequence. The complex adds interest to the streetscape hereabouts. Overall, it is of regional significance and is a Protected Structure in the Draft Tullamore Development Plan 2010-16.

Rating Regional Protection Tullamore RPS 23-398 Action None (in RPS)

Associated with OFIAR-017-053

Other dbase

References

Garner, W. Tullamore Architectural Heritage (Dublin: An Foras Forbartha, Page(s) 20 1980).



OFIAR-017-039_02 FWH 31/07/2003 General view of site from north.



OFIAR-017-039_03 FWH 31/07/2003 Malt house 1 from north-east.



OFIAR-017-039_04 FWH 31/07/2003 Detail of east elevation of malt house 1.





OFIAR-017-039_06 FWH 31/07/2003 Grain store 1 (left) and malt house 1(right), from south-east.



OFIAR-017-039_07 FWH 31/07/2003 Grain store 2, from north-east.



 $OFIAR-017-039_08 \quad FWH \quad 31/07/2003 \qquad Datestone \ on \ east \ gable \ of \ grain \ store \ 2.$



OFIAR-017-039_09 FWH 31/07/2003 Grain store 2: interior of first floor.



OFIAR-017-039_10 FWH 31/07/2003 Grain store 2: shutter detail on first floor.



OFIAR-017-039_11 FWH 31/07/2003 Malt house 2 from north-west.



OFIAR-017-039_12 FWH 31/07/2003 General view of site from south-west. Malt house 2 at left.



Site no	OFIAR-017-042

County Planning	Offaly Tullamore UDC		Tullar n ap	more 48		Town Six-inc	Tullamore h map 17
Summary	Site of 18th/early River, west of H		wate	r-powered fl	our mill on let	ft bank of	f Tullamore
History	map. The 1840s had at 14ft x 3ft 6in wheel, also t	Mill Valuation 6in waterwher o two sets of ser to an adjoin	n book el pov stones ing m	notes two overing two seconds. One of the	corn mills und ets of stones, ese entries un 17-038). Own	er Thomand the doubtedled by The	other a 10ft x 3ft y refers to this nomas Roberts in

Component OFIAR-017-042 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 233626 224868 +/- 10m

Survey date 16/07/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Use N/A Condition N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of flour mill on left bank of Tullamore River, west of High St. Supplied by

headrace off Tullamore River. Site now redeveloped as car park for new apartments.

Interest None

Evaluation Of no industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-017-038

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

|--|

County	Offaly	Townland Meelaghans	Town
DI	04-100	D '	O'm to all man 4

Six-inch map 17 **Planning** Offaly CC Discovery map 48

Summary Site of 18th/early 19th century water-powered corn mill on Toberfin River.

History Cited as corn mill on 1838 OS six-inch map. The corn mill is noted in 1840s Mill

> Valuation book as being operated by Owen Owens. A 12ft x 3ft 6in waterwheel drove two sets of stones. Valuation notes that had not worked for seven years. Not cited in subsequent records although the building continues to be shown on the 1884 and

1910 OS maps.

Component OFIAR-017-047 1

Type Grain mill (water) **Function** Grain milling

Category Food processing & products Context Industry

Irish Grid 239840 222532 +/- 10m

Fred Hamond Survey date 17/07/2003 Surveyor

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill on left bank of Toberfin River, a short distance north of main road.

> This watercourse is now much lower than the surrounding land, suggesting that the mill may have been affected by the Brosna drainage scheme in the mid 1800s.

Interest None

Evaluation No industrial heritage signficance.

Action Record only **Protection** Rating

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 73 of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-017-	049	Egans' Malt House
County	Offaly	Townland Tullamore	Town Tullamore
Planning	Tullamore UD	C Discovery map 48	Six-inch map 17
Summary	(belonging to F	22 distillery and mid-19th century map 2 & H Egan) incorporated into moder t. Site also formerly contained a stea	n residential and commercial
History	concern; its ou six-inch map. 1841. The prei 1840s, indicati According to a	lished in 1822 by Henry and Charles tput for 1832 was 30,000 gallons. It i John Locke of the Kilbeggan Distiller mises served as a temporary workhong that distilling had ceased by then painted sign at the NE corner of the 1852. The probably utilized and enl	s explicitly cited on the 1838 OS y leased the site from 1839 to use during the Famine in the premises, P. and H. Egan began

Component OFIAR-017-049 1

Type Bonded warehouse; Distillery Function Distilling; Malting; Timber

(steam); Malt house; Malt kiln; processing & products

buildings. Although buildings are shown on the 1884 map, none is explicitly cited. The 1890 large-scale OS town map records a steam saw mill and bonded warehouses. The 1910 OS 25-inch map cites a malt house only. Recently renovated and partly

Saw mill (steam)

Category Drink processing & products; Context Industry

Timber processing & products

rebuilt as shops and apartments.

Irish Grid 234165 225095 +/- 10m

Survey date 31/07/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Excellent Use Dwelling/Retail outlet

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

Description The complex comprises an extensive range of multi-storey buildings arranged around

a central courtyard at the far end of Market Square.

East block

This block fronts O'Carroll Street and comprises two distinct units. At north is a three-storey/two-bay former kiln. Pitched artificial slate roof with skylights and mock pyramid ventilator to middle of ridge (the original vent was of rectangular plan with a pitched roof). Plastic rainwater goods. The ground and first floors are of random rubble (repointed in cement), with dressed quoins to the north gable. The top floor is of brick and appears to be of two phases judging by the contrasting colour to the brickwork on each bay. Originally there were square headed openings to the ground and first floors. These have been replaced with new openings - two wide segmental headed shop fronts to the ground floor and two pairs of windows to each of the upper floors. The window openings have with cement rendered architraves and uPVC windows. There are pseudo eaves gablets over the windows (not present originally). A large painted sign on the north gable reads "P & H Egan Ltd/ Malsters/ 1852". The rear extension (to west) has modern one-storey rendered extensions.

A two-storey/four bay building abuts the south gable of the malt kiln. Some, if not all, has been rebuilt during the site's recent redevelopment. The roof, rainwater goods and walls are detailed as above. There was formerly a tall elevator projecting from the roof. New door and window openings have been inserted, also detailed as the kiln. There is also a modern one-storey extension to rear.

South-east block

This block is bounded by O'Carroll St to east and Market St to south. It is of L plan, two storeys high and seven bays wide to each street elevation. Much, if not all, of it has been rebuilt. Hipped artificial slate roof, rendered chimneys and plastic rainwater goods; boarded advanced eaves to south elevation. Walls are cement-pointed random rubble to east elevation and cement-rendered to south; rear elevation is pebble dashed. New square-headed window insertions, with rendered architraves and uPVC windows.

West block

This block is bounded by Gashouse Lane to west and Market St to south. Also of L plan, it is three storeys high and 11 bays wide to west/ five bays wide to south. Roof and chimneys detailed as SE block. Ogee rainwater goods. Walls are painted lined cement render throughout. Openings as SE block, with thin concrete cills. In the middle of the west elevation is a reconstructed semi-elliptical archway. It is of ashlar limestone with radial voussoirs, string course at arch spring level, moulded cornice and pair of modern steel gates. The section south of this arch has an elongated blank name panel between its upper floors.

North block

This block fronts Harbour Street. It is three storeys high to east and centre, and twostoreys high at west. Pitched artificial roof with skylights. Central section is higher than flanking units and formerly had three distinctive pyramidal vented roofs (indicating malt kilns). Random rubble walls and brick eaves, and dressed quoins to NW corner. Rear elevation is finished with cement harling. Modern square-headed window openings inserted throughout. Top floor windows to east section have brick heads and jambs. Tie bar plates present on north and east elevations.

Courtyard block

Running south from the east end of the north block is a three-storey/17-bay modern apartment block. Its footprint appears to follow that of an earlier building. Detailed as the west block.

Interest Historical; Setting

Evaluation

This site's architectural and historical merits have been diminished by the rebuilding of many of the original buildings. It is particularly unfortunate that the three pyramidal roofs on the north block were removed during the site's redevelopment. Even the semi-elliptical archway has been relocated from its original position. Nevertheless, the scale of the original exposed rubble facades to east and north and modern rendered facades to south and west are of streetscape interest and clearly reflect the site's industrial past.

Although the NIAH rates the site as being of regional industrial heritage significance, so much original detailing has been lost that it is rated here of local significance only. The north block and arch along the west side are Protected Structures in the Draft Tullamore Development Plan 2010-16.

Rating Local Protection Tullamore RPS 23- Action

263; Tullamore RPS 23-275

Associated with

Other dbase NIAH 14807067 (R); NIAH 14807079 (R)

References

Byrne, M. Distilling in Tullamore. In Offaly Independent, 17 Jan 1992. Page(s)

Garner, W. Tullamore Architectural Heritage (Dublin: An Foras Forbartha, Page(s) 48, 51

Irish Architectural Archive, Merion Sq., Dublin. Page(s) S-564-3, S-564-4

Page(s) 23

Irish Architectural Archive, Merion Sq., Dublin. Page(s) S-564-6

Tullamore Dew Heritage Centre. Tullamore: a Short Introduction and Trails of the Town (Tullamore: Tullamore Dew Heritage Centre, 2000).

OFIAR-017-049_01 FWH 31/07/2003 General view from north-east.



OFIAR-017-049_02 FWH 31/07/2003 General view from south-east.



OFIAR-017-049_03 FWH 31/07/2003 General view from south-west.



OFIAR-017-049_04 FWH 31/07/2003 General view from north-west.



OFIAR-017-049_05 FWH 31/07/2003 North end of east elevation, from north-east.



 $OFIAR-017-049_06 \quad FWH \quad 31/07/2003 \qquad North \ end \ of \ east \ elevation, from \ east.$



 $OFIAR-017-049_07 \quad FWH \quad 31/07/2003 \qquad \text{Archway in middle of west elevation, from west.}$



OFIAR-017-049_08 FWH 31/07/2003 View of courtyard, looking north.



Site no	OFIAR-017-050 Manley's Brewery
County	Offaly Townland Tullamore Town Tullamore
Planning	Tullamore UDC Discovery map 48 Six-inch map 17
Summary	Site of 18th/early 19th century brewery and late 19th century malt house at NW end of Tanyard Lane.
History	Marked as brewery on 1838 OS six-inch map. Recorded in 1854 Griffith Valuation as belonging to Henry Manley. House, offices and brewery rated at £50. Cited as brewery on 1885 OS map, but as malt house on 1890 large-scale town map. Shown but uncaptioned on 1910 map.
Component	OFIAR-017-050 1
Туре	Brewery; Malt house Function Brewing; Malting
Category	Drink processing & products Context Industry
Irish Grid	233993 224950 +/- 10m
Survey date	16/07/2003 Surveyor Fred Hamond
Building	Remains No visible remains Condition N/A Use N/A
Waterworks	Remains N/A Condition N/A Use N/A
Plant	Remains No visible remains Condition N/A Use N/A
Machinery	Remains No visible remains Condition N/A Use N/A
Description	Site redeveloped as Offaly County Council offices and library headquarters.
Interest	None
Evaluation	No industrial heritage significance.
Rating	Record only Protection Action
Associated v	with OFIAR-017-078

References

Other dbase

Site no OFIAR-017-051 County Offaly Townland Tullamore

Planning Tullamore UDC Discovery map 48 Six-inch map 17

Summary Site of late 19th century steam-powered saw mills where extension to Bridge Hotel

now stands.

History Explicitly cited as steam saw mills on 1890 large-scale OS town map and as saw mills

on 1910 OS 25-inch map. Uncertain whether purpose built, or set up in an existing

Town

Tullamore

building. May have been owned by Goodbodys.

Component OFIAR-017-051 1

Type Saw mill (steam) Function Timber processing & products

Category Timber processing & products Context Industry

Irish Grid 233817 225052 +/- 10m

Survey date 16/07/2003 Surveyor Fred Hamond

Remains No visible remains

Building Remains No visible remains Condition N/A Use N/A

Waterworks Remains N/A Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Site of saw mill on left bank of Tullamore River just downstream from road bridge,

Condition N/A

Use N/A

now occupied by recent extension to Bridge Hotel.

Interest None

Plant

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Byrne, M. Tullamore Town Album (Tullamore, 1988).

Page(s) Plate 106

Site no	OFIAR-017-052	
County	Offaly Townland Tullamore Town Tullamore	ore
Planning	Tullamore UDC Discovery map 48 Six-inch map	17
Summary	Site of 18th/early 19th century brewery in what is now car park to Bridge Shopp Centre, west of High St.	ping
History	Cited as brewery on 1838 OS six-inch map. Spans mill race, so may have bee powered. Not recorded in 1850s Griffith Valuation books, nor are any buildings depicted on subsequent OS maps.	
Component	OFIAR-017-052 1	
Туре	Brewery (water) Function Brewing	
Category	Drink processing & products Context Industry	
Irish Grid	233776 224904 +/- 10m	
Survey date	16/07/2003 Surveyor Fred Hamond	
Building	Remains No visible remains Condition N/A Use N/A	

Condition N/A

Condition N/A

Condition N/A

Use N/A Use N/A

Use N/A

Description Site of brewery in what is now car park to Bridge Shopping Centre.

None

Waterworks

Machinery

Interest

Plant

Evaluation No industrial heritage significance.

Remains No visible remains

Remains No visible remains

Remains No visible remains

Rating Record only Protection Action

Associated with

Other dbase

References

Site no	OFIAR-017-0	53			Tarleton's Malt Store
County	Offaly	Townland 1	Tullamore		Town Tullamore
Planning	Tullamore UDC	Discovery m	ap 48		Six-inch map 17
Summary					side of Tanyard Lane, towards west ssrs Tarleton as malt house in late
History	Cited as brewery on 1838 OS six-inch map. Recorded in 1854 Griffith Valuation as Old brewery, offices and yard, all rated at £17 and belonging to Patrick Aylward. Marked as malt houses on 1890 large-scale town map. Then belonged to Tarletons (subsequently Egan & Tarleton Ltd). Buildings demolished 1990s.				
Component	OFIAR-017-053	1			
Туре	Brewery; Malt ho	ouse	Fun	ction	Brewing; Malting
Category	Drink processing	g & products	Con	text	Industry
Irish Grid	234024 224878	+/- 10m			
Survey date	16/07/2003	Survey	or Fre	d Han	nond
Building	Remains No vi	sible remains	Condition	N/A	Use N/A
Waterworks	Remains N/A		Condition	N/A	Use N/A
Plant	Remains No vi	sible remains	Condition	N/A	Use N/A
Machinery	Remains No vi	sible remains	Condition	N/A	Use N/A
Description	Site of brewery and later malt house on north side of Tanyard Lane, towards west end. Demolished and redeveloped as Tarleton Hall apartments and car park.				
Interest	None				
Evaluation	No industrial her	ritane significar	nce		

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-017-039

Other dbase

References

Byrne, M. The People of Tullamore in the Twentieth Century (Tullamore: Page(s) 40 Esker Press, 2000).

C:40 mg	OFIAD 047 0F4
Site no	OFIAR-017-054

County Planning	Offaly Tullamore UDC	Townland T		ore 48	Town Six-inc	Tullamore h map 17
Summary	Site of late 18th, redeveloped for	•	tury tar	nnery and later 19th ce	ntury mal	t house, now
History	A tannery is cited here on the 1838 OS six-inch map. Uncaptioned buildings are marked on the 1884 map - probably the malt house explicitly captioned on the 1890 large-scale town map. An uncaptioned building is on the 1910 OS map.					

Component OFIAR-017-054 1

Type Tannery Function Leather products

Category Animal-based products Context Industry

Irish Grid 234034 224817 +/- 10m

Survey date 16/07/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains N/A Condition N/A Use N/A **Plant** Condition N/A Use N/A Remains No visible remains Remains No visible remains Condition N/A Use N/A Machinery

Description Nothing of this tannery survives.

Component OFIAR-017-054 2

Type Malt house Function Malting

Category Drink processing & products Context Industry

Irish Grid 234023 224834 +/- 10m

Survey date Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A Use N/A Condition N/A **Plant** Remains N/A Use N/A Condition N/A Use N/A Machinery Remains N/A

Site redeveloped for housing. The architecture of the corner block (its pyramidal roof being in the style of a malt kiln) is a reminder of the site's former function (but

possibly not its original form).

Interest None

Description

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

OFIAR-017-054_01 FWH 16/07/2003 General view of redeveloped site, from north-east.



Site no	OFIAR-017-058
County Planning	Offaly Townland Tullamore Town Tullamore Tullamore UDC Discovery map 48 Six-inch map 17
Summary	Site of late 19th/early 20th century mill on north side of Tullamore Harbour. Apparently cut up gorse for feeding to horses (probably those hauling barges on the Grand Canal).
History	Marked as Chop mill on 1910 large-scale town map. Said to have chopped up gorse for feeding to horses. No building shown at this location on OS maps prior to 1910.
Component	OFIAR-017-058 1
Туре	Chop mill Function Inland waterway
Category	Transport Context Infrastructure
Irish Grid	234176 225244 +/-10m
Survey date	16/07/2003 Surveyor Fred Hamond
Building	Remains No visible remains Condition N/A Use N/A
Waterworks	Remains N/A Condition N/A Use N/A
Plant	Remains No visible remains Condition N/A Use N/A
Machinery	Remains No visible remains Condition N/A Use N/A
Description	Site of gorse-processing mill now occupied by later 20th century industrial units.
Interest	None
Evaluation	No industrial heritage significance.
Rating	Record only Protection Action
Associated v	with OFIAR-017-012?

References

Other dbase

Site no	OFIAR-017-062		
County Planning	Offaly Townland Tulla Tullamore UDC Discovery map	more 48	Town Tullamore Six-inch map 17
Summary	Mid 20th century four-storey distille outlet.	ery-related grain st	ore. Refurbished as Texas retail
History	Not on 1910 OS map or previous e	ditions.	
Component	OFIAR-017-062 1		
Туре	Grain store	Function Di	stilling
Category	Drink processing & products	Context Inc	dustry
Irish Grid	233880 225290 +/-10m		
Survey date	Surveyor	Fred Hamon	d
Building	Remains Complete Co	ondition Good	Use Store
Waterworks	Remains N/A Co	ondition N/A	Use N/A
Plant	Remains N/A Co	ondition N/A	Use N/A
Machinery	Remains N/A Co	ondition N/A	Use N/A
Description	Not surveyed in detail.		
Interest			
Evaluation	Not evaluated.		

Rating Protection Action

Associated with

Other dbase

References

Photograph in Local Studies section of Offaly County Library, Tullamore (copyright Offaly Historical Society).

Page(s) Acc no. 801; inv. no. D

Site no OFIAR-017-064

County Planning	Offaly Tullamore UDC	Townland Discovery r		more 48		Town Six-inc	Tullamore h map 17
Summary	Substantial dere associated with west of Bridge S	Tullamore Dis			•		•
History	The east end of 1838 OS map. T explicitly cited o map. In its prese	he west end n 1890 large-	is first scale	shown or OS town p	n 1884 OS six-i olan, and maltir	nch map. ngs on 19	Malt houses are 10 OS 25-inch

Component OFIAR-017-064 1

Type Malt house Function Malting

Category Drink processing & products Context Industry

Irish Grid 233765 225078 +/- 10m

Survey date 16/07/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A

Machinery Remains Some remains Condition Poor Use Disused

Description

Substantial derelict remains of maltings formerly belonging to Tullamore Distillery (OFIAR-017-036), behind west end of Patrick St. Comprises a malt house at east end (component 1) and malt kiln at west end (component 2).

The malt house is a derelict late 19th century double-pile/three-storey/11-bay building aligned east-west along the north bank of the Tullamore River. Ground and first floor walls are of random rubble but raised in mass concrete during the 1900s to accommodate a curved corrugated-asbestos roof, now collapsed. Square-headed openings. Original openings have brick heads and jambs. Some hinged and louvered shutters survive. Ground floor window openings to river elevation have security bars. Internally, the floors run across both piles. The upper floors have screeded timber boards over joists resting on transoms with intermediate metal columns. The transoms under the first floor are of timber, and those to the second floor are steel joists. Large cast-iron steep tanks at the east end of the first and second floors are carried on RSJs.

Component OFIAR-017-064 2

Type Malt kiln Function Malting

Category Drink processing & products Context Industry

Irish Grid 233737 225084 +/- 10m

Survey date 16/07/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A

Machinery Remains Traces Condition Poor Use Disused

Description

The malt kiln is a derelict late 19th century four-storey building aligned north-south at west end of complex. Hipped artificial slate roof with raised open-sided ridge ventilator. Metal rainwater goods, partly missing. Random rubble walls except top floor, which is of brick; all covered in tar (for insulation). Tie plates to all floors. Largely devoid of openings, except for small square-headed openings to ground floor and east elevation of top floor. An enclosed arched walkway links the first floor with the adjoining malt house. South gable formerly abutted by a three-storey building, now demolished.

Internally, the ground floor contains two oil-fired furnace (by Hubbard Combustion Ltd, Kingston-upon-Thames), and electrically-powered fans (by Drake & Fletcher, Maidstone). A timber-sheeted brick duct from each furnace rises vertically through each upper floor. The upper floors have boarded floors over joists resting on RSJs; their walls are sheeted in timber for insulation. Top two floors not accessible (but formerly via building to south).

Interest Architectural; Historical; Setting

Evaluation

Although now derelict, the utilitarian architectural form of the malt kiln is still clearly evident and forms a distinctive element to the streetscape. Both it and the associated malt house retain some of their contents and are also of historical interest in being associated with the Tullamore Distillery. This site is regional industrial heritage significance and both the malt house and kiln are Protected Structures in the Draft Tullamore Development Plan 2010-16.

Whilst the kiln could be preserved or adaptively reused, the malt floor may be too ruinous to restore. In both cases, it is recommended that detailed drawings and photographs be made.

Rating Regional Protection Tullamore RPS 23- Action None (in RPS);

202; Tullamore RPS

23-403

Associated with OFIAR-017-036

Other dbase NIAH 14807003 (R)

References

Irish Architectural Archive, Merion Sq., Dublin.

Page(s) S-570-11

Drawings

OFIAR-017-064_01 FWH 16/07/2003 North elevation of malt house, from north-west.



OFIAR-017-064_02 FWH 16/07/2003 South elevation of malt house, from south-east.



OFIAR-017-064_03 FWH 16/07/2003 Link between malt house and kiln, from north.



 $OFIAR-017-064_04 \quad FWH \quad 16/07/2003 \quad \quad Looking \ east \ along \ ground \ floor \ of \ malt \ house. \ Note \ timber \ transoms.$



OFIAR-017-064_05 FWH 16/07/2003 Looking east along first floor of malt house. Note metal transoms.



OFIAR-017-064_06 FWH 16/07/2003 Looking east along top floor of malt house. Roof has collapsed.



 $OFIAR-017-064_07 \quad FWH \quad 16/07/2003 \qquad Looking \ east \ over \ collapsed \ roof \ of \ malt \ house.$



 $OFIAR-017-064_08 \quad FWH \quad 16/07/2003 \qquad Steep \ tank \ at \ east \ end \ of \ first \ floor \ of \ malt \ house.$



OFIAR-017-064_09 FWH 16/07/2003 Malt kiln, from north-west.



OFIAR-017-064_10 FWH 16/07/2003 Malt kiln, from south-east.



OFIAR-017-064_11 FWH 16/07/2003 Oil-fired furnace on ground floor of malt kiln.



 $OFIAR-017-064_12 \quad FWH \quad 16/07/2003 \qquad Electrical \ blower \ fan \ on \ ground \ floor \ of \ malt \ kiln.$



OFIAR-017-064_13 FWH 16/07/2003 Looking north on first floor of malt kiln.



OFIAR-017-064_14 FWH 16/07/2003 Heating duct on first floor of malt kiln.



Site no	OFIAR-017-0	65					
County	Offaly	Townland	Tullamore			Town	Tullamore
Planning	Tullamore UDC	Discovery m	ap 48			Six-inc	h map 17
Summary	Site of 19th cent				amore Dis	tillery situa	ated at what is
History	Buildings are she Valuation notes Rated at £115. 0	them as being	part of Bern	ard Da	aly's distille	ry (OFIAR	R-017-036).
Component	OFIAR-017-065	1					
Туре	Malt house		Fun	ction	Malting		
Category	Drink processing	g & products	Con	text	Industry		
Irish Grid	233766 225033	+/- 10m					
Survey date	16/07/2003	Surve	or Fre	d Han	nond		
Building	Remains No vi	sible remains	Condition	N/A	Use	N/A	
Waterworks	Remains N/A		Condition	N/A	Use	N/A	
Plant	Remains N/A		Condition	N/A	Use	N/A	
Machinery	Remains N/A		Condition	N/A	Use	N/A	
Description	Site of malt hous	ses now occup	ied by exten	sion to	Bridge H	otel.	

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-017-036

Other dbase

References

Site no OFIAR-017-070		
	Cito no	2 047 070

County Planning	Offaly Tullamore UDC	Townland Tulla	more 48	Town	Tullamore h map 17
Summary	High Street, opp	osite O'Connor Sq	by T.P. & R. Goodbody in uare. Destroyed by fire in er Bridge Shopping Centre	1886 and	
History	c.150 people we brand names ind Premises said to Dublin. Howeve	ere employed in the cluded Bird's Eye, (o have been destro r, still cited as toba	m and Robert James God production of pipe tobacc Golden Flake, York River a yed by fire 1886 and the v cco factory on 1890 large- map; probably then part of	co, cigare and Qual vorkforce scale tow	ttes and snuff; ker Twist. relocated to vn map.

Component OFIAR-017-070 1

Type Tobacco factory Function Tobacco processing & products

Category Other industry Context Industry

Irish Grid 233805 225005 +/- 10m

Survey date 16/07/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of tobacco factory to rear of west frontage of High St, opposite O'Connor Square.

Site now under Bridge Shopping Centre.

Component OFIAR-017-070 2

Type	Malt house	Function	Distilling
Category	Drink processing & products	Context	Industry

Irish Grid 233805 225005 +/- 10m

Survey date 16/07/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A **Plant** Condition N/A Use N/A Remains N/A Machinery Remains N/A Condition N/A Use N/A

Description Site of malt house to west of High St, opposite O'Connor Square, now redeveloped

as Bridge Shopping Centre.

Interest NoneEvaluation Although this was the only tobacco manufactory in Co Offaly, the absence of any

physical remains makes the site of no industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-017-036

Other dbase

Junior Chamber, 1994).

References

Byrne, M. When Tullamore had a tobacco industry. In Offaly Independent, 24 Jan 1992.

Joyce, J. St. G. The King's County: History, Topography and Antiquities (Birr: Midland Tribune).

Tullamore Dew Heritage Centre. Tullamore: a Short Introduction and Trails of the Town (Tullamore: Tullamore Dew Heritage Centre, 2000).

Tullamore Junior Chamber. Know your Tullamore (Tullamore: Tullamore Page(s) 99

Site no	OFIAR-017-0	72			Egan's Brewery
County	Offaly	Townland Tulla	more	Tow	n Tullamore
Planning	Tullamore UDC	Discovery map	48	Six-	inch map 17
Summary	•	rewery, established nder Bridge Shoppi		vest side of High	St, behind Brewery
History	Michael Bryne s Valuation notes was producing 3	arked here on the 1 tates that the brewe that it belonged to 60-40 barrels per da 0 and 1910 large-so	ery was establ Robert Devere y and employ	ished in 1830s. T ell and was rated a ing 50 men. Expli	he 1854 Griffith
Component	OFIAR-017-072	1			
Туре	Brewery		Function	Brewing	
Category	Drink processing	g & products	Context	Industry	

Survey date 16/07/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

+/- 10m

Description Site of brewery behind Brewery Tap in High Street, now demolished to make way for

Bridge Shopping Centre.

233802 224982

Interest None

Irish Grid

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Byrne, M. Tullamore Town Album (Tullamore, 1988).

Page(s) Plate 110

Tullamore Dew Heritage Centre. Tullamore: a Short Introduction and Trails of the Town (Tullamore: Tullamore Dew Heritage Centre, 2000).

Page(s) 33

Site no	OFIAR-017-076	Tullamore Dew Heritage Centre
County	Offaly Townland Tu	lamore Town Tullamore
Planning	Tullamore UDC Discovery map	48 Six-inch map 17
Summary	Canal, the main conduit by which Tullamore Dew Heritage Centre. the Offaly Archaeological and His	7 belonging to D.E. Williams Ltd. Adjoins Grand the product was transported to Dublin. Now houses Malt silos formerly stood where the building housing storical Society's Research Centre now stands. Also and canalside metal swivel crane. A narrow public and canal.
History		ager of the nearby distillery (OFIAR-017-036) in n on site on 1910 OS map. Converted to Tullamore s.
Component	OFIAR-017-076 1	
Туре	Bonded warehouse	Function Distilling
Category	Drink processing & products	Context Industry
Irish Grid	233871 225347 +/-10m	
Survey date	Surveyo	Fred Hamond
Building	Remains Complete	Condition Good Use Heritage centre
Waterworks	Remains N/A	Condition N/A Use N/A
Plant	Remains N/A	Condition N/A Use N/A
Machinery	Remains N/A	Condition N/A Use N/A
Description	Not surveyed in detail.	
Component	OFIAR-017-076 2	
Туре	Malt silo	Function Distilling
Category	Drink processing & products	Context Industry
Irish Grid	233844 225343 +/- 10m	
Survey date	Surveyo	Fred Hamond
Building	Remains No visible remains	Condition N/A Use N/A
Waterworks	Remains N/A	Condition N/A Use N/A
Plant	Remains N/A	Condition N/A Use N/A
Machinery	Remains N/A	Condition N/A Use N/A
Description	Not surveyed in detail.	

Component OFIAR-017-076 3

Type Quay Function Distilling

Category Drink processing & products Context Industry

Irish Grid 233872 225355 +/- 10m

Survey date Surveyor Fred Hamond

Building Remains Complete Condition Good Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A
Use N/A

Description Not surveyed in detail. Site encompasses crane.

Interest

Evaluation Not evaluated. This building and associated crane are Protected Structures in the

Draft Tullamore Development Plan 2010-16.

Rating Protection Tullamore RPS 23- Action

294; Tullamore RPS

23-295

Associated with OFIAR-017-036

Other dbase NIAH 14807099 (R); NIAH 14807100 (R)

References

Byrne, M. The People of Tullamore in the Twentieth Century (Tullamore: Page(s) 36

Esker Press, 2000).

Byrne, M. Tullamore Town Album (Tullamore, 1988). Page(s) Plate 62

Garner, W. Tullamore Architectural Heritage (Dublin: An Foras Forbartha, Page(s) 56

1980).

Irish Architectural Archive, Merion Sq., Dublin. Page(s) S-571-2

Irish Architectural Archive, Merion Sq., Dublin. Page(s) S-571-3

Tullamore Dew Heritage Centre. Tullamore: a Short Introduction and Trails Page(s) 19

of the Town (Tullamore: Tullamore Dew Heritage Centre, 2000).

Site no	OFIAR-017-083
County	Offaly Townland Wood of O Town
Planning	Offaly CC Discovery map 48 Six-inch map 17
Summary	Traces of 18th/19th century water-powered corn mill on a tributary of the Tullamore River.
History	Not cited in 1840s Mill Valuation book or explicitly captioned on any OS map. Its sole reference is in the 1854 Griffith Valuation which records it as belonging to John Cobb. The house, offices, corn mill were rated at £16. Roofless shell shown on 1910 map.
Component	OFIAR-017-083 1
Туре	Grain mill (water) Function Grain milling
Category	Food processing & products Context Industry
Irish Grid	238248 227276 +/- 10m
Survey date	17/07/2003 Surveyor Fred Hamond
Building	Remains Traces Condition Poor Use Disused
Waterworks	Remains Traces Condition Poor Use Disused
Plant	Remains No visible remains Condition N/A Use N/A
Machinery	Remains N/A Condition N/A Use N/A
Description	Located on lane off south side of main road. Overgrown rubble stone fragments of what was probably the mill survive at the head of a presumed tailrace.
Interest	None
Evaluation	No special industrial heritage significance

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Site no	OFIAR-017-08	5	Salts Mill; Tullamore Gaol
County	Offaly	Townland Spollanstow	n Town Tullamore
Planning	Tullamore UDC I	Discovery map 48	Six-inch map 17
Summary		0 ,	/multi-bay wool spinning mill situated gaol. Now in light industrial and office use.
History	except for the fror the surviving faça and winding. Ever	nt block. Salts (Ireland) I de in 1938. Processes in ntually taken over by Tu	in 1922 and was largely demolished in 1937 Ltd opened a worsted spinning mill behind ncluded drawing, twisting, reeling, spinning llamore Yarns. The mill closed in 1982 and estate known as the Kilcruttin Business Park.

Component OFIAR-017-085 1

Type Spinning mill Function Wool

Category Textile manufacture & products Context Industry

Irish Grid 233571 224441 +/- 10m

Survey date 16/07/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Good Use Offices/Light industry

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

Description

Substantial remains of 1938 single-storey/multi-bay wool spinning mill situated immediately behind façade of 1830 town gaol. Now in light industrial and office use. The façade of the former gaol is set back from the main road (Cormac St) and aligned NE-SW. The entire façade is of ribbon-pointed random limestone blocks. At centre is an imposing segmental-headed entrance gate and flanking crenellated square towers. Over the doorway is a plaque commemorating the laying of the foundation stone by Charles William, Baron Tullamore, on 13 September 1826. A high curtain wall runs to both sides, with advanced dentillated coping and segmental-headed vehicle entrance at NE.

Behind this façade are two- and three-storey mill offices. The block at SW has a flat concrete roof, and that to NE a mansard slate roof with dormer windows to the street elevation. The walls to the rear elevation of these blocks are of squared limestone to the ground floor and smooth cement rendered to the upper floors. All openings are square-headed and those to the ground floor have dressed stone surrounds. The windows are multi-paned metal and uPVC casements.

Behind the office block is the spinning mill proper. Its 19 bays are aligned parallel with the street façade. The roof is of sawtooth profile and clad in artificial slate and corrugated asbestos sheeting. There are continuous windows to each bay's NW profile. Cast-iron ogee rainwater goods. The walls are smooth cement rendered to their NW and SW elevations. The other elevations are of ribbon-pointed limestone blocks. The SE elevation has a blocking course along its eaves. Square-headed openings with concrete heads; uPVC windows and timber doors. Pitched- and flatroofed canopies span the yard between the mill and office block.

A tapered brick chimney of square cross-section rises from the south end of one of the bays towards the front. It is now utilized by an modern oil-fed boiler. At the southern corner of the site is a large cast-iron water tank supported on a braced steel framework. Immediately east of the main mill block is a later one-storey/six-bay unit.

Its roof is of sawtooth profile and clad in corrugated metal. The walls are cement harled.

The interior of the mill is subdivided with concrete blockwork into various workshops and stores, with an access corridor down the middle. The roofs have sarked undersides and are supported on angled steel trusses. No original plant or machinery survives.

Interest Architectural; Historical; Rarity; Setting

Architecturally, this building is of interest as it incorporates the imposing remains of **Evaluation**

> the gaol and is also one of only two purpose-built 20th century spinning mills in the county (the other is the Midland Tribune building in Birr, OFIAR-035-053). Historically, the site is also of interest as a gaol and in reflecting the inception of a major industry in Tullamore after Partition. The façade also has considerable streetscape merit. It is of regional industrial heritage significance and is a Protected

Structure in the Draft Tullamore Development Plan 2010-16.

Protection Tullamore RPS 23-242 Rating Regional Action None (in RPS)

Associated with

Other dbase NIAH 14807046 (R)

References

Byrne, M. Tullamore Town Album (Tullamore, 1988).	Page(s)	Plate 121
Byrne, M. Tullamore Town Album (Tullamore, 1988).	Page(s)	Plate 29
Byrne, M. Tullamore Town Album (Tullamore, 1988).	Page(s)	Plate 30
Byrne, M. Tullamore Town Album (Tullamore, 1988).	Page(s)	Plates 122, 123
Byrne, M. 'Tullamore: the growth process, 1785-1841'. In Nolan W. and O'Neill, T.P. (eds), Offaly: History and Society (Dublin: Geography Publications, 1998).	Page(s)	586
Garner, W. Tullamore Architectural Heritage (Dublin: An Foras Forbartha, 1980).	Page(s)	13-15

Sheely, M. Architecture in Offaly. In Journal Co Kildare Archaeological

Page(s) 21 Society, vol.14 (1964-65).

Tullamore Junior Chamber. Know your Tullamore (Tullamore: Tullamore Page(s) 99 Junior Chamber, 1994).

OFIAR-017-085_01 FWH 16/07/2003 Gaol façade, from north.





OFIAR-017-085_03 FWH 16/07/2003 Rear of front office block, from east.



OFIAR-017-085_04 FWH 16/07/2003 General view of spinning mill, from north-west.



OFIAR-017-085_05 FWH 16/07/2003 General view of spinning mill, from south.



OFIAR-017-085_06 FWH 16/07/2003 General view of spinning mill, from south-east.



OFIAR-017-085_07 FWH 16/07/2003 Roof of spinning mill (north-west elevation).



OFIAR-017-085_08 FWH 16/07/2003 Interior of mill.



 $OFIAR-017-085_09 \quad FWH \quad 16/07/2003 \qquad Water tank at south end of site, from north.$



Site no OFIAR-017-090

County Planning	Offaly Tullamore UDC	Townland Tulla	amore 48	Town Tullamore Six-inch map 17
Summary	Incorporates late	e 18th/early 19th ce	malt house associated wit entury water-powered flou ght-iron entrance gates fro	r mill on Tullamore

History

Cited as a flour mill on the 1838 OS six-inch map and similarly described in the 1840s Mill Valuation book, when it was operated by Michael Molloy. It had a 12ft x 7ft waterwheel to three sets of stones and the relatively high valuation of £35.6s.0d. According to the 1854 Griffith Valuation, it was vacant at that time, although still valued at £45. Seemingly acquired by Tullamore Distillery and redeveloped as a maltings in later 1800s. Buildings shown on 1884 and 1910 OS maps.

Component OFIAR-017-090 1

Type Grain mill; Malt house Function Grain milling; Distilling

Category Food processing & products; Drink Context Industry

processing & products

Irish Grid 233816 225070 +/- 10m

Survey date 31/07/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

Description

A four-storey/multi-bay block of T plan, aligned east-west on the right bank of the Tullamore River, just west of the main road. Wall breaks indicate that this block evolved over several phases. On the river frontage at west is a nine-bay building, abutted at east by a three-storey building with central return to north. This return has a later extension to its north gable.

Roof is now missing; hipped to east end. Walls of random rubble with ashlar limestone eaves course. Openings have shallow segmental heads and brick dressings (stepped to jambs); those to top floor of diminished height. Some louvered shutters survive to upper openings, but mostly infilled with concrete blockwork. Some of the ground floor openings to the north elevation of the east section had segmental-arched overlights, subsequently infilled with random rubble. The west gable is abutted by another malt house (OFIAR-017-064). All internal floors removed. The site was formerly accessed through a pair of wrought-iron gates on Patrick St, immediately west of the Credit Union. The gates are hung from the adjoining buildings and have dogbars to their bottom halves. Each gate carries the date "1822". What this date signifies is uncertain as the Tullamore Distillery was not established until 1829. A wrought-iron over-arch reads "Tullamore Distillery/ B. Daly & Company Ltd/ Licensed Distillers".

Interest Architectural; Historical

Evaluation The style of the stone and brickwork suggests that this building is largely of mid 19th

century date and was undoubtedly associated with the Tullamore Distillery. It is of architectural interest because of its scale, and also of historical note because of its association with Daly's Distillery. It is of regional industrial heritage merit and warrants inclusion in the Record of Protected Structures.

Rating Regional Protection Action RPS

Associated with OFIAR-017-036

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-017-090_01 FWH 31/07/2003 General view from south-west of river frontage.



OFIAR-017-090_02 FWH 16/07/2003 General view from south-west of river frontage.



OFIAR-017-090_03 FWH 16/10/2003 Looking west along north elevation.



OFIAR-017-090_04 FWH 16/10/2003 Looking east along north elevation.



OFIAR-017-090_05 FWH 16/07/2003 Entrance gates at Patrick Street.



OFIAR-017-090_06 FWH 16/07/2003 1822 detailing on Patrick Street gates.



Site no	OFIAR-017-091	D.E. Williams Head Office
County	Offaly Townland T	ullamore Town Tullamore
Planning	Tullamore UDC Discovery ma	ap 48 Six-inch map 17
Summary		arters of the Tullamore Distillery (D.E. Williams Ltd). and originally belonged to George Ross, a brewer.
History	Associated with nearby Tullamo	ore Distillery (OFIAR-017-036). Building shown on editions.
Component	OFIAR-017-091 1	
Туре	Distillery office	Function Distilling
Category	Drink processing & products	Context Industry
Irish Grid	233851 225118 +/-10m	
Survey date	Survey	or Fred Hamond
Building	Remains Complete	Condition Good Use House
Waterworks	Remains N/A	Condition N/A Use N/A
Plant	Remains N/A	Condition N/A Use N/A
Machinery	Remains N/A	Condition N/A Use N/A
Description	Not surveyed in detail.	
Interest		
Evaluation	Not evaluated. This building is a Development Plan 2010-16.	a Protected Structure in the Draft Tullamore
Rating	Protection	Tullamore RPS 23-201 Action
Associated v	vith OFIAR-017-036	
Other dbase	NIAH 14807002 (R)	

References

Byrne, M. The People of Tullamore in the Twentieth Century (Tullamore: Page(s) 37

Esker Press, 2000).

Tullamore Dew Heritage Centre. Tullamore: a Short Introduction and Trails Page(s) 21 of the Town (Tullamore: Tullamore Dew Heritage Centre, 2000).

Site no	OFIAR-017-092
---------	---------------

County Planning	Offaly Tullamore UDC	Townland Tul		·	Town Six-incl	Tullamore h map 17
Summary	An early 19th century building converted in 1890s to the bottling of whiskey for Tullamore Distillery.					
History	Building shown on 1838 OS map and subsequent editions. However, not utilized for whiskey bottling until c.1897 under direction of Daniel Williams, manager of the adjoining Tullamore Distillery (OFIAR-017-036).					

Component OFIAR-017-092 1

Type Bottling works Function Distilling

Category Drink processing & products Context Industry

Irish Grid 233856 225147 +/- 10m

Survey date Surveyor Fred Hamond

Use Store Building Remains Complete Condition Good Waterworks Remains N/A Condition N/A Use N/A Plant Remains N/A Condition N/A Use N/A Remains N/A Condition N/A Use N/A Machinery

Description Not surveyed in detail.

Interest

Evaluation Not evaluated.

Rating Protection Action

Associated with OFIAR-017-036

Other dbase

References

Byrne, M. The People of Tullamore in the Twentieth Century (Tullamore: Page(s) 37

Esker Press, 2000).

Byrne, M. Tullamore Town Album (Tullamore, 1988). Page(s) Plate 109
Irish Architectural Archive, Merion Sq., Dublin. Page(s) S-560-5

Irish Architectural Archive, Merion Sq., Dublin. Page(s) S-570-9

Tullamore Dew Heritage Centre. Tullamore: a Short Introduction and Trails of the Town (Tullamore: Tullamore Dew Heritage Centre, 2000).

ls Page(s) 15-18

Site no OFIAR-017-107

County Planning	Offaly Offaly CC	Townland Capp	pancur 48	Town Six-inch map 17
Summary	Site of 18th/early 19th century water-powered corn mill on minor tributary of Tullamore River.			
History	book as a corn two sets of ston	mill belonging to Ja es and ancillary ma	chinery. Not in Griffith V	in 1840s Mill Valuation x 4ft 8in waterwheel drove aluation of 1854. Buildings he former mill is uncertain.

Component OFIAR-017-107 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 239302 224364 +/- 10m

Survey date 15/12/2004 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Use N/A Condition N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description No evident traces of any mill at this location.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-018-018
---------	---------------

County	Offaly	Townland	Townparks (Lower	Town	
•	·		Philipstown By)		
Planning	Offaly CC	Discovery	map 48	Six-inch map 18	
Summary	Site of 18th/early 19th century water-powered corn mill on tributary of Philipstown River.				
History	book notes the drove two pair Thomas Barry	e mill as working s of stones, but is noted as its were rated at £	ng under Mrs Denis. A 12ft at not worked for two years operator in 1854 Griffith	aps. The 1840s Mill Valuation t x 4ft waterwheel formerly s. Appears to have restarted as Valuation. The house, office ormant, the mill and house were	

Type Grain mill (water) **Function** Grain milling

Category Food processing & products Context Industry

Irish Grid 246639 226386 +/- 10m

Fred Hamond Survey date 11/06/2003 Surveyor

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill on tributary of Philipstown River, just east of junction of old and new

main roads. The site has been cleared and new sheds erected.

Interest None

Evaluation No industrial heritage interest.

Rating Record only **Protection** Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-018-02	23			Castlebarnagh Windmill
County	Offaly		Townparks (L Philipstown E		Town
Planning	Offaly CC	Discovery m	ap 49		Six-inch map 18
Summary	Site of 18th centu	ury windmill o	n hill overloo	king [Daingean.
History					8 and 1884 OS six-inch maps. Not on tof use in early 1800s.
Component	OFIAR-018-023	1			
Туре	Grain mill (wind)		Fun	ction	Grain milling
Category	Food processing	& products	Con	text	Industry
Irish Grid	248142 227843	+/- 10m			
Survey date	11/06/2003	Surve	yor Fre	d Han	nond
Building	Remains No vis	ible remains	Condition	N/A	Use N/A
Waterworks	Remains N/A		Condition	N/A	Use N/A
Plant	Remains No vis	ible remains	Condition	N/A	Use N/A
Machinery	Remains No vis	ible remains	Condition	N/A	Use N/A
Description	Site of windmill o course.	n a grassy kn	oll immediat	ely we	est of 17th tee of Castle Barna golf
Interest	None				
Evaluation	No industrial heri	tage interest.			
Rating	Record only	Protection			Action
Associated v	vith				_
Other dbase					

References

Site no	OFIAR-018-024	Philipstown Distillery			
County	Offaly Townland Townparks Philipstow				
Planning	Offaly CC Discovery map 48	Six-inch map 18			
Summary	Site of 18th century distillery beside Daingean Courthouse. Extant in 1812 but in ruins on 1838 OS map. Not shown on 1884 or 1910 maps.				
History	Distillery marked on 1812 map. Recorded as in ruins on 1838 OS six-inch map.				
Component	OFIAR-018-024 1				
Туре	Distillery F	Function Distilling			
Category	Drink processing & products	Context Industry			
Irish Grid	247266 227349 +/-10m				
Survey date	11/06/2003 Surveyor	Fred Hamond			
Building	Remains No visible remains Condition	tion N/A Use N/A			
Waterworks	Remains N/A Condition	tion N/A Use N/A			
Plant	Remains No visible remains Condition	tion N/A Use N/A			
Machinery	Remains No visible remains Condition	tion N/A Use N/A			
Description	Site of distillery immediately NE of court Philipstown).	rthouse at south end of Daingean (then			
Interest	None				
Evaluation	No industrial heritage interest.				
Rating	Record only Protection	Action			
Associated v	vith				
Other dbase					

References

Kennedy, Robert. Map of the holding of Richard Baynham in the town of Philipstown in the King's County (1812).

Page(s)

Site no Uriak-ulo-uzo	Site no	OFIAR-018-026
-----------------------	---------	---------------

County Planning	Offaly Offaly CC	Townland Lugn Discovery map	nore 48	Town Six-inch map 18
Summary	Site of 18th/ea	arly 19th century water	er-power	ed corn mill and kiln on Tullamore River.
History	1840s Valuation waterwheel dread offices, corn manother corn read of the second	on book as working u ove two sets of stone nill and kiln were rate nill (OFIAR-025-009)	nder Bai s. Yarr v d at £9 (at this t	OS six-inch map. The corn mill is noted in tholomew Yarr. A 13ft 3in x 4ft 2in was also owner in 1854 when the house, Griffith Valuation). He also operated ime as well. The mill is shown on the 1884 10 map; the kiln had disappeared by this

Component OFIAR-018-026 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 244532 222301 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill on Tullamore River, just north of minor road. The Old Mill Boarding

Kennels are nearby to west.

Component OFIAR-018-026 2

Type Grain kiln Function Grain milling

Category Food processing & products Context Industry

Irish Grid 244568 222289 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A Use N/A **Plant** Remains N/A Condition N/A Use N/A Machinery Remains N/A Condition N/A Use N/A

Description Site of detached kiln associated with corn mill.

Evaluation No industrial heritage interest.

Rating Record only Protection Action

Associated with OFIAR-025-009

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-018-035				
County	Offaly Townland Drumcaw or Mountlucas Town				
Planning	Offaly CC Discovery map 48 Six-inch map 18				
Summary	Site of mill of unknown function discovered in Drumcaw towland during land reclamation in 1957.				
History	Reported in Leinster Leader (December 1957) as being uncovered during land reclamation.				
Component	OFIAR-018-035 1				
Туре	Mill Function Unknown				
Category	Unknown Context Industry				
Irish Grid	251346 226667 +/-1000m				
Survey date	Surveyor Fred Hamond				
Building	Remains No visible remains Condition N/A Use N/A				
Waterworks	Remains No visible remains Condition N/A Use N/A				
Plant	Remains No visible remains Condition N/A Use N/A				
Machinery	Remains No visible remains Condition N/A Use N/A				
Description	Site of unlocated mill of unknown function in Drumcaw townland.				
Interest	Archaeological				
Evaluation	Although of some archaeological interest, the lack of upstanding remains makes this site of no special industrial heritage interest.				
Rating	Record only Protection Action				
Associated v					
Other dbase	SMR OF018-026				
References					

Page(s)

Archaeological Survey of Ireland record.

Site no	OFIAR-018-042
County	Offaly Townland Townparks (Lower Town Philipstown By)
Planning	Offaly CC Discovery map 48 Six-inch map 18
Summary	Site of a watermill cited in 1570 document.
History	A document of c.1570 refers to a watermill at Daingean.
Component	OFIAR-018-042 1
Туре	Mill Function Unknown
Category	Unknown Context Industry
Irish Grid	246368 227418 +/- 1000m
Survey date	Surveyor Fred Hamond
Building	Remains No visible remains Condition N/A Use N/A
Waterworks	Remains No visible remains Condition N/A Use N/A
Plant	Remains No visible remains Condition N/A Use N/A
Machinery	Remains No visible remains Condition N/A Use N/A
Description	Unlocated mill site.
Interest	Archaeological
Evaluation	Although of sime archaeological interest, the lack of upstanding remains makes this site of no special industrial heritage interest.
Rating	Record only Protection Action

Associated with

Other dbase SMR OF018-006006-

References

Archaeological Survey of Ireland record.

Page(s)

Site no	OFIA	R-019	- 004

County	Offaly	Townland Scrub or Pigeonpark	Town
Planning	Offaly CC	Discovery map 49	Six-inch map 19
Summary	Site of late 19th/early 20th century saw mill. Not water powered.		
History	This saw mill is first cited on the 1910 OS six-inch map in a farmyard complex west of a minor road. No water power in evidence.		

Component OFIAR-019-004 1

Type Saw mill Function Timber processing & products

Category Timber processing & products Context Industry

Irish Grid 252024 223070 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A
Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

Description No trace of saw mill in farmyard behind house (St Joseph's), west of minor road.

Interest None

Evaluation No industrial heritage interest.

Rating Record only Protection Action

Associated with

Other dbase

References

Site no	OF	IAR	-019	-006
---------	----	-----	------	------

County Planning	Offaly Offaly CC	Townland Clonavoe Discovery map 49	Town Six-inch map 19
Summary	Traces of 18th River.	n/early 19th century water-pov	vered corn mill on tributary of Philipstown
History	Noted as a corn mill on the 1838, 1884 and 1910 OS six-inch maps. Recorded in 1840s Mill Valuation book as belonging to Margaret Ryan. A 9ft x 2ft 6in wheel drow two sets of stones. Still owned by Margaret Ryan in 1853 (Griffith Valuation). The mand kiln were rated at £9 - this suggests a very modest enterprise. The mill race is cited as disused on the 1910 map, indicating that the mill was defunct by that date.		

Component OFIAR-019-006 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 257618 222773 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill and kiln in former farmyard complex on tributary of Philipstown

River, south of minor road.

Interest None

Evaluation No industrial heritage interest.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

Site no	. ()FIΔ	R-0	19-0	010
	, .	71 I/	11\-U	コンニ	910

County Planning	Offaly Offaly CC	Townland Clonbulloge Discovery map 49	Town Clonbulloge Six-inch map 19
Summary	Site of 18th/early 19th century water-powered corn mill on Figile River. Now marked by an ornamental paddlewheel.		
History	Corn mill cited on 1838 OS six-inch map. Noted in 1840s Mill Valuation book as belonging to Marquis of Downshire but no longer working. A 13ft x 3ft 9in wheel drove two sets of stones. The mill is cited in 1853 Griffith Valuation as dilapidated and was accordingly rated at only 15 shillings. No building shown on 1910 map.		

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 260912 223506 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A

Waterworks Remains Traces Condition Fair Use Disused

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill on Figile River, immediately west of Clonbulloge Bridge. A

reproduction paddle-type waterwheel has been erected in a section of restored race. It is of welded steel with 24 timber floats and measures 3.35m diameter by 1.37m wide (11ft x 4ft 6in). The tailrace is culverted under the road through a masonry stone

arch.

Interest None

Evaluation No industrial heritage interest.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-019-010_01 FWH 13/06/2003 Ornamental waterwheel at site of mill.



Site no	OFIAR-021	-009 Waller's Maltings	; {Bridge Malt House}; {Haughton's Mills}
County	Offaly	Townland Kylebeg or Banagher	Town Banagher
Planning	Offaly CC	Discovery map 53	Six-inch map 21
Summary		of late 1800s maltings belonging to F.A. Was	

Haughton's Mills, which also utilized steam power in mid 1800s.

History

There was a mill here in the later 1700s and it is shown with an external waterwheel on its north gable on an engraving of c.1800. The water was channelled through the end arches of a multi-arched bridge which formerly spanned the Shannon at this point. Cited as Haughtons Mills on 1838 and 1884 OS six-inch maps. Not recorded in 1840s Mill Valuation book, indicating that it was probably out of use at this time. Also vacant in the 1854 Griffith Valuation. At that time it comprised a flour and corn (steam) mill, offices, all rated at £45. This description indicates that a steam engine had been installed by this time, whether to augment or replace the waterwheel. Taken over by F.A. Waller c.1880 and cited as Bridge Malt House on 1909 OS map. The premises closed in 1970s when Waller amalgamated with D.E. Williams of Tullamore to from the Williams Waller Group. However, malting continued at the Crank Malt House (OFIAR-021-011) and Banagher Maltings (OFIAR-029-011).

Component OFIAR-021-009 1

Type Grain mill (steam; water); Malt Function Grain milling; Malting

house: Malt kiln

Food processing & products; Drink Category Context Industry

processing & products

Irish Grid 200520 215728 +/- 10m

Survey date Surveyor Fred Hamond 25/06/2003

Remains Substantial remains Condition Poor Use Disused Building Waterworks Remains Traces Use Disused

Use N/A **Plant** Remains No visible remains Condition N/A

Machinery Remains No visible remains Use N/A Condition N/A

Description Derelict shell of a five-storey/12-bay grain mill and maltings with 20th century

additions beside the quay just downstream from Banagher Bridge on the left bank of

Condition Poor

the River Shannon.

Building 1

The main block is five storeys high by 12 bays long and is aligned north-south with its north gable fronting the river. Internally divided into two six-bay units, with a wall between. There is a clear wall break between the two sections, that at south being a later addition to what appears to have been the original 18th century flour mill. The pitched roofs to both sections are missing, as are the rainwater goods; the roof on the south section was slightly higher. Random rubble walls with dressed stone eaves. The north end of the north section is tarred and indicate the former presence of a kiln. This appears to have been a malt kiln, inserted in place of the former grain milling machinery and of which there are now no internal traces. Square-headed openings, diminished in height to the top floor. The window openings to the north section have flat red-brick heads and stone jambs and cills; those to south section

have flat yellow-brick heads and jambs but no cills. Remnants of 2x2 timber casement windows. Segmental brick headed doorways at both ends of east elevation. The east elevation is partly abutted by a 20th century two-storey extension with corrugated asbestos/metal monopitched roof and mass concrete walls. Other buildings also abutted this elevation, as well as at west, but all have been demolished. Inside, vestiges of timber floor beams and joists survive. Some of the timber beams in the south section rest on a reinforced-concrete framework (the latter was probably inserted on conversion to a maltings). The walls are painted and plastered. There is a large cement-rendered elevator pit in the floor in the north section.

Building 2

At the SW end of building 1 is a five-storey/two-bay building running east-west. Its hipped roof is missing. Half-round metal rainwater goods. The bottom two floors are of rendered random rubble and the floors above of brick - probably a later heightening. Stepped brick buttresses to south and east sides. Square-headed openings without cills. East end of south gable has later insertions. Refloored such that now only four floors internally. Timber joists rest on RSJ beams.

Building 3

The west elevation of building 1 and north side of building 2 were formerly abutted by a two-storey addition with curved roof (the line of which is evident on building 2). This building was replaced in the later 1900s by a steel-famed concrete block building. Shallow pitched roof clad in profiled metal on steel trusses. It appears to be unfinished.

Building 4

East of building 1 is a detached two-storey/three bay building which was probably mill related (perhaps an office). Latterly refurbished with pitched artificial slate roof and painted cement-rendered walls. Now disused.

The premises are enclosed to south by a high random rubble wall, now overgrown. Entrance gates are of corrugated metal and are hung from original square dressed stone piers. At NE is a small quay constructed of dressed limestone blocks which dates from the improvements to the Shannon Navigation by the Commissioners of Public Works in the 1840s.

Waterworks, plant and machinery

There are the infilled vestiges of what may have been the end of the stone-lined tailrace of the original grain mill just downstream from the quay. Archaeological investigation would be necessary to confirm this. No plant or machinery survives.

Interest Architectural; Historical; Setting

Evaluation

Although derelict, this is still an architecturally imposing site and one of the larger grain mills to survive in Co Offaly. Historically, it is of interest as a water- and steam-powered flour mill which was adapted to become one of Messrs Waller's maltings. Its juxtaposition to the river and presence of the quay reflect the importance of the Shannon as a conduit for trade at that time (some 40 years before the arrival of the railway in the town in 1884). It is also an important landscape feature, especially when viewed from the bridge and river. Overall, it is of regional industrial heritage significance and merits its inclusion as a Protected Structure in the Co Offaly County Development Plan 2009-15.

Rating Regional Protection Offaly RPS 39-29 Action None (in RPS)

Associated with

Other dbase NIAH 14810031 (R)

References

Lewis, S. An A-Z of Offaly in 1837 (Tullamore: Esker Press, 1999. Extracts from Lewis's 1837 Topographical Dictionary of Ireland).

Page(s)

Photographic Collection in Local Studies section of Offaly County Library Headquarters, Tullamore.

Page(s) Photos 3153, 3401

Trodd, V. Banagher on the Shannon: a Historical Guide to the Town (1985).

Page(s) 11

Trodd, V. Banagher on the Shannon: a Historical Guide to the Town (1985).

Page(s) 18-19

OFIAR-021-009_01 FWH 25/06/2003 General view from north-east.



OFIAR-021-009_02 FWH 25/06/2003 View from north-east. The original mill comprises the right-hand half and the later maltings the left section.



 $OFIAR-021-009_03 \quad FWH \quad 25/06/2003 \qquad \mbox{View from south-east. Building 2 in foreground.}$



OFIAR-021-009_04 FWH 25/06/2003 View from south-west.



OFIAR-021-009_05 FWH 25/06/2003 View from north-west.



OFIAR-021-009_06 FWH 14/07/2003 Vestiges of possible tailrace.



OFIAR-021-009_07 FWH 25/06/2003 Internal view of north section of building 1 (former mill), looking north.



Internal reinforced-concrete framework inside south section of building 1 (maltings).



 $OFIAR-021-009_09 \quad FWH \quad 25/06/2003 \qquad Floor \ detailing \ in \ building \ 2 \ (maltings).$



Site no	OFIAR-021-011 Crank Ma		Crank Malt House
County	Offaly	Townland Kylebeg or Banagher	Town Banagher
Planning	Offaly CC	Discovery map 53	Six-inch map 21
Summary	1800s. In later 1 Minch Norton as	ly 19th century brewery. Also extensive malt 1900s, operated by Williams-Waller Ltd and, s a grain drying facility. Now owned by Green malt kilns, malt houses and modern grain dry	from mid 1990s, by ncore Ltd. The premises
History	Brewery noted on 1838 and 1884 OS six-inch maps. Cited as a vacant brewery, stores and offices in 1854 Griffith Valuation book; rated at £40. The 1909 OS map shows a roofless shell. Situated beside it on this map is Crank Malt House. Malting was instigated by F.A. Waller in late 1800s. Amalgamated with D.E. Williams of Tullamore in 1970s to form Williams Waller Group. The group also operated the Banagher Maltings at Garrycastle (OFIAR-029-011). Greencore Ltd took over operations in 1996. At the time of survey, the premises were being used as a grain drying facility.		40. The 1909 OS map hk Malt House. Malting with D.E. Williams of up also operated the core Ltd took over

Component O	FIAR-021-011 1
-------------	----------------

Туре	Brewery	Function	Brewing
Category	Drink processing & products	Context	Industry
Irish Grid	200752 215508 +/- 10m		
Survey date	25/06/2003 Survey	or Fred Han	nond
Building	Remains No visible remains	Condition N/A	Use N/A
Waterworks	Remains N/A	Condition N/A	Use N/A
Plant	Remains No visible remains	Condition N/A	Use N/A
Machinery	Remains No visible remains	Condition N/A	Use N/A
Description	Site of brewery at entrance to m	naltings.	

Type Malt kiln Function Malting

Category Drink processing & products Context Industry

Irish Grid 200748 215462 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description Single-bay, three-stage former malt kiln at SE end of site. Latterly converted to grain

screening but disused at time of survey.

Pyramidal natural slate roof surmounted with a square slated ventilator. No rainwater goods. Yellow brick walls with square-headed openings. Several large corrugated steel silos in yard to west.

Internally, the ground and first floors are of concrete and the top floor of slitperforated steel mesh supported on a metal frame. Sections of flooring have been removed to accommodate a forced-air grain drier which rises the full height of the interior and which is controlled from an electrical switch panel on the ground floor. At its top end is a reciprocating sieve and fan. Discharged into the silos in the west pile of component 3. There are also two chain augers at the base of the drier.

Component OFIAR-021-011 3

Type Malt house Function Malting

Category Drink processing & products Context Industry

Irish Grid 200762 215482 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Fair Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description

Double-pile, three-storey former malt house aligned north-south and abutting north end of kiln (component 2). Latterly gutted and converted to grain storage but now derelict. Pitched corrugated asbestos roof and metal rainwater goods. Two square corrugated metal elevator heads project from roof. Random rubble walls, rendered to west pile. Square-headed openings; brick heads to ground and first floor openings. Loading doors to upper floors on north gable.

Concrete ground floor and painted/plastered walls. The first floor of the east pile has been removed and the original timber second floor is now supported on concrete columns to take the weight of stored grain. The floors in the west pile have also been removed to make way for circular steel silos fed from the grain cleaner in the adjoining kiln. The elevators and augers are controlled from an electric switch panel on the ground floor. There is also a grain intake elevator at the south end of the block and a chute to the kiln.

Type Maltings office Function Malting

Category Drink processing & products Context Industry

Irish Grid 200786 215510 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Fair Use Disused

Waterworks Remains N/A Condition N/A Use N/A

Plant Remains N/A Condition N/A Use N/A

Machinery Remains N/A Condition N/A Use N/A

Description Four-bay, two-storey former office aligned north-south along east side of site, to north

of component 3. Presumed to have been an office but latterly used as a workshop

and store. Disused by time of survey.

Pitched artificial slate roof with rendered chimney to each gable. Steel gutters on boarded eaves. Rendered random rubble walls. Square-headed openings. West elevation has main entrance door flanked by tripartite 1/1 sash windows. First floor has single 1/1 sashes. All windows have concrete cills. A single-storey lean-to abuts

the east elevation. No features of interest internally.

Component OFIAR-021-011 5

Type Malt house Function Malting

Category Drink processing & products Context Industry

Irish Grid 200802 215523 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Fair Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description A four-bay, two-storey former malt house, now disused. Abuts north gable of office

(component 4).

Flat concrete roof and mass concrete walls and square-headed openings. Both floors are of concrete and the walls are painted and plastered. The upper floor is supported

on a longitudinal steel beam over concrete columns

Type Grain store Function Malting

Category Drink processing & products Context Industry

Irish Grid 200819 215537 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description A long two-storey building aligned north-south along the east side of the premises at

north end of component 5. Now a derelict shell except for north end which has been

refurbished as offices (artificial slate roof).

Vestiges of pitched corrugated asbestos roof survive, but mostly gone. Random rubble walls with advanced stone eaves. External concrete pilasters along west elevation were associated with an abutting building, now gone which extended across the entire yard. Square-headed openings trimmed with brick but mostly infilled; some also have timber grilles.

Internally, the ground floor is timber sheeted. Walls painted and plastered. The first

floor is of mass concrete over reinforced-concrete transoms.

Component OFIAR-021-011 7

Type Malt kiln Function Malting

Category Drink processing & products Context Industry

Irish Grid 200817 215551 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Fair Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description Single-bay, three-stage former malt kiln at north end of site. Converted to a grain

drying facility but disused by time of survey.

Pyramidal natural slate roof surmounted by a square slated ventilator. Metal rainwater goods. Walls are of random rubble and yellow brick and have square-headed openings. An oil-fired furnace projects from the east end of the south elevation.

Internally, the ground floor is of concrete. The original upper floors have been removed and replaced with a single mass concrete floor supported on concrete beams and columns; the corrugated metal falsework is still in place under the floor. The upper floor was used to dry grain. It is sarked to the underside of the slates and plastered to the undersides of the rafters for insulation.

Type Grain store Function Brewing; Malting

Category Drink processing & products Context Industry

Irish Grid 200790 215537 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Fair Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description Two multi-bay, two-storey buildings aligned north-south along the east side of Crank

Lane. Probably associated with the original brewery and presumed to have been

grain stores. Now partly used as a chemical store.

The north building has a pitched natural slate roof, now partly missing. Random rubble walls, partly rendered. Square-headed openings with brick trim; louvered to first floor. Internally, the ground floor is of concrete. The first floor has been removed. Tied common rafter roof.

The south building is slightly lower and shorter. It has a pitched corrugated asbestos roof. Walls are of random rubble, partly rendered and chamfered to SE corner. Square-headed openings to ground floor only, all with brick or dressed stone heads. Loading door to first floor of south gable. Internally a mass concrete first floor has been inserted, supported on reinforced-concrete beams.

At the south end of the premises is an extensive assemblage of grain silos and miscellaneous buildings containing modern grain drying and cleaning equipment.

Component OFIAR-021-011 9

Type Brewery house Function Brewing; Malting

Category Drink processing & products Context Industry

Irish Grid 200823 215557 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Offices

Waterworks Remains N/A Condition N/A Use N/A

Plant Remains N/A Condition N/A Use N/A

Machinery Remains N/A Condition N/A Use N/A

Description A seven-bay, two-storey house aligned approximately east-west along the main road

at the north end of the premises. Probably associated with the original brewery and then with the maltings. Now restored and used by West Offaly Development

Association as visitors' centre, tourist information centre and hostel.

Pitched natural slate roof with three rendered chimneys and metal rainwater goods. Painted and rendered walls. Semicircular projecting bay towards east end of street façade contains entrance door with ornate pedimented dressed stone surround.

Square-headed windows with 6/6 sashes and stone cills.

Interest Architectural; Historical; Setting

Evaluation This extensive complex is prominently situated along the south side of the main

street. Crank House is of particular architectural merit and is a Protected Structure in the 2009-15 County Development Plan (number 39-18). The two former kilns are of historical interest due to their association with the maltings. However, the convertion of their interiors has diminished their character to such an extent that they are now

only of local industrial heritage significance.

Rating Local Protection Offaly RPS 39-18 Action

Associated with OFIAR-029-011

Other dbase NIAH 14810020 (R)

References

Photographic Collection in Local Studies section of Offaly County Library Page(s) Photo 3294 Headquarters, Tullamore.

Trodd, V. Banagher on the Shannon: a Historical Guide to the Town (1985). Page(s) 26

OFIAR-021-011_01 FWH 25/06/2003 General view of site from north-west. Crank house at left.



OFIAR-021-011_02 FWH 25/06/2003 General view of site from south. Kiln (component 2) at right.



OFIAR-021-011_03 FWH 25/06/2003 Kiln (component 2) from south.



OFIAR-021-011_04 FWH 25/06/2003 Kiln (component 2) from east.



OFIAR-021-011_05 FWH 25/06/2003 Kiln (component 2): warm air intake to drier.



OFIAR-021-011_06 FWH 25/06/2003 Kiln (component 2): top of drier.



OFIAR-021-011_07 FWH 25/06/2003 Former malt house (component 3), from north-east.



OFIAR-021-011_08 FWH 25/06/2003 Former malt house (component 3): east pile, looking south.



OFIAR-021-011_09 FWH 25/06/2003 General view of north half of premises, from south. Component 4 at foreground right.



 $OFIAR-021-011_10 \quad FWH \quad 25/06/2003 \qquad Office \ (component \ 4), from \ south-west.$



OFIAR-021-011_11 FWH 25/06/2003 Malt house (component 5): ground floor, looking south.



OFIAR-021-011_12 FWH 25/06/2003 Former grain store (component 6), from south-west.



OFIAR-021-011_13 FWH 25/06/2003 Kiln (component 7), from south.



 $OFIAR-021-011_14 \quad FWH \quad 25/06/2003 \qquad \text{Kiln (component 7): ground floor showing warm air intake duct.}$



OFIAR-021-011_15 FWH 25/06/2003 Grain stores (component 8), from south-east.



 $OFIAR-021-011_16 \quad FWH \quad 25/06/2003 \qquad \text{Modern grain silos at south end of site}.$



OFIAR-021-011_17 FWH 25/06/2003 Crank House (component 9), from north-east.



 $OFIAR-021-011_18 \quad FWH \quad 25/06/2003 \qquad Crank \ House \ (component \ 9): entrance \ door \ detail.$



OFIAR-021-011_19 FWH 25/06/2003 Rear view of Crank House.



	Site no	OFIAR-021-012
--	---------	---------------

County Planning	Offaly Offaly CC	Townland Curr	aghavarna and Portavolla	Town Banagher Six-inch map 21
Summary	Dereleict remains distillery, established in late 1700s/early 1800s, but out of use by mid 1800s.			
History	Noted as distillery on 1838 and 1884 OS six-inch maps. Recorded as vacant in 1854 Griffith Valuation book; rated at £45. Most of the buildings had disappeared by the 1909 OS map and none is captioned.			

Type Distillery Function Distilling

Category Drink processing & products Context Industry

Irish Grid 200913 215614 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Poor Use Agricultural building

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Ruinous shell of former distillery and associated buildings in enclosed site behind east side of Main Street.

Only the SE section of the distillery survives, aligned NE/SW and 2½ or three-storeys high. Its NE gable has been demolished (where the main distillery was located) and its SE side has been slightly reduced in height to accommodate a modern monopitched corrugated metal roof. Random rubble walls, now very overgrown. Segmental-headed doorways and square-headed window openings with brick dressings. Now derelict and used as an animal byre. Most of the flooring has been removed.

The ground immediately NE of this building is enclosed by a random rubble wall and contains two detached two-storey/three-bay buildings. The 1838 OS map suggests that they were contemporary with the distillery. Both have pitched natural slate roofs, random rubble walls and square-headed openings with brick dressings. One has chimneys and was a dwelling or office. Both are now floorless and derelict.

Interest None

Evaluation The surviving remnants of this distillery are now of no special industrial heritage

signficance.

Rating Record only Protection Action

Associated with

Other dbase

References

OFIAR-021-012_01 FWH 25/06/2003 Vestiges of distillery complex, from north-west.



OFIAR-021-012_02 FWH 25/06/2003 Vestiges of distillery complex, from south-east.



OFIAR-021-012_03 FWH 25/06/2003 General view of yard to north, looking south. The distiller is at right.





 $OFIAR-021-012_05 \quad FWH \quad 25/06/2003 \quad \quad Building \ at \ south-east \ corner \ of \ yard, \ from \ west.$



Site no	OFIAR-02	22-017			Greyb	rook Mill; {Black Mill}
County	Offaly	Townland T	onlemone			Town
Planning	Offaly CC	Discovery ma	ap 53			Six-inch map 22
Summary	Traces of 18	3th/early 19th centu	ry water-pov	wered	flour mill a	and kiln on Little River.
History	A flour mill and kiln are cited on the 1838 and 1884 OS six-inch maps. The 1840s Mill Valuation book records it as an oat mill under Dennis Doorley. A 15ft 6in x 3ft 10in waterwheel drove two sets of stones. The 1854 Griffith Valuation notes John Doorley as owner. The house, a herd's house and the corn mill were rated at £15. Cited as "Gaybrook Mill (corn)" on 1909 OS map. According to owner, the mill worked until destroyed by fire in 1934.				ey. A 15ft 6in x 3ft 10in lation notes John Doorley rated at £15. Cited as	
Component	OFIAR-022-	-017 1				
Туре	Grain kiln; G	Grain mill (water)	Fun	ction	Grain mi	lling
Category	Food proces	ssing & products	Con	text	Industry	
Irish Grid	206768 217	7311 +/- 10m				
Survey date	25/06/2003	Survey	or Fre	d Han	nond	
Building	Remains T	races	Condition	Fair	Use	Disused
Waterworks	Remains T	races	Condition	Fair	Use	Disused
Plant	Remains N	lo visible remains	Condition	N/A	Use	N/A
Machinery	Remains T	races	Condition	Fair	Use	Disused
Description	Buildings	our mill and kiln on	loft bank of	l ittla [Divor alon	a south side of road

Traces of flour mill and kiln on left bank of Little River, along south side of road opposite farmhouse. Aligned east-west, this mill has been reduced almost to foundation level and its north wall has been removed completely. Surviving walls of random rubble construction. At east end is two-storey/single-bay store with pitched corrugated metal roof, random rubble walls (heightened in concrete), and brick-trimmed square-headed openings. No obvious evidence of the kiln.

Waterworks, plant and machinery

Infilled internal waterwheel pit on west gable. Pond, head and tailraces also infilled except for a short length of headrace just above wheelpit.

Four millstone fragments built into/ set against walls. On west gable are: (1) half of a granite centrepiece to a French burr runner, and (2) segments from a 1.37m (4ft 6in) dia burr. At the east end of the south wall are: (3) the gritstone centrepiece of a burr runner, and (4) the other half of item 1.

Opposite is a one-storey/six bay house and two-storey outbuilding, the openings of which are attractively trimmed in yellow brick.

Interest	None

Evaluation Although the two-storey outbuilding on the opposite side of the road is a Protected

Structure in the Co Offaly Development Plan 2009-15 (number 30-29), the actual mill

remains are of no special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Cloghan History Committee. A History of Cloghan Parish (1988).

Page(s) 30

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills of Ireland c.1850 (Dublin, 2000).

Page(s)

OFIAR-022-017_01 FWH 25/06/2003 Remains of mill from north-east.



OFIAR-022-017_02 FWH 25/06/2003 Mill remains (at background left), from south-east.



OFIAR-022-017_03 FWH 25/06/2003 Millstone fragments on west gable.



$OFIAR-022-017_04 \quad FWH \quad 25/06/2003 \qquad \text{Farmyard outbuilding on opposite side of road}.$



Site no OFIAR-022-020 **Dooley's Mill** County Offaly Townland Moystown Demesne Town **Planning** Offaly CC **Discovery map** 47 Six-inch map 22 Summary Derelict shell of 18th/early 19th century water-powered flour mill and kiln on River Brosna. Also remains of head and tail races. Cited as a flour mill on the 1838 and 1885 OS maps. A flour mill is cited in 1840s Mill **History** Valuation book belonging to Peter Callaghan. A 16ft 6in x 10ft wheel drove two sets of stones. The 1854 Griffith Valuation notes John Dooly as occupant of flour mill: it and the kiln rated at £30. A roofless shell is shown on the 1909 map.

Component OFIAR-022-020 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 204620 220933 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused Waterworks Remains Some remains Condition Poor Use Disused Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Ruinous shell of a flour mill and kiln on right bank of River Brosna just downstream from road bridge.

Buildings

The mill is $4\frac{1}{2}$ storeys high and of L plan. Its main section is five bays wide and is aligned approximately north-south. The return, also $4\frac{1}{2}$ storeys high, is at the north end of its west side. Hipped roofs are missing. Chimney to gable of return. Rendered random rubble walls with advanced dressed stone eaves; severely cracked in places. Square-headed openings with brick heads. Some finely dressed stone cills survive to the windows. The angle between the main block and return is infilled with a $4\frac{1}{2}$ storey/two-bay extension, detailed as main block. All floors removed internally. The mill's north gable is abutted by a two-storey/single-bay kiln. Pitched roof missing. Random rubble walls with brick eaves. Drying floor removed, but vestiges of brick vaulting survive.

Waterworks, plant and machinery

The partly infilled head and tail races are still evident in the vicinity of the mill. All vestiges of the waterworks above the bridge, including the weir, are gone. An external waterwheel pit is evident on the mill's south gable. It is lined with squared rubble masonry and is 3.1m (10ft) wide. The wheel was probably of the low breastshot paddle variety. No machinery survives.

Interest Architectural; Setting

Evaluation Architecturally, this building is typical of later 18th/earlier 19th century purpose-built

flour mills. The number and regularity of the openings on its principal elevations are typical of such mills. It is also an imposing landscape feature and visible from the

main road. Unfortunately it is too incomplete to be more than of local industrial heritage merit.

Rating Local Protection Action

Associated with

Other dbase

References

Garner, W. Churches and Houses of Architectural Interest in Co Offaly (Tullamore: Offaly Historical Society, 1985).

Page(s) 44

Ryan, B. A Land by the River of God: a History of Ferbane Parish from Earliest Times to c.1900 (Ferbane, 1994).

Page(s) 239

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills of Ireland c.1850 (Dublin, 2000).

Page(s)

OFIAR-022-020_01 FWH 24/06/2003 East elevation of mill.



OFIAR-022-020_02 FWH 24/06/2003 West elevation of mill.



OFIAR-022-020_03 FWH 24/06/2003 Remains of brick vaulting in kiln.



Site no	OFIAR-022-021
Site no	UTIAK-UZZ-UZ I

County Planning	Offaly Offaly CC	Townland Moystown Demesne Discovery map 47	Town Six-inch map 22
Summary	Site of 18th/ea Brosna.	arly 19th century water-powered flax and	d corn mills and kiln on River
History	A flax mill and a flour mill are cited in the same building on 1838 OS six-inch map. However, it is a flour mill and a corn mill which are cited in 1840s Mill Valuation book, both belonging to G.B. L'Estrange. The 1854 Griffith Valuation notes Beresford L'Estrange as occupant of corn mill (no mention of flax mill). The corn mill, kiln and ancillary buildings were rated at £13.10s.0d. Cited as a flour mill in the 1885 OS map, but uncaptioned on the 1909 edition.		

Component OFIAR-022-021 1

Type Flax mill (water); Grain kiln; Grain Function Flax & linen; Grain milling

mill (water)

Category Textile manufacture & products; Context Industry

Food processing & products

Irish Grid 204199 220677 +/- 10m

Survey date 24/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains Traces Condition Fair Use Disused

Description Site of grain mill, kiln and flax mill on right bank of River Brosna, south east of

Moystown House. Three millstones survive in a field bank in the vicinity of the mill site: (1) a one-piece gritstone runner, complete with cast-iron stone spindle, 5ft 3in dia x 12in thick; (2) a one-piece grit bedstone, 5ft 3in dia x 10in thick; (3) a one-piece conglomerate bedstone, 5ft 6in dia x 8in thick. These are presumed to come from the

grain mill.

Interest None

Evaluation The millstones are of no special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

OFIAR-022-021_01 FWH 24/06/2003 Millstones in field bank close for former mill site.



Site no	OFIAR-022-028			
County	Offaly Townland Lumcloon Town			
Planning	Offaly CC Discovery map 54 Six-inch map 22			
Summary	Unlocated watermill cited in 17th century documentation.			
History	Settlement and associated watermill cited in 17th century document in Lumcloon townland.			
Component	OFIAR-022-028 1			
Туре	Mill (water) Function Unknown			
Category	Unknown Context Industry			
Irish Grid	212390 218982 +/- 1000m			
Survey date	Surveyor Fred Hamond			
Building	Remains No visible remains Condition N/A Use N/A			
Waterworks	Remains No visible remains Condition N/A Use N/A			
Plant	Remains No visible remains Condition N/A Use N/A			
Machinery	Remains No visible remains Condition N/A Use N/A			
Description	Not surveyed in detail.			
-				
Interest	Archaeological			
Evaluation	Although of some archaeological interest, the lack of upstanding remains makes this site of no special industrial heritage interest.			
Rating	Record only Protection Action			

Associated with

Other dbase SMR OF022-02703-

References

Archaeological Survey of Ireland record.

Page(s)

Site no	OFIAR-023-007			Millbrook Mill
County	Offaly	Townland Lumcl	oon	Town
Planning	Offaly CC	Discovery map	54	Six-inch map 23
Summary	Site of 18th/early 19th century water-powered flour mill on Silver River. In use as a school by 1885.			
History	Noted as Millbrook flour mill on 1838 OS six-inch map. Cited in 1840s Mill Valuation book as belonging to Bernard Callaghan. A 14ft x 3ft 5in wheel drove two sets of stones. The 1854 Griffith Valuation notes occupant as Peter Callaghan. Two houses, offices and the corn mill were rated at £18. The mill was in use as a school by time of 1885 OS map. A roofless shell is shown on the 1910 map.			
Component	OFIAR-023-007 1			
Type	Grain mill (wate	r)	Function	Grain milling

Context

Industry

Irish Grid 213771 219296 +/- 10m

Survey date 12/06/2003 Surveyor Fred Hamond

Food processing & products

Building Remains No visible remains Condition N/A Use N/A Waterworks Condition N/A Use N/A Remains No visible remains Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of flour mill on Silver River, east of Millbrook Road. This area is now within the

grounds to the former Ferbane power station.

Interest None

Category

Evaluation No industrial heritage signficance.

Rating Record only Protection Action

Associated with

Other dbase

References

Site no	OFIAR-024-004
---------	---------------

County Planning	Offaly Offaly CC	Townland Killui	rin 54	Town Six-inch map 24
Summary	Site of 18th/ear	ly 19th century wate	er-powered corn mill on tri	ibutary of Clodiagh River.
History	corn mill is note 6in x 4ft waterw	ed in 1840s Mill Valu heel drove two sets pant. House, offices	nch map, along with and a uation book as belonging t s of stones. The 1854 Grif s, corn mill rated at £6. Un	to George Carroll. A 13ft

Component OFIAR-024-004 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 229876 219029 +/- 10m

Survey date 12/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill on tributary of Clodiagh River, NE of Killurin House. The land has

been extensively reclaimed and no traces survive.

Interest None

Evaluation No industrial heritage signficance.

Rating Record only Protection Action

Associated with

Other dbase

References

Site no	OFIAR-024-0	009	
County	Offaly	Townland Derrymore (Ballyboy By)	Town
Planning	Offaly CC	Discovery map 48	Six-inch map 24
Summary	Site of 18th/ear	y 19th century water-powered corn mill on tr	ibutary of River Brosna.
History		ed on 1838 and 1884 OS six-inch maps. The ation book under Thomas Finamore and had	

by a 14ft 6in by 6ft waterwheel. In 1854, the occupant was Wilbert Fenamore (Griffith Valuation). The corn mill and offices were rated at £3.15s.0d. Shown as a roofless

Component OFIAR-024-009 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 222207 220304 +/- 10m

shell on 1910 OS map.

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A

Waterworks Remains Traces Condition Poor Use Disused

Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill on tributary of River Brosna, a short distance north of minor road and

just beyond a derelict farmhouse. The headrace is mostly infilled, but the overgrown

tailrace is still discernible.

Interest None

Evaluation No industrial heritage signficance.

Rating Record only Protection Action

Associated with

Other dbase

References

Site no	OFIAR-024-013
OILE IIU	OI IAIN-024-013

County Offaly Townland Cully Town

Planning Offaly CC Discovery map 48 Six-inch map 24

Summary Unlocated mill cited in 1655 Down Survey.

History Mill of unknown function cited in Cully townland in 1655 Down Survey.

Component OFIAR-024-013 1

Type Mill Function Unknown

Category Unknown Context Industry

Irish Grid 223454 221416 +/- 1000m

Survey date 10/06/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains No visible remains Condition N/A Use N/A Condition N/A **Plant** Remains No visible remains Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Unlocated mill site in Cully townland.

Interest Archaeological

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase SMR OF024-050---

References

Archaeological Survey of Ireland record. Page(s)

See OFIAR-016-051 Page(s)

Site no	OFIAR-025-005
SITA NA	()
	OI IAIN-UZU-UUU

County Planning	Offaly Offaly CC	Townland Millb	orook 54	Town Six-inch map 25
Summary	Derelict overgrown remains of 18th/early 19th century water-powered corn mill on tributary of Clodiagh River.			
History	Mill Valuation drove two sets	book as belonging to s of stones. The 1854	Robert Ta 4 Griffith Va	maps. The corn mill is noted in 1840s rleton. A 15ft x 3ft 11in waterwheel aluation book notes John Conroy as y cited on 1909 OS map.

Component OFIAR-025-005 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 237013 218614 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Poor Use Disused Use Disused Waterworks Remains Traces Condition Poor **Plant** Remains No visible remains Use N/A Condition N/A Machinery Remains Traces Condition Poor Use Disused

Description Buildings

Derelict overgrown remains of corn mill on right bank of tributary of Clodiagh River, behind house on east side of road. Aligned east-west, only the north and east walls of this 2½ storey mill survive. Of random rubble construction with square-headed openings. Foundations of small seed house abut at south.

Waterworks, plant and machinery

The pond and headrace have been infilled, but the dry tailrace is still visible. Waterwheel pit 1.3m (4ft 3in) wide on east gable; score marks on wall suggest that 4.57-4.88m (15-16ft) diameter and high breastshot. Inside is a one-piece shelling stone and fragments of a worn 1.52m (5ft) dia bedstone.

Interest None

Evaluation No special industrial heritage significance.

Rating Local Protection Action

Associated with

Other dbase

References

 $OFIAR-025-005_01 \quad FWH \quad 11/06/2003 \qquad Overgrown \ mill \ from \ south-east.$



OFIAR-025-005_02 FWH 11/06/2003 Fragment of shelling stone.



Site no	OFIAR-025-007
Site no	OFIAR-023-001

County	Offaly	Townland Killeigh	Town Killeigh
Planning	Offaly CC	Discovery map 54	Six-inch map 25

Summary 18th/early 19th century brewery.

History Noted as brewery on 1838 OS six-inch map only. Buildings shown on 1884 and 1909

maps.

Component OFIAR-025-007 1

Type Brewery Function Brewing

Category Drink processing & products Context Industry

Irish Grid 236811 218273 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Fair Use Agricultural building

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description A two-storey building of L plan on corner with main road possibly relates to the former

brewery. Pitched natural slate roof and rendered random rubble walls with advanced eaves. Original openings have brick trim, but have been infilled and rendered over. There is a single square-headed 3/6 sash window to the first floor of the north

elevation.

Continues east along main road as a one-storey range of buildings which form part of

an extensive farmyard complex. Adjoined by a two-storey/three-bay dwelling,

probably of mid/later 19th century date.

Interest Historical; Setting

Evaluation The outbuildings are of historical interest and occupy a prominent location in the

centre of the village. They are of local industrial heritage significance. The

outbuildings and adjacent two-storey house are Protected Structures.

Rating Local Protection Offaly RPS 34-06; Action

Offaly RPS 34-07

Associated with

Other dbase NIAH 14813006 (R); NIAH 14813007 (R)

References

OFIAR-025-007_01 FWH 11/06/2003 General view from north-west.



 $\label{eq:ofine_optimize} \mbox{OFIAR-025-007_02} \quad \mbox{FWH} \quad \mbox{11/06/2003} \quad \mbox{ View from west. Presumed brewery is at left.}$



Site no	OFIAR-025-009

Offaly

County

Planning	Offaly CC	Discovery map	48	Six-inch map 25

Summary Site of 18th/early 19th century water-powered corn mill on tributary of Toberfin River.

Townland Newtown (Geashill By)

Town

History A corn mill is cited on the 1838 and 1884 OS six-inch maps. The corn mill is recorded in 1840s Mill Valuation book as being operated by Francis Sadler. A 14ft x 4ft 6in waterwheel drove two sets of stones. In 1854, it was operated by Bartholomew Yarr.

The house, office and corn mill were rated at £7.10s.0d. Yarr also operated another corn mill (OFIAR-018-026) at this time as well. No building shown on 1909 map.

Component OFIAR-025-009 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 240454 220764 +/- 10m

Survey date 11/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill on tributary of Toberfin River, just south of minor road.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-018-026

Other dbase

References

Site no	OFIAR-025-014
SHE HO	UFIAR-0/3-014

County Planning	Offaly Offaly CC	Townland Killeenmore Discovery map 48	Town Six-inch map 25		
Summary	Substantial remains of 18th/early 19th century water-powered grain mill on tributary of Toberfin River, now converted into holiday accommodation.				
History	book as a cor two sets of sto	mill on 1838 OS six-inch map. Desc n mill belonging to Thomas Grogan. ones. Michael Casey owned the pren fices, corn mill were rated at £7. Pro	An 11ft x 2ft 3in waterwheel drove nises in 1854 (Griffith Valuation).		

Component OFIAR-025-014 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

explicitly cited on the OS map of this date.

Irish Grid 237532 220793 +/- 10m

Survey date 17/07/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Good Use Dwelling Waterworks Remains Traces Condition Poor Use Disused.

Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description A two-storey former corn mill aligned east-west with modern two-storey extension to

west; refurbished as holiday accommodation. Pitched cement-tile roof with new chimneys and plastic rainwater goods. Original section has random rubble walls; extension finished in harled cement. Square-headed window openings are mostly new insertions, with modern doors and uPVC windows. Small 1½ storey mill house with rear extensions on roadside.

According to owner, the waterwheel pit was on the west gable of the mill, but has been subsumed in the modern extension. No trace of mill pond to south of mill. Traces of bypass channel survives, but head and tailraces have been infilled.

Interest Historical

Evaluation Essentially only the shell of the original mill building survives, the character of which

has been compromised somewhat by the detailing of the new insertions. Now of no

special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

 $OFIAR-025-014_01 \quad FWH \quad 17/07/2003 \qquad General \ view \ of \ mill \ (at \ left), \ from \ north.$



Site no	OFIAR-026-	015	Bogtown M	Mill; Fennel's Mill; Connor's Mi	
County	Offaly	Townland B	ogtown	Town	
Planning	Offaly CC	Discovery ma	ap 54	Six-inch map 26	
Summary	Site of 18th/ea	rly 19th century v	water-powered o	corn mill and kiln on Ennie River.	
History	A corn mill and kiln are cited on the 1838, 1885 and 1910 OS six-inch maps. According to 1840s Mill Valuation book, the corn mill was operated by Thomas and Mark Connor. A 14ft x 3ft waterwheel drove one set of stones. It is not valued, suggesting a very small enterprise. Thomas Connor worked the mill in 1851 (Griffith Valuation). The house, offices and corn mill were rated at £6 - again reflecting a very small concern. A Thomas Connor was also operating a corn mill elsewhere in the county at the same time (OFIAR-005-001), but whether they are the same person is uncertain. The mill continued in use until 1935, a drainage scheme on River Barrow having cut off the water supply.				
Component	OFIAR-026-01	5 1			
Type	Grain kiln; Gra	in mill (water)	Function	n Grain milling	
Category	Food processir	ng & products	Context	t Industry	
Irish Grid	249641 21631	8 +/- 10m			
Survey date	13/06/2003	Survey	or Fred Ha	lamond	
Building	Remains No	visible remains	Condition N/A	'A Use N/A	

Description Site of corn mill and kiln on Ennie River, on east side of minor road at junction.

Condition N/A

Condition N/A

Condition N/A

Use N/A

Use N/A

Use N/A

Interest None

Waterworks

Machinery

Plant

Evaluation No industrial heritage significance.

Remains No visible remains

Remains No visible remains

Remains No visible remains

Rating Record only Protection Action

Associated with OFIAR-005-001?

Other dbase

References

Goode, P.J. Cloneygowan and District: History, Heritage and People of a

Page(s) 34

Midlands Village (2002).

014	OFIAD 000 044	
Site no	OFIAR-026-016	j

County	Offaly	Townland Enag	ghan	Town
Planning	Offaly CC	Discovery map	54	Six-inch map 26
Summary	Site of 18th/ear River.	rly 19th century wate	er-powered corn mill, kilı	n and tuck mill on Cushina
History	the 1840s Mill Milner. The cortuck mill, which "Mills" and a kil William Millner	Valuation book as a in mill had a 13ft 6in is not explicitly cite In are also recorded ; rated at £8. This su	corn mill and tuck mill o	o two sets of stones. The a 12ft x 2ft 10in wheel. uation as belonging to vere still operating.

Component OFIAR-026-016 1

Type Grain kiln; Grain mill (water); Tuck Function Grain milling; Wool

mill (water)

Category Food processing & products; Context Industry

Textile manufacture & products

Irish Grid 251257 218229 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Remains No visible remains Condition N/A Use N/A Machinery

Description Site of water-powered corn mill, kiln and tuck mill on Cushina River, behind

farmhouse off minor secondary road. The water table hereabouts may have been

affected by Bord na Mona peat working activities.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Site no	OFIAR-	026-017				Wyre's Mill; {Mill of Down}
County	Offaly	Townlar	nd (Gorteenard		Town
Planning	Offaly CC	Discove	ry m	ap 54		Six-inch map 26
Summary		th/early 19th cer Inquisition of 10				rn mill on Ennie River. A mill is cited wn Survey.
History	A mill is cited here in an Inquisition of 1617 and in the 1655 Down Survey. It successor is cited on 1838, 1885 and 1910 OS six-inch maps. A corn mill is noted in 1840s Mill Valuation book as belonging to Daniel Wire. A 12ft x 2ft 6in waterwheel drove a single pair of stones. The 1851 Griffith Valuation notes the same occupant. The house, offices and corn mill were rated at £31.					
Component	OFIAR-02	26-017 1				
Туре	Grain mill	(water)		Fu	nction	Grain milling
Category	Food prod	essing & produc	ts	Co	ntext	Industry
Irish Grid	245684 2	217153 +/- 10	m			
Survey date	13/06/200	3 S	urve	yor Fı	ed Han	nond
Building	Remains	No visible rema	ains	Condition	n N/A	Use N/A
Waterworks	Remains	No visible rema	ains	Condition	n N/A	Use N/A
Plant	Remains	No visible rema	ains	Condition	n N/A	Use N/A
Machinery	Remains	No visible rema	ains	Condition	n N/A	Use N/A
Description	Site of corn mill on Ennie River, north of minor road.					
Interest	Archaeolo	ogical				
Evaluation	document	s. For this reaso	n it i	s on the Re	cord of	peing cited in 17th century Monuments and Places (OF026- idustrial heritage significance as

there are no above-ground remains.

Rating Protection RMP OF026-023---**Action** Record only

Associated with

Other dbase SMR OF026-023---

References

Archaeological Survey of Ireland record.

Page(s)

Goode, P.J. Cloneygowan and District: History, Heritage and People of a

Midlands Village (2002).

Page(s) 34

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills

Page(s)

of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-027-004
Site no	UFIAK-02/-004

County	Offaly	Townland Mill (Grove	Town	
Planning	Offaly CC	Discovery map	55	Six-inch map 27	
Summary	Site of 18th/early 19th century water-powered flour mill on Figile River.				
History	Cited as flour mill on 1838 and 1884 OS six-inch maps, and as corn mill on 1910 map. Cited in 1840s Mill Valuation book as belonging to Dennis Rynne. An 11ft x 2ft wheel drove 2 pairs of stones. The 1853 Griffith Valuation notes occupant at Maria				

Component OFIAR-027-004 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 260026 218531 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Byrne; corn mill and offices rated at £8.

Building Remains No visible remains Condition N/A Use N/A

Waterworks Remains Traces Condition Poor Use Disused

Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of flour mill on Figile River, west of minor road. Ground reclaimed for pasture.

Headrace on east side of road reused as field drain.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Site no OFIAR-027-005

County	Offaly	Townland Brac	knagh	Town
Planning	Offaly CC	Discovery map	55	Six-inch map 27
Summary	Site of 18th/early 19th century water-powered flour mill on Figile River. Superseded by late 19th/early 20th century smithy.			
History	book as belong Noted in 1853	ging to Simon Frezel	34 OS six-inch maps. Cite II. A 10ft x 2ft 10in wheel of being operated by John A	drove two sets of stones.

Component OFIAR-027-005 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 261207 217696 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A

Waterworks Remains Some remains Condition Poor Use Disused

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Site of flour mill on Figile River, on south side of minor road. Now occupied by

farmyard complex. A dried up water channel is visible along the west side of the

minor road to its south.

Component OFIAR-027-005 2

Type Smithy Function Agricultural engineering

Category Engineering Context Industry

Irish Grid 261207 217696 +/- 10m

Survey date Surveyor Fred Hamond

Building Remains Complete Condition Fair Use Disused Waterworks Remains N/A Condition N/A Use N/A

Plant Remains N/A Condition N/A Use N/A

Machinery Remains N/A Condition N/A Use N/A

Description Not surveyed in detail.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

References

Other dbase

0:1	OFIAD 000 000
Site no	OFIAR-029-008

County	Offaly	Iownland Cloghan Beg	Iown
Planning	Offaly CC	Discovery map 53	Six-inch map 29

Summary Shell of 18th century wind-powered corn mill on low rise to east of minor road.

History Although this windmill was undoubtedly erected in the 18th century, the 1838 OS sixinch map shows only a triangulation point at this location. However, it is explicitly

captioned as Old windmill on the 1885 and 1910 maps.

Component OFIAR-029-008 1

Type Grain mill (wind) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 198530 213054 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Shell of a four-storey former wind-powered corn mill on low rise to east of road. Walls

of cylindrical profile and random rubble construction; probably stands to near original height. It measures 6.4m (21ft) externally and has 76cm (2ft 6in) thick walls. Two opposite doorways to ground floor with collapsed heads. Two square-headed window openings to first and second floors; cap floor has no windows. Internal floors gone, but instep to first floor and socket holes to upper floors indicate their former position.

Interest Architectural; Rarity; Setting

Evaluation Compared to watermills, windmills are rare in Co Offaly; this is one of six attested

sites, and one of only two surviving windmills (the other is OFIAR-011-001). It is of some architectural interest, its cylindrical profile and rubble stone construction being typical of 18th century windmill construction. It is a prominent landmark hereabouts and is undoubtedly of regional heritage signifiance. Although the windmill is a Protected Structure in the Co Offaly Development Plan 2009-15, it also warrants

inclusion in the Record of Monuments & Places.

Rating Regional Protection Offaly RPS 39-43 Action RMP

Associated with

Other dbase NIAH 14929014 (R)

References

OFIAR-029-008_01 FWH 25/06/2003 General view from south.



OFIAR-029-008_02 FWH 25/06/2003 General view from north.



OFIAR-029-008_03 FWH 25/06/2003 Interior, showing floor beam sockets.



Site no	OFIAR-029-011	Banagher Distillery; Banagher Maltings;			
		Garrycastle Distillery			

County	Offaly	Townland	Garrycastle	Town

Discovery map

Summary

Planning

Offaly CC

Derelict traces of 18th/early 19th century water-powered grain mill on Rapemills River. Converted to a distillery in mid 1800s, of which traces also survive. From 1870s until present, the site has been used as a maltings. Now operated by Greencore Ltd.

53

Six-inch map 29

History

Cited as a corn mill, flour mill and kiln on the 1838 OS map. According to the 1840s Mill Valuation book, the site comprised an oat mill and a flour mill under William Armstrong. The oatmeal mill had two pairs of stones driven by an 18ft x 4ft waterwheel and is described as nearly new. The flour mill had a 30ft x 6ft wheel to two sets of stones, but the machinery was not in good repair. Along with the one at Tully Woollen Mill (OFIAR-002-014), this was the largest diameter wheel in the county at that time. The complex is described as a disused distillery in the 1854 Griffith Valuation book. This was probably in the former grain mill buildings. Although out of use, it still merited a £40 valuation.

In 1873, the Banagher Distillery Company was formed. F.A. Waller and Captain C.A. Armstrong (a relation of William Armstrong) were two of its directors. The company purchased the site from the Banagher Flax Company. At that time, the premises contained two waterwheels, a 35hp steam engine and six pairs of millstones. It is uncertain whether any flax processing actually took place during the ownership of the flax company (it may have been for storage, or never got off the ground). A massive new distillery was completed in 1875 but, although distilling began, the company when into liquidation in the same year. The liquidator carried on operations and in 1877 sold the premises to the Banagher Whiskey Distillery Co. This company met with little success and was wound up in 1881. At that time, the distillery had three stills with a total capacity of 43,000 gallons, greater than that of the established distilleries at Birr, Kilbeggan and Tullamore. The distillery was sold to Adam Scott, a wine merchant in 1884 and he continued operations under the name of the Banagher Distillery Co Ltd. It is this distillery which is cited on the 1885 OS map. However, his company was wound up in 1890 and its assets transferred to the Dublin City & Banagher Distilleries Ltd. This new venture seems to have run at a loss and was sold to the Whiskey Distillers Syndicate Ltd in 1897. They operated it for only two years and the distillery finally closed in 1899.

In 1903, Daniel E. Williams took over the maltings section of the distillery and, in 1914, the entire site. The 1910 OS map cites a malt house, filter beds and disused distillery. Williams appears to have also had an ancillary furniture works on the site, in the form of the Shannon Steam Cabinet and Chair Works.

In 1970s, Williams amalgamated with Messrs Waller to form the Williams Waller Group. The maltings were re-equipped and most of the original grain mill and distillery buildings were probably demolished at the same time. The group also operated the Crank Malt House in Banagher (OFIAR-021-011). Greencore Ltd took over operations in 1996 and operated under the name of Minch Malt. At the time of this survey, the maltings was producing 35,000 tons of malt per year.

[Because it was the smallest of the company's Irish maltings, economies of scale forced the site's eventual closure in 2005].

Component OFIAR-029-011 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 201525 213861 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description The maps suggest that the mill and kiln were aligned NE-SW along the north side of

the block at the NW corner of the site. No traces survive.

Component OFIAR-029-011 2

Type Grain store Function Grain milling

Category Food processing & products Context Industry

Irish Grid 201561 213861 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description This multi-bay, five-storey former grain store abutted the NE end of the former grain

mill. Pitched natural slate roof with raised stone verges and metal rainwater goods. Walls of random rubble with dressed stone eaves. Segmental brick-trimmed windows, all in filled. Abutting its east elevation is a two-storey annex with pitched natural slate roof and random rubble walls. This annex is partly abutted along its

north side by a brick buildings, now truncated to one storey.

Internally, the ground floor is of concrete and has plastered/painted walls. The first floor is supported on timber transoms with cast-iron supporting columns down the middle of the floor. The upper floors are disused.

Component OFIAR-029-011 3

Type Distillery (steam; water) Function Distilling

Category Drink processing & products Context Industry

Irish Grid 201500 213849 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Traces Condition Poor Use Disused

Waterworks Remains No visible remains Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Old photographs and maps show a number of massive buildings in the middle and

along the west side of the NW block, all distillery-related. Those in the middle of the block have been completely cleared and those along the west side have been reduced to single-storey shells. The remnant at the north end of the west elevation of the block is of squared limestone construction and has a wide brick-trimmed

segmental headed doorway (now infilled) to its west gable.

Component OFIAR-029-011 4

Type Malt kiln Function Distilling

Category Drink processing & products Context Industry

Irish Grid 201516 213828 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description At the south end of the west side of the NW block is a building reduced from three

storeys to one. Old photographs indicate that it was a kiln, probably for malting. It is

of brick with semicircular headed openings along its west elevation.

Component OFIAR-029-011 5

Type Grain store Function Grain milling

Category Food processing & products Context Industry

Irish Grid 201556 213824 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Fair Use Store Waterworks Remains N/A Condition N/A Use N/A Condition N/A **Plant** Remains N/A Use N/A Machinery Remains N/A Condition N/A Use N/A

Description A two-storey building aligned NE-SW along the south side of the NW block. OS maps

suggest that it was probably contemporary with the former grain mills. Pitched natural slate roof, two brick chimneys to north elevation, and metal rainwater goods. Walls are painted and rendered. Square-headed openings. Partly in use as a store.

Component OFIAR-029-011 6

Type Distillery office Function Distilling

Category Drink processing & products Context Industry

Irish Grid 201567 213840 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Fair Use Factory canteen

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A
Use N/A

Description A two-storey, five-bay building, possibly once used as offices for the former distillery.

Aligned north-south along east side of NW block. Pitched artificial slate roof with two brick chimneys and plastic rainwater goods. Brick walls, rendered to the ground floor of the east elevation. Square-headed openings. Windows are 1/1 sliding sash (some replaced with plastic frames), with stone cills. Common cill course to first floor. Now

used as staff canteen.

Component OFIAR-029-011 7

Type Malt kiln Function Distilling

Category Drink processing & products Context Industry

Irish Grid 201596 213796 +/- 10m

Fred Hamond Survey date 25/06/2003 Surveyor

Condition Fair Use Disused Building Remains Some remains

Waterworks Remains N/A Condition N/A Use N/A Plant Remains N/A Condition N/A Use N/A Machinery Remains N/A Condition N/A Use N/A

Description Of the original maltings complex which formerly comprised the block at the SE corner

of the site, only a three-storey malt kiln survives. Hipped natural slate roof with boarded eaves and plastic rainwater goods. Vestiges of a ventilator at south end of roof ridge. Brick walls, partly rendered. All openings infilled and abutting buildings

demolished.

Component OFIAR-029-011 8

Malt house Function Type Malting

Industry Category Drink processing & products Context

Irish Grid 201618 213849 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Condition Good Building Remains Complete Use Maltings

Waterworks Remains N/A Condition N/A Use N/A

Plant Remains Substantial remains Condition Good Use Maltings

Machinery Remains Substantial remains Condition Good Use Maltings

Description Extensive complex of later 20th century maltings-related buildings occupies the

remainder of the site. Generally steel-framed multi-storey buildings clad in corrugated asbestos or metal sheeting. Also a number of silos, some of which occupy the infilled former mill pond. Not inspected in detail. A dressed limestone plaque embedded in a concrete plinth near the reception block details the foundation of the Banagher

Distilling Co in 1873 and itemises its board of directors and contractors involved with

the distillery's construction.

Interest Technical

The industrial heritage significance of this once very extensive complex has been **Evaluation**

> greatly reduced through the demolition of most of its principal buildings. Although the modern malting equipment is of some tehcnical interest, the complex is now only of

local interest in respect of its 19th and earlier 20th century remains.

Action Rating Local **Protection**

Associated with OFIAR-021-011

Other dbase

References

Byrne, M. The Banagher Distillery: Part 1. In Offaly Independent, 20 June Page(s) 1992.

Byrne, M. The Banagher Distillery: Part 2. In Offaly Independent, 3 July Page(s)

1992.

Midland Tribune, 25 Jan 1991. Page(s)

Midland Tribune, 9 April 1994. Page(s)

Photographic Collection in Local Studies section of Offaly County Library Page(s) Photo 526, Headquarters, Tullamore. 540

Trodd, V. Banagher on the Shannon: a Historical Guide to the Town (1985). Page(s) 27

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s)

of Ireland c.1850 (Dublin, 2000).

Wright, J. Offaly One Hundred Years Ago (Tullamore: Esker Press, 1989. Page(s) 106 First published 1890 by the King's County Directory).

OFIAR-029-011_01 FWH 25/06/2003 General view of complex from west.



OFIAR-029-011_02 FWH 25/06/2003 Grain mill store (component 2, left) and former office (component 6, right), from SW.



OFIAR-029-011_03 FWH 25/06/2003 Ground floor of grain mill store (component 2).



OFIAR-029-011_04 FWH 25/06/2003 Distillery building (component 3, left) and malt kiln (component 4, right), from west.



OFIAR-029-011_05 FWH 25/06/2003 Grain store (component 5), from south.



OFIAR-029-011_06 FWH 25/06/2003 Malt kiln (component 6), from SE.



OFIAR-029-011_07 FWH 25/06/2003 Modern malting complex, from east.



OFIAR-029-011_08 FWH 25/06/2003 1873 commemorative plaque.



Site no	OFIAR-029-015				Dolan's Mill		
County	Offaly	Townland	Lavagh			Town	
Planning	Offaly CC	Discovery m	1ap 53		:	Six-inch ma	ip 29
Summary		Site of 18th/early 19th century water-powered corn mill on River Shannon. Originally said to have been a tuck mill.					
History	A flour mill is cited in the 1838 and 1885 OS six-inch maps. Reputedly a tuck mill originally. The 1840s Mill Valuation book notes that it had not worked for some years. Its operator at that time was Timothy Killeen and a 12ft x 3ft 8in waterwheel drove three sets of stones. The 1854 Griffith Valuation notes the occupant at Richard Scott and it was rated at £18 (suggesting back in use). Not shown on 1910 map.						
Component	OFIAR-029-015 1						
Туре	Grain mill (wate	er); Tuck mill (w	vater) Fur	nction	Grain millin	g; Wool	
Category	Food processing & products; Context Industry Textile manufacture & products						
Irish Grid	196152 21425	6 +/- 10m					
Survey date	25/06/2003	Surve	yor Fre	ed Hamo	ond		
Building	Remains No v	isible remains	Condition	N/A	Use N/	'A	
Waterworks	Remains Som	e remains	Condition	Poor	Use Di	sused	
Plant	Remains No v	isible remains	Condition	N/A	Use N/	'A	
Machinery	Remains No v	isible remains	Condition	N/A	Use N/	'A	
Description	Site of flour mill (and possibly also a tuck mill) on left bank of River Shannon just west of Kilscragh Bridge. Wide head- and tail races still evident in vicinity of mill, both partly stone-lined. One wall of the waterwheel pit also survives.						
Interest	None						_
Evaluation	No industrial he	eritage significa	nce.				
Rating	Record only Protection Action						
Associated with							
Other dbase							
References Bracken, R. Dolan's Mill. In The Lusmagh Herb: the Annals of a Country Parish (1982).					11		
	Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 75 of Ireland c.1850 (Dublin, 2000).					75	
	lan, M. The old canal. In The Lusmagh Herb: the Annals of a Country Page(s) 30						

Site no	OFIAR-030-002				
County	Offaly	Townland Millto	wn (Garrycas	le By) Town	
Planning	Offaly CC	Discovery map	53	Six-inc	h map 30
Summary	Townland name implies former presence of mill. Probably site of 17th/18th century water-powered corn mill on tributary of Rapemills River.				
History	•		•	ation books, so prob subsequent OS six-	
Component	OFIAR-030-002	: 1			
Туре	Mill (water)		Function	Unknown	

Category Unknown Context Industry

Irish Grid 203169 212122 +/- 100m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A
Waterworks Remains No visible remains Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description No evident traces of former mill on tributary of Rapemills River, in vicinity of Milltown

House. Precise location could not be determined, but probably in vicinity of former

pond on river.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 76 of Ireland c.1850 (Dublin, 2000).

Site no OFIAR-030

County Planning	Offaly Offaly CC	Townland Balla	ghanoher 53	Town Six-inch map 30
Summary			er-powered corn mill, kiln	<u> </u>
	Rapemills Riv		si poworou com miii, kiiii	
History	A corn mill and rape mill & kiln are cited on 1838 and 1884 OS six-inch maps. Only the corn mill is noted in the 1840s Mill Valuation book, operated by W.F. Dillon. A 15ft x 3ft 11in waterwheel drove two sets of stone. The rape mill had apparently been destroyed by a meteorite in 1830s or '40s. The 1854 Griffith Valuation notes Frederick Dillon as owner. House, offices and mill rated at £25. No mills cited on 1909 OS map.			

Component OFIAR-030-003 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 204805 210205 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Condition N/A Remains No visible remains Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill on Rapemills River, along east side of main road.

Component OFIAR-030-003 2

Type Grain kiln; Oilseed mill (water) Function Grain milling; Oilseed milling

Category Food processing & products Context Industry

Irish Grid 204835 210209 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Condition N/A **Plant** Remains No visible remains Use N/A Remains No visible remains Condition N/A Use N/A Machinery

Description Site of rape mill and kiln on Rapemills River, in farmyard immediately east of road

bridge. A ruinous random rubble building at the east end of the yard may be

associated and would merit further investigation.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 75 of Ireland c.1850 (Dublin, 2000).

Wright, J. Offaly One Hundred Years Ago (Tullamore: Esker Press, 1989. Page(s) 96 First published 1890 by the King's County Directory).

0:4	OFIAD 000 004
Site no	OFIAR-030-004

County Planning	Offaly Offaly CC	Townland Bally	vnaguilsha 53	Town Six-inch map 30
Summary	Derelict overgrown remains of 18th/early 19th century water-powered corn mill and kiln on Rapemills River.			
History	Corn mill and kiln cited on 1838 OS six-inch map. The corn mill is noted in 1840s Mill Valuation book as belonging to Smith Berry. A 14ft x 5ft waterwheel drove three sets of stones. Berry owned the mill in 1854 (Griffith Valuation). The house, offices and corn mill were rated at £16. Not cited on 1884 OS map and only roofless partial shell shown on 1909 edition. May have been associated with a flour mill a short distance to north (OFIAR-030-008).			

Component OFIAR-030-004 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 209514 209760 +/- 10m

Survey date 27/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Poor Use Disused Waterworks Remains Some remains Condition Poor Use Disused Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Overgrown derelict remains of corn mill and kiln on left bank of Rapemills River, west

of Eglish Bridge. Aligned NE/SW. Only two walls survive, of random rubble with flat brick heads; may have been four storeys originally, but now reduced to three.

Waterwheel position not determinable. Tailrace still evident.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-030-008?

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 72 of Ireland c.1850 (Dublin, 2000).

OFIAR-030-004_01 FWH 27/06/2003 Mill remains from east.



-				
Site no	ΩF	IAR.	-ハマハ	-008

County	Offaly	Townland Eglish	Town	
Planning	Offaly CC	Discovery map 53	Six-inch map 30	
Summary	Remains of 18th/early 19th century water-powered flour mill on Rapemills River. Described in 1854 Valuation book as a bleach house.			
History	Flour mill cited on 1838 OS six-inch map, but not recorded in 1840s Mill Valuation book. Map suggest that waterwheel was internal. Noted as a vacant bleach house 1854 Griffith Valuation. Not explicitly cited on 1884 or 1909 OS maps. May have b associated with a corn mill at Irishtown House (OFIAR-030-004).		ternal. Noted as a vacant bleach house in on 1884 or 1909 OS maps. May have been	

Component OFIAR-030-008 1

Flax & linen; Grain milling Type Bleach works (water); Grain mill Function

(water)

Category Textile manufacture & products; Context Industry

Food processing & products

209547 209892 Irish Grid +/- 10m

Survey date 27/06/2003 Fred Hamond Surveyor

Building Remains Substantial remains Condition Poor Use Disused Use Disused Waterworks Remains Some remains Condition Poor

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Use N/A Condition N/A

Description Derelict two-storey/six-bay former mill, now in use as an animal byre. Aligned east-

west on right bank of river. Pitched corrugated metal replacement roof and random rubble walls. Square-headed openings with brick heads; timber louvers to first floor.

External stone steps to first floor door on west gable. Traces of head and tailraces.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only **Protection** Action

OFIAR-030-004? **Associated with**

Other dbase

References

OFIAR-030-008_01 FWH 27/06/2003 General view from south-west.



Site no OFIAR-031-005 Park Mill County Offaly **Townland** Park (Ballyboy By) Town Kilcormac **Planning** Offaly CC Discovery map 54 Six-inch map 31 **Summary** Derelict remains of disused 18th/early 19th century water-powered flour mill, kiln, store and dwelling overlooking Silver River at east end of Kilcormac. Mill converted to corn stores and a second kiln installed in late 19th/early 20th century.

History

A water-powered corn mill is shown on the 1838 and 1885 OS six-inch maps. According to the 1840s Mill Valuation book, the corn mill was operated by Robert Drought. It had a 16ft x 8ft waterwheel driving three sets of stones and ancillary equipment. Drought was still running the mill in 1854, when it was rated at £52.5s.0d (Griffith Valuation). By 1909, it had been converted into corn stores. Owned for a time by D. & E. Williams of Tullamore.

Component OFIAR-031-005 1

Function Type Grain kiln; Grain mill (water) Grain milling

Category Food processing & products Context Industry

Irish Grid 218722 214095 +/- 10m

Fred Hamond Survey date 01/08/2003 Surveyor

Use Disused Building Remains Substantial remains Condition Poor

Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A

Machinery Remains Traces Use Disused Condition Poor

Description

Derelict remains of 18th/early 19th century flour mill complex overlooking Silver River at east end of Kilcormac. The premises contains a mil and kiln, separate second kiln, and also a store and dwelling.

The mill is a five-storey/four-bay building aligned north-south with a five-storey kiln return at NE and a three-storey return at SE, all on the east side of the yard. The hipped roofs and rainwater goods to this block are missing. Random rubble walls with finely dressed stone eaves. Square-headed openings with brick heads and jambs. The windows are without cills and are of diminished height to the top floor. All internal floors have been removed.

The north wall of the three-storey return has largely collapsed. There is a doorway (now blocked) at first floor level on its east gable.

The five-storey return incorporates a four-floor kiln. On the ground floor is a furnace and electrically-powered hot-air fan. The warm air was ducted through the first floor into a screeded space underneath the drying floor at top. The latter has remains of 30cm (12in) perforated ceramic tiles on a metal sub-frame. A photograph of 1957 shows a pyramidal ventilator over the roof of this section. This kiln was probably inserted in the late 1800s when the mill was converted to a grain store. The upper floors are in a poor structural state.

The site is enclosed by a high random rubble wall, with an entrance to the main road. One of the original dressed stone gate piers survives. There is also an infilled entrance at the east end of the road boundary.

On the opposite side of the road, at the road junction just east of the bridge over the Silver River, is a one-piece conglomerate millstone runner measuring 1.37m (4ft 6in) in diameter. It may well have come from the mill.

Waterworks, plant and machinery

The head and tail races are long infilled. There was formerly an external waterwheel pit on the outside face of the south gable, also now infilled. A 2.74m (9ft) diameter cast-iron pit wheel survives insitu inside this gable. The axle connecting it to the former waterwheel has been removed.

Component OFIAR-031-005 2

Type Grain kiln Function Grain milling

Category Food processing & products Context Industry

Irish Grid 218692 214089 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A
Use N/A

Description On the west side of the yard is derelict two-storey/single-bay kiln aligned east-west.

Half-hipped natural slate roof. Raised open-sided pyramidal ventilator to ridge. Random rubble walls with square-headed openings. The east end of the roof formerly abutted the taller adjoining store (component 3); the upper floors of the latter have been removed, thus exposing this end of the kiln. The brick vaulting to the furnace

survives internally. The drying floor was inaccessible.

Component OFIAR-031-005 3

Type Grain store Function Grain milling

Category Food processing & products Context Industry

Irish Grid 218706 214082 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Good Use Workshop

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A
Condition N/A Use N/A

Description Abutting the east end of the kiln (component 2) and running south therefrom (ie

parallel with the mill) is a two-storey/five bay former store. It was originally four storeys high but has been truncated to its present form. Monopitched corrugated-metal roof spans to a slightly lower east elevation (originally half-hipped). Random rubble walls and finely dressed eaves (rebuilt on west side only). Two segmental brick-headed doorways at north end of east elevation, but otherwise square headed openings with brick heads and jambs. Vestiges of first and second floors survive

internally. Now used as a workshop.

Component OFIAR-031-005 4

Type Mill house Function Grain milling

Category Food processing & products Context Industry

Irish Grid 218706 214082 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Complete Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains Some remains Condition Poor Use Disused

Description At the NW corner of the premises is a derelict single-storey/two-bay former dwelling,

now derelict. Hipped natural slate roof, brick chimneys. Random rubble walls with square-headed openings. The north wall is also the street boundary to the site; two

windows to this elevation.

Interest Architectural; Historical; Setting

Evaluation Architecturally, this mill is of note in terms of its scale, massing, quality and

uniformity of its material, and detailing (e.g. brick trim to openings). The two kilns are also of architectural interest. The site is also of historical interest as a purpose-built flour mill, reflecting the importance of wheat growing in this locality in the late 18th/early 19th century. The complex is also a prominent landscape feature, particularly on the eastern approach to Kilcormac. Overall, the site is of regional significance and merits its inclusion as a Protected Structure in the Co Offaly

Development Plan 2009-15.

Rating Regional Protection Offaly RPS 41-14 Action None (in RPS)

Associated with

Other dbase NIAH 14815014 (R)

References

Kilcormac Historical Society. Kilcormac-Killoughey Parish Album (1996). Page(s) 9
Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 71
of Ireland c.1850 (Dublin, 2000).

OFIAR-031-005_01 FWH 12/06/2003 General view of complex from north-west. Note house and kiln in foreground.



OFIAR-031-005_02 FWH 12/06/2003 General view of complex from north.



OFIAR-031-005_03 FWH 12/06/2003 General view of complex from south-east.



OFIAR-031-005_04 FWH 12/06/2003 General view of complex from south-west.



OFIAR-031-005_05 FWH 12/06/2003 Mill from north.



OFIAR-031-005_06 FWH 01/08/2003 Mill, from south-west.



OFIAR-031-005_07 FWH 01/08/2003 Pit wheel at south end of mill.



 $OFIAR-031-005_08 \quad FWH \quad 01/08/2003 \quad \quad Looking up \ through \ floors \ of \ kiln \ in \ north-east \ corner \ of \ mill.$



 $OFIAR-031-005_09 \quad FWH \quad 01/08/2003 \qquad Furnace \ and \ fan \ on \ ground \ floor \ of \ kiln \ in \ mill.$



OFIAR-031-005_10 FWH 01/08/2003 Brick vaulting in kiln.



OFIAR-031-005_11 FWH 01/08/2003 Store, from south.



 $OFIAR-031-005_12 \quad FWH \quad 01/08/2003 \qquad Refurbished interior of store, to north.$



 $OFIAR-031-005_13 \quad FWH \quad 31/07/2003 \qquad \text{Millstone on opposite side of road}.$



Site no	OFIAR-031-007			Ballyboy Mill; I	-lanagan's Mill
County	Offaly	Townland Ballyb	oy (Ballyboy	By) Tow n	Ballyboy
Planning	Offaly CC	Discovery map	54	Six-ir	nch map 31
Summary	Remains of 18th/early 19th century water-powered three-storey flour and oat mill on Silver River. Also late 19th/early 20th century saw mill. Wall of mill incorporates carved head from medieval monastery.				
History	Noted as flour mill on 1838 and 1885 OS six-inch maps. According to the 1840s Mill Valuation book, the complex comprised a corn mill and flour mill under William Delany. The former had two sets of stones powered by a 14ft x 3ft 9in waterwheel. The latter also had two pairs of stones, driven off a 13ft 8in x 3ft wheel. The two mills were undoubtedly under the one roof. Delany was also operating nearby flour/tuck mills at Ballynacarrig (OFIAR-032-002). Delany was still running the two mills in 1854 (Griffith Valuation). A saw mill was operational by 1909 as the OS map cites corn and saw mills.			der William in waterwheel. eel. The two mills arby flour/tuck two mills in 1854	
Component	OFIAR-031-00)7 1			
Туре	Grain kiln; Gra	nin mill (water); Saw	Function	Grain milling; Tin	nber processing &

mill (water) products

Category Food processing & products; Context Industry

Timber processing & products

Irish Grid 220377 213983 +/- 10m

Survey date 12/06/2003 Surveyor Fred Hamond

Remains Substantial remains Condition Fair Use Store Building Waterworks Remains Substantial remains Condition Poor Use Disused

Plant Remains No visible remains Use N/A Condition N/A

Machinery Remains Traces Condition Fair Use Disused

Description A three-storey former mill on east side of road at north end of Ballyboy. The building

incorporates the mill, stores, kiln and saw mill in extension to rear.

Mill

A three-storey/three-bay mill, aligned north-south; now gutted and used as a store. Pitched natural slate roof. Half-round rainwater goods. Random rubble walls and dressed stone eaves. A carved head, said to be from a monastery at Letter, is built into the west wall at first floor level. Square-headed openings. Windows have metal frames.

Store

Contiguous with the mill's north gable is a derelict four-storey/four-bay store (probably one of the two mills cited in the 1840s Valuation). Hipped roof removed. Detailed as mill; some windows have brick jambs. At south end of west elevation is brick segmental-headed tailrace arch from internal waterwheel.

Kiln

Abutting rear of store's south end are the ruinous remains of former kiln. Unusually, it is built on a metal framework spanning the intake channel to the wheel. Traces of furnace, metal sub-floor and 30cm (12in) square perforated clay tiles. A three-storey store abuts to north, along east side of the store.

Saw mill

At the SE corner of the block is where the saw mill was probably located. It has a lean-to corrugated-metal roof. Powered by an overhead pulley train from inside the adjoining grain mill.

Waterworks, plant and machinery

The head- and tailraces are still evident east and west of the mill respectively. Inside the mill is a waterwheel pit with curved cast-iron sluice and two rack-and-pinion mechanisms. Its size and height relative to the headrace suggests that the wheel was of the low breastshot variety and measured c.4.57m diameter by 2.44m wide (15ft \times 8ft).

In the garden of the adjoining house is a one-piece conglomerate millstone with left-hand dress. There are also two cast-iron flax scutching rings (formerly with five handles apiece) lying against the mill's south gable. These may have belonged to a nearby flax scutching mill (OFIAR-031-019).

Interest Archaeological; Technical; Setting

Evaluation The kiln is somewhat unusual in being built over the waterwheel intake channel. The

complex is also a prominent landscape feature on the north approach to Ballyboy. The carving is of archaeological interest. As only the shell of the mill survives, its heritage significance is greatly diminished and it is now only of local heritage significance. It is a Protected Structure in the Co Offaly Development Plan 2009-15.

Rating Local Protection Offaly RPS 42-01 Action

Associated with OFIAR-032-002

Other dbase NIAH 14816001 (R)

References

Gill, J. Ballyboy: a Journey Through Time. Unpublished MS, Local Studies Page(s) 13 Section, Offaly County Library Headquarters, Tullamore.

Kilcormac Historical Society. Kilcormac-Killoughey Parish Album (1996). Page(s) 15

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-031-007_01 FWH 12/06/2003 General view of site from north-west.



OFIAR-031-007_02 FWH 12/06/2003 West elevation of mill.



OFIAR-031-007_03 FWH 12/06/2003 Carved head on west wall of mill (above window head).



OFIAR-031-007_04 FWH 12/06/2003 West elevation of store, from south-west. Note tailrace arch (boarded over).



 $OFIAR-031-007_05 \quad FWH \quad 12/06/2003 \qquad Waterwheel \ emplacement, \ looking \ to \ sluice \ gates.$





OFIAR-031-007_07 FWH 12/06/2003 Millstone in garden of mill house.



OFIAR-031-007_08 FWH 12/06/2003 Flax scutching rings against south gable of mill.



Site no	OFIAR-031	Manor Mill			
County	Offaly	Townland Ballyoran	Town		
Planning	Offaly CC	Discovery map 54	Six-inch map 31		
Summary	Ruinous shell of 18th/early 19th century water-powered flour mill on Silver River. Name suggests that it was possibly the site of a manorial mill.				
History	Cited as a flour mill on the 1838 OS six-inch map. Noted in the 1840s Mill Valuation book as a corn mill worked by William Delaney. It had a 12ft 6in x 4ft waterwheel				

driving two sets of stones. At the time of valuation, however, it had not been worked for the previous three or four years. It seems to have restarted as it was being operated by James Jackson in 1854 (Griffith Valuation). It is cited as a flour mill on

Component OFIAR-031-008 1

Type Grain kiln; Grain mill (water) Function Grain milling

the 1885 OS map, and as Manor Mill on the 1909 map.

Category Food processing & products Context Industry

Irish Grid 220925 214202 +/- 10m

Survey date 12/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused Waterworks Remains Traces Condition Poor Use Disused Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Ruinous shell of 18th/early 19th century flour mill on right bank of Silver River, a short distance east of Ballyboy.

Buildings

The mill is a 2½ storey building aligned north-south and is abutted at east by a one-storey store, at north by a 2½ storey store, and at NE by a two-storey kiln. All roofs are now gone. The walls are of random rubble with square headed openings. The store at east has brick trim and may therefore be a later addition. The base of the furnace survives inside the kiln, along with remains of the metal framework to the drying floor. No floor survive internally.

To the north of the mill complex is the shell of a two-storey/three-bay house which may be associated. Adjoined by farm outbuildings and all surrounded by a random rubble wall.

Waterworks, plant and machinery

Foundation traces of the weir survive, but the head- and tailraces have been infilled. There was formerly an external waterwheel on the mill's south gable. The waterwheel pit has dressed stone sides and is 2.13m (7ft) wide. The curvature of the back end of the pit indicates a wheel of 3.66-4.27m (12-14ft) diameter. A curved recess on the inside face of this pit suggests that a segment wheel was affixed to the waterwheel axle and drove the internal machinery via a bull nut. Traces of the sluice control mechanism survive. No machinery survives.

Evaluation Historically, this mill is of some interest in being the possible site of a manorial mill.

The present waterworks may date from a mid 19th century refurbishment of a

disused earlier mill. It is of local industrial heritage significance.

Rating Local Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-031-008_01 FWH 12/06/2003 General view from north (showing main store).



OFIAR-031-008_02 FWH 12/06/2003 Remains of kiln furnace and sub floor.



OFIAR-031-008_03 FWH 12/06/2003 Waterwheel pit on south gable; note curved recess on inside face of pit.



Site no	OFIAR-031-011
OILE IIO	

County Planning	Offaly Offaly CC	Townland Frankford Discovery map 54	Town Kilcormac Six-inch map 31		
Summary	Site of 18th/early 19th century water-powered brewery on Silver River.				
History	Brewery cited in 1838 OS six-inch map. Recorded in 1854 Griffith Valuation as being operated by Robert Mitchell; he also operated a nearby distillery at this time (OFIAR-031-012). Rated at £12. Probably out of use by 1880s as not explicitly cited on 1885 OS map. Not depicted on 1909 map.				

Component OFIAR-031-011 1

Type Brewery (water) Function Brewing

Category Drink processing & products Context Industry

Irish Grid 218107 214244 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A
Waterworks Remains No visible remains Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

Description Site of brewery on left bank of Silver River. A sewage treatment works now occupies

this site.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-031-012

Other dbase

References

Site no	OFIAR-031-	012	Kilcormac Maltings	
County	Offaly	Townland Frankford	Town Kilcormac	
Planning	Offaly CC	Discovery map 54	Six-inch map 31	
Summary	Site of 18th/early 19th century distillery on left bank of Silver River. Adjoined by disused mid 19th century maltings which survives virtually intact.			
History	Cited as a distillery on 1838 OS six-inch map. Recorded in 1854 Griffith Valuation as being operated by Robert Mitchell; he also operated a nearby brewery at this time as well (OFIAR-031-011). On the 1885 map, the distillery is a much smaller complex, not cited explicitly and probably disused. A sizeable maltings is shown on the 1885 and 1909 maps. During the 20th century, the site was owned by D.E. Williams (of Tullamore Dew fame), and then by Messrs Larkin, Maher & McCann until the 1970s. It has been used for domestic storage purposes since then.			

Component	OFIAR-031-012	1
-----------	---------------	---

Type Distillery Function Distilling

Category Drink processing & products Context Industry

Irish Grid 218198 214151 +/- 10m

Survey date 31/07/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Nothing remains of the distillery. Whitewell House lies adjacent and was formerly

known as Distillery House; it still occupied. Along the road to north is a high rubble

stone boundary wall.

Component OFIAR-031-012 2

Function Type Malt house; Malt kiln Malting

Drink processing & products Category Context Industry

Irish Grid 218221 214112 +/- 10m

Survey date Surveyor Fred Hamond 31/07/2004

Building Remains Complete Condition Fair Use Disused

Use N/A Waterworks Remains N/A Condition N/A

Condition N/A Plant Remains N/A Use N/A

Machinery Remains Traces Condition Poor Use Disused

Description A disused later 19th century four-storey/11-bay malt house aligned east-west;

comprises germinating floors and kiln at west end. Half-hipped natural slate roof surmounted by a sackhoist head and two kiln vents. Random rubble walls brought to courses. The kiln section has been tarred to improve insulation. All openings are square-headed and have stepped brick jambs. A corrugated-metal lean-to loading bay abuts the east end of the north elevation.

Internally, the walls are painted and plastered. The upper floors of the malting floors comprise cement-screeded timber boards over joists and beams. The roof is constructed of tied common rafters and the undersides of the slates are plastered. The ground floor of the kiln contains two furnaces. The warm air rose in a brick duct through the timber-lined first floor to a space underneath the drying floor and was dispersed through perforated ceramic tiles to the top floor. The ceiling above this floor is plastered to retain heat. Rain water is now penetrating the kiln area. A set of stairs and an electrically-powered sack hoist are located at the west end of the malting floors, next the kiln. There is also a malt barrow by R. Boby (Bury St

Edmunds).

Interest Architectural; Setting

Architecturally, the maltings are of interest in terms of their scale, quality of **Evaluation**

construction and internal configuration. Of the eight maltings recorded in Co Offaly, this is the only one to survive in an unaltered, reasonably sound state. Historically, it is also of interest as one of the few maltings in the county to lie outside the main distilling towns of Tullamore, Birr and Banagher. It is also a prominent local landmark and a reminder of the village's industrial past. It is of regional industrial heritage significance and merits its inclusion as a Protected Structure in the Co Offaly

Development Plan 2009-15.

Rating **Protection** Offaly RPS 41-04 Action None (in RPS) Regional

Associated with OFIAR-031-011

Other dbase NIAH 14815004 (R)

References

OFIAR-031-012_01 FWH 12/06/2004 General view from south.



OFIAR-031-012_02 FWH 12/06/2004 General view from north. Note kiln at right.



OFIAR-031-012_03 FWH 12/06/2004 Loading bay at east end of north elevation.



OFIAR-031-012_04 FWH 31/07/2003 Looking east across first floor of malting.



OFIAR-031-012_05 FWH 31/07/2003 Malt barrow.



OFIAR-031-012_06 FWH 31/07/2003 Looking east across top floor of malting.



OFIAR-031-012_07 FWH 31/07/2003 East end of top floor of malting.



 $OFIAR-031-012_08 \quad FWH \quad 31/07/2003 \qquad Electric sack \ ho ist \ at \ north-west \ end \ of \ top \ floor \ of \ mallting.$



OFIAR-031-012_09 FWH 31/07/2003 Furnaces at west on ground floor of kiln.



OFIAR-031-012_10 FWH 31/07/2003 First floor of kiln. Note timber-lined walls and brick duct (at left).



OFIAR-031-012_11 FWH 31/07/2003 Second floor of kiln. Note perforated tiles.



OFIAR-031-012_12 FWH 31/07/2003 Kiln drying floor, looking east.



OFIAR-031-012_13 FWH 31/07/2003 Deteriorated section of kiln ceiling.



OFIAR-031-012_14 FWH 12/06/2004 Rubble boundary wall along west side of site.



OFIAR-031-012_15 FWH 12/06/2004 Distillery House, from south-west.



Site no	OFIAR-031-013
Site IIO	OFIAK-USI-UIS

County Planning	Offaly Offaly CC	Townland Fran	kford 54	Town Kilcormac Six-inch map 31
Summary	Traces of 18th/early 19th century water-powered flour mill on Silver River. Also site of late 19th/early 20th century hydraulic ram supplying water to St Joseph's Laundry.			
History	A flour mill is cited on 1838 OS six-inch map. 1840s Mill Valuation book notes its owner as Charles Burris. A 15ft x 6ft 10in waterwheel drove two sets of stones. The mill was vacant in 1854 (Griffith Valuation). The house, offices, mill and stores were rated at £18. Not explicitly cited in later OS maps. Hydraulic rams captioned on 1909 OS 25-inch map.			

Component OFIAR-031-013 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 218353 214139 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains Traces Condition Fair Use Disused Waterworks Remains Some remains Condition Poor Use Disused Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Traces of flour mill on left bank of Silver River at Kilcormac. Comprises a truncated

random rubble wall aligned east-west parallel with river and section of east gable with segmental arch headrace intake. The headrace has been incorporated into a public park. A local development group intended to install a waterwheel inside the mill to generate electric lighting. A concrete waterwheel pit was inserted before the project

ran out of funds.

Component OFIAR-031-013 2

Type Hydraulic ram Function Water supply

Category Water supply & related processes Context Settlement

Irish Grid 218353 214139 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains N/A Condition N/A Use N/A

Waterworks Remains Some remains Condition Poor Use Disused

Plant Remains N/A Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description No traces survive.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 71 of Ireland c.1850 (Dublin, 2000).

OFIAR-031-013_01 FWH 13/06/2003 Mill remains from east.



Site no OFIAR-031-014

County	Offaly	Townland Kilna	ngall	Town
Planning	Offaly CC	Discovery map	54	Six-inch map 31
Summary				ed flour mill on Silver River. Also a kiln SE side of the road, opposite the flour
History	A flour mill, kiln and another mill of unknown function are cited on 1838 OS six-inch map. The 1840s Mill Valuation book notes a corn mill operated by Andrew Mooney. A 13ft x 2ft 4in waterwheel drove two sets of stones. Mooney also noted in 1854 Griffith Valuation. House, offices, corn mill and kiln then rated at £8. Although the same buildings are shown on the 1884 map, none is explicitly cited. Site cleared by 1909.			

Component OFIAR-031-014 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 217489 214816 +/- 10m

Survey date 12/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Use N/A Condition N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of flour mill on Silver River at Barnaboy Bridge. Located on right bank of river,

on NE side of road.

Component OFIAR-031-014 2

Type Grain kiln Function Grain milling

Category Food processing & products Context Industry

Irish Grid 217480 214799 +/- 10m

Survey date 12/06/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains N/A Condition N/A Use N/A Condition N/A Plant Remains N/A Use N/A Machinery Remains N/A Condition N/A Use N/A

Description Site of kiln on SW side of road, opposite flour mill.

Component OFIAR-031-014 3

Type Mill (water) Function Unknown

Category Unknown Context Industry

Irish Grid 217471 214807 +/- 10m

Survey date 12/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Use N/A Remains No visible remains Condition N/A Remains No visible remains Condition N/A Plant Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of mill of unknown function immediately downstream from Barnaboy Bridge, on

right bank of river.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

Site no OFIAR-031-019

CountyOffalyTownlandBallyboy (Ballyboy By)TownBallyboy

Planning Offaly CC Discovery map 54 Six-inch map 31

Summary Possible vestiges of 20th century flax scutching mill.

History Not explicitly cited on OS maps.

Component OFIAR-031-019 1

Type Flax mill? Function Flax & linen

Category Textile manufacture & products Context Industry

Irish Grid 220372 213856 +/- 10m

Survey date 12/06/2003 Surveyor Fred Hamond

Building Remains Traces Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

wachinery Remains No visible remains Condition N/A Use N/A

Truncated shell of former two-storey building said to have been a flax mill. Aligned north-south on east side of road. Random rubble walls, repointed in cement to road elevation. The openings to this elevation have also been infilled. No evidence of waterpower. Two scutching rings at Ballyboy Mill, a short distance to the north

(OFIAR-031-007) may have belonged to this mill.

Interest None

Description

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

OFIAR-031-019_01 FWH 12/06/2003 Mill remains from north-west.



0:4	OFIAD 004 000
Site no	OFIAR-031-020

County Planning	Offaly Offaly CC	Townland Curr	raghmore (Eglish By)	Town Six-inch map 31	
Summary	Remains of 18th/early 19th century water-powered corn mill and kiln on tributary of Silver River.				
History	book notes Al two sets of sto	oraham Whitfield as ones. Cited in 1854 Gifices and mill were ra	operator of corn mill. Briffith Valuation as be	nch map. 1840s Mill Valuation A 16ft x 5ft waterwheel drove elonging to Edward Warren. citly captioned on 1885 or	

Component OFIAR-031-020 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 215333 213277 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Condition Poor Use Disused Building Remains Some remains Remains Traces Waterworks Use Disused Condition Poor Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description

Overgrown derelict shell of corn mill on tributary of Silver River at Berana Cottage, north of Kilcormac-Birr road. Three-storey/three-bay building aligned east-west and of L plan. Random rubble walls (some not to full height) with brick eaves, and square-headed openings with brick trim. The waterwheel was probably on the west gable. The tailrace is still evident, running north from the building. To the south is the ruinous one-storey shel of IBerana Cottage.

Component OFIAR-031-020 2

Type Grain kiln Function Grain milling

Category Food processing & products Context Industry

Irish Grid 215349 213277 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains N/A Condition N/A Use N/A Plant Remains N/A Condition N/A Use N/A Use N/A Machinery Remains N/A Condition N/A

Description No traces of detached kiln, to east of mill, survive.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 72 of Ireland c.1850 (Dublin, 2000).

OFIAR-031-020_01 FWH 25/06/2003 Mill remains from south-east.



OFIAR-031-020_02 FWH 25/06/2003 Derelict mill house from north-west.



Site no	OFIAR-032	Ballynacarrig Mills	
County	Offaly	Townland Ballynacarrig	Town
Planning	Offaly CC	Discovery map 54	Six-inch map 32
Summary	Derelict shell of 18th/early 19th century water-powered flour mill, tuck mill and kiln on Silver River. Also used in later 1800s as a saw mill. A watermill is cited hereabouts on the 1655 Down Survey.		

History

This mill may be on the site of a watermill depicted on the Down Survey of 1655. However, the scale and construction of the present mill suggests that it post-dates 1750. It is probably the same mill as that cited by Sir Charles Coote in his 1801 Statistical Survey of the King's County, "where flour is made ... Mr Delany the proprietor" (pp 89-90).

It is cited as a flour mill and cloth mill on the 1838 OS map and 1840s Mill Valuation book. According to the latter, the flour mill was under William Delany and had a 13ft 2in x 3ft waterwheel to three sets of stones. At the time of valuation, however, the machinery had been removed and the mill had not worked for four years. Delany is also noted as operating a nearby corn and flour mill (OFIAR-031-007).

The tuck mill (described as a cloth mill) had a 12ft x 2ft wheel to one set of stocks. However, it was now in ruins and also had not worked for the previous four years. Delany also is noted in the 1854 Griffith Valuation as operating the (grain) mill and another one nearby (OFIAR-031-007). The premises comprise a house, offices and mill, all with a rateable valuation of £6.5s.0d. This relatively low figure is surprising considering that the complex is much larger than many others with higher ratings and suggests that it was probably out of use.

The 1885 OS 6" map records the complex as a flour mill and a saw mill. The reinstatement of operations may have happened in the 1860s, when the adjoining farmyard was developed (the stable bears an 1868 datestone). It is likely that the emphasis was now on the milling of oats rather than wheat (as implied by the designation 'flour' mill). The width of the waterwheel pit now present in the mill compared with the dimensions of the waterwheels cited above suggests that a new wheel was probably installed. The milling and sawing equipment was probably on either side of it.

The complex is captioned 'Ballynacarrig Mills (corn & saw)' on the 1910 map. Its designation as a 'corn' mill indicates oatmeal production.

The presence of mass concrete on the headrace embankment and in the waterwheel pit indicates that it remained in use until well into the 20th century.

Component	OFIAR-032-002 1			
Туре	Grain kiln; Grain mill (water); Sav mill (water); Tuck mill (water)	w Function	Grain milling; Timber processing & products; Wool	
Category	Food processing & products; Context Industry Timber processing & products; Textile manufacture & products			
Irish Grid	222588 213589 +/-10m			
Survey date	12/06/2003 Surveyor	r Fred Ham	nond	
Building	Remains Substantial remains (Condition Poor	Use Disused	
Waterworks	Remains Substantial remains (Condition Poor	Use Disused	
Plant	Remains No visible remains 0	Condition N/A	Use N/A	
Machinery	Remains Traces	Condition Poor	Use Disused	

Description

This mill complex is located on the left bank of the Silver River, just upstream from Ballynacarrig Bridge. It is accessible from the main road via a laneway running parallel with the river.

Buildings

The complex comprises a U-plan block incorporating a three-storey mill aligned northsouth, a three-storey return parallel to the mill's east elevation, a three-storey store return at right angles to the south end of its west elevation, and a two-storey kiln return at the north end of the same side.

The buildings, which are now derelict and partly overgrown, are roofless save for remnants of a pitched natural slate roof on one of the stores. All the walls are of random rubble masonry, brought to courses. Some of the walls have advanced brick eaves and most have traces of render. All openings are square-headed and some have rendered brick dressings. The store at SW retains some 6/3 sliding sash windows and replacement casements.

Internally, all the rooms are floorless except the SW store. The top floor of this section is incorporated into a one-storey dwelling, now ruinous, abutting at south. The ends of cast-iron drying floor beams are also clearly evident on the kiln where they are secured on the outside face of its north wall.

Waterworks, plant and machinery

The weir has been removed to improve the flow of the river, but a wide headrace (now dry) can still be traced around the riverbank from its former location to the mill. The bank separating it from the river is of earth, but part of it has been pitched with stone and repaired with mass concrete. There is an overspill at the end of the headrace just before it enters the mill. The tailrace is culverted under the mill yard to an open channel which is ducted under the road through a semicircular arched stone culvert.

The internal waterwheel was located in the middle of the main block. The width of the wheel pit is 2.2m (7ft 3in).

The existing complex undoubtedly incorporated the corn, tuck and saw mills. No machinery now survives except at the entrance to the site, on the main road, where there is a one-piece conglomerate runner millstone 1.37m (4ft 6in) in diameter. Set into a nearby wall is an octagonal centrepiece of another grindstone.

Interest

Archaeological; Architectural; Historical; Setting

Evaluation

The complex is of some architectural interest because of its massing and scale. It is also of historical interest in having incorporated such a diverse range of past industrial activities and being the only mill in Co Offaly explicitly cited by Coote. The buildings would repay more detailed inspection as wall breaks are apparent between the main block and some of the returns. This suggests a multi-phase site, the last addition to which might conceivably have been in the 1860s. The complex is a notable landscape feature hereabouts on account of its proximity to the road and

The site is of regional heritage interest and warrants its designations both as a Recorded Monument (OF032-00701-) for its archaeological interest and as a Protected Structure in the Co Offaly Development Plan 2009-15 on account of its upstanding remains.

Rating

Regional

Protection RMP OF032-00701-; Offaly RPS 42-07;

Action

None (in RMP

Offaly RPS 42-08

and RPS)

Associated with OFIAR-031-007

Other dbase NIAH 14932002 (R); NIAH 14932003 (R); SMR OF032-00701-

References

Archaeological Survey of Ireland record.

Coote, Sir Charles. Statistical Survey of the King's County (Dublin, 1801). Page(s) 89-90

Page(s)

Garner, W. Churches and Houses of Architectural Interest in Co Offaly Page(s) 41 (Tullamore: Offaly Historical Society, 1985).

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-032-002_01 FWH 12/06/2003 View from west showing mill in middle background, kiln at left and store return at



OFIAR-032-002_02 FWH 12/06/2003 View from north-east with mill at centre/right, and store return at left.



OFIAR-032-002_03 FWH 12/06/2003 External north elevation of kiln showing projecting ends of metal drying floor beams.



OFIAR-032-002_04 FWH 12/06/2003 Looking west along headrace at weir end.



OFIAR-032-002_05 FWH 12/06/2003 Looking up waterwheel pit towards water intake end. Note semi-elliptical brick arch at far end.



OFIAR-032-002_06 FWH 12/06/2003 Millstone at roadside entrance to premises.



Site no OFIAR-032-004

County	Offaly	Townland Capp	agowlan	Town		
Planning	Offaly CC	Discovery map	54	Six-inch map 32		
Summary	Site of 18th/early 19th century water-powered corn mill on Silver River.					
History	Cited as corn mill on 1838 OS six-inch map. The 1840s Mill Valuation book notes the cornmill as being operated by Jonathan Yates. A 13ft 6in x 3ft3in waterwheel drove three sets of stones. Still operated by Yates in 1854 Griffith Valuation. Premises rated at £5. Not explicitly cited on 1885 or 1910 maps.					

Component OFIAR-032-004 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 222305 213761 +/- 10m

Survey date 12/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A
Waterworks Remains No visible remains Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill on right bank of Silver River to west of Ballynacarrig Bridge.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 74 of Ireland c.1850 (Dublin, 2000).

Site no	OFIA	\R-032	2-005

County Planning	Offaly Offaly CC	Townland Killoughy Discovery map 54		Town Six-inch map 32		
Summary	Remains of 18th/early 19th century water-powered corn mill on tributary of Silver River.					
History	Noted in 1838 and 1885 OS maps as corn mill. 1840s Mill Valuation book notes its owner as Thomas Malone. A 13ft x 2ft 6in waterwheel drove two sets of stones. James Malone was the owner in 1854 (Griffith Valuation). The corn mill and offices were rated at only £2.15s.0d. Probably inoperative by early 1900s as not cited on 1910 map.					

Component OFIAR-032-005 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 227175 214200 +/- 10m

Survey date 12/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Poor Use Disused

Waterworks Remains No visible remains Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Derelict overgrown shell of corn mill on tributary of Silver River, south of minor road.

Comprises a $2\frac{1}{2}$ storey/single-bay building aligned east-west. Random rubble walls with square-headed openings. Entered from ground floor (south elevation) and first-floor (east gable). No roof or internal floors, nor evidence of waterworks. Infilled

waterwheel pit on west gable.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 74 of Ireland c.1850 (Dublin, 2000).

OFIAR-032-005_01 FWH 12/06/2003 Mill remains from south-west.



Site no	OFIAR-033-008
OILE IIU	OI IAI\-033-000

County	Offaly	Townland Clonygowan	Town
Planning	Offaly CC	Discovery map 54	Six-inch map 33

Summary Site of 18th/early 19th century brewery. Not water powered.

History Cited as brewery on 1838 OS six-inch map.

Component OFIAR-033-008 1

Type Brewery Function Brewing

Category Drink processing & products Context Industry

Irish Grid 248052 215478 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Remains N/A Waterworks Condition N/A Use N/A Use N/A **Plant** Remains No visible remains Condition N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of brewery behind what is now Gorman's Food Market, at NW side of Fair Green.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Site i	10	n	FL	ΔΕ	2-N	31	3-N	09
OILE I	10	J	1 1/	П І	\ -U	J.	ノーひ	UJ

County	Offaly	Townland Garryhinch	Town
Planning	Offaly CC	Discovery map 54	Six-inch map 33
Summary	Site of 18th cer	ntury water-powered mill on tributary of Riv	ver Barrow. In ruins by 1838.

History Cited as "Mill (in ruins)" on 1838 OS six-inch map.

Component OFIAR-033-009 1

Type Mill (water) Function Unknown

Category Unknown Context Industry

Irish Grid 248514 211296 +/- 10m

Survey date 17/07/2003 Surveyor Fred Hamond

Condition N/A Use N/A Building Remains No visible remains Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of mill on small tributary of River Barrow, on south side of minor road north of

Garryhinch Cross Roads.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Site no	OFIAR-034-007
SILE IIU	OFIAN-034-001

County Planning	Offaly Offaly CC	Townland Kilm Discovery map	alogue 55	Town	Portarlington h map 34	
Summary	Site of 18th/ear	ly 19th century wat	er-powered flour and corn	mill on R	iver Barrow.	
History	Cited as flour mill on 1838 OS six-inch map. Noted in 1840s Mill Valuation as belonging to Henry Odlum. A 12ft x 10ft waterwheel powered three sets of stones. Sti worked by Odlum in 1851 when described in Griffith Valuation as flour and corn mills; its £85 rating implies a sizeable enterprise (10th highest in Co Offaly). Premises possibly incorporated into adjoining malting (OFIAR-034-008) in later 1800s.					

Component OFIAR-034-007 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 253604 212420 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Remains No visible remains Use N/A Machinery Condition N/A

Description Site of flour mill on left bank of River Barrow.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-034-008

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

County	Offaly	Townland Kilmalogue	Town Portarlington	
Planning	Offaly CC	Discovery map 55	Six-inch map 34	
Summary	Remains of mid 19th century maltings now in use as retail outlet.			

Not recorded in 1850s Griffith Valuation. Malt house cited on 1884 OS six-inch map, along with a large block to its south. Marked as The Maltings on 1910 map.

Context

Industry

Component OFIAR-034-008 1

History

Category

Type Malt house Function Malting

Irish Grid 253574 212449 +/- 10m

Survey date 13/06/2003 Surveyor Fred Hamond

Drink processing & products

Building Remains Substantial remains Condition Good Use Retail outlet

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description A detached three-storey/six-bay former malt house now in use as sports' goods

wholesale outlet. Aligned east-west at north end of yard. Pitched profiled metal roof, plastic rainwater goods, random rubble walls (partly cement rendered), square headed openings with brick dressings (and bars to upper floors). North and south elevations partly abutted by modern buildings. Internally gutted of original fixtures and fittings. The second floor had been removed. Roof supported on common rafters

over single purlins on king-post trusses.

Interest None

Evaluation No special industrial heritage merit.

Rating Record only Protection Action

Associated with OFIAR-034-007

Other dbase

References

Halpin, T.B. Breweries in the Queen's County. Typescript in Local Studies Page(s) Dept of Laois County Library, Portlaoise (1999).

OFIAR-034-008_01 FWH 13/06/2003 Former malt house from north-east.



OFIAR-034-008_02 FWH 13/06/2003 Former malt house from south-east.



OFIAR-034-008_03 FWH 13/06/2003 Original roof trusses.



Site no OFIAR-035-001

County Planning	Offaly Offaly CC	Townland Bunn	evan 53	Town Six-inch map 35		
Summary	Overgrown shell of 18th/early 19th century water-powered corn mill and kiln and site of a second kiln on Little Brosna River.					
History	Cited in 1838 OS six-inch map as a corn mill and corn kiln (the latter on the NW side of the road). Described in the 1840s Mill Valuation book as an oat mill under John Cruise. It had a 13ft x 3ft 2in waterwheel to two sets of stones. According to Griffith Valuation, worked by H. and J. Leicester in 1854; rated at £40. The corn mill is also cited on the 1884 and 1909 maps.					

Component OFIAR-035-001 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 203289 208044 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused Waterworks Remains Some remains Condition Poor Use Disused Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Derelict shell of four-storey/five-bay former flour mill and three-storey kiln return at

rear, aligned NW/SE on east of road.

Building

Probably a hipped roof originally, but long gone. Random rubble walls with finely dressed stone eaves. Square-headed opening with brick heads and jambs. Windows have stone cills; those to top floor diminished in height. Two-storey lean-to on NW gable of mill. North end of east elevation abutted by kiln, now roofless and detailed as mill. Furnace survives, along with fragments of 30cm (12in) square perforated clay tiles from drying floor. Just across the river, in Derrinsallow townland (Co Tipperary), is a derelict six-storey flour mill.

Waterworks, plant and machinery

Powered off Little Brosna River. A 2.9m (9ft 6in) wide headrace is still evident along the front (SW elevation) of the mill. The waterwheel was at the north end of this side, but nothing of it or the machinery survives.

Component OFIAR-035-001 2

Type Grain kiln Function Grain milling

Category Food processing & products Context Industry

Irish Grid 203286 208102 +/- 10m

Survey date 25/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A Use N/A Condition N/A **Plant** Remains N/A Use N/A Use N/A Remains N/A Machinery Condition N/A

Description No traces of kiln on west side of road.

Interest Architectural; Setting

Evaluation Architecturally, the scale and uniformity of this mill is typical of late 18th/early 19th

century flour mills. It is also a significant landscape feature hereabouts. Overall, it is of local industrial heritage significance and is a Protected Structure in the Co Offaly

Development Plan 2009-15.

Rating Local Protection Offaly RPS 48-03 Action

Associated with

Other dbase NIAH 14935011(R)

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 75 of Ireland c.1850 (Dublin, 2000).

OFIAR-035-001_01 FWH 25/06/2003 South-east elevation.



OFIAR-035-001_02 FWH 25/06/2003 Furnace on ground floor of kiln.



Site no	OFIAR-035-	007	Maltings Craft Centre		
County	Offaly	Townland Townparks (Ballybritt By)	Town Birr		
Planning	Birr UDC	Discovery map 53	Six-inch map 35		
Summary	Substantial remains of later 19th century malt house and kiln on west side of Castle Street, converted in 1990s to craft studios and leisure facilities.				
History	captioned. Offi Belonged to re adjoining distill Recorded as m ventilators, ind	Buildings are shown hereabouts in the 1838 OS six-inch map but none is explicitly captioned. Offices (named as Queen's Stores) cited here in 1854 Griffith Valuation. Belonged to representatives of Robert and Simpson Robinson, owners of the adjoining distillery and malt stores (OFIAR-035-047 and 035-062 respectively). Recorded as maltings on 1909 map. A photo of Birr c.1920 shows two pyramidal roof ventilators, indicating a double kiln. The building was converted to a craft shops and leisure facilities in 1990s.			

Component OFIAR-035-007 1

Type Malt house; Malt kiln Function Malting

Category Drink processing & products Context Industry

Irish Grid 205796 204834 +/- 10m

Survey date 26/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Excellent Use Craft studios

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description

A five-storey/six bay former malt house and kiln, converted to craft studios and leisure facilities in 1990s. Aligned north-south along west side of Castle St. On the street (east) elevation only the top two floors are visible as the building is cut into the slope. The surviving remains and c.1920 photograph suggest that the malt floors were at middle and north, with a double kiln at south.

Replacement hipped artificial slate roof with plastic rainwater goods on boarded eaves. Random rubble walls, with dressed stone quoins and concrete ring beam around top; rendered to east (street) elevation. Excepting top floor openings, all are square- or shallow segmental headed, with brick heads and jambs. Top floor window openings have concrete heads and finely-dressed stone jambs. All openings have modern replacement windows/doors. West elevation has brick-headed semi-elliptical arched door and window openings to ground floor. Also door on south gable at first floor level, and on east elevation at second floor level. Modern flat-roofed extension to east end of north elevation.

There are four floors internally (the top two original floors are now one), all gutted of original features. A plaque on south wall notes that Father Michael Crotty (1795-1862) ministered from these premises during the Crotty schism (1820-50).

Interest Architectural; Setting

Evaluation

Architecturally, this building is of interest on account of its size and contrasting materials (stone and brick) and also a prominent streetscape feature at this end of Castle St. However, its original character is somewhat diminished by the new roof, which is of a different profile and materials to the original. Although a Protected

Structure in the Draft Birr Development Plan 2010-16, it is of only local industrial heritage significance.

Rating Local Protection Birr RPS 53-206 Action

Associated with OFIAR-035-047; OFIAR-035-062

Other dbase NIAH 14819100 (R)

References

Barber, P. Birr: Pictures from the Past (Dublin: Blackwater Press, 1997). Page(s) 18

OFIAR-035-007_01 FWH 26/06/2003 General view of site from south-east.



OFIAR-035-007_02 FWH 26/06/2003 General view of site from north-west.



Site no	OFIAR-035	5-009	Manor Saw Mill	
County	Offaly	Townland Townparks (Ballybritt By)	Town Birr	
Planning	Birr UDC	Discovery map 53	Six-inch map 35	
Summary	north bank of	8th/early 19th century flour mill on site of 17t Camcor River. Converted to saw mill in 1887 incorporated into Birr Technology Centre.		

History

A mill is shown at this location on a 1691 map of Birr. This appears to have been the manorial mill for the town. Noted as belonging to a Mr Robinson in 1826 (he also owned a brewery and distillery in Castle St (OFIAR-035-029 and 035-047 respectively). Cited as flour mill on 1838 OS six-inch map; this was undoubtedly a rebuild of the 17th century mill.

The 1840s Valuation Book notes owner as Christopher Robinson. Described as flour and corn mill, with an 18ft x 15ft waterwheel driving nine sets of stones (six in flour mill, three in corn mill). Only one other mill in the county (Erry Mill, Clara - OFIAR-008-038) had this number of stones at this time (the average was two or three sets). The wheel was also the widest in the county (the average was 4ft). The valuation of the property was £93 - the highest in the county.

In 1854, its owners were Jeremiah Maher and John Sutherland (Griffith Valuation). The flour mill, offices and yard were rated at £86 - the ninth highest rating of all industrial sites in Co Offaly.

Converted to a saw mill in 1887. Cited as Manor Saw Mill on 1909 map; a turbine is also noted. After the saw mill stopped, the turbine was removed to Ballyduff Mill, near Tullamore (OFIAR-016-002).

In 2000-01, the derelict remains were incorporated into a new technology centre by Shannon Development.

Component OFIAR-035-009 1

Type Grain mill (water); Saw mill (water) Function Grain milling; Timber processing &

products

Category Food processing & products;

Timber processing & products

Context Industry

Irish Grid 205948 204634 +/- 10m

2000 10 20 100 1 17 10111

Survey date 26/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Excellent Use Offices

Waterworks Remains Substantial remains Condition Fair Use Disused

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Buildings

Remains of flour/saw mill on right bank of Camcor River, east of Castle Street Bridge now incorporated into new block of buildings. The derelict three-storey shell was largely dismantled and a new building erected on its footprint in 2000-2001. Although much of the stonework was reused, this is essentially a new building bearing little semblance to the original.

Waterworks, pland and machinery

The weir survives at Oxmantown Bridge. It is set diagonally across the river and has a sloping apron with cascade fish pass at its west end. There are three timber sluice

gates (on a steel frame) at the intake to the headrace. The latter is relatively wide and would also have acted as a pond. It is open as far as the mill but has been infilled within the premises; the water is now diverted back to the river. The headrace entered the premises under a wide semi-elliptical brick arch. The tailrace is infilled. The waterwheel pit is still visible on the north gable of the east block. It has a dressed stone apron indicating a breastshot type waterwheel. No machinery survives.

Interest Archaeological

Evaluation This site is of archaeological interest as a manorial mill. Although the weir and

surviving section of headrace are of landscape interest and the waterwheel pit is still evident, so little of the 19th century mill survives that the site is now only of local

industrial heritage significance.

Rating Local Protection Action

Associated with

Other dbase SMR OF035-012011-

References

Archaeological Survey of Ireland record. Page(s)

Barber, P. Birr: Pictures from the Past (Dublin: Blackwater Press, 1997). Page(s) 88

Birr Technology Centre publication commemorating opening. Page(s)

Cooke, T.L. The Picture of Parsonstown (Dublin, 1826. Reprinted by Offaly Page(s) 160

Chronicle, 1929).

Details of 200-2001 conversion in Birr Planning Office, files PD-1126 and Page(s)

PD-1189.

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s)

of Ireland c.1850 (Dublin, 2000).

OFIAR-035-009_01 FWH 26/06/2003 Birr Technology Centre, from south.



OFIAR-035-009_02 FWH 26/06/2003 Birr Technology Centre, from south-east.



OFIAR-035-009_03 FWH 26/06/2003 Birr Technology Centre, from north-east. Note headrace intake arch.



OFIAR-035-009_04 FWH 26/06/2003 Birr Technology Centre, from north. Waterwheel pit is on left gable.



OFIAR-035-009_05 FWH 26/06/2003 Waterwheel pit.





OFIAR-035-009_07 FWH 26/06/2003 Weir at Oxmanstown Bridge, from east.



Site no	OFIAR-035-010 Hackett's Distiller					tt's Distillery	
County Planning	Offaly Birr UDC	Townland Discovery m		Ballybı	ritt By)	Town Six-inc	Birr h map 35
Summary	Site of 18th/earl	y 19th century	distillery.				
History	as marked on O survived by 190	Cited as Hackett's Distillery in 1822 map of Birr. Still at work in 1826. Disused by 1838 as marked on OS six-inch map as Old Distillery. Only roofless shells of buildings survived by 1909 OS survey. The town gasworks (OFIAR-036-068) was occupying the west end of the premises by this time.					
Component	OFIAR-035-010	1					
Туре	Distillery		Fun	ction	Distilling		
Category	Drink processing	g & products	Con	itext	Industry		
Irish Grid	206044 204560	+/- 10m					
Survey date	26/06/2003	Survey	or Fre	d Han	nond		
Building	Remains No vi	sible remains	Condition	N/A	Use I	N/A	
Waterworks	Remains N/A		Condition	N/A	Use I	N/A	
Plant	Remains No vi	sible remains	Condition	N/A	Use I	N/A	
Machinery	Remains No vi	sible remains	Condition	N/A	Use I	N/A	
Description	Site of distillery	now occupied l	by playing fie	eld (at	east) and fo	ormer gas	sworks (at west).
Interest	None						
Evaluation	No industrial her	ritage significar	nce.				
Rating	Record only	Protection			1	Action	
Associated v	Associated with						
Other dbase							
References							

References

1822 map of Birr. Page(s)

Cooke, T.L. The Picture of Parsonstown (Dublin, 1826. Reprinted by Offaly Page(s) 159 Chronicle, 1929).

Site no	OFIAR-035-013
Site IIO	OFIAR-USS-UIS

County Planning	Offaly Birr UDC	Townland Clo	noghil Upper 53	Town Six-inch map 35	
Summary	Overgrown she Camcor River.	ell of 18th/early 19th	h century wate	r-powered grain and oil mills on	
History	Cited as flour and oil mills on 1838 and 1884 OS six-inch maps. 1840s Mill Valuation book records John Palmer as their operator. A 13ft x 4ft 6in waterwheel drove two pairs of stones in the flour mill, and a 13ft 6in x 2ft wheel drove a set of preparatory stones and rollers in the rape mill. Palmer was also the owner in 1854 (Griffith Valuation). The house, offices, corn mill and rape mill were rated at £70, indicating a sizeable concern. Only the corn mill appears to have been working in 1909, being marked on the six-inch map of that date.				

Component OFIAR-035-013 1

Type Grain mill (water); Oilseed mill Function Grain milling; Oilseed milling

(water)

Category Food processing & products Context Industry

Irish Grid 207906 204650 +/- 10m

Survey date 27/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Poor Use Disused Waterworks Remains No visible remains Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Overgrown derelict remains of flour and oil mills on left bank of Camcor River,

behind Springfield House and west of Springfield Bridge. Surviving north and west walls stand three-storey high and are of random rubble with brick eaves course and

square-headed openings. Races infilled.

Adjoining mill house is two-storeys/three-bays and has been refurbished.

Interest None

Evaluation The combination of grain milling and oil production are of interest. However, so little

of the original mill now survives that the site is of no special industrial heritage

significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-035-013_01 FWH 27/06/2003 Mill remains from south.



Site no	OFIAR-035	o-016	Kilmaine Mill		
County	Offaly	Townland Kilmaine	Town		
Planning	Offaly CC	Discovery map 54	Six-inch map 35		
Summary	Traces of 18th/early 19th century water-powered corn mill on Fuerawn River.				
History	Cited as Old mill on the 1838 OS map. Not recorded in 1840s Mill Valuation book. Subsequently refurbished or rebuilt as cited in 1854 Griffith Valuation as belonging to Charles Foster and comprising corn mills and offices, rated at £18. Marked as Kilmaine corn mill on 1909 OS map.				

Component OFIAR-035-016 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 212476 204247 +/- 10m

Survey date 26/06/2003 Surveyor Fred Hamond

Building Remains Traces Condition Poor Use Disused

Waterworks Remains No visible remains Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Traces of corn mill on right bank of Fuerawn River, at west side of farmyard just

north of minor road. Foundations of a random rubble building survive. The races

have been infilled.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

OFIAR-035-016_01 FWH 26/06/2003 Mill remains from south-west.



Site no	OFIAR-035-018
OILE HO	OI IAIX-033-010

County Planning	Offaly Offaly CC	Townland Ballinree (Ballybritt By) Discovery map 53	Town Six-inch map 35		
Summary	Derelict remains	s of 18th/early 19th century water-powered e Brosna River.	d corn mill and kiln on		
History	A corn mill and detached kiln are cited on 1838 OS six-inch map. Not recorded in 1840s Mill Valuation book. Noted in 1854 Griffith Valuation as belonging to Griffith Clements. The house, office and corn mill were rated at £10. Only the kiln is explicitly cited on the 1884 OS map. Mill disused by 1909 (as evidenced by disused mill race on map).				

Component OFIAR-035-018 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 207593 203145 +/- 10m

Survey date 27/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused Waterworks Remains Some remains Condition Poor Use Disused Plant Remains Some remains Condition Poor Use Disused Machinery Remains No visible remains Condition N/A Use N/A

Description A three-storey/two bay corn mill aligned east west on left bank of a tributary of Little

Brosna River.

Buildings

Pitched roof is now gone. Random rubble walls, part rendered, and with two stone buttresses to north side. Square-headed openings; some with brick heads. Internal floors removed. Abutted on east gable by two-storey/single-bay kiln, similarly detailed and without internal floor. This kiln presumably replaced the detached one shown on the 1838 OS map.

Waterworks, plant and machinery

The head and tailraces are still visible as overgrown ditches. Waterwheel pit on west gable of mill. Timber axle and two cast-iron hubs (with flanges for eight arms apiece) survives. Hubs are 99cm (3ft 3in) apart, suggesting a wheel width of similar dimension. Probably high breastshot feed. No machinery survives.

Component OFIAR-035-018 2

Type Grain kiln Function Grain milling

Category Food processing & products Context Industry

Irish Grid 207577 203156 +/- 10m

Survey date 27/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A Use N/A Plant Remains N/A Condition N/A Use N/A Machinery Remains N/A Condition N/A Use N/A

Description No traces survive of detached kiln to NW of mill.

Interest None

Evaluation Although some vestiges of the waterwheel survive, the mill is too incomplete to be of

any special industrial heritage merit.

Rating Record only Protection Action

Associated with

Other dbase

References

OFIAR-035-018_01 FWH 27/06/2003 North elevation of mill (right) and kiln (left).



OFIAR-035-018_02 FWH 27/06/2003 East elevation of kiln.



OFIAR-035-018_03 FWH 27/06/2003 Waterwheel axle and hub.



Site no	OFIAR-035	-029	Robinson's Brewery	
County	Offaly	Townland Townparks (Ballybritt By)	Town Birr	
Planning	Birr UDC	Discovery map 53	Six-inch map 35	
Summary	Site of 18th/early 19th century brewery and remains of grain store now incorporated into restaurant/b&b complex.			
History	Robinson's brewery is noted in Castle St in 1826. Robinson also owned the distillery on the west side of the street (OFIAR-035-047) and a nearby flour mill (035-009). It is explicitly cited as a brewery on the 1838 OS six-inch map, at the south end of the block now occupied by Spinners Town House at the NE corner of Castle Street. It is recorded as Old brewery in the 1854 Griffith Valuation. The fact that it has a zero rating suggests that it was disused. The site is also captioned as Old brewery on the 1884 OS map, but is uncaptioned on the 1909 edition. A building shown on all map editions along the east side of the premises is presumed to have been a grain store.			

Component OFIAR-035-029 1

Type Brewery Function Brewing

Category Drink processing & products Context Industry

Irish Grid 205817 204867 +/- 10m

Survey date 27/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A
Waterworks Remains N/A Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

Description No obvious remains of brewery survive at south end of Spinners Town House

complex.

Component OFIAR-035-029 2

Type Grain store Function Brewing

Category Drink processing & products Context Industry

Irish Grid 205820 204894 +/- 10m

Survey date 27/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Store Waterworks Remains N/A Condition N/A Use N/A Condition N/A Plant Remains N/A Use N/A Machinery Remains N/A Condition N/A Use N/A

Description A three-storey former grain store presumably associated with the former brewery and

now incorporated into the Spinners Town House complex. It has a natural slate roof (hipped to north and pitched to south), and brick chimney to south gable. Half-round steel gutters on advanced eaves. Random rubble walls. West elevation, facing into the yard, has an arcade of nine segmental-arch doorways to ground floor. Window and loading door openings to upper floors are square-headed openings and trimmed with brick. Most of the window openings have timber louvres; no cills. East elevation is devoid of openings. Not inspected internally, but seemingly used as a store. This building forms the east side of a U-shaped block arranged around an internal courtyard. The remaining buildings are similarly detailed and have been converted into b&b acccommodation (along west side) and restaurant (along north side).

Interest Architecture; Historical; Setting

Evaluation The grain store is a good example of its type and also has historical interest due to its

association with Robinson's Brewery. It is of local industrial heritage significance.

Rating Local Protection Action

Associated with

Other dbase NIAH 14819099 (R)

References

Cooke, T.L. The Picture of Parsonstown (Dublin, 1826. Reprinted by Offaly Page(s) 163 Chronicle, 1929).

OFIAR-035-029_01 FWH 26/06/2003 North elevation of former brewery premises, now Spinners Town House complex.



OFIAR-035-029_02 FWH 26/06/2003 Grain store from south-west.



OFIAR-035-029_03 FWH 26/06/2003 Grain store from north-east.



Site no	OFIAR-035	5-031		Whiteford Mill		
County	Offaly	Townland Crin	kill	Town		
Planning	Offaly CC	Discovery map	53	Six-inch map 35		
Summary		Remains of 18th/early 19th century water-powered flour mill and kiln on tributary of Little Brosna River. Now incorporated into farm outbuildings.				
History	Cited as flour mill and corn kiln on 1838 OS six-inch map. 1840s Mill Valuation book notes the complex as a flour mill under Thomas Hackett. A 24ft x 6ft 6in waterwheel drove four sets of stones. This was the fourth largest diameter wheel in the county at this time. Thomas Hackett was also owner in 1854 (Griffith Valuation). Premises described as house, offices, flour mill and corn mill, all rated at £105 (the fifth highest rated industrial complex in Co Offaly). Noted in 1884 OS map as flour mil, and as Whiteford cornmill on 1909 map. Was apparently five storeys high by 11 bays wide, but largely demolished before the present owner purchased the site.					
Component	OFIAR-035-0	031 1				
Туре	Grain kiln; Gı	rain mill (water)	Function	Grain milling		
Category	Food process	sing & products	Context	Industry		
Irish Grid	206957 2034	482 +/- 10m				
		_				

Building	Remains	Some remains	Condition	Poor	Use Disused
Waterworks	Remains	No visible remains	Condition	N/A	Use N/A
Plant	Remains	No visible remains	Condition	N/A	Use N/A
Machinery	Remains	No visible remains	Condition	N/A	Use N/A

Surveyor

Survey date 27/06/2003

Description Remains of flour mill and kiln on tributary of Little Brosna River, now incorporated into farm outbuildings. The actual mill remains comprise a random rubble wall up to 5m high in places which now forms south side of an outbuilding. Internal waterwheel

pit at west end, now indicated by score marks in dressed stone side.

Immediately west of this pit is a two-storey outbuilding, possibly a store originally, but now a poultry shed. Pitched corrugated asbestos roof, random rubble walls with brick eaves, and square-headed openings.

Fred Hamond

Adjoining the east end of the mill remains are the overgrown vestiges of a grain kiln, now truncated to 1½ storeys. Random rubble walls and square-headed openings with brick trim. Hearth and brick vaulting survive internally.

To NE is former two-storey/three-bay mill house, still in use as dwelling.

The head and tailraces are infilled. The pond was directly behind the mill but has been removed.

Interest	None		
Evaluation	Although this was once a sizeable enterprise, the demolition of most of the mill now makes it of no special industrial heritage merit.		
Rating	Record only	Protection	Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 72 of Ireland c.1850 (Dublin, 2000).

OFIAR-035-031_01 FWH 27/06/2003 Waterwheel pit remains at west end of mill.



OFIAR-035-031_02 FWH 27/06/2003 Store at west end of mill, from north-east.



OFIAR-035-031_03 $\,$ FWH $\,$ 27/06/2003 $\,$ Kiln , from north-east.



OFIAR-035-031_04 FWH 27/06/2003 Hearth and vaulting inside kiln.



OFIAR-035-031_05 FWH 27/06/2003 Mill house, from south-east.



Site no	OEL	\R-03	こしろろ
SILE IIU	OFIF	1N-U3:	ว-บออ

County Planning	Offaly Offaly CC	Townland Clonbrone (Eglish By) Discovery map 53	Town Six-inch map 35	
Summary	Site of 18th/early 19th century water-powered corn mill on Camcor River.			
History	Corn mill cited on 1838 and 1884 OS six-inch maps. The 1840s Mill Valuation book notes the corn mill's operator as Nathaniel Mills. A 13ft x 2ft 6in waterwheel drove two sets of stones. Not cited in 1850s Griffith Valuation. The river's realignment in mid 1800s as part of a drainage scheme may have caused the mill to stop.			

Component OFIAR-035-033 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 210866 204608 +/- 10m

Survey date 26/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A
Waterworks Remains No visible remains Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill on right bank of Camcor River. The river has been realigned since

the mill was in use.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 72 of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-035-034	Birr Distillery

County	Offaly	Townland Clonoghil Upper	Town Birr
Planning	Birr UDC	Discovery map 53	Six-inch map 35

Summary

Substantial derelict remains of distillery founded by R. and J. Wallace in 1805 on Camcor River just upstream from Elmgrove Bridge. Site encompasses miscellaneous distillery buildings, maltings, kiln and malt mill. Part of bonded warehouse now converted to accommodation.

History

Distillery established in 1805 by R. and J. Wallace. The complex is described in the 1840s Mill Valuation book as a distillery and corn mill, operated by Michael Hackett. It had a 16ft x 11ft 3in waterwheel driving three sets of stones.

The 1854 Griffith Valuation book also notes Michael Hackett as operating the distillery and a malt mill. The premises were rated at £75 - second only to the Tullamore Distillery (OFIAR-017-036) in value. Hackett also owned corn and malt stores just downstream from Elmgrove Bridge (OFIAR-035-046).

When surveyed by Alfred Barnard in 1887, the distillery contained two pot stills, mash tun, washbacks, grain stores, malting floors, kiln, mill (for grinding/rolling malt), and bonded warehouses. Its output at that time was 200,000 gallons per year. Stopped production following a fire in 1889. Partly converted into accommodation in late 1900s.

Component OFIAR-035-034 1

Type Bonded warehouse; Distillery; Function Distilling

Grain mill (water); Malt house;

Malt kiln

Category Drink processing & products Context Industry

Irish Grid 206666 205025 +/- 10m

Survey date 12/09/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Dwelling/Disused

Waterworks Remains No visible remains Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description

Substantial remains of early 19th century distillery complex on left bank of Camcor River, just upstream from Elmgrove Bridge. The buildings are arranged around a central courtyard and bounded to north and west by the river. Most of the site is ruinous, but part has been converted to a dwelling. Inspection and interpretation were restricted on account of access difficulties.

The section at south, facing the main road, is a three-storey/13-bay building aligned east-west. According to Barnard, this was a bonded warehouse. Hipped natural slate roof and plastic rainwater goods. Random rubble walls, advanced stone eaves and dressed quoins. Square-headed openings with brick heads/jambs and stone cills; those to top floor of diminished size. Semi-elliptical brick-trimmed doorway to centre and wide brick segmental archway at west; the latter is infilled with stone. Window openings to ground and top floor have shutters; those to first floor are modern 6/6 sashes. This section now serves as holiday accommodation. Partly-attached square stone/brick chimney at SE corner.

West end is abutted by derelict three-storey building running north, parallel with river. Barnard notes that this was the malt house. Walls and openings detailed as front section (as are all other buildings). Malt kiln at north end thereof, complete with pyramidal roof (no access).

Rear of east end of front block is abutted by a roofless three-storey building which forms the east side of the courtyard. Barnard notes that this was the still house, tun room, spirit store and racking room.

North side of courtyard comprises a four-storey building, now roofless and derelict. Barnard describes this section as the back house, cooling loft and mill. On its rear (north) elevation is a substantial tapered square brick chimney with a segmental arched channel underneath (possibly related to the former mill race). The east end of the four-storey building is abutted by a three-storey section, also now a ruined shell. This latter building is distinguished by two large segmental arched openings on its south elevation. The east end of this façade is abutted by a ruinous building running south. There may be a freestanding chimney hereabouts, but dense overgrowth obscured inspection.

Premises enclosed by high random rubble wall. On main road is a segmental-headed entrance trimmed with brick and with a pair of wrought-iron gates.

Interest None

Evaluation

Architecturally, this complex is of interest on account of its scale, massing and detailing (particularly the wide archways). It is also of historical interest in reflecting Birr's importance as a distilling centre during the 19th century. It is also a prominent landscape feature. The site is of regional significance and merits its current designation as a Protected Structure in the Draft Birr Development Plan 2010-16.

Rating Regional Protection Birr RPS 49-301 Action None (in RPS)

Associated with OFIAR-035-046

Other dbase NIAH 14819235 (R)

References

Barber, P. Birr: Pictures from the Past (Dublin: Blackwater Press, 1997). Page(s) 38

Barnard, A. The Whisky Distilleries of the United Kingdom. London: Harper's Weekly Gazette, 1887. (Reprinted by David & Charles, Newton Abbot, 1969).

Maguer, M. 1000 Years of Irish Whiskey (Dublin: O'Brien Press, 1980). Page(s) 137, 139

Maguire, E.B. Irish Whiskey: a History of Distilling in Ireland (Dublin: Gill and Macmillan, 1973).

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 72 of Ireland c.1850 (Dublin, 2000).

OFIAR-035-034_01 FWH 27/06/2003 General view from south-west.



OFIAR-035-034_02 FWH 27/06/2003 General view from south.



OFIAR-035-034_03 FWH 12/09/2003 South block, from south-east.





OFIAR-035-034_05 FWH 12/09/2003 West end of south elevation of south block.





OFIAR-035-034_07 FWH 12/09/2003 Archway at east end of north block, from south.



 $OFIAR-035-034_08 \quad FWH \quad 12/09/2003 \qquad \text{Base of chimney abutting north side of north block, from east.}$



OFIAR-035-034_09 FWH 12/09/2003 Boundary and entrance on main road, from south.



Site no OFIAI	R-035-035
---------------	-----------

County	Offaly	Townland	Ballindarra	Town

Planning Offaly CC Discovery map 53 Six-inch map 35

Summary Site of 18th/early 19th century malt mill on Little Brosna River.

History Notes as Old malt mill on 1838 OS six-inch map.

Component OFIAR-035-035 1

Type Grain mill (water) Function Malting

Category Drink processing & products Context Industry

Irish Grid 205256 203456 +/- 10m

Survey date 27/06/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of malt mill on right bank of Little Brosna River, just south of Riverbank

Restaurant at east end of road bridge.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Site no	OFIAR-035-046	Elmgrove Mill
		g. 0 v 0

County Offaly Townland Townparks (Ballybritt By) Town Birr

PlanningBirr UDCDiscovery map53Six-inch map35

Summary

Substantial remains of 18th/early 19th century brewery and c.1830 grain store associated with Birr Distillery. Downstream from Elmgrove Bridge on east approach to Birr. Store recently converted into apartments.

History

A brewery and "new" mill are cited on the 1838 OS six-inch map. However, it is uncertain whether the latter was ever used as a mill as it not recorded in the 1840s Mill Valuation book. The 1854 Griffith Valuation notes Michael Hackett as operating the site as corn and malt stores. The brewery was vacant and in ruins at that time. Hackett also owned the distillery, mill and stores just upstream from Elmgrove Bridge (OFIAR-035-034). Although the brewery was defunct, it is still explicitly cited on the 1879 and 1884 OS maps. The building known as the New Mill is also shown on these maps.

Barnard records this site as belonging to Birr Distillery in 1887. He notes two five-floor granaries and two drying kilns; the sub-floors were used as bonded warehouses. The mill was converted to apartments in 2002 under section 23 of the Finance Act.

Component OFIAR-035-046 1

Type Brewery; Malt kiln Function Brewing; Distilling

Category Drink processing & products Context Industry

Irish Grid 206609 204901 +/- 10m

Survey date 27/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Good Use Store Waterworks Remains N/A Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description

This complex comprises a former 18th/early 19th centurybrewery/kiln and 1830s grain store, both on the right bank of the Camcor River just downstream from Elmgrove Bridge. The brewery/kiln and store are in separate ownership. The brewery comprises a three-storey/10-bay building aligned north-south at the west end of the site. Now in use as a domestic store. Original hipped natural slate roof was replaced c.1975 by a pitched corrugated metal roof (gables raised in concrete blockwork). Half-round metal rainwater goods. Rendered random rubble walls with brick eaves (the latter with concrete blockwork over). Square-headed openings, with modern timber louvers (formerly vertical wooden bars). First floor loading door to road (north) gable. Internally, the walls are painted. The upper floors comprise timber boards over joists and beams; most of the first floor has been removed. South gable abutted by former malt kiln, only the vaulted brick base of which partially survives. This structure was already ruinous by 1879, being marked as roofless on the large-scale town map of that date.

Component OFIAR-035-046 2

Type Grain kiln; Grain store Function Brewing; Distilling

Category Drink processing & products Context Industry

Irish Grid 206639 204895 +/- 10m

Survey date 27/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Excellent Use Dwelling

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A
Use N/A

Description

The New Mill is a four-storey/nine-bay building aligned east-west along the riverbank. Its overgrown shell was converted into apartments in 2002. Pitched natural slate roof with aluminium ogee rainwater goods. Random rubble walls with dressed quoins; some sections were rebuilt during conversion work. Square-headed openings with brick heads/jambs; some are new insertions and all windows have concrete cills. Also infilled segmental brick arches to gables and south elevation. A modern flat-roofed, timber-clad stairwell abuts the east end of the north elevation and give access to balconies along this frontage. Modern cantilevered balconies also added to east gable and river elevation. The shell of a two-storey grain kiln on the east gable was removed during conversion work.

On the east side of the site is the one-storey partial shell of a rubble stone building. There were formerly also two buildings along the roadside; these were already foundations by the time of the conversion work and were removed.

Just below the road bridge is a fall in the river; this is probably natural rather than the remains of a weir. There is no evidence of any head- or tailrace.

Interest Historical; Setting

Evaluation Historically, this site is of interest in being associated with the brewing and distilling

industries. There is no conclusive evidence that water power was ever utilized. The complex is also a significant streetscape feature. The two buildings are of local industrial heritage significance and also designated as.Protected Structures in the

Draft Birr Development Plan 2010-16.

Rating Local Protection Birr RPS 53-324; Birr Action

RPS 53-325

Associated with OFIAR-035-034

Other dbase NIAH 14819230 (R); NIAH 14819231 (R)

References

Barnard, A. The Whisky Distilleries of the United Kingdom. London: Harper's Page(s) 491 Weekly Gazette, 1887. (Reprinted by David & Charles, Newton Abbot, 1969).

Cooke, T.L. The Picture of Parsonstown (Dublin, 1826. Reprinted by Offaly Page(s) 161 Chronicle, 1929).

D. Noonan. Excavation Report on the Old Mill, Newbridge St, Birr (to appear Page(s)

to Excavations 2002, ed by I. Bennett).

Midland Tribune, 12 Jan 1991. Page(s)



OFIAR-035-046_02 FWH 27/06/2003 East elevation of former brewery, from north-east.



 $OFIAR-035-046_03 \quad FWH \quad 27/06/2003 \qquad South gable of former brewery and kiln remains.$



OFIAR-035-046_04 FWH 27/06/2003 Interior of former brewery, looking south.



OFIAR-035-046_05 FWH 27/06/2003 Grain store, from north-east.



OFIAR-035-046_06 FWH 27/06/2003 Grain store, from south-east.



OFIAR-035-046_07 FWH 27/06/2003 Grain store, from south-west.



OFIAR-035-046_08 FWH 12/09/2003 Infilled archway on south gable of grain store.



OFIAR-035-046_09 FWH 27/06/2003 For sale sign on grain store apartments.



OFIAR-035-046_10 FWH 12/09/2003 Ruinous remains on east side of site, from south-west.



 $OFIAR-035-046_11 \quad FWH \quad 27/06/2003 \quad \quad Looking \ upstream \ to \ Elmgrove \ Bridge. \ Note fall \ in \ bed \ of \ river.$



Site no	OFIAR-035-0	047	Robinson's Distillery
County	Offaly	Townland Townparks (Ballybritt By)	Town Birr
Planning	Birr UDC	Discovery map 53	Six-inch map 35
Summary		y 19th century distillery, of which only the f Camcor River/ west side of Castle Street	
History	1818. Steam postreet (OFIAR-Constillery on an This site probable being operated driving four sets Valuation. Beloof the adjoining Cited as a distill	illery is noted in Castle St in 1826; it had bower is noted. Robinson also owned the brust-035-029) and a nearby flour mill (035-009) 1822 map of Birr and as a distillery on 1830 oly incorporated the corn mill noted in the by Robert Robinson. This mill had a 15ft 6 s of stones. Described as a dilapidated disinged to the representatives of Robert and offices and malt stores (OFIAR-035-007 allery on the 1884 OS map but buildings untiliams Waller (malsters) in 1900s. Converti	ewery on the east side of the . Cited as Robinson's . Cited as Robinson's

Component OFIAR-035-047 1

Type Distillery (steam) Function Distilling

Category Drink processing & products Context Industry

Irish Grid 205768 204870 +/- 10m

Survey date 26/06/2003 Surveyor Fred Hamond

Building Remains Traces Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Nothing survives of the once-extensive distillery which lay between Castle Street and

the Camcor River apart from the truncated north elevations of the now-demolished

buildings along the northern boundary of the site.

Component OFIAR-035-047 2

Type Malt house; Malt kiln; Grain mill Function Distilling

(water)

Category Drink processing & products Context Industry

Irish Grid 205734 204843 +/- 10m

Survey date 26/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Excellent Use Hotel Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description

A 19th century maltings, malt kiln and presumed malt mill, now converted into a 13-bed hotel. Comprises a four-storey/six bay building aligned north-south along the right bank of Camcor River. Its south gable is abutted by a three-storey/two-bay malt kiln of square plan.

Hipped natural slate roofs; that to kiln surmounted by a clock tower (to mimic the original square open ventilator). Ogee rainwater goods. Random rubble walls and advanced brick eaves. The ground floor of the east elevation of the malt house is of strap-pointed brick. Stone quoins to malt house and brick quoins to kiln. Square-headed openings with brick heads and jambs. Eaves dormers inserted along river elevation of malt house. Window openings have modern uPVC windows and plastic cills. The two concrete-headed doorways into the kiln have been bricked up as windows. Canopy over segmental-headed entrance door at SE end of maltings. Wide segmental brick arch on river elevation of maltings, with abutting single-storey conservatory.

Internally, the building has been gutted and the three upper floors replaced by two. The ground floors of the malt house and kiln are now a restaurant/kitchen and bar respectively. All the upper floors have been converted to bedrooms.

Interest None

Evaluation This complex is of architectural interest in terms of its composition - the malt house

at one end and the malt kiln at the other. The building is also of historical interest in being one of the last vestiges of Robinson's Distillery. It also greatly enhances the riverscape hereabouts. Although gutted and reconfigured internally, the building has regional heritage significance and warrants its current designation as a Protected

Structure in the Draft Birr Development Plan 2010-16.

Rating Regional Protection Birr RPS 53-207 Action None (in RPS)

Associated with OFIAR-035-007; OFIAR-035-062

Other dbase NIAH 14819101 (R)

References

Barber, P. Birr: Pictures from the Past (Dublin: Blackwater Press, 1997).

Page(s) 86

Cooke, T.L. The Picture of Parsonstown (Dublin, 1826. Reprinted by Offaly Page(s) 159-160

Chronicle, 1929).

Cooke, T.L. The Picture of Parsonstown (Dublin, 1826. Reprinted by Offaly Page(s) 163 Chronicle, 1929).

Maguire, E.B. Irish Whiskey: a History of Distilling in Ireland (Dublin: Gill and Page(s) 363 Macmillan, 1973).

Midland Tribune, 15 Oct 1994.

Page(s)

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 72 of Ireland c.1850 (Dublin, 2000).

OFIAR-035-047_01 FWH 26/06/2003 General view from south-east.



OFIAR-035-047_02 FWH 26/06/2003 General view from south-west.



OFIAR-035-047_03 FWH 26/06/2003 Kiln (left) and maltings, from north-east.



Site no	OFIAR-0)35-053			Midland Tribune
County	Offaly	Townland T	Townparks (I	Ballybritt	By) Town Birr
Planning	Birr UDC	Discovery m	ap 53		Six-inch map 35
Summary		Os textile spinning factor to offices and printw			f Kinnitty Road. Subsequently une newspaper.
History	Desmond		er by Max B	irr. Subs	food & Sons. Designed by sequently converted into
Component	OFIAR-03	5-053 1			
Туре	Newspape Spinning n	er printing works; mill	Fun	ction	Printing & publishing; Wool
Category		ustry; Textile ure & products	Cor	ntext	ndustry
Irish Grid	207105 20	04534 +/- 10m			
Survey date	31/07/2003	3 Surve	yor Fre	d Hamo	nd
Building	Remains	Complete	Condition	Good	Use Newspaper print works
Waterworks	Remains	N/A	Condition	N/A	Use N/A
Plant	Remains	No visible remains	Condition	N/A	Use N/A
Machinery	Remains	No visible remains	Condition	N/A	Use N/A
Description	aligned NV The office cement rei seven bays door to cei flanking pa concrete c The narrow bays has a Cement-rei headed op apexes. No interna equipment	N/SE along south side block fronting the roundered walls with block is of windows flank a ntre with multi-pane anels. Window openicills. Bay windows to wer factory to the read corrugated asbesto endered walls; a block penings with metal-frank access, but presumet.	de of Kinnitty and has a hip ocking course tripartite rec overlight (for ngs contain both floors car is aligned is roof of sav king course amed window hed to be con	r Road, oped native over exessed exeming with metal-from the parallel over the down easies. Circumplete in	storey/nine-bay factory to rear, on eastern outskirts of Birr. ural slate roof. Painted smooth aves. Square-headed openings: ntrance bay at centre. Glazed ndow to first floor lobby) and blank amed casements and have gable. with front block. Each of its nine rofile with glazing to NE pitch. In the side obscures the roof. Square-ular ventilation holes to gable on respect of newspaper printing all railings on a rendered wall.

Interest Architectural; Historical; Rarity; Setting

Evaluation

Apart from the 1930s woollen factory in Tullamore (OFIAR-017-085), this is the only purpose-built spinning mill of its type in Co Offaly. Architecturally, it still retains its original coherence and detailing despite its change of use. It is of technical interest as the only newspaper print works in the county and is also a prominent feature of the streetscape. Overall, it is of regional significance and warrants its current designation as a Protected Structure in the Draft Birr Development Plan 2010-16.

Associated with

Other dbase NIAH 14935006 (R)

References

Barber, P. Birr: Pictures from the Past (Dublin: Blackwater Press, 1997). Irish Architectural Archive. Proposed factory for B. Wood & Son, 1950.

Page(s) 85, 87
Page(s) Offaly 63/67R1

OFIAR-035-053_01 FWH 31/07/2003 General view from north.



OFIAR-035-053_02 FWH 31/07/2003 Street façade and main entrance.



OFIAR-035-053_03 FWH 31/07/2003 General view from south.



OFIAR-035-053_04 FWH 31/07/2003 General view from west.



Site no	OFIAR-035-0	60						
County	Offaly	Townland		ghil Upper?; ⁻ britt By)?	Townparks	Town	Birr	
Planning	Birr UDC	Discovery	map	53		Six-incl	h map	35
Summary	Unlocated site of 18th/early 19th century water-powered tuck mill on Camcor River at Elmgrove Bridge.							
History	Extant in early 1 six-inch map.	820s (cited b	by T.L. (Cooke in 182	6), but not e	explicitly o	cited in	1838 OS
Component	OFIAR-035-060	1						
Туре	Tuck mill (water)		Function	Wool			

Category Textile manufacture & products Context Industry

Irish Grid 206663 204939 +/- 100m

Survey date 27/06/2003

Fred Hamond Surveyor

Use N/A Building Remains No visible remains Condition N/A Waterworks Use N/A Remains No visible remains Condition N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Unlocated site of tuck mill on Camcor River in vicinity of Elmgrove Bridge.

Interest None

Evaluation No industrial heritage significance.

Record only **Action** Rating **Protection**

Associated with

Other dbase

References

Cooke, T.L. The Picture of Parsonstown (Dublin, 1826. Reprinted by Offaly Page(s) 161 Chronicle, 1929).

Site no OFI	AR-035-062
-------------	------------

County	Offaly	Townland Townparks (Ballybritt By)	Town Birr			
Planning	Birr UDC	Discovery map 53	Six-inch map 35			
Summary	Site of malt stores in use in 1850s. Associated with Robinsons' Distillery.					
History	Explicitly cite representativ	shown here on the 1838 OS six-inch map and as malt stores in 1854 Griffith Valuation. Bees of Robert and Simpson Robinson, owners IAR-035-007 and 035-047 respectively).	elonged to the			

Component OFIAR-035-062 1

Type Malt store Function Malting

Category Drink processing & products Context Industry

Irish Grid 205770 204754 +/- 10m

Survey date 27/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains N/A Condition N/A Use N/A Plant Remains N/A Condition N/A Use N/A Machinery Remains N/A Condition N/A Use N/A

Description Site of malt store. Area recently redeveloped for housing.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-035-007; OFIAR-035-047

Other dbase

References

Site no	OFIAR-035-071
SITE NO	

County	Offaly	Townland	Townparks (Ballybritt By)	Town	Birr
--------	--------	----------	---------------------------	------	------

Planning Birr UDC Discovery map 53 Six-inch map 35

Summary Site of tuck mill marked on late 17th century town map.

History Site of tuck mill marked on 1691 town plan.

Component OFIAR-035-071 1

Type Tuck mill (water) Function Wool

Category Textile manufacture & products Context Industry

Irish Grid 205651 204866 +/- 100m

Survey date Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains No visible remains Condition N/A Use N/A Condition N/A **Plant** Remains No visible remains Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site of tuck mill in what is now Birr Demesne.

Interest Archaeological

Evaluation Although of archaeological interest as a 17th century mill, the site has no upstanding

remains and is therefore of no industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase SMR OD035-012017-

References

Archaeological Survey of Ireland record.

Page(s)

Site no OFIAR-036-018

County	Offaly	Townland Ballyshane (Ballybritt By)	Town				
Planning	Offaly CC	Discovery map 54	Six-inch map 36				
Summary	Site of 18th/early 19th century water-powered corn mill on tributary of Camcor River.						
History	Explicitly cited of cleared by 1909	on 1838 OS six-inch map only. Building show edition.	n on 1885 map, but site				

Component OFIAR-036-018 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 218285 204212 +/- 10m

Survey date 26/06/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A
Waterworks Remains No visible remains Condition N/A Use N/A
Plant Remains No visible remains Condition N/A Use N/A
Machinery Remains No visible remains Condition N/A Use N/A

Description Site of corn mill on left bank of tributary of Camcor River. This field is known as "Mill

Meadow".

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Scully, T. Slieve Bloom from Father to Son (Roscrea: Slieve Bloom Rural Page(s) 80 Development Society, 2002).

Site no	ΛEI	AR-	126	04 O
Site no	UFI	AK-I	J.5'D-	บาร

County Planning	Offaly Offaly CC	Townland Balli	ncur (Ballybritt By) 54	Town Six-inch map 36	
Summary	Traces of 18th/e		vater-powered grain mill o	on tributary of Camcor	
History	Cited as mill on 1838 OS six-inch map, along with a starch house to its north. Recorded as a flour mill in 1840s Mill Valuation book. Then occupied by Maria Foster. A 16ft x 3ft 9in waterwheel drove two sets of stones. In 1854, the owners were Maria Foster and Andrew Mitchell (Griffith Valuation). The house, offices and corn mill were rated at £45 - a relatively high valuation considering what now survives. Cited as mill on 1885 OS map. John Feehan notes a flax mill near				

Kinnitty, but uncertain whether refers to this site. All the buildings were roofless by the

Component OFIAR-036-019 1

1909 OS.

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 217858 205675 +/- 10m

Survey date 26/06/2003 Surveyor Fred Hamond

Remains Traces Building Condition Poor Use Disused

Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Remains No visible remains Use N/A Condition N/A

Machinery

Description Fragmentary random rubble foundation courses of presumed mill to east of small

stream running north.

Component OFIAR-036-019 2

Type Starch house Function Unknown

Textile manufacture & products Category Context Industry

Irish Grid 217841 205714 +/- 10m

Survey date 26/06/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Remains No visible remains Use N/A Machinery Condition N/A

No traces of former starch house survive. Description

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Feehan, J. The Landscape of Slieve Bloom: a Study of its Natural and Page(s) 125 Human Heritage (Dublin: Blackwater Press, 1979).

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 75 of Ireland c.1850 (Dublin, 2000).

OFIAR-036-019_01 FWH 26/06/2003 Remains of mill from south.



Site no	OFIAR-037	7-002	Cadamstown Mill
County	Offaly	Townland Cadamstown	Town
Planning	Offaly CC	Discovery map 54	Six-inch map 37
Summary	used as a wo	pay, $4\frac{1}{2}$ storey water-powered corn mil ollen weaving factory and saw mill in land earlier mill adjoin.	
History	Datestone on	door jamb attests to erection by SM [=	S Manifold] in 1831. According to

History

Datestone on door jamb attests to erection by SM [= S Manifold] in 1831. According to owner, superseded an earlier mill on this site. Cited in the 1838 OS six-inch map as a mill. Described in the 1840s Mill Valuation book as a corn mill operated by Daniel Maryfold [sic]. It had a 14ft 3in x 2ft 8in waterwheel driving two sets of stones. There was also a shelling mill (for removing the outer skin from oats) with a 15ft 4in x 2ft 8in wheel. The 1854 Griffith Valuation notes George Manifold as the operator. Its rateable valuation was £30. Also cited as a mill on the 1885 OS map. According to the present owner, it was used as a weaving factory for woollen cloth by William Slevin from 1889 to 1903. However, may have continued as cited as a woollen mill on the 1909 map. Owner also stated that the building was used by Pat Slevin as a saw mill until c.1914, when became defunct.

Component OFIAR-037-002 1

Type Grain kiln; Grain mill (water); Saw Function Grain milling; Timber processing &

mill (water); Weaving factory products; Wool

Category Food processing & products; Context Industry

Timber processing & products; Textile manufacture & products

Irish Grid 222692 208515 +/- 10m

Survey date 26/06/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused Waterworks Remains Some remains Condition Poor Use Disused Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Building

A detached five-bay, 4½-storey former water-powered corn mill aligned east-west on left bank of Silver River, just below road bridge. It is cut into the slope such that only the top three storeys are visible from the road. Half-hipped roof is now missing. Unrendered random rubble walls with dressed stone eaves. Square-headed openings with stone heads and jambs; no cills to windows. One of the door jambs bears the inscription "SM 1831". On one of the door heads is painted "W Slevin". The east gable is abutted by a three-storey lean-to. The ghost of a former kiln is visible on the west gable. None of the floors survive inside.

Nearby is the former mill house, now refurbished and greatly enlarged

Waterworks, plant and machinery

The mill pond was directly south of the mill but has been infilled. One of the two headraces still carries water. The tailrace is culverted back to the river. The ground floor of the mill is divided into three sections,w ith the waterwheel pit in the middle section. The pit measures 99cm (3ft 3in) wide and the long-gone wheel was probably c.4.27m (14ft) in diameter, with an overshot or pitchback feed. It drove machinery in

the west section of the mill, none of which survives. A channel running parallel with the wheel pit apparently housed a similarly-sized waterwheel which drove a second mill in the east section.

Component OFIAR-037-002 2

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 222691 208509 +/- 10m

Survey date 26/06/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Poor Use Disused Waterworks Remains Some remains Condition Poor Use Disused

Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description The ruinous remains of a building towards the east end of the south elevation of the

present mill (component 1) were, according to the owner, those of an earlier mill

known as Mo

Interest Architectural; Historical; Setting

Evaluation A good example of a medium-sized corn mill which is also of historical interest

because of its attested date (1831) and presence of an earlier mill. The various changes of use are of note and the building also adds interest to the landscape. For all these reasons, It is of regional industrial heritage significance and merits its inclusion as a Protected Structure in the Co Offaly Development Plan 2009-15.

Rating Regional Protection Offaly RPS 51-02 Action None (in RPS)

Associated with

Other dbase NIAH 14817002 (R)

References

Feehan, J. The Landscape of Slieve Bloom: a Study of its Natural and Page(s) 125 Human Heritage (Dublin: Blackwater Press, 1979).

Feehan, J. The Landscape of Slieve Bloom: a Study of its Natural and Page(s) 126

Human Heritage (Dublin: Blackwater Press, 1979).

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s)

of Ireland c.1850 (Dublin, 2000).

OFIAR-037-002_01 FWH 26/06/2003 Mill complex from south.



OFIAR-037-002_02 FWH 26/06/2003 Mill complex from east.



OFIAR-037-002_03 FWH 26/06/2003 Mill from north-east.



OFIAR-037-002_04 FWH 26/06/2003 Mill from north-east.



OFIAR-037-002_05 FWH 26/06/2003 Mill from north-west.



OFIAR-037-002_06 FWH 26/06/2003 Internal waterwheel pits.



OFIAR-037-002_07 FWH 26/06/2003 "SM 1831" inscribed stone on door jamb.



Site no OFIAR-037-005

County Offaly Townland Cadamstown **Town**

Planning Offaly CC **Discovery map** 54 Six-inch map 37

Millstone extraction site on bed of Silver River north of Cadamstown Bridge. **Summary**

Date unknown, but probably in use during 18th and/or 19th centuries. **History**

Component OFIAR-037-005 1

Type Millstone quarry Function Stone

Category Mineral extraction, processing & Context Industry

products

Irish Grid 222714 208533 +/- 10m

Fred Hamond Survey date Surveyor

Building Remains Substantial remains Condition Fair Use Disused

Waterworks Remains N/A Use N/A Condition N/A Plant Remains N/A Condition N/A Use N/A

Machinery Remains N/A Condition N/A Use N/A

Description Not surveyed in detail.

Rarity Interest

Of regional industrial heritage significance as an attested millstone production site. **Evaluation**

Merits inclusion in Record of Monuments & Places.

Action RMP Rating Regional **Protection**

Associated with

Other dbase SMR OF037-001---

References

Scully, T. Slieve Bloom from Father to Son (Roscrea: Slieve Bloom Rural Page(s) 87

Development Society, 2002).

Site no OFIAI	R-038-009
---------------	-----------

County	Offaly	Townland Rath More	Town			
Planning	Offaly CC	Discovery map 53	Six-inch map 38			
Summary	Unlocated 18th/early 19th century water-powered threshing mill cited in 1840s Mill Valuation book. Possibly associated with Rathmore Demesne.					
History	Cited in 1840s Mill Valuation book as a threshing mill belonging to Edward Synge. A 13ft 6in wheel drove the thresher.					

Component OFIAR-038-009 1

Type Threshing mill (water) Function Grain processing

Category Farming production Context Agriculture & fishing

Irish Grid 207821 197964 +/- 1000m

Survey date Surveyor Fred Hamond

Condition N/A Building Remains No visible remains Use N/A Waterworks Remains No visible remains Condition N/A Use N/A Condition N/A Plant Remains No visible remains Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Not surveyed. Presumed to be a site.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

_			_	_	_	_			_				_	_
15	M	1-(Q	3	-0	R	Δ	FI	ח	(no		ite	S
,	w	/-L		.5	-u	ĸ	А		. ,		no	١	ITE	- 5

County	Offaly	Townland Aghagurty	Town
Planning	Offaly CC	Discovery map 54	Six-inch map 39
Summary	Traces of mic Closed c.191	1 19th century water-powered corn mi	ill on tributary of Camcor River.
History	worked by Ed	rn on 1838 OS six-inch map. 1854 Gr lward Carry; rated at £10. Explicitly c	

Component OFIAR-039-005 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 216474 201168 +/- 10m

Survey date 26/06/2003 Surveyor Fred Hamond

Building Remains Traces Condition Poor Use Disused Waterworks Remains Some remains Condition Poor Use Disused Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains Traces Condition Poor Use Disused

Description Derelict remains of corn mill on right side of tributary of Camcor River, at end of lane

off minor road. Only the east wall of two-storey mill survives. Amongst the internal wall collapse is a one-piece conglomerate millstone, 1.52m (5ft) in diameter; also a stone nut and spindle, and an octagonal centre of a French burrstone. A partly infilled

headrace is evident to east.

Component OFIAR-039-005 2

Type Mill house Function Grain milling

Category Food processing & products Context Industry

Irish Grid 216461 201220 +/- 10m

Survey date 26/06/2003 Surveyor Fred Hamond

Building Remains Complete Condition Poor Use Disused

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A
Use N/A

Description North-west of the mill is a derelict former mill house. It is a two-storey/three bay

building with hipped natural slate roof, random rubble walls and square-headed

openings, and radial over-light to entrance door.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Scully, T. Slieve Bloom from Father to Son (Roscrea: Slieve Bloom Rural Page(s) 57 Development Society, 2002).

OFIAR-039-005_01 FWH 26/06/2003 Remains of mill from south-west.



OFIAR-039-005_02 FWH 26/06/2003 Mill house from south.



Site no	OFIAR-039-0)11			
County Planning	Offaly Offaly CC	Townland Knock	carley 54	Town Six-inch map 39	
Summary		century water-power century saw mill (u		and kiln on tributary of Camcor ter powered).	
History	Cited as corn mill on 1838, 1885 and 1909 OS six-inch maps. Noted in 1840s Mill Valuation book as belonging to Thomas Mitchell and incorporating both corn and flour mills. A 14ft x 3ft waterwheel in the corn mill drove two sets of stones, whilst a 14ft 6in x 3ft wheel in the flour mill also drove two sets of stones. However the flour mill did not work very often. Mitchell was also working the mill in 1851 (Griffith Valuation). The house, offices, corn mill and kiln were then rated at £30, indicating a sizeable enterprise. According to Tony Scully, latterly owned by Bennetts and worked until 1950s.				
Component	OFIAR-039-011	1			
Туре	Grain kiln; Grain mill (water)	n mill (water); Saw	Function	Grain milling; Timber processing & products	
Category	Food processing Timber process		Context	Industry	
Irish Grid	216016 199522	2 +/- 10m			
Survey date	26/06/2003	Surveyor	Fred Han	nond	
Building	Remains Some	e remains Cor	ndition Fair	Use Agricultural building	

Waterworks Remains No visible remains Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Remains of former corn/saw mill and kiln on left bank of tributary of Camcor River,

SW of Knockarley Bridge. Buildings now refurbished for agricultural use. The corn mill was originally three storeys high and is aligned approximately east-west. Two of its surviving walls (at south and east) have been incorporated into an open-sided byre. The east end appears to be a later addition. Replacement monopitched corrugated metal roof, random rubble walls and square-headed openings.

Miscellaneous farm outbuildings and two-storey/three-bay former mill house at road

(for sale at time of survey). No traces of waterworks, plant or machinery.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Feehan, J. The Landscape of Slieve Bloom: a Study of its Natural and Human Heritage (Dublin: Blackwater Press, 1979).

Scully, T. Slieve Bloom from Father to Son (Roscrea: Slieve Bloom Rural Development Society, 2002).

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-039-011_01 FWH 26/06/2003 Mill remains from south-east.



0:4	OFIAD 000 044
Site no	OFIAR-039-014

CountyOffalyTownlandBallygaddy (Ballybritt By)Town

Planning Offaly CC Discovery map 54 Six-inch map 39

Summary Site of 18th/early 19th century malt house.

History A malt house is cited on the 1838 OS six-inch map.

Component OFIAR-039-014 1

Type Malt house Function Malting

Category Drink processing & products Context Industry

Irish Grid 213014 199086 +/- 10m

Survey date 26/06/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains N/A Condition N/A Use N/A Plant Remains N/A Condition N/A Use N/A Machinery Condition N/A Use N/A Remains N/A

Description Site of malt house in what is now farmyard just west of Ballygaddy Cross Roads.

Existing buildings may possibly incorporate fabric from it.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Site no OFIAR-041-004

County	Offaly	Townland Kilcomin	Town
Planning	Offaly CC	Discovery map 53	Six-inch map 41
Summary			n century water-powered grain mill and I is cited hereabouts on 1655 Down

History

Captioned as a flour mill on the 1838 OS map. Described in the 1840s Mill Valuation book as a flour mill operated by John Tracy. It had a 15ft x 3ft 4in waterwheel driving two sets of stones. The 1854 Griffith Valuation describes the premises as flour and corn mill, offices, all operated by John Tracy and rated at £40. Shown, but not captioned on the 1885 OS map. Cited as a disused corn mill on the 1909 OS map. Although this mill is probably of early 19th century date, a water-powered mill is also cited hereabouts in 1655 Down Survey.

Component OFIAR-041-004 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 202622 191083 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused Waterworks Remains Some remains Condition Poor Use Disused Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Building

A four-storey L-shaped block incorporating two three-storey returns and a two-storey kiln, all now derelict. The main section of the block is aligned east-west. Gables indicate that its roof was formerly pitched; vestiges of natural slate. Walls of random rubble, with dressed stone quoins and vestiges of lime render. Square-headed openings with flat brick heads and rendered stone jambs; no cills to windows. No internal floors survive, nor any machinery.

The west and middle sections of the south elevation are abutted by two three-storey roofless returns. The west end of the north elevation was formerly abutted by another return, now gone.

The east gable is abutted by a very derelict two-storey kiln (fragments of perforated clay tiles). A relatively modern Dutch barn has been erected in the corner formed by the return, mill and kiln.

Waterworks, plant and machinery

The headrace has been infilled. It ran under the mill in a northerly direction then turned 90 degrees to feed the wheel. The line of the tailrace can be discerned running north from the mill along a field boundary.

The waterwheel formerly sat at the east end of the north elevation. Only its pit remains, with curved dressed stone apron. The level of the intake feed suggests a pitchback or high breastshot wheel 21-22ft diameter by upwards of 7ft wide (this is much larger than the one in the 1840s Valuation and is evidently a later replacement). No machinery survives.

Interest Archaeological; Historical

Evaluation Of archaeological interest as a possible mid 17th century mill site. Too little now

survives of the upstanding mill to make it of regional interest. It is now primarily of

local industrial heritage interest for historical reasons.

Rating Local Protection Action

Associated with

Other dbase SMR OF041-005---

References

Archaeological Survey of Ireland record.

Page(s)

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills of Ireland c.1850 (Dublin, 2000).

Page(s) 74

OFIAR-041-004_01 FWH 01/08/2003 General view from north-east.



OFIAR-041-004_02 FWH 01/08/2003 General view from south.



OFIAR-041-004_03 FWH 01/08/2003 Waterwheel pit from west looking towards tailrace end.



Site no	OFIAR-041-005
---------	---------------

County	Offaly	Townland Kilco	min	Town
Planning	Offaly CC	Discovery map	53	Six-inch map 41
Summary	Ruinous rema	-	ouble-pile	/two-storey (+ attic) distillery. Uncertain if
History	neighbouring	•	AR-041-0	ap. MacMahon states that it and a 06) were both out of use by 1818. er OS maps.

Component OFIAR-041-005 1

Type Distillery Function Distilling

Category Drink processing & products Context Industry

Irish Grid 202523 190751 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Poor Use Disused Waterworks Remains No visible remains Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Ruinous remains of distillery aligned north-south behind modern house to west of

minor road. Double-pile/two-storey (+ attic) building. Formerly with pitched and half-hipped roofs to east and west piles respectively; the former now has replacement corrugated metal monopitched roof. Openings have flat, segmental and semi-elliptical brick heads and jambs. Large semicircular arched openings in south gables of both piles. Gable loading doors to first and attic floors of west pile. Traces of

abutting buildings at south and east. No evidence of any water power.

Interest Historical

Evaluation Now primarily of historical interes, the surviving remains are of local industrial

heritage significance.

Rating Local Protection Action

Associated with

Other dbase

References

MacMahon, N. In the Shadow of the Fairy Hill: a History of Shinrone and Ballingarry from Pre-Christian Times to the Early 1900s (Shinrone: Kilcommon Press, 1998).

Page(s) 90-91

OFIAR-041-005_01 FWH 01/08/2003 General view from north.



 $OFIAR-041-005_02 \quad FWH \quad 01/08/2003 \quad \quad Interior \ of \ east \ pile, \ looking \ south.$



Site no	OFIAR-041-0	006			Kilcommon Distillery	
County	Offaly	Townland	Ballytoran		Town	
Planning	Offaly CC	Discovery m	ap 53		Six-inch map 41	
Summary	Ruinous shells of two multi-bay, multi-storey random rubble buildings and related house associated with 18th century distillery.					
History	ceased producti but not captione	According to MacMahon, this was once one of Co Offaly's foremost distilleries. It had ceased production by 1818. Cited as Old Distillery on 1838 OS map. Buildings shown but not captioned on later OS maps. Not cited in the 1840s mill valuation book, nor in the 1850s Grififth valuation.				
Component	OFIAR-041-006	i 1				
Туре	Distillery		Fun	ction [Distilling	
Category	Drink processing	g & products	Cor	ntext I	ndustry	
Irish Grid	202725 190687	7 +/- 10m				
Survey date	01/08/2003	Surve	yor Fre	ed Hamoi	nd	
Building	Remains Subs	tantial remains	Condition	Poor	Use Disused	
Waterworks	Remains N/A		Condition	N/A	Use N/A	
Plant	Remains No vi	isible remains	Condition	N/A	Use N/A	
Machinery	Remains No vi	isible remains	Condition	N/A	Use N/A	
Description	The site comprises thee sections: (1) a 10-bay, four-storey building aligned NW/SE, (2) a multi-bay, three-storey building aligned NE/SW, and (3) the former owner's house fronting the road. Building 1 is a half-hipped roofless shell of random rubble with corbelled yellow brick eaves. All door and window openings have semi-elliptical brick heads; no cills to windows. A now-demolished building abutted its SE gable. All internal floors now missing. Building 2 is partly truncated to two storeys at one end. Roof now missing; profile uncertain. Random rubble walls with brick segmental-headed openings. Miscellaneous small outbuildings now abut it. The former owner's house is a two-storey, five-bay building fronting the main road. It has a pitched corrugated metal roof, the steepness of which suggests that it was thatched originally. Rendered chimney to each gable. Cement-harled walls. Square-headed openings. Windows have replacement uPVC windows; stone cills.					
Interest	Architectural; Hi	istorical; Settin	g			
Evaluation	architectural me heritage signfica	erit because of ance and warra	its scale and ints its inclus	l a promi	his complex is also of nence. It is of regional industrial Protected Structure in the Coouse is likewise included.	
Rating	Regional	Protection	Offaly RP		Action None (in RPS)	

References

MacMahon, N. In the Shadow of the Fairy Hill: a History of Shinrone and Ballingarry from Pre-Christian Times to the Early 1900s (Shinrone: Kilcommon Press, 1998).

Page(s) 90-91

OFIAR-041-006_01 FWH 01/08/2003 Building 1, from south-west.



OFIAR-041-006_02 FWH 01/08/2003 Building 1, from north-east.



 $OFIAR-041-006_03 \quad FWH \quad 01/08/2003 \quad \quad Building \ 2, from \ south-east.$



 $OFIAR-041-006_04 \quad FWH \quad 01/08/2003 \qquad Building \ 2, from \ east.$



OFIAR-041-006_05 FWH 01/08/2003 South-west elevation of mill house.



Site no	OFIAR-041-007
Site IIO	OFIAR-041-001

County Planning	Offaly Offaly CC	Townland Rush	neen 53	Town Six-inch map 41
Summary	18th/early 19th	century water-powe	ered corn mill on	tributary of Little Brosna River.
History	corn mill opera stones. Noted a along with a ho	ted by Mary Tiguin. as belonging to Mary	A 16ft x 3ft 2in v yanne Tiquin in 7 s, at £10. Captio	1840s Mill Valuation book as a waterwheel drove three sets of 1851 Griffith Valuation and rated, oned as Corn mill (in ruins) on 1884

Component OFIAR-041-007 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 202660 190165 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Waterworks Remains No visible remains Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Site competely cleared of all buildings. The former mill pond is now a flat marshy

area.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-042-008	Mill Park
County	Offaly Townland 6	Glasderry More Town
Planning	Offaly CC Discovery ma	ap 53 Six-inch map 42
Summary	Place name suggests 18th cent knowledge.	tury mill site, of which there is no trace or local
History	'Mill Park' is cited on 1838 and captioned Mill Grove on 1909 e	1885 OS maps. The plantation adjoining to east is edition.
Component	OFIAR-042-008 1	
Туре	Mill?	Function Unknown
Category	Unknown	Context Industry
Irish Grid	208413 194830 +/-10m	
Survey date	01/08/2003 Survey	or Fred Hamond
Building	Remains No visible remains	Condition N/A Use N/A
Waterworks	Remains No visible remains	Condition N/A Use N/A
Plant	Remains No visible remains	Condition N/A Use N/A
Machinery	Remains No visible remains	Condition N/A Use N/A
Description		e of former mill of unknown function. No traces evident er House. A water channel now supplies a fish pond
Interest	None	
Evaluation	No industrial heritage significar	nce.
Rating	Record only Protection	Action

References

Other dbase

Site no	OFIAR-042	2-009	Brosna Maltings
County	Offaly	Townland Drumakeenan (Clon Ettagh Par)	lisk By, Town
Planning	Offaly CC	Discovery map 53	Six-inch map 42
Summary	Derelict remains of substantial mid 19th century maltings belonging to Merrs Perry incorporating an 18th/early 19th century water-powered flour mill. Large waterwhe and power transmission gearing survive.		
History		the 1840s Mill Valuation book as a floor 10ft waterwheel driving five pairs of	French burr stones. The wheel

turned at 3½ rpm and was the fifth largest diameter wheel in the county at this time. The premises had a rating of £84.10s.0d - the second highest in the county after Manor Mill, Birr (OFIAR-035-009). Dowd may also have been operating another nearby flour mill at this time (OFIAR-042-010). Noted in the 1851 Griffith Valuation as belonging to Robert Dowd, along with a miller's house and office. It was rated at £150 at that time. This rating is equalled by

house and office. It was rated at £150 at that time. This rating is equalled by Charlestown Mill, Clara (OFIAR008-042) and surpassed only by Erry Mill, Clara (OFIAR-008-038). Dowd was also operating the above flour mill at this time as well. Cited as Brosna malt house on 1885 OS map, and as Brosna Maltings on 1909 edition. Probably in the hands of Messrs Perry by this time.

Component OFIAR-042-009 1

Type Grain kiln; Grain mill (water); Malt Function Grain milling; Malting

house

Category Food processing & products; Drink Context Industry

processing & products

210185 191883 +/- 10m

Survey date 18/07/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused Waterworks Remains Substantial remains Condition Fair Use Disused Plant Remains Complete Condition Poor Use Disused Machinery Remains Some remains Condition Poor Use Disused

Description Buildings

Irish Grid

This block comprises three contiguous bays all aligned east -west. The north bay stands six floors high, including basement and attic. The roof is largely missing but there are vestiges of a half-hip gable at its west end covered with natural slates over common rafters and single purlins. The walls are of random rubble, with ashlar eaves and dressed quoins; also vestiges of lime render. Square-headed openings with brick heads and jambs; no cills to windows. Window frames are 4x4-pane metal frames and 2x3 timber casements. Apart from the ground floor, there are no internal floors or machinery. There are remains of perforated zinc sheeting which probably belonged to a former kiln.

The middle bay is four storeys high (including attic) and has similar roof and wall detailing to the north section. Its east gable is inset slightly from those on either side and its west end projects. Its west gable is abutted by a single-storey roofless waterwheel house. Internally, the floors are now missing. At on corner of the ground floor is a jack-arch ceiling (three arches), probably part of a former kiln. The south bay is similar to the north section. Although very overgrown, it appears to

be largely devoid of openings. A ground floor door and window both have voussoired stone heads and jambs and the windows have stone cills. There is a chimney on its east gable.

A plaque built into a new boundary wall to a house on the north side of the road past the complex reads "Perry's Mill". This was presumably from a gatepost or one of the buildings in the complex.

Waterworks

The mill pond is still discernible a short distance south of the block, albeit largely infilled. The masonry sluice gate emplacement at its outlet survives. The head- and tailraces survive as drainage channels.

Plant

The waterwheel on the return projecting from the west gable of the middle bay is of the high breastshot variety and measures 14ft in diameter by 14ft wide. It is of metal construction throughout, with eight spoked arms and 40 curved buckets (all unventilated). Cast on to the rim is "Jacob Clonmel 1855". Apart from its metal soleplate and some buckets, the wheel survives intact.

Machinery

The power transmission machinery is contained within the projecting west gable of the middle bay. A cast-iron segment wheel affixed to the mill side of the waterwheel connects with a bull nut mounted on the outer end of a cast-iron axle. At the other end of this axle, in side the mill, is a bevelled pitwheel which drives a wallower mounted at the bottom end of the cast-iron upright shaft.

Mounted on the axle between the bull nut and pitwheel is a spur gear connected to a smaller pinion. Along the axle on which this pinion is mounted is a large pulley wheel and small external pulley wheel. It is uncertain whether the latter was an external drive to the machinery, or an external power take-off driven from the waterwheel. The collapsed remains of other shafts and gears are also visible inside the building.

Interest Architectural; Historical; Technical

Evaluation This is one of the largest surviving industrial sites in Co Offaly, albeit in a very

derelict state. The sheer scale of the buildings, historical link with the Perrys, and survival of the waterwheel and principal gearing all make it of regional industrial heritage signficance. It merits inclusion in the Record of Protected Structures.

Rating Regional Protection Action RPS

Associated with OFIAR-042-010

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 73 of Ireland c.1850 (Dublin, 2000).

OFIAR-042-009_01 FWH 18/07/2003 General view from north-east.



OFIAR-042-009_02 FWH 18/07/2003 General view from south-east.



OFIAR-042-009_03 FWH 18/07/2003 General view from south-west.



OFIAR-042-009_04 FWH 18/07/2003 General view from west.



OFIAR-042-009_05 FWH 18/07/2003 Looking west inside middle bay.



OFIAR-042-009_06 FWH 18/07/2003 Collapsed remains of perforated zinc floor in north pile.



OFIAR-042-009_07 FWH 18/07/2003 Waterwheel.



OFIAR-042-009_08 FWH 18/07/2003 Waterwheel axle.



OFIAR-042-009_09 FWH 18/07/2003 Founder's mark (Jacob Clonmel 1855).




OFIAR-042-009_10 FWH 18/07/2003 Bull nut driven by segment wheel on inner end of waterwheel axle.



OFIAR-042-009_11 FWH 18/07/2003 Power transmission gearing at west end of middle bay.



OFIAR-042-009_12 FWH 18/07/2003 Name plaque on entrance to house opposite maltings.



Site no	OFIAR-042-010
OILE HU	

County Offaly Townland Drumakeenan (Clonlisk By, Town

Roscrea Par)

Planning Offaly CC Discovery map 53 Six-inch map 42

Summary Ruinous remains of mid 19th century water-powered corn mill on right bank of Little

Brosna River.

History First shown on 1885 OS six-inch map and captioned as a mill. Marked as a disused

corn mill on 1909 edition. This may be the flour mill cited in the 1840s Mill Valuation book as belonging to Richard Dowd. An 18ft x 7ft 6in wheel drove four sets of stones (however, this valuation entry could refer to OFIAR-042-011). The property was valued at £71.11s.0d - the fourth highest in the county. Dowd also owned Brosna flour mill at this time (OFIAR-042-009). Belonged to Robert Dowd in 1851, when described as a flour mill and rated at £80 (Griffith Valuation). Dowd was also operating the other

flour mill at this time as well.

Component OFIAR-042-010 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 210622 191539 +/- 10m

Survey date 18/07/2003 Surveyor Fred Hamond

Building Remains Some remains Condition Poor Use Disused

Waterworks Remains Some remains Condition Poor Use Disused

Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Ruinous remains of corn mill on right bank of Little Brosna River. Aligned east-west

along north side of race, just above river. Overgrown partial remains of roofless random rubble building, at least three storeys high and of L plan. Square-headed openings, some with brick heads and jambs. Overgrown head and tailraces still evident; now dry. The infilled wheelpit, on south wall, is 2.36m (7ft 9in) wide.

Interest None

Evaluation No special industrial heritage significance.

Rating Record only Protection Action

Associated with OFIAR-042-009

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-042-010_01 FWH 18/07/2003 Mill remains from north-east.



Site no	OFIAR-042-011 Fanure Mill			
County	Offaly Townland Drumakeenan (Clonlisk By, Town Roscrea Par)			
Planning	Offaly CC Discovery map 53 Six-inch map 42			
Summary	Traces of 18th/early 19th century water-powered flour mill on Little Brosna River. Waterworks reused for Roscrea Fish Farm.			
History	Cited as a flour mill on 1838 and 1885 OS six-inch maps, and as Fanure corn mill on 1909 map. This may be the flour mill cited in the 1840s Mill Valuation book as belonging to Adam Acres. A 16ft x 6ft 3in wheel drove three sets of stones (however, this valuation entry could refer to OFIAR-042-010). It was valued at £53.13s.3d - the sixth most valuable premises in the county. Belonged to George Acres in 1851, when the house, offices and flour mil were rated at £87 - the eighth highest in Co Offaly (Griffith Valuation).			
Component	OFIAR-042-011 1			
Туре	Grain mill (water) Function Grain milling			
Category	Food processing & products Context Industry			
Irish Grid	210978 190640 +/-10m			
Survey date	18/07/2003 Surveyor Fred Hamond			
Building	Remains Traces Condition Good Use Fish farm			
Waterworks	Remains Substantial remains Condition Good Use Fish farm			
Plant	Remains No visible remains Condition N/A Use N/A			
Machinery	Remains No visible remains Condition N/A Use N/A			
Description	Buildings Traces of 18th/early 19th century water-powered flour mill on east side of Little Brosna River. Vestiges of the mill survive as a random rubble wall along the tailrace at north end of existing complex. Remains have been incorporated into fish farm supplied by the former pond and races. The adjoining former mill house, a double- pile/two-storey/three-bay building, has been refurbished as offices, but is now disused. Waterworks, plant and machinery The waterworks are now used by the fish farm. The waterwheel is long gone but its pit survives at the NE end of the former mill. It is 1.98m (6ft 6in) wide and the fall of water was upwards of 4.57m (15ft). No machinery survives.			
Interest	None			
Evaluation	This was once a sizeable concern, but has largely been demolished and is now of no special industrial heritage significance.			
Rating	Record only Protection Action			
Associated v	vith			

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-042-011_01 FWH 18/07/2003 Remains of former mill.



OFIAR-042-011_02 FWH 18/07/2003 Waterwheel pit.



OFIAR-042-011_03 FWH 18/07/2003 Former mill house, from west.



Site no	OFIAR-042	-012	Hillsborough Mills	
County	Offaly	Townland Drumakeenan (Clonli Roscrea Par)	sk By, Town	
Planning	Offaly CC	Discovery map 53	Six-inch map 42	
Summary	Derelict shells of a 18th/early 19th century water-powered grain mills and kiln on Little Brosna River. The flour mill was used for a timeas a tuck mill.			
History	Valuation boo waterwheel dr by Buckley. It, teaser, scrubb finishing wooll The 1851 Grif cloth mills whi	cited on the 1838 OS map, with a clot on the a flour mill operated by Henry iving a two pairs of French burr stone too, was powered by 18ft x 4ft water ers, stocks, and napping machines (i. en cloth). Fith Valuation notes Buckley as continch had a combined rating of £100 - the cited on the 1885 OS map and Hillster.	Buckley. It had an 18ft x 4ft s. The cloth mill was also operated wheel and contained a willy, e.e. equipment for washing and using to operated the flour and he sixth highest in Co Offaly.	

Component OFIAR-042-012 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 211298 190631 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused Waterworks Remains Some remains Condition Poor Use Disused Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Buildings

A five-storey, five-bay roofless shell of former oatmeal mill, aligned east-west at NW corner of premises. Now roofless, but gables indicate a half-hipped profile. Very overgrown rendered random rubble walls with stone eaves and dressed stone quoins. Square-headed openings with yellow brick jambs. No floors survive internally.

Waterworks, plant and machinery

Pond and headrace infilled. Traces of tailrace along north side of access lane from road. Waterwheel pit on west gable, 1.52m (5ft) wide. No machinery survives.

Component OFIAR-042-012 2

Type Grain kiln; Grain mill (water); Tuck Function Grain milling; Wool

mill (water)

Category Food processing & products; Context Industry

Textile manufacture & products

Irish Grid 211319 190617 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused Waterworks Remains Some remains Condition Poor Use Disused

Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Buildings

A five-bay, five-storey roofless shell of former flour/tuck mill, aligned north-south at SE corner of premises. Now roofless, but gables indicate a hipped profile. Rendered random rubble walls with stone eaves and dressed stone quoins. Square-headed openings with rendered brick heads and stone jambs; window cills partly removed. Upper floor openings are diminished in height. No floors survive internally.

East elevation abutted by a two-storey former grain kiln, now without roof or drying floor. Vestiges of random rubble furnace and ghost of vaulting on inside face of wall.

Waterworks, plant and machinery

Pond and headrace infilled. Traces of tailrace along north side of access lane from road. Waterwheel pit on north gable with dressed stone apron; 2.29m (7ft 6in) wide. Level of intake feed indicates a high breastshot wheel. No machinery survives.

Interest Architectural; Historical

Evaluation The scale of these buildings attests to the importance of grain milling in this area

during the late 1700s/ early 1800s. The mills are also of historical interest and also add interest to the landscape hereabouts. Despite being only shells, their size makes them of regional industrial heritage merit. The two mills merit their inclusion as

Protected Structures in the Co Offaly Development Plan 2009-15.

Rating Regional Protection Offaly RPS 61-18 Action None (in RPS)

Associated with OFIAR-042-025

Other dbase NIAH 14942021(R)

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 76 of Ireland c.1850 (Dublin, 2000).

OFIAR-042-012_01 FWH 01/08/2003 General view of grain mill (left) and cloth mill (right).



OFIAR-042-012_02 FWH 01/08/2003 Grain mill, from south.



OFIAR-042-012_03 FWH 01/08/2003 Grain/cloth mill, from south-west.



OFIAR-042-012_04 FWH 01/08/2003 Grain/cloth mill, from north-east.



OFIAR-042-012_05 FWH 01/08/2003 Interior of grain/cloth mill, looking south-west.



OFIAR-042-012_06 FWH 01/08/2003 Waterwheel pit at north end of grain/cloth mill.



OFIAR-042-012_07 FWH 01/08/2003 Waterwheel pit at north end of grain/cloth mill.



 $OFIAR-042-012_08 \quad FWH \quad 01/08/2003 \qquad \text{Kiln in grain/cloth mill.}$



Site no OFIAR-042-017

County Offaly Townland Clyduff (Clonlisk By); Town

{Milltown}

Planning Offaly CC Discovery map 53 Six-inch map 42

Summary Derelict shell of 18th/early 19th century water-powered flour mill with remains of

waterwheel on tributary of Little Brosna River.

History A flour mill is cited on the 1838 OS six-inch map. The 1840s Mill Valuation book notes

a flour mill under James Bergin. A 14ft x 2ft 9in wheel drove two sets of stones. The 1851 Griffith Valuation notes the flour mill as being operated by John Bergin; he was also operating a nearby flour mill at this time as well (OFIAR-043-002). Not explicitly

cited on 1885 or 1909 OS maps.

This location was formerly part of Milltown townland until the boundary was changed. This suggests that there was a mill hereabouts in the 1700s if not before. Whether it

was at this spot is, however, uncertain.

Component OFIAR-042-017 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 207081 190570 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused

Waterworks Remains Substantial remains Condition Poor Use Disused

Plant Remains Some remains Condition Poor Use Disused

Machinery Remains No visible remains Condition N/A Use N/A

Description Buildings

A four-storey, seven-bay building aligned east-west. Although now roofless, gables indicate it formerly had a pitched natural slate roof. Random rubble walls with dressed quoins and eaves. Flat-headed brick-trimmed openings. Internally divided into three structural bays, all without floors and overgrown. No evidence of kiln.

Waterworks, plant and machinery

Overgrown mill pond at rear. Water therefrom still flows through waterwheel pit. The tailrace arch is evident on the north elevation but the water is now piped underneath the made-up ground in front of the mill.

The east bay contains a wide waterwheel pit, divided into two longitudinal sections, one to accommodate the wheel and the other for the overspill from the pond. The waterwheel remains comprise a round timber axle, one cast-iron hub (partly broken), two timber arms and two fragments of rim covered in limescale. It appears to have been 4.27m dia by 1.22m wide (14ft x 4ft) and to have had a pitchback or high breastshot feed. No machinery survives.

Interest Architectural; Historical

Evaluation This building is a typical medium-sized mill and has some technical interest on

account of its wheel remains. It is of local industrial heritage significance.

Rating Local Protection Action

Associated with OFIAR-043-002

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-042-017_01 FWH 01/08/2003 Mill from north-east.



OFIAR-042-017_02 FWH 01/08/2003 Waterwheel remains.



Site no	OFIAR-042-0	026				
County	Offaly		Drumakeena Roscrea Par)		nlisk By,	Town
Planning	Offaly CC	Discovery m	ap 53			Six-inch map 42
Summary	Site of 18th/earl	y 19th century	water-power	ed cor	n mill on Li	ttle Brosna River.
History	the 1840s Mill V Denis and Willia	Cited as a mill on 1838 OS six-inch map, and as a corn mill on 1885 map. Not cited in the 1840s Mill Valuation book. Possibly cited in 1851 Griffith Valuation as belonging to Denis and William Loughnane and rated at £15. Appears to have been out of use by 1909 as no longer explicitly cited on map of that date.			Valuation as belonging to	
Component	OFIAR-042-026	i 1				
Туре	Grain mill (wate	r)	Fun	ction	Grain mill	ing
Category	Food processing	g & products	Con	text	Industry	
Irish Grid	210887 190873	3 +/- 10m				
Survey date	18/07/2003	Surve	or Fre	d Ham	nond	
Building	Remains No vi	isible remains	Condition	N/A	Use	N/A
Waterworks	Remains No vi	isible remains	Condition	N/A	Use	N/A
Plant	Remains No vi	isible remains	Condition	N/A	Use	N/A
Machinery	Remains No vi	isible remains	Condition	N/A	Use	N/A
Description	Site of corn mill	on right bank of	of Little Bros	na Riv	er.	
Interest	None					

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

Site no	OFIAR-042-0)27		
County	Offaly	Townland Shir	nrone	Town Shinrone
Planning	Offaly CC	Discovery map	53	Six-inch map 42
Summary	Site of 18th/early 19th century brewery.			
History	Cited as a brewery on the 1838 OS map, but otherwise not documented in the valuation books or later OS maps. Map shows no races in vicinity, indicating that not water-powered.			
Component	OFIAR-042-027	' 1		
Type	Brewery		Function	Brewing

Category Drink processing & products

Context Industry

Irish Grid 204698 192440 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains N/A Condition N/A Use N/A **Plant** Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description This area has been redeveloped for housing and no traces of the brewery survive.

Interest None

Evaluation No industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase

References

MacMahon, N. In the Shadow of the Fairy Hill: a History of Shinrone and Ballingarry from Pre-Christian Times to the Early 1900s (Shinrone: Kilcommon Press, 1998).

Page(s) 92

Site no	OFIAR-042-028
Site no	UTIAK-U4Z-UZO

County Offaly Townland Drumakeenan (Clonlisk By, Town

Ettagh Par)

Planning Offaly CC Discovery map 53 Six-inch map 42

Summary Derelict shell of 18th/early 19th century water-powered flour mill on tributary of Little

Brosna River.

History Cited as a flour mill on the 1838 OS map. Described in the 1840s Mill Valuation book

as a corn mill operated by Patrick Fitzpatrick. It had a 13ft x 2ft 2in waterwheel driving two sets of stones. Fitzpatrick was also operating the mill in 1851 (Griffith Valuation).

Not explicitly cited on 1885 or 1909 OS maps.

Component OFIAR-042-028 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 210113 192799 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused

Waterworks Remains No visible remains Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Derelict roofless shell of five-bay, three-storey grain mill aligned north-south.

Random rubble walls. Much of north end has collapsed and what remains is in very poor condition and heavily overgrown. Square-headed openings with brick heads and rendered brick jambs. Stone cills to windows. The external waterwheel pit on the

north gable has been infilled.

Interest None

Evaluation No special industrial heritage merit.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 73 of Ireland c.1850 (Dublin, 2000).

OFIAR-042-028_01 FWH 01/08/2003 General view from west.



OFIAR-042-028_02 FWH 01/08/2003 General view from north-west.



Site no OFIAR-042-029

County Offaly Townland Aghadouglas Town

Planning Offaly CC Discovery map 53 Six-inch map 42

Summary Traces of 18th/early 19th century water-powered mill of unknown function on tributary

of Little Brosna River.

History Cited as a ruined mill on 1838 and 1885 OS six-inch maps. Function unknown.

Component OFIAR-042-029 1

Type Mill (water) Function Unknown

Category Unknown Context Industry

Irish Grid 210213 193165 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Traces Condition Poor Use Disused

Waterworks Remains No visible remains Condition N/A Use N/A

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Traces of mill on tributary of Little Brosna River, in field to east of minor road. Only a

gable wall now survives: two storeys high, of random rubble and with square headed

opening to upper floor.

A 46cm dia rotary hand guern (one of a pair of stones) was found nearby by Caimin

O'Brien.

Interest None

Evaluation No special industrial heritage signficance.

Rating Record only Protection Action

Associated with

Other dbase

References

OFIAR-042-029_01 FWH 01/08/2003 Mill remains from west.



OFIAR-042-029_02 C. O'Bi01/2009

Hand quern found near mill.



Site no OFIAR-042-030 Woods' Mill

County Offaly Townland Keeloge (Clonlisk By) Town

Planning Offaly CC Discovery map 53 Six-inch map 42

Summary

Roofless shell of a five-storey, six-bay 18th/early 19th century water-powered flour mill and kiln on tributary of Little Brosna River. Subsequently used as a saw mill.

History

A flour mill and kiln are captioned on the 1838 OS map. The complex is described in the 1840s Mill Valuation book as comprising two flour mills, both operated by Thomas Woods. One had an 18ft x 2ft 6in waterwheel (with 56 buckets) and the other a 16ft 6in x 3ft 9in wheel (with 41 buckets); they turned at 8½ and 9rpm respectively and drove, between them, three pairs of French burr stones, a shelling stone, elevators and flour dressers. The 1851 Griffith Valuation describes the site as comprising a house, offices, corn and flour mill, all valued at £45 and still operated by Thomas Woods. The 1885 OS map also captions the flour mill and kiln. According to MacMahon, the mill was converted to a saw mill in 1894. An uncaptioned roofless shell is shown on the 1909 map.

Component OFIAR-042-030 1

Type Grain kiln; Grain mill (water); Saw Function Grain milling; Timber processing &

mill (water) products

Category Food processing & products; Context Industry

Timber processing & products

Irish Grid 204514 191253 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused

Waterworks Remains Substantial remains Condition Poor Use Disused

Plant Remains No visible remains Condition N/A Use N/A

Machinery Remains No visible remains Condition N/A Use N/A

Description Buildings

Main section of mill is aligned NW-SE and faces towards the public road. It is six-bays wide and five storeys high. Hipped roof, now missing. Walls of random rubble (still with traces of render), and advanced eaves course. Except for three-centred voussoired arch to the entrance doorway at the left and right ends of the ground floor frontage, all openings are square-headed and regularly spaced. The window openings to the top floor are diminished in height. None retain their frames, all are without cills and those to the ground and first floors have metal security bars.

There is a shallow five-storey, single-bay return to the SW end of the back of this section. Its ground and first floors contain a vaulted brick arch (part of its apex has collapsed). This may have been part of the kiln of which no other floors survive. Fragments of perforated clay tile are to be found through the site indicating the former presence of a kiln.

There is a slightly longer return at the other end of the mill's back wall, also a roofless shell. Abutting the SW gable of that return is a five-storey, two-bay addition (clear wall break) which was originally probably a store. Hipped roof now missing. Walls detailed as main block. Structural crack down SW gable.

The SE gable of the mill is abutted by a two-storey (+ attic), single-bay building. Roof now missing but of gabled profile. Walls detailed as main block. No internal floors, fixtures or fittings. Possibly once an office. No floors survive internally.

At the entrance of the premises is the partial shell of a two-bay, single-storey rubble stone building.

Waterworks, plant and machinery

The overgrown headrace is still visible above the mill but pond immediately behind the mill has been infilled. The headrace entered the mill between the two rear returns via two shallow segmental arches, one to each former wheel. One pit is 1.8m (6ft) wide and the other is 1.0m (3ft 3in) wide. The wheels probably had a breastshot feed. The tailraces emerge from the front wall of the mill through two segmental arches. An open channel, piped under the road, returns the water to the river. No machinery survives.

Interest Architectural; Historical; Setting

Evaluation This prominent roadside mill is typical of medium-sized late 18th/early 19th flour

mills. This one has added interest in that it milled both wheat and oats using two separate internal waterwheels. Although only a ruinous shell, its scale and situation makes it of regional industrial heritage significance. It merits its inclusion as a

Protected Structure in the Co Offaly Development Plan 2009-15.

Rating Regional Protection Offaly RPS 61-14 Action None (in RPS)

Associated with

Other dbase NIAH 14942006 (R)

References

MacMahon, N. In the Shadow of the Fairy Hill: a History of Shinrone and Ballingarry from Pre-Christian Times to the Early 1900s (Shinrone: Kilcommon Press, 1998).

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) 76 of Ireland c.1850 (Dublin, 2000).

OFIAR-042-030 01 FWH 01/08/2003 General view of north-east (front) elevation.



OFIAR-042-030_02 FWH 01/08/2003 Mill from south-east.



OFIAR-042-030_03 FWH 01/08/2003 Barrel vaulted return.



OFIAR-042-030_04 FWH 01/08/2003 Headrace intake on back wall of mill.



Site no OFIAR-042-033

County	Offaly	Townland Clareen	Town	
Planning	Offaly CC	Discovery map 53	Six-inch map 42	
Summary	19th century grain kiln and site of brewery, both associated with Clareen House.			
History	The present no		aving operated here in the late 1700s. is shown on the 1838 OS map. None of	

Component OFIAR-042-033 1

Type Brewery Function Brewing

Category Drink processing & products Context Industry

Irish Grid 205849 194172 +/- 100m

Survey date 01/08/2003 Surveyor Fred Hamond

BuildingRemainsNo visible remainsConditionN/AUse N/AWaterworksRemainsN/AConditionN/AUse N/APlantRemainsNo visible remainsConditionN/AUse N/AMachineryRemainsNo visible remainsConditionN/AUse N/A

Description No traces of the brewery are now apparent.

Component OFIAR-042-033 2

Type Grain kiln Function Grain processing

Category Farming production Context Agriculture & fishing

Irish Grid 205850 194195 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Good Use Store Waterworks Remains N/A Condition N/A Use N/A Plant Remains N/A Condition N/A Use N/A Machinery Remains N/A Condition N/A Use N/A

Description Grain kiln contained at east end of two-storey building abutting three-storey granary

at end of range of buildings along north side of farmyard associated with Clareen

House.

The building has a pitched natural slate roof, rendered random rubble walls and square-headed openings with brick trim (rendered over) and Georgian-pane frames. Internally, the kiln has a flagged stone floor, but there are no traces of any furnace. The drying floor above comprises 12-inch square clay tiles laid on cast-iron joists across the room. The joists are supported by a transverse metal beam over a metal post. Cement screed has been laid over the top surface of the tiles. The roof has tied common rafters and is internally plastered. However, there is no ridge ventilator. The adjoining three-storey granary has a hipped natural slate roof and is similarly detailed.

Interest Architectural

Evaluation This farmyard complex is of local heritge interest on account of its scale and

completeness. Both it and the house are Protected Structures in the 2009-15 Co

Offaly Development Plan.

Rating Local Protection Offaly RPS 57-07 Action

Associated with

Other dbase NIAH 14942009 (R)

References

MacMahon, N. In the Shadow of the Fairy Hill: a History of Shinrone and Ballingarry from Pre-Christian Times to the Early 1900s (Shinrone: Kilcommon Press, 1998).

Page(s) 91-93

OFIAR-042-033_01 FWH 01/08/2003 North range of farmyard at Clareen House, from south.



 $OFIAR-042-033_02 \quad FWH \quad 01/08/2003 \qquad \text{Kiln (at centre), with three-storey granary to right, from south-west.}$



OFIAR-042-033_03 FWH 01/08/2003 Underside of kiln drying floor.



OFIAR-042-033_04 FWH 01/08/2003 Kiln drying floor.



OFIAR-042-033_05 FWH 01/08/2003 Clareen House, from south-west.



Site no OFIAR-042-042

County Offaly Townland Drumakeenan (Clonlisk By, Town

Ettagh Par)

Planning Offaly CC Discovery map 53 Six-inch map 42

Summary Site of mill marked on 1655 Down Survey.

History Site of mill of unknwon function on 1655 Down Survey.

Component OFIAR-042-042 1

Type Mill Function Unknown

Category Unknown Context Industry

Irish Grid 210741 191797 +/- 1000m

Survey date Surveyor Fred Hamond

Building Remains No visible remains Condition N/A Use N/A Condition N/A Waterworks Remains No visible remains Use N/A Use N/A **Plant** Remains No visible remains Condition N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Unlocated mill site.

Interest Archaeological

Evaluation Although of archaeological interest as a 17th century mill, the site has no upstanding

remains and is therefore of no industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase SMR OF042-041--

References

Archaeological Survey of Ireland record.

Page(s)

Site no	OFIAR-043	3-002		Fancroft Mill; Bergin's Mill
County	Offaly	Townland Fand	croft	Town
Planning	Offaly CC	Discovery map	54	Six-inch map 43
Summary	on Little Bros ancillary mac	na River, complete w	ith water mpasses	orly 19th century water-powered grain mill wheel, gearing, millstones and some a four-storey grain store, two-storey and waterworks.
History	flour mill. Des	scribed in the 1840s N	1ill Valua	e. Cited in 1838 OS six-inch map as a tion book as a corn mill operated by John lriving two sets of stones. The 1851 Griffith

Valuation notes it as a flour mill, still operated by John Bergin; he was also operating a nearby flour mill at this time as well (OFIAR-042-017). Casting date on waterwheel suggests that it may have been re-equipped around 1883. On the 1886 map, the east section of the mill block is cited as a flour mill, and the west end as a corn mill. Cited

Component OFIAR-043-002 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

as Fancroft Mills (corn) on 1909 OS map.

Irish Grid 213353 192605 +/- 10m

Survey date 18/07/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Store
Waterworks Remains Substantial remains Condition Fair Use Disused
Plant Remains Complete Condition Fair Use Disused
Machinery Remains Substantial remains Condition Fair Use Disused

Description Buildings

This four-storey (+ attic), six-bay flour mill is aligned east-west across the north end of the site. Pitched natural slate roof with decorative clay ridge tiles, cement verges. Three skylights to south pitch. Semicircular rainwater goods. Walls are of squared sandstone rubble, brought to courses. Ashlar eaves. The left section on the south elevation is two openings wide and appears to be a later extension as quoins belonging to the earlier right-hand section (four openings wide) are visible under the lime render. The walls of the extension are of split random rubble.

Openings are square-headed with voussoired stone heads (mostly rendered over). All the windows are without cills. Some timber window frames survive.

There is an infilled segmental-headed opening from the waterwheel pit towards in the west end of the building on its south elevation. A dovecot has been affixed to the outside of the second floor window at this end.

The east gable was formerly abutted by a three-storey building, long demolished. The ghost of its pitched roof survives and some tie-in stones up both quoins. In the apex is an attic window (stone head and brick jambs).

The west end of the north elevation was formerly abutted by a two-storey building. Again, the ghost of its pitched roof is evident. The stonework along this elevation is of split random rubble (in contrast to the squared stone on the south façade). Towards the right-hand end is a segmental-headed opening for the headrace intake. Internally, the ground floor of the west section is flagged. It contains a waterwheel, described below. The upper floors are accessed by timber staircases. The first floor

comprises floorboards over joists resting on timber beams supported on timber columns. The floors over the waterwheel are now missing. The roof comprises common rafters over single purlins resting on A trusses. The floors and roof of the east section are similarly detailed.

Waterworks

Immediately north of the mill is the millpond, now dry, overgrown and partly infilled. There is no trace of the sluice gate on the channel into the mill. An overspill runs under the return to the grain store. The tailrace and bypass channel emerge as a single channel at the south side of the yard, between the mill house and weighbridge office. The channel is culverted under the road.

Plant

Along the east side of the west section of the mill is an internal breastshot waterwheel measuring 4.57m in diameter by 1.98m wide (15ft x 6ft 6in). It is of cast-iron construction throughout save for the curved metal wrought-iron buckets and soleplate. 'Byrne 1883 Dublin' is cast on each segment of the rim. It is in fair condition except for the deteriorating soleplates. The water was controlled by a two-step rack-and-pinion sluice gate.

Machinery

At the west end of the ground floor of the west section is a bucket elevator. It was driven by a lineshaft from the mill proper and raised the grain to the attic, from where it was discharged into the grain store.

At the west end of the ground floor of the east section is a great spurwheel transmission to three sets of millstones on the floor above. The gears and shafts are of cast-iron except for the timber upright shaft and cogs to the stone spindles. The stone nuts were disconnected from the great spurwheel by jack rings. Tentering (adjustment of the gap between the stones) was by means of a screw operating through the axis of each stone spindle. This floor also contains three bucket elevators and an inclined metal reel (for flour dressing).

The first floor of the east section contains three sets of millstones - a one-piece shelling stone and two French burrs for grinding (one is 1.37m/ 4ft 6in dia). There are also the remains of grain cleaning equipment, a reciprocating sieve, elevators and a pulley drive off the crown wheel at the top of the upright shaft.

The second and third floors are devoid of machinery except for the elevators up to the attic floor. There is also a lineshaft pulley drive up to the attic floor on the third floor.

The attic floor contains the elevator discharges, a pulley drive (formerly to a sieve, now gone), and remains of a sackhoist.

Component OFIAR-043-002 2

Type Grain mill (water); Grain store Function Grain milling

Category Food processing & products Context Industry

Irish Grid 213336 192588 +/- 10m

Survey date 18/07/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Store
Waterworks Remains Some remains Condition Poor Use Disused

Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description

This L-plan three-storey (+ attic) grain store is aligned north-south and abuts the west gable of the mill; it is six openings wide. It is cited as a corn mill on the 1886 OS sixinch map, but it appears to have subsequently been converted into a grain store. Natural slate roof, half-hipped to its south gable. Slate-hung hip-roofed eaves dormers along east and north pitches. The roof has been partly reslated (natural slates) and has new galvanised semicircular gutters.

Walls are of split random rubble with ashlar eaves and dressed quoins. Square-headed openings with flat brick heads and stone jambs; no cills to windows. Some 6/6 sliding sash windows survive to first floor and louvers to second floor. Many window openings on east pitch are infilled with concrete blocks. Unusual 'arabesque' brick heads to two of the ground floor doorways on east elevation.

A modern open-sided shed abuts the right-hand end of the west elevation, and a twostorey former store abuts the middle (described below). A bypass channel from the millpond runs underneath the return. This may originally have housed a waterwheel to power the former corn mill.

Internally, the walls are plastered and painted. The ground floor is of concrete. An electrically-driven bucket elevator runs from the ground to attic floor. Modern toilets have been installed at the north end of the ground floor.

The floorboards to the upper floors rest directly on timber transoms supported on timber uprights. There is a grain auger lying loose on the second floor. Part of the floor has been removed at the north end. The roof comprises tied common rafters. The undersides of the slates are plastered. Evidence of deterioration along east pitch, below dormers.

A two-storey building, probably a store originally, abuts the middle of the west elevation of the grain store. The ground along the north elevation has been built up such that only the first floor is visible on this side.

The roof of this section has been refurbished with natural slate (three skylights to north pitch). The west gable is half-hipped. Semicircular metal rainwater goods. Unrendered split random rubble walls. Square-headed openings. Window openings contain replacement 6/6 timber sliding sashes. Semi-glazed doors to ground floor of south elevation and first floor of north elevation.

Internally refurbished as a café and meeting room.

Immediately SE of the south gable of the grain store is a single-bay/ single-storey flat-roofed weighbridge office of 20th century date. Drive-on weighing platform on north side.

Component OFIAR-043-002 3

Type Mill house Function Grain milling

Category Food processing & products Context Industry

Irish Grid 213376 192558 +/- 10m

Survey date 18/07/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Dwelling

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description A double-pile, three-bay/ two-storey house of T plan. Hipped natural slate roof,

rendered chimneys, cement-rendered walls embellished with stucco quoins and string course at first floor level. Replacement galvanised semicircular metal gutters. Square-headed openings. Windows are 3/6 and 6/6 sliding sashes, and also margined

casements.

Interest Architectural; Historical; Technical; Setting

Evaluation This mill complex is of architectural interest because of its scale, range of buildings,

and contribution to the local setting. It is also of historical merit, being a good example of a late 18th/early 19th century flour mill, probably re-equipped around 1883. The mill is also of technical interest as it retains its waterwheel and principal

gearing and machinery.

In recent years, the owner has availed of grants provided by Offaly CC to restore the roofs in a manner in keeping with the mill's character. This is an important first step if the interiors are to be preserved. Only the main part of the grain store roof is now in need of repairs.

The mill complex is of regional industrial heritage significance. The inclusion of the mill buildings and associated house as Protected Structures in the Co Offaly

Development Plan 2009-15 is warranted.

Rating Regional Protection Offaly RPS 62-01; Action None (in RPS)

Offaly RPS 62-02

Associated with OFIAR-042-017

Other dbase NIAH 14943002 (R); NIAH 14943003 (R)

References

Feehan, J. The Landscape of Slieve Bloom: a Study of its Natural and Page(s) 125

Human Heritage (Dublin: Blackwater Press, 1979).

Garner, W. Churches and Houses of Architectural Interest in Co Offaly Page(s) 43

(Tullamore: Offaly Historical Society, 1985).

Scully, T. Slieve Bloom from Father to Son (Roscrea: Slieve Bloom Rural Page(s) 131-132

Development Society, 2002).

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s)

of Ireland c.1850 (Dublin, 2000).

OFIAR-043-002_01 FWH 18/07/2003 General view of complex from east. Mill etc at left and mill house at right.



OFIAR-043-002_02 FWH 18/07/2003 General view of mill (left), grain store (middle) and store (right), from north-west.



OFIAR-043-002_03 FWH 18/07/2003 General view of mill (right) and grain store (left), from south-east.



OFIAR-043-002_04 FWH 18/07/2003 South elevation of mill.



OFIAR-043-002_05 FWH 18/07/2003 Mill from north-east.



OFIAR-043-002_06 FWH 18/07/2003 Intake from millpond to waterwheel at west end of north side of mill.



OFIAR-043-002_07 FWH 18/07/2003 Mill: waterwheel on ground floor of west bay.



OFIAR-043-002_08 FWH 18/07/2003 Maker's name and date on waterwheel.



OFIAR-043-002_09 FWH 18/07/2003 Mill: ground floor of east bay, looking west.



OFIAR-043-002_10 FWH 18/07/2003 Mill: Pitwheel, wallower and upright shaft on ground floor of east bay.



OFIAR-043-002_11 FWH 18/07/2003 Mill: stone nut tentering and jack ring.



 $OFIAR-043-002_12 \quad FWH \quad 18/07/2003 \qquad \text{Mill: inclined shelling stone rotary sieve on ground floor of east bay.}$



OFIAR-043-002_13 FWH 18/07/2003 Mill: first floor of east bay, showing stones, truer, crown wheel and lineshaft.



OFIAR-043-002_14 FWH 18/07/2003 Mill: stones on first floor.



OFIAR-043-002_15 FWH 18/07/2003 Mill: third floor of east bay, looking west.



OFIAR-043-002_16 FWH 18/07/2003 Mill: attic floor of east bay, looking west.



OFIAR-043-002_17 FWH 18/07/2003 Mill: floorless sections of west bay, looking west.



OFIAR-043-002_18 FWH 18/07/2003 Grain store: 'arabesque' doorway on ground floor.



OFIAR-043-002_19 FWH 18/07/2003 Grain store: attic floor, looking north.



OFIAR-043-002_20 FWH 18/07/2003 Grain store: first floor, looking north.



 $OFIAR-043-002_21 \quad FWH \quad 18/07/2003 \qquad Weighbridge \ office \ and \ platform. \ Note \ tailrace \ at \ left.$



OFIAR-043-002_22 FWH 18/07/2003 Mill house, from south.



Site no	OFIAR-0)43-004				Hanlon's Mill
County	Offaly	Townland	Ballyduff (Ba	llybritt	t By)	Town
Planning	Offaly CC	Discovery n	nap 54			Six-inch map 43
Summary	Site of 18t	h/early 19th century	water-power	ed co	rn mill on un	named river.
History	Valuation I stones. Th	Corn mill cited on 1838, 1885 and 1909 OS six-inch maps. Noted in 1840s Mill Valuation book as belonging to John Hanlon. A 16ft x 4ft wheel drove two sets of stones. The 1851 Griffith Valuation also notes John Hanlon as operator. The house, offices and corn mill were rated at £11.10s.0d. Site cleared during land reclamation in 1970s.				
Component	OFIAR-04	3-004 1				
Туре	Grain mill	(water)	Fun	ction	Grain milli	ng
Category	Food proc	essing & products	Con	text	Industry	
Irish Grid	217470 1	91658 +/- 10m				
Survey date	18/07/2003	3 Surve	eyor Fre	d Han	nond	
Building	Remains	No visible remains	Condition	N/A	Use N	N/A
Waterworks	Remains	No visible remains	Condition	N/A	Use N	N/A
Plant	Remains	No visible remains	Condition	N/A	Use N	N/A
Machinery	Remains	No visible remains	Condition	N/A	Use N	I/A

Interest None

Description

Evaluation No industrial heritage signficance.

Site of corn mill on unnamed river.

Rating Record only Protection Action

Associated with

Other dbase

References

Scully, T. Slieve Bloom from Father to Son (Roscrea: Slieve Bloom Rural Page(s) 69 Development Society, 2002).

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

Site no	OFIAR-044-	-007	Springmount Mill		
County	Offaly	Townland Gorraun (Clonlisk By)	Town		
Planning	Offaly CC	Discovery map 59	Six-inch map 44		
Summary	Derelict three-storey shell of 18th/early 19th century water-powered flour mill on tributary of Ollatrim River. Retains waterwheel and pitwheel.				
History	as a corn mill of driving a single operator. Along	or mill in the 1838 OS map. Described in the operated by Benjamin Armitage. It had a 14 e set of stones. The 1851 Griffith Valuation g with the house and ancillary buildings, it we 1885 OS map, and as a corn mill on the 1	ft x 4ft 4in waterwheel also notes Armitage as its vas rated at £28. Cited as a		

Component OFIAR-044-007 1

Type Grain kiln; Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 199189 185842 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Poor Use Disused Waterworks Remains Substantial remains Condition Poor Use Disused Plant Remains Substantial remains Condition Poor Use Disused Machinery Remains Traces Condition Fair Use Disused

Description Buildings

Roofless shell of three-storey, six-bay mill aligned north-south in farmyard associated with Springmount House. Gables indicate that formerly had a pitched natural slate roof. Walls are of random rubble, with advanced stone eaves and traces of render. Square-headed openings. Window openings to ground floor have rendered brick trim. Remnants of 6/6 sash windows to upper floors. No floors survive inside.

At north end of west elevation is a single-bay, two-storey return, probably once the kiln and now very overgrown. There are fragments of 12-inch square perforated clay tiles scattered about. On the west elevation of this return is a single-storey random rubble lean-to.

In middle of east elevation is a small single-storey annex. Projecting from the north end of this elevation is a range of farm outbuildings, now derelict.

Waterworks, plant and machinery

Remains of overgrown mill pond at east. Tailrace still visible, but now dry. On north gable of mill is an external high breastshot waterwheel of cast-iron construction save for its 2x8 arms, 40 angled buckets and soleplate, all of which are of timber. Most of the soleing and buckets have rotted away. Measures 16ft dia by 4ft 9in wide. Bears its maker's name on rim: "Harrison, Lee City Foundry Limerick". A cast-iron pitwheel is affixed to the other end of the axle inside the mill but there is otherwise no machinery.

Component OFIAR-044-007 2

Type Mill house Function Grain milling

Category Food processing & products Context Industry

Irish Grid 199201 185806 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Complete Condition Good Use Dwelling

Waterworks Remains N/A Condition N/A Use N/A
Plant Remains N/A Condition N/A Use N/A
Machinery Remains N/A Condition N/A Use N/A

Description South of the mill is a two-storey, three-bay mill house aligned north-south. Hipped

natural slate roof with two chimneys and aluminium gutters. Rendered random rubble walls. Principal façade faces west and is symmetrical. Entrance to centre of façade, with 8-panel timber door and spoked overlight. Flanked to each side and to first floor

with 6/6 sash windows.

Interest Technical

Evaluation This mill is primarily of interest because of the survival of its waterwheel and the fact

that it bears its maker's name. It is of local industrial heritage signficance and a

Protected Structure in the Co Offaly Development Plan 2009-15.

Rating Local Protection Offaly RPS 63-08 Action

Associated with

Other dbase NIAH 14944011 (R)

References

O'Riain, S. Dunkerrin: a Parish in Ely O'Carroll (Dunkerrin: Dunkerrin History Page(s) 74 Committee, 1988).

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

OFIAR-044-007_01 FWH 01/08/2003 General view of mill from south-west.



OFIAR-044-007_02 FWH 01/08/2003 Waterwheel.



OFIAR-044-007_03 FWH 01/08/2003 End-on view of waterwheel.



OFIAR-044-007_04 FWH 01/08/2003 Maker's name on waterwheel (Harrison, Lee City Foundry Limerick).



 $OFIAR-044-007_05 \quad FWH \quad 01/08/2003 \qquad Mill \ house, \ from \ west.$



Site no	OFIAR-045-0	009				Franckfort Mill
County	Offaly	Townland F	ranckfort			Town
Planning	Offaly CC	Discovery ma	ap 59			Six-inch map 45
Summary						s on tributary of Little 1830s but reverted to
History	used for a time a 1840s Mill Valua Kelly. A 15ft x 2 Valuation book	as a distillery a ation books not ift 2in wheel dro notes James Ko e mill is not cite	s it is cited a es its revers ove a single elly as the o	as such sion to a pair of wner. T	on the 18 a corn mil pair of st The house	ill appears to have been 339 OS six-inch map. The I, operated by Thomas ones. The 1851 Griffith e, offices and corn mill were maps; on the latter map it is
Component	OFIAR-045-009	1				
Туре	Distillery; Grain mill (water)	mill (water); Tu	ıck Fur	ection	Distilling	; Grain milling; Wool
Category	Drink processing & processing & promanufacture & processing & processi	oducts; Textile	ood Cor	ntext	Industry	
Irish Grid	205144 185463	3 +/- 10m				
Survey date	01/08/2003	Survey	or Fre	ed Ham	ond	
Building	Remains No vi	isible remains	Condition	N/A	Use	N/A
Waterworks	Remains No vi	isible remains	Condition	N/A	Use	N/A
Plant	Remains No vi	isible remains	Condition	N/A	Use	N/A
Machinery	Remains No vi	isible remains	Condition	N/A	Use	N/A
Description	Site of corn mill side of minor ro					Brosna River on north ite.
Interest	None					
Evaluation	No industrial he	ritage signfican	ce.			
Rating	Record only	Protection				Action
Associated v	vith					
Other dbase						

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

0:4	0 E1 4	D	45 04	
Site no	OFIA	NK-U	45-0 1	15

_				_
County	Offaly	Townland Clon	llisik	Town
Planning	Offaly CC	Discovery map	59	Six-inch map 45
Summary	Remains of 18th Little Brosna Ri		y 3½ storey water-powered	d flour mill on tributary of
History	belonging to Mitwo sets of ston and offices rate According to pro	chael Kelly. Describ les. Kelly also the o ld at £30, indicating esent owner, the pr	inch map. Noted in 1840s bed as flour mill with a 14f wner in 1851 Griffith Valu- a sizeable complex. emises were purchased by ill. Not cited in 1885 or 19	t x 3ft 6in waterwheel to ation. House, flour mill y his grandfather from

Component OFIAR-045-015 1

Type Grain mill (water) Function Grain milling

Category Food processing & products Context Industry

Irish Grid 204898 188895 +/- 10m

Survey date 01/08/2003 Surveyor Fred Hamond

Building Remains Substantial remains Condition Fair Use Agricultural building

Waterworks Remains Substantial remains Condition Fair Use Disused

Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Buildings

Remains of flour mill on tributary of Little Brosna River, to north of minor road. Aligned east-west in farmyard behind house. The west section survives as a 3½ storey/three-bay building now in use as agricultural outbuilding. Corrugated metal roof (1922 replacement), random rubble walls, square-headed windows. East section demolished. Replacement first floor; top floor removed.

Waterworks, plant and machinery

Head and tail races still evident; the headrace has been piped in the vicinity of the mill. The waterwheel was probably internal, but no wheelpit now evident. No machinery survives.

Interest None

Evaluation No special industrial heritage signficance.

Rating Record only Protection Action

Associated with

Other dbase

References

Valuation Mill Book, 1840s. Reproduced by Hogg, W. The Millers and Mills Page(s) of Ireland c.1850 (Dublin, 2000).

 $OFIAR-045-015_01 \quad FWH \quad 01/08/2003 \qquad Mill \ from \ south-west.$



OFIAR-045-015_02 FWH 01/08/2003 Mill from south-east.



OFIAR-045-015_03 FWH 01/08/2003 Mill from north-east.



County Offaly Townland Clonlisk Town

Planning Offaly CC Discovery map 59 Six-inch map 45

Summary Unlocated mill site on 1655 Down Survey.

History Down Survey map of 1655 shows mill of unknown function in townland.

Component OFIAR-045-016 1

Type Mill Function Unknown

Category Unknown Context Industry

Irish Grid 205139 188313 +/- 1000m

Survey date Surveyor Fred Hamond

Use N/A Building Remains No visible remains Condition N/A Waterworks Remains No visible remains Condition N/A Use N/A Plant Remains No visible remains Condition N/A Use N/A Machinery Remains No visible remains Condition N/A Use N/A

Description Unlocated mill site.

Interest Arhcaeological

Evaluation Although of archaeological interest, the absence of upstanding remains makes this

site of no industrial heritage significance.

Rating Record only Protection Action

Associated with

Other dbase SMR OF045-043---

References

Archaeological Survey of Ireland record.

Page(s)

Site no	OFIAR-046-005
County	Offaly; Townland Ballycormick; Co Tipperary Town Tipperary
Planning	Offaly CC; Discovery map 59 Six-inch map 46 Tipperary CC
Summary	Weir on Ollatrim River which diverts water to Victoria Mills, Co Tipperary.
History	Diverted water to Victoria Mills, Co Tipperary (shown on 1840 OS map Co Tipperary sheet 22).
Component	OFIAR-046-005 1
Туре	Mill weir Function Grain milling
Category	Food processing & products Context Industry
Irish Grid	200143 179354 +/- 10m
Survey date	01/08/2003 Surveyor Fred Hamond
Building	Remains N/A Condition N/A Use N/A
Waterworks	Remains No visible remains Condition N/A Use N/A
Plant	Remains N/A Condition N/A Use N/A
Machinery	Remains N/A Condition N/A Use N/A
Description	Site of weir on Ollatrim River associated with Victoria Mills, Co Tipperary.
Interest	None
Evaluation	No industrial heritage signficance.

Protection

Action

Rating Record only

Associated with

Other dbase

References

SITE INDEXES

- 1. **Name** Townland Type Site component no
- 2. **Townland** Type Function Site component no
- 3. **Town** Type Function Site component no
- 4. **Grid easting** Grid northing Type Site component no
- 5. **Type** Function Townland Site component no
- 6. **Statutory Protection** Site component no

1. NAME						
Name	Townland	Туре	Site component	t		
Ballyboy Mill	Ballyboy (Ballyboy By)	Grain kiln; Grain mill (water); Saw mill (water)	OFIAR-031-007	1		
Ballyduff Mill	Ballyduff (Ballycowan By)	Grain kiln; Grain mill (water)	OFIAR-016-002	1		
Ballynacarrig Mills	Ballynacarrig	Grain kiln; Grain mill (water); Saw mill (water); Tuck mill (water)	OFIAR-032-002	1		
Banagher Distillery	Garrycastle	Distillery (steam; water)	OFIAR-029-011	3		
Banagher Distillery	Garrycastle	Distillery office	OFIAR-029-011	6		
Banagher Distillery	Garrycastle	Grain kiln; Grain mill (water)	OFIAR-029-011	1		
Banagher Distillery	Garrycastle	Grain store	OFIAR-029-011	2		
Banagher Distillery	Garrycastle	Grain store	OFIAR-029-011	5		
Banagher Distillery	Garrycastle	Malt house	OFIAR-029-011	8		
Banagher Distillery	Garrycastle	Malt kiln	OFIAR-029-011	4		
Banagher Distillery	Garrycastle	Malt kiln	OFIAR-029-011	7		
Banagher Maltings	Garrycastle	Distillery (steam; water)	OFIAR-029-011	3		
Banagher Maltings	Garrycastle	Distillery office	OFIAR-029-011	6		
Banagher Maltings	Garrycastle	Grain kiln; Grain mill (water)	OFIAR-029-011	1		
Banagher Maltings	Garrycastle	Grain store	OFIAR-029-011	2		
Banagher Maltings	Garrycastle	Grain store	OFIAR-029-011	5		
Banagher Maltings	Garrycastle	Malt house	OFIAR-029-011	8		
Banagher Maltings	Garrycastle	Malt kiln	OFIAR-029-011	4		
Banagher Maltings	Garrycastle	Malt kiln	OFIAR-029-011	7		
Belmont Mills	Bellmount or Lisderg	Electricity generating station (water)	OFIAR-014-004	7		
Belmont Mills	Bellmount or Lisderg	Electricity generating station (water)	OFIAR-014-004	8		
Belmont Mills	Bellmount or Lisderg	Grain kiln; Grain mill (water); Oilseed mill (water)	OFIAR-014-004	1		
Belmont Mills	Bellmount or Lisderg	Grain mill (electric; water)	OFIAR-014-004	2		
Belmont Mills	Bellmount or Lisderg	Mill building	OFIAR-014-004	4		
Belmont Mills	Bellmount or Lisderg	Mill building	OFIAR-014-004	5		
Belmont Mills	Bellmount or Lisderg	Mill building	OFIAR-014-004	9		
Belmont Mills	Bellmount or Lisderg	Mill house	OFIAR-014-004	3		
Belmont Mills	Bellmount or Lisderg	Mill house	OFIAR-014-004	6		
Belmont Mills	Bellmount or Lisderg	Tuck mill (water)	OFIAR-014-004	10		
Bergin's Mill	Fancroft	Grain mill (water)	OFIAR-043-002	1		
Bergin's Mill	Fancroft	Grain mill (water); Grain store	OFIAR-043-002	2		

- · · · · · · · · · · · · · · · · · · ·			05145 040 000	
Bergin's Mill	Fancroft	Mill house	OFIAR-043-002	3
Birr Distillery	Clonoghil Upper	Bonded warehouse; Distillery; Grain mill (water); Malt house; Malt kiln	OFIAR-035-034	1
Black Mill	Tonlemone	Grain kiln; Grain mill (water)	OFIAR-022-017	1
Blue House	Ballycumber	Blue mill	OFIAR-007-021	1
Bogtown Mill	Bogtown	Grain kiln; Grain mill (water)	OFIAR-026-015	1
Bridge Malt House	Kylebeg or Banagher	Grain mill (steam; water); Malt house; Malt kiln	OFIAR-021-009	1
Brosna Maltings	Drumakeenan (Clonlisk By, Ettagh Par)	Grain kiln; Grain mill (water); Malt house	OFIAR-042-009	1
Cadamstown Mill	Cadamstown	Grain kiln; Grain mill (water); Saw mill (water); Weaving factory	OFIAR-037-002	1
Cadamstown Mill	Cadamstown	Grain mill (water)	OFIAR-037-002	2
Castlebarnagh Windmill	Townparks (Lower Philipstown By)	Grain mill (wind)	OFIAR-018-023	1
Charlestown House	Kilcoursey	Mill house	OFIAR-008-064	1
Charlestown no.1 Mill	Kilcoursey	Engine house (steam); Grain kiln; Grain mill (water; steam)	OFIAR-008-009	1
Charlestown no.2 Mill	Kilcoursey	Grain kiln; Grain mill (water)	OFIAR-008-042	1
Charlestown no.2 Mill	Kilcoursey	Mill building	OFIAR-008-042	2
Clashawaun Works	Erry (Armstrong)	Chimney	OFIAR-008-028	1
Clashawaun Works	Erry (Armstrong)	Electricity generating station (water)	OFIAR-008-028	4
Clashawaun Works	Erry (Armstrong)	Engine house (steam)	OFIAR-008-028	5
Clashawaun Works	Erry (Armstrong)	Engine house (steam)	OFIAR-008-028	11
Clashawaun Works	Erry (Armstrong)	Factory canteen	OFIAR-008-028	3
Clashawaun Works	Erry (Armstrong)	Factory garage	OFIAR-008-028	8
Clashawaun Works	Erry (Armstrong)	Factory house	OFIAR-008-028	9
Clashawaun Works	Erry (Armstrong)	Factory house	OFIAR-008-028	10
Clashawaun Works	Erry (Armstrong)	Factory office	OFIAR-008-028	7
Clashawaun Works	Erry (Armstrong)	Jute factory (electricity; steam)	OFIAR-008-028	12
Clashawaun Works	Erry (Armstrong)	Jute factory (electricity; steam; water)	OFIAR-008-028	6
Clashawaun Works	Erry (Armstrong)	Jute store	OFIAR-008-028	2
Clashawaun Works	Erry (Armstrong)	Railway siding	OFIAR-008-028	13
Coleraine flour mill	Loughaun	Grain kiln; Grain mill (water)	OFIAR-008-016	1

Connor's Mill	Bogtown	Grain kiln; Grain mill (water)	OFIAR-026-015	1
Crank Malt House	Kylebeg or Banagher	Brewery	OFIAR-021-011	1
Crank Malt House	Kylebeg or Banagher	Brewery house	OFIAR-021-011	9
Crank Malt House	Kylebeg or Banagher	Grain store	OFIAR-021-011	6
Crank Malt House	Kylebeg or Banagher	Grain store	OFIAR-021-011	8
Crank Malt House	Kylebeg or Banagher	Malt house	OFIAR-021-011	3
Crank Malt House	Kylebeg or Banagher	Malt house	OFIAR-021-011	5
Crank Malt House	Kylebeg or Banagher	Malt kiln	OFIAR-021-011	2
Crank Malt House	Kylebeg or Banagher	Malt kiln	OFIAR-021-011	7
Crank Malt House	Kylebeg or Banagher	Maltings office	OFIAR-021-011	4
D.E. Williams Head Office	Tullamore	Distillery office	OFIAR-017-091	1
Dolan's Mill	Lavagh	Grain mill (water); Tuck mill (water)	OFIAR-029-015	1
Dooley's Mill	Moystown Demesne	Grain kiln; Grain mill (water)	OFIAR-022-020	1
Edenderry Saw Mill	Edenderry	Footwear factory	OFIAR-012-027	2
Edenderry Saw Mill	Edenderry	Saw mill (steam)	OFIAR-012-027	1
Egan's Brewery	Tullamore	Brewery	OFIAR-017-072	1
Egans' Malt House	Tullamore	Bonded warehouse; Distillery (steam); Malt house; Malt kiln; Saw mill (steam)	OFIAR-017-049	1
Elmgrove Mill	Townparks (Ballybritt By)	Brewery; Malt kiln	OFIAR-035-046	1
Elmgrove Mill	Townparks (Ballybritt By)	Grain kiln; Grain store	OFIAR-035-046	2
Erry Mill	Erry (Maryborough)	Electricity generating station (water); Engine house (steam)	OFIAR-008-038	7
Erry Mill	Erry (Maryborough)	Grain kiln; Grain mill (water)	OFIAR-008-038	1
Erry Mill	Erry (Maryborough)	Mill building	OFIAR-008-038	2
Erry Mill	Erry (Maryborough)	Mill building	OFIAR-008-038	5
Erry Mill	Erry (Maryborough)	Mill building	OFIAR-008-038	6
Erry Mill	Erry (Maryborough)	Mill building	OFIAR-008-038	9
Erry Mill	Erry (Maryborough)	Mill chimney	OFIAR-008-038	8
Erry Mill	Erry (Maryborough)	Mill house	OFIAR-008-038	3
Erry Mill	Erry (Maryborough)	Mill house	OFIAR-008-038	4
Fancroft Mill	Fancroft	Grain mill (water)	OFIAR-043-002	1
Fancroft Mill	Fancroft	Grain mill (water); Grain store	OFIAR-043-002	2
Fancroft Mill	Fancroft	Mill house	OFIAR-043-002	3
Fanure Mill	Drumakeenan (Clonlisk	Grain mill (water)	OFIAR-042-011	1

	By, Roscrea Par)			
Fennel's Mill	Bogtown	Grain kiln; Grain mill (water)	OFIAR-026-015	1
Flanagan's Mill	Ballyboy (Ballyboy By)	Grain kiln; Grain mill (water); Saw mill (water)	OFIAR-031-007	1
Franckfort Mill	Franckfort	Distillery; Grain mill (water); Tuck mill (water)	OFIAR-045-009	1
Garrycastle Distillery	Garrycastle	Distillery (steam; water)	OFIAR-029-011	3
Garrycastle Distillery	Garrycastle	Distillery office	OFIAR-029-011	6
Garrycastle Distillery	Garrycastle	Grain kiln; Grain mill (water)	OFIAR-029-011	1
Garrycastle Distillery	Garrycastle	Grain store	OFIAR-029-011	2
Garrycastle Distillery	Garrycastle	Grain store	OFIAR-029-011	5
Garrycastle Distillery	Garrycastle	Malt house	OFIAR-029-011	8
Garrycastle Distillery	Garrycastle	Malt kiln	OFIAR-029-011	4
Garrycastle Distillery	Garrycastle	Malt kiln	OFIAR-029-011	7
Greybrook Mil	Tonlemone	Grain kiln; Grain mill (water)	OFIAR-022-017	1
Grogan Mill	Ballycumber	Bleach works (water); Grain kiln; Grain mill (water)	OFIAR-007-008	1
Hackett's Distillery	Townparks (Ballybritt By)	Distillery	OFIAR-035-010	1
Hanlon's Mill	Ballyduff (Ballybritt By)	Grain mill (water)	OFIAR-043-004	1
Haughton's Mills	Kylebeg or Banagher	Grain mill (steam; water); Malt house; Malt kiln	OFIAR-021-009	1
Hillsborough Mills	Drumakeenan (Clonlisk By, Roscrea Par)	Grain kiln; Grain mill (water); Tuck mill (water)	OFIAR-042-012	2
Hillsborough Mills	Drumakeenan (Clonlisk By, Roscrea Par)	Grain mill (water)	OFIAR-042-012	1
Kilcommon Distillery	Ballytoran	Distillery	OFIAR-041-006	1
Kilcormac Maltings	Frankford	Distillery	OFIAR-031-012	1
Kilcormac Maltings	Frankford	Malt house; Malt kiln	OFIAR-031-012	2
Kilmaine Mill	Kilmaine	Grain mill (water)	OFIAR-035-016	1
Lumley's Warehouse	Tullamore	Malt house	OFIAR-017-039	1
Maltings Craft Centre	Townparks (Ballybritt By)	Malt house; Malt kiln	OFIAR-035-007	1
Manley's Brewery	Tullamore	Brewery; Malt house	OFIAR-017-050	1
Manor Mill	Ballyoran	Grain kiln; Grain mill (water)	OFIAR-031-008	1

Manor Saw Mill	Townparks (Ballybritt By)	Grain mill (water); Saw mill (water)	OFIAR-035-009	1
Marchbrook Mill	Moyally; {Parkwood}	Grain mill (water)	OFIAR-001-003	1
Midland Tribune	Townparks (Ballybritt By)	Newspaper printing works; Spinning mill	OFIAR-035-053	1
Mill of Down	Gorteenard	Grain mill (water)	OFIAR-026-017	1
Mill Park	Glasderry More	Mill?	OFIAR-042-008	1
Millbrook Mill	Lumcloon	Grain mill (water)	OFIAR-023-007	1
Old Factory	Kilcoursey	Weaving factory	OFIAR-008-054	1
Park Mill	Park (Ballyboy By)	Grain kiln	OFIAR-031-005	2
Park Mill	Park (Ballyboy By)	Grain kiln; Grain mill (water)	OFIAR-031-005	1
Park Mill	Park (Ballyboy By)	Grain store	OFIAR-031-005	3
Park Mill	Park (Ballyboy By)	Mill house	OFIAR-031-005	4
Philipstown Distillery	Townparks (Lower Philipstown By)	Distillery	OFIAR-018-024	1
Robinson's Brewery	Townparks (Ballybritt By)	Brewery	OFIAR-035-029	1
Robinson's Brewery	Townparks (Ballybritt By)	Grain store	OFIAR-035-029	2
Robinson's Distillery	Townparks (Ballybritt By)	Distillery (steam)	OFIAR-035-047	1
Robinson's Distillery	Townparks (Ballybritt By)	Malt house; Malt kiln; Grain mill (water)	OFIAR-035-047	2
Salts Mill	Spollanstown	Spinning mill	OFIAR-017-085	1
Springmount Mill	Gorraun (Clonlisk By)	Grain kiln; Grain mill (water)	OFIAR-044-007	1
Springmount Mill	Gorraun (Clonlisk By)	Mill house	OFIAR-044-007	2
Tarleton's Malt Store	Tullamore	Brewery; Malt house	OFIAR-017-053	1
Tarleton's Maltings	Tullamore	Malt house	OFIAR-017-039	1
Tullamore Dew Heritage Centre	Tullamore	Bonded warehouse	OFIAR-017-076	1
Tullamore Dew Heritage Centre	Tullamore	Malt silo	OFIAR-017-076	2
Tullamore Dew Heritage Centre	Tullamore	Quay	OFIAR-017-076	3
Tullamore Distillery	Tullamore	Distillery; Engine house (steam); Grain mill (steam)	OFIAR-017-036	1
Tullamore Gaol	Spollanstown	Spinning mill	OFIAR-017-085	1
Waller's Maltings	Kylebeg or Banagher	Grain mill (steam; water); Malt house; Malt kiln	OFIAR-021-009	1
Whiteford Mill	Crinkill	Grain kiln; Grain mill (water)	OFIAR-035-031	1
Woods' Mill	Keeloge (Clonlisk By)	Grain kiln; Grain mill (water); Saw mill (water)	OFIAR-042-030	1
Wyre's Mill	Gorteenard	Grain mill (water)	OFIAR-026-017	1

2. TOWNLAND				
Townland	Туре	Function	Site componen	ıt
Acantha	Distillery	Distilling	OFIAR-009-005	2
Acantha	Grain kiln; Grain mill (water)	Grain milling	OFIAR-009-005	1
Acantha	Tuck mill (water)	Wool	OFIAR-009-021	1
Aghaboy	Grain kiln; Grain mill (water)	Grain milling	OFIAR-014-034	1
Aghadouglas	Mill (water)	Unknown	OFIAR-042-029	1
Aghagurty	Grain mill (water)	Grain milling	OFIAR-039-005	1
Aghagurty	Mill house	Grain milling	OFIAR-039-005	2
Aghamore (Lower Philipstown By)	Grain kiln; Grain mill (water)	Grain milling	OFIAR-010-014	1
Annaghmore (Garrycastle By)	Grain mill (water)	Grain milling	OFIAR-013-006	1
Ballaghanoher	Grain kiln; Oilseed mill (water)	Grain milling; Oilseed milling	OFIAR-030-003	2
Ballaghanoher	Grain mill (water)	Grain milling	OFIAR-030-003	1
Ballicknahee	Mill (wind)	Unknown	OFIAR-002-010	1
Ballincur (Ballybritt By)	Grain mill (water)	Grain milling	OFIAR-036-019	1
Ballincur (Ballybritt By)	Starch house	Unknown	OFIAR-036-019	2
Ballindarra	Grain mill (water)	Malting	OFIAR-035-035	1
Ballinree (Ballybritt By)	Grain kiln	Grain milling	OFIAR-035-018	2
Ballinree (Ballybritt By)	Grain kiln; Grain mill (water)	Grain milling	OFIAR-035-018	1
Ballyboy (Ballyboy By)	Flax mill?	Flax & linen	OFIAR-031-019	1
Ballyboy (Ballyboy By)	Grain kiln; Grain mill (water); Saw mill (water)	Grain milling; Timber processing & products	OFIAR-031-007	1
Ballybruncullin	Mill	Unknown	OFIAR-007-032	1
Ballycormick; Co Tipperary	Mill weir	Grain milling	OFIAR-046-005	1
Ballycumber	Bleach works (water); Grain kiln; Grain mill (water)	Flax & linen; Grain milling	OFIAR-007-008	1
Ballycumber	Blue mill	Flax & linen	OFIAR-007-021	1
Ballycumber	Grain mill (water); Tuck mill (water)	Grain milling; Wool	OFIAR-007-018	1
Ballyduff (Ballybritt By)	Grain mill (water)	Grain milling	OFIAR-043-004	1
Ballyduff (Ballycowan By)	Grain kiln; Grain mill (water)	Grain milling	OFIAR-016-002	1
Ballygaddy (Ballybritt By)	Malt house	Malting	OFIAR-039-014	1
Ballyhugh	Grain kiln; Grain mill (water); Saw mill (water)	Grain milling; Timber processing & products	OFIAR-011-021	1
Ballykilleen (Kilcoursey By)	Grain mill (water)	Grain milling	OFIAR-002-017	1

	1	1		11
Ballynacarrig	Grain kiln; Grain mill (water); Saw mill (water); Tuck mill (water)	Grain milling; Timber processing & products; Wool	OFIAR-032-002	1
Ballynaguilsha	Grain kiln; Grain mill (water)	Grain milling	OFIAR-030-004	1
Ballynasrah or Tinnycross	Grain kiln	Grain milling	OFIAR-009-006	2
Ballynasrah or Tinnycross	Grain mill (water)	Grain milling	OFIAR-009-006	1
Ballyoran	Grain kiln; Grain mill (water)	Grain milling	OFIAR-031-008	1
Ballyshane (Ballybritt By)	Grain mill (water)	Grain milling	OFIAR-036-018	1
Ballytoran	Distillery	Distilling	OFIAR-041-006	1
Barnan	Grain mill (wind)	Grain milling	OFIAR-010-016	1
Bellmount or Lisderg	Electricity generating station (water)	Electricity	OFIAR-014-004	8
Bellmount or Lisderg	Electricity generating station (water)	Grain milling	OFIAR-014-004	7
Bellmount or Lisderg	Grain kiln; Grain mill (water); Oilseed mill (water)	Grain milling; Oilseed milling	OFIAR-014-004	1
Bellmount or Lisderg	Grain mill (electric; water)	Grain milling	OFIAR-014-004	2
Bellmount or Lisderg	Mill building	Grain milling	OFIAR-014-004	4
Bellmount or Lisderg	Mill building	Grain milling	OFIAR-014-004	5
Bellmount or Lisderg	Mill building	Grain milling	OFIAR-014-004	9
Bellmount or Lisderg	Mill house	Grain milling	OFIAR-014-004	3
Bellmount or Lisderg	Mill house	Grain milling	OFIAR-014-004	6
Bellmount or Lisderg	Tuck mill (water)	Wool	OFIAR-014-004	10
Bogtown	Grain kiln; Grain mill (water)	Grain milling	OFIAR-026-015	1
Bohernagrisna	Grain mill (water)	Grain milling	OFIAR-007-022	1
Bracklin Big	Grain kiln	Grain milling	OFIAR-009-015	2
Bracklin Big	Grain mill (water)	Grain milling	OFIAR-009-015	1
Bracklin Little	Grain mill (water)	Grain milling	OFIAR-009-018	1
Bracknagh	Grain mill (water)	Grain milling	OFIAR-027-005	1
Bracknagh	Smithy	Agricultural engineering	OFIAR-027-005	2
Bunrevan	Grain kiln	Grain milling	OFIAR-035-001	2
Bunrevan	Grain kiln; Grain mill (water)	Grain milling	OFIAR-035-001	1
Cadamstown	Grain kiln; Grain mill (water); Saw mill (water); Weaving factory	Grain milling; Timber processing & products; Wool	OFIAR-037-002	1
Cadamstown	Grain mill (water)	Grain milling	OFIAR-037-002	2
Cadamstown	Millstone quarry	Stone	OFIAR-037-005	1
Cappagowlan	Grain mill (water)	Grain milling	OFIAR-032-004	1
Cappancur	Grain mill (water)	Grain milling	OFIAR-017-107	1

				1
Cappydonnell Little	Grain kiln; Grain mill (water)	Grain milling	OFIAR-002-006	1
Castlearmstrong	Grain kiln; Grain mill (water)	Grain milling	OFIAR-007-016	1
Charleville Demesne	Bone mill (water); Saw mill (water); Threshing mill (water); Water pump (water)	Bone and fat products; Grain processing; Timber processing & products; Water supply	OFIAR-016-031	1
Clara	Bone mill (water); Grain mill (water)	Bone and fat products; Grain milling	OFIAR-008-045	1
Clareen	Brewery	Brewing	OFIAR-042-033	1
Clareen	Grain kiln	Grain processing	OFIAR-042-033	2
Cloghan Beg	Grain mill (wind)	Grain milling	OFIAR-029-008	1
Cloghatanny	Grain kiln; Grain mill (water); Tuck mill (water)	Grain milling; Wool	OFIAR-008-001	1
Clonavoe	Grain kiln; Grain mill (water)	Grain milling	OFIAR-019-006	1
Clonbrone (Eglish By)	Grain mill (water)	Grain milling	OFIAR-035-033	1
Clonbulloge	Grain mill (water)	Grain milling	OFIAR-019-010	1
Clonin	Threshing mill (horse)	Grain processing	OFIAR-011-030	1
Clonlisik	Grain mill (water)	Grain milling	OFIAR-045-015	1
Clonlisk	Mill	Unknown	OFIAR-045-016	1
Clonmacnoise	Grain kiln; Grain mill (water)	Grain milling	OFIAR-005-001	1
Clonoghil Upper	Bonded warehouse; Distillery; Grain mill (water); Malt house; Malt kiln	Distilling	OFIAR-035-034	1
Clonoghil Upper	Grain mill (water); Oilseed mill (water)	Grain milling; Oilseed milling	OFIAR-035-013	1
Clonoghil Upper?	Tuck mill (water)	Wool	OFIAR-035-060	1
Clonygowan	Brewery	Brewing	OFIAR-033-008	1
Clyduff (Clonlisk By); {Milltown}	Grain mill (water)	Grain milling	OFIAR-042-017	1
Corbane	Grain mill (water)	Grain milling	OFIAR-014-001	1
Cornafurrish and Corrabeg	Grain kiln; Grain mill (water)	Grain milling	OFIAR-007-017	1
Cranasallagh	Grain kiln; Grain mill (water)	Grain milling	OFIAR-007-019	1
Crinkill	Grain kiln; Grain mill (water)	Grain milling	OFIAR-035-031	1
Croghan Demesne	Grain kiln	Grain milling	OFIAR-010-013	1
Croghan Demesne	Grain mill (water)	Grain milling	OFIAR-010-012	1
Cully	Mill	Unknown	OFIAR-024-013	1
Curraghavarna and Portavolla	Distillery	Distilling	OFIAR-021-012	1
Curraghmore (Eglish By)	Grain kiln	Grain milling	OFIAR-031-020	2

		1		-11
Curraghmore (Eglish By)	Grain mill (water)	Grain milling	OFIAR-031-020	1
Derryiron	Grain kiln; Grain mill (water)	Grain milling	OFIAR-004-011	1
Derrymore (Ballyboy By)	Grain mill (water)	Grain milling	OFIAR-024-009	1
Doon Demesne	Grain kiln	Grain milling	OFIAR-006-003	2
Doon Demesne	Grain mill (water)	Grain milling	OFIAR-006-003	1
Doon Demesne	Tuck mill (water)	Wool	OFIAR-006-003	3
Down (Lower Philipstown By)	Grain kiln; Grain mill (water)	Grain milling	OFIAR-010-010	1
Drumakeenan (Clonlisk By, Ettagh Par)	Grain kiln; Grain mill (water); Malt house	Grain milling; Malting	OFIAR-042-009	1
Drumakeenan (Clonlisk By, Ettagh Par)	Grain mill (water)	Grain milling	OFIAR-042-028	1
Drumakeenan (Clonlisk By, Ettagh Par)	Mill	Unknown	OFIAR-042-042	1
Drumakeenan (Clonlisk By, Roscrea Par)	Grain kiln; Grain mill (water); Tuck mill (water)	Grain milling; Wool	OFIAR-042-012	2
Drumakeenan (Clonlisk By, Roscrea Par)	Grain mill (water)	Grain milling	OFIAR-042-010	1
Drumakeenan (Clonlisk By, Roscrea Par)	Grain mill (water)	Grain milling	OFIAR-042-011	1
Drumakeenan (Clonlisk By, Roscrea Par)	Grain mill (water)	Grain milling	OFIAR-042-012	1
Drumakeenan (Clonlisk By, Roscrea Par)	Grain mill (water)	Grain milling	OFIAR-042-026	1
Drumcaw or Mountlucas	Mill	Unknown	OFIAR-018-035	1
Edenderry	Footwear factory	Footwear manufacture	OFIAR-012-027	2
Edenderry	Grain mill (wind)	Grain milling	OFIAR-012-024	1
Edenderry	Saw mill (steam)	Timber processing & products	OFIAR-012-027	1
Eglish	Bleach works (water); Grain mill (water)	Flax & linen; Grain milling	OFIAR-030-008	1
Enaghan	Grain kiln; Grain mill (water); Tuck mill (water)	Grain milling; Wool	OFIAR-026-016	1
Erry (Armstrong)	Chimney	Jute	OFIAR-008-028	1
Erry (Armstrong)	Electricity generating station (water)	Jute	OFIAR-008-028	4
Erry (Armstrong)	Engine house (steam)	Jute	OFIAR-008-028	5
Erry (Armstrong)	Engine house (steam)	Jute	OFIAR-008-028	11
Erry (Armstrong)	Factory canteen	Jute	OFIAR-008-028	3
Erry (Armstrong)	Factory garage	Jute	OFIAR-008-028	8
Erry (Armstrong)	Factory house	Jute	OFIAR-008-028	9

Erry (Armstrong)	Factory house	Jute	OFIAR-008-028	10
Erry (Armstrong)	Factory office	Jute	OFIAR-008-028	7
Erry (Armstrong)	Jute factory (electricity; steam)	Jute	OFIAR-008-028	12
Erry (Armstrong)	Jute factory (electricity; steam; water)	Jute	OFIAR-008-028	6
Erry (Armstrong)	Jute store	Jute	OFIAR-008-028	2
Erry (Armstrong)	Railway siding	Jute	OFIAR-008-028	13
Erry (Marlborough)	Mill	Unknown	OFIAR-008-065	1
Erry (Maryborough)	Electricity generating station (water); Engine house (steam)	Grain milling	OFIAR-008-038	7
Erry (Maryborough)	Grain kiln; Grain mill (water)	Grain milling	OFIAR-008-038	1
Erry (Maryborough)	Grain silo	Grain milling	OFIAR-008-053	1
Erry (Maryborough)	Mill building	Grain milling	OFIAR-008-038	2
Erry (Maryborough)	Mill building	Grain milling	OFIAR-008-038	5
Erry (Maryborough)	Mill building	Grain milling	OFIAR-008-038	6
Erry (Maryborough)	Mill building	Grain milling	OFIAR-008-038	9
Erry (Maryborough)	Mill chimney	Grain milling	OFIAR-008-038	8
Erry (Maryborough)	Mill house	Grain milling	OFIAR-008-038	3
Erry (Maryborough)	Mill house	Grain milling	OFIAR-008-038	4
Erry (Maryborough)	Railway siding	Grain milling	OFIAR-008-053	2
Fahy	Grain mill (wind)	Grain milling	OFIAR-011-001	1
Fancroft	Grain mill (water)	Grain milling	OFIAR-043-002	1
Fancroft	Grain mill (water); Grain store	Grain milling	OFIAR-043-002	2
Fancroft	Mill house	Grain milling	OFIAR-043-002	3
Ferbane	Brewery	Brewing	OFIAR-014-039	1
Franckfort	Distillery; Grain mill (water); Tuck mill (water)	Distilling; Grain milling; Wool	OFIAR-045-009	1
Frankford	Brewery (water)	Brewing	OFIAR-031-011	1
Frankford	Distillery	Distilling	OFIAR-031-012	1
Frankford	Grain mill (water)	Grain milling	OFIAR-031-013	1
Frankford	Hydraulic ram	Water supply	OFIAR-031-013	2
Frankford	Malt house; Malt kiln	Malting	OFIAR-031-012	2
Gallen	Grain kiln; Grain mill (water)	Grain milling	OFIAR-014-035	1
Garrycastle	Distillery (steam; water)	Distilling	OFIAR-029-011	3
Garrycastle	Distillery office	Distilling	OFIAR-029-011	6
Garrycastle	Grain kiln; Grain mill (water)	Grain milling	OFIAR-029-011	1
Garrycastle	Grain store	Grain milling	OFIAR-029-011	2

Garrycastle	Grain store	Grain milling	OFIAR-029-011	5
Garrycastle	Malt house	Malting	OFIAR-029-011	8
Garrycastle	Malt kiln	Distilling	OFIAR-029-011	4
Garrycastle	Malt kiln	Distilling	OFIAR-029-011	7
Garryhinch	Mill (water)	Unknown	OFIAR-033-009	1
Glasderry More	Mill?	Unknown	OFIAR-042-008	1
Gorraun (Clonlisk By)	Grain kiln; Grain mill (water)	Grain milling	OFIAR-044-007	1
Gorraun (Clonlisk By)	Mill house	Grain milling	OFIAR-044-007	2
Gorteen (Kilcoursey By)	Mill	Unknown	OFIAR-002-019	1
Gorteenard	Grain mill (water)	Grain milling	OFIAR-026-017	1
Keeloge (Clonlisk By)	Grain kiln; Grain mill (water); Saw mill (water)	Grain milling; Timber processing & products	OFIAR-042-030	1
Kilclare; Co Westmeath	Mill race	Flax & linen	OFIAR-008-012	1
Kilcomin	Distillery	Distilling	OFIAR-041-005	1
Kilcomin	Grain kiln; Grain mill (water)	Grain milling	OFIAR-041-004	1
Kilcoursey	Bleach works	Flax & linen	OFIAR-008-025	1
Kilcoursey	Engine house (steam); Grain kiln; Grain mill (water; steam)	Grain milling	OFIAR-008-009	1
Kilcoursey	Grain kiln; Grain mill (water)	Grain milling	OFIAR-008-042	1
Kilcoursey	Mill building	Grain milling	OFIAR-008-042	2
Kilcoursey	Mill house	Grain milling	OFIAR-008-064	1
Kilcoursey	Weaving factory	Cotton	OFIAR-008-054	1
Killeenmore	Grain mill (water)	Grain milling	OFIAR-025-014	1
Killeigh	Brewery	Brewing	OFIAR-025-007	1
Killina	Grain kiln; Grain mill (water)	Grain milling	OFIAR-016-040	1
Killoughy	Grain mill (water)	Grain milling	OFIAR-032-005	1
Killurin	Grain mill (water)	Grain milling	OFIAR-024-004	1
Kilmaine	Grain mill (water)	Grain milling	OFIAR-035-016	1
Kilmalogue	Grain mill (water)	Grain milling	OFIAR-034-007	1
Kilmalogue	Malt house	Malting	OFIAR-034-008	1
Kilnagall	Grain kiln	Grain milling	OFIAR-031-014	2
Kilnagall	Grain mill (water)	Grain milling	OFIAR-031-014	1
Kilnagall	Mill (water)	Unknown	OFIAR-031-014	3
Knockarley	Grain kiln; Grain mill (water); Saw mill (water)	Grain milling; Timber processing & products	OFIAR-039-011	1
Kylebeg or Banagher	Brewery	Brewing	OFIAR-021-011	1
Kylebeg or Banagher	Brewery house	Brewing; Malting	OFIAR-021-011	9

Kylebeg or Banagher	Grain mill (steam; water); Malt house; Malt kiln	Grain milling; Malting	OFIAR-021-009	1
Kylebeg or Banagher	Grain store	Brewing; Malting	OFIAR-021-011	8
Kylebeg or Banagher	Grain store	Malting	OFIAR-021-011	6
Kylebeg or Banagher	Malt house	Malting	OFIAR-021-011	3
Kylebeg or Banagher	Malt house	Malting	OFIAR-021-011	5
Kylebeg or Banagher	Malt kiln	Malting	OFIAR-021-011	2
Kylebeg or Banagher	Malt kiln	Malting	OFIAR-021-011	7
Kylebeg or Banagher	Maltings office	Malting	OFIAR-021-011	4
Lavagh	Grain mill (water); Tuck mill (water)	Grain milling; Wool	OFIAR-029-015	1
Lea More	Grain mill (water); Tuck mill (water)	Grain milling; Wool	OFIAR-015-010	1
Lehinch	Grain mill (water)	Grain milling	OFIAR-008-029	1
Loughaun	Grain kiln; Grain mill (water)	Grain milling	OFIAR-008-016	1
Lugmore	Grain kiln	Grain milling	OFIAR-018-026	2
Lugmore	Grain mill (water)	Grain milling	OFIAR-018-026	1
Lumcloon	Grain mill (water)	Grain milling	OFIAR-023-007	1
Lumcloon	Mill (water)	Unknown	OFIAR-022-028	1
Meelaghans	Grain mill (water)	Grain milling	OFIAR-017-047	1
Mill Grove	Grain mill (water)	Grain milling	OFIAR-027-004	1
Millbrook	Grain mill (water)	Grain milling	OFIAR-025-005	1
Milltown (Garrycastle By)	Mill (water)	Unknown	OFIAR-030-002	1
Monasteroris	Grain kiln; Grain mill (water)	Grain milling	OFIAR-012-001	1
Monasteroris	Grain mill (wind)	Grain milling	OFIAR-012-002	1
Mountwilson	Threshing mill (horse)	Grain processing	OFIAR-011-035	1
Moyally; {Parkwood}	Grain kiln; Grain mill (water)	Grain milling	OFIAR-001-002	1
Moyally; {Parkwood}	Grain mill (water)	Grain milling	OFIAR-001-003	1
Moystown Demesne	Flax mill (water); Grain kiln; Grain mill (water)	Flax & linen; Grain milling	OFIAR-022-021	1
Moystown Demesne	Grain kiln; Grain mill (water)	Grain milling	OFIAR-022-020	1
Mucklagh	Grain mill (water); Tuck mill (water)	Grain milling; Wool	OFIAR-016-034	1
Newtown (Geashill By)	Grain mill (water)	Grain milling	OFIAR-025-009	1
Newtown (Kilcoursey By, Kilcumreragh Par)	Grain mill (water); Saw mill (water)	Grain milling; Timber processing & products	OFIAR-002-015	1
Park (Ballyboy By)	Grain kiln	Grain milling	OFIAR-031-005	2
Park (Ballyboy By)	Grain kiln; Grain mill (water)	Grain milling	OFIAR-031-005	1
Park (Ballyboy By)	Grain store	Grain milling	OFIAR-031-005	3

Park (Ballyboy By)	Mill house	Grain milling	OFIAR-031-005	4
Rahan Demesne	Grain mill (water); Tuck mill	Grain milling; Wool	OFIAR-016-007	1
	(water)			
Rath More	Threshing mill (water)	Grain processing	OFIAR-038-009	1
Rusheen	Grain mill (water)	Grain milling	OFIAR-041-007	1
Scrub or Pigeonpark	Saw mill	Timber processing & products	OFIAR-019-004	1
Shinrone	Brewery	Brewing	OFIAR-042-027	1
Skehanagh	Grain kiln; Grain mill (water); Tuck mill (water)	Grain milling; Wool	OFIAR-014-036	1
Spollanstown	Spinning mill	Wool	OFIAR-017-085	1
Toberdaly	Kiln	Unknown	OFIAR-011-032	1
Toberdaly	Threshing mill (horse)	Grain processing	OFIAR-011-031	1
Tonlemone	Grain kiln; Grain mill (water)	Grain milling	OFIAR-022-017	1
Townparks (Ballybritt By)	Brewery	Brewing	OFIAR-035-029	1
Townparks (Ballybritt By)	Brewery; Malt kiln	Brewing; Distilling	OFIAR-035-046	1
Townparks (Ballybritt By)	Distillery	Distilling	OFIAR-035-010	1
Townparks (Ballybritt By)	Distillery (steam)	Distilling	OFIAR-035-047	1
Townparks (Ballybritt By)	Grain kiln; Grain store	Brewing; Distilling	OFIAR-035-046	2
Townparks (Ballybritt By)	Grain mill (water); Saw mill (water)	Grain milling; Timber processing & products	OFIAR-035-009	1
Townparks (Ballybritt By)	Grain store	Brewing	OFIAR-035-029	2
Townparks (Ballybritt By)	Malt house; Malt kiln	Malting	OFIAR-035-007	1
Townparks (Ballybritt By)	Malt house; Malt kiln; Grain mill (water)	Distilling	OFIAR-035-047	2
Townparks (Ballybritt By)	Malt store	Malting	OFIAR-035-062	1
Townparks (Ballybritt By)	Newspaper printing works; Spinning mill	Printing & publishing; Wool	OFIAR-035-053	1
Townparks (Ballybritt By)	Tuck mill (water)	Wool	OFIAR-035-071	1
Townparks (Ballybritt By)?	Tuck mill (water)	Wool	OFIAR-035-060	1
Townparks (Lower Philipstown By)	Distillery	Distilling	OFIAR-018-024	1
Townparks (Lower Philipstown By)	Grain mill (water)	Grain milling	OFIAR-018-018	1
Townparks (Lower Philipstown By)	Grain mill (wind)	Grain milling	OFIAR-018-023	1
Townparks (Lower Philipstown By)	Mill	Unknown	OFIAR-018-042	1
Tullamore	Bonded warehouse	Distilling	OFIAR-017-076	1
Tullamore	Bonded warehouse; Distillery (steam); Malt house; Malt	Distilling; Malting; Timber processing	OFIAR-017-049	1

	kiln; Saw mill (steam)	& products		
Tullamore	Bottling works	Distilling	OFIAR-017-092	1
Tullamore	Brewery	Brewing	OFIAR-017-072	1
Tullamore	Brewery (water)	Brewing	OFIAR-017-052	1
Tullamore	Brewery; Malt house	Brewing; Malting	OFIAR-017-050	1
Tullamore	Brewery; Malt house	Brewing; Malting	OFIAR-017-053	1
Tullamore	Chop mill	Inland waterway	OFIAR-017-058	1
Tullamore	Distillery office	Distilling	OFIAR-017-091	1
Tullamore	Distillery; Engine house (steam); Grain mill (steam)	Distilling	OFIAR-017-036	1
Tullamore	Grain mill (steam; water)	Grain milling	OFIAR-017-038	1
Tullamore	Grain mill (water)	Grain milling	OFIAR-017-042	1
Tullamore	Grain mill; Malt house	Grain milling; Distilling	OFIAR-017-090	1
Tullamore	Grain store	Distilling	OFIAR-017-062	1
Tullamore	Malt house	Distilling	OFIAR-017-070	2
Tullamore	Malt house	Malting	OFIAR-017-039	1
Tullamore	Malt house	Malting	OFIAR-017-054	2
Tullamore	Malt house	Malting	OFIAR-017-064	1
Tullamore	Malt house	Malting	OFIAR-017-065	1
Tullamore	Malt kiln	Malting	OFIAR-017-064	2
Tullamore	Malt silo	Distilling	OFIAR-017-076	2
Tullamore	Quay	Distilling	OFIAR-017-076	3
Tullamore	Saw mill	Timber processing & products	OFIAR-017-037	1
Tullamore	Saw mill (steam)	Timber processing & products	OFIAR-017-051	1
Tullamore	Tannery	Leather products	OFIAR-017-054	1
Tullamore	Tobacco factory	Tobacco processing & products	OFIAR-017-070	1
Tully (Kilcoursey By, Ardarcher or Horseleap Par); {Tully (Kilcoursey By, Kilmanagh Parish)}	Tuck mill (water)	Wool	OFIAR-002-014	1
Wood of O	Grain mill (water)	Grain milling	OFIAR-017-083	1

	3. TOWN				
Town	Type Function Site compone			nt	
Ballyboy	Flax mill?	Flax & linen	OFIAR-031-019	1	
Ballyboy	Grain kiln; Grain mill (water); Saw mill (water)	Grain milling; Timber processing & products	OFIAR-031-007	1	
Ballycumber	Blue mill	Flax & linen	OFIAR-007-021	1	
Ballycumber	Grain mill (water); Tuck mill (water)	Grain milling; Wool	OFIAR-007-018	1	
Banagher	Brewery	Brewing	OFIAR-021-011	1	
Banagher	Brewery house	Brewing; Malting	OFIAR-021-011	9	
Banagher	Distillery	Distilling	OFIAR-021-012	1	
Banagher	Grain mill (steam; water); Malt house; Malt kiln	Grain milling; Malting	OFIAR-021-009	1	
Banagher	Grain store	Brewing; Malting	OFIAR-021-011	8	
Banagher	Grain store	Malting	OFIAR-021-011	6	
Banagher	Malt house	Malting	OFIAR-021-011	3	
Banagher	Malt house	Malting	OFIAR-021-011	5	
Banagher	Malt kiln	Malting	OFIAR-021-011	2	
Banagher	Malt kiln	Malting	OFIAR-021-011	7	
Banagher	Maltings office	Malting	OFIAR-021-011	4	
Birr	Bonded warehouse; Distillery; Grain mill (water); Malt house; Malt kiln	Distilling	OFIAR-035-034	1	
Birr	Brewery	Brewing	OFIAR-035-029	1	
Birr	Brewery; Malt kiln	Brewing; Distilling	OFIAR-035-046	1	
Birr	Distillery	Distilling	OFIAR-035-010	1	
Birr	Distillery (steam)	Distilling	OFIAR-035-047	1	
Birr	Grain kiln; Grain store	Brewing; Distilling	OFIAR-035-046	2	
Birr	Grain mill (water); Saw mill (water)	Grain milling; Timber processing & products	OFIAR-035-009	1	
Birr	Grain store	Brewing	OFIAR-035-029	2	
Birr	Malt house; Malt kiln	Malting	OFIAR-035-007	1	
Birr	Malt house; Malt kiln; Grain mill (water)	Distilling	OFIAR-035-047	2	
Birr	Malt store	Malting	OFIAR-035-062	1	
Birr	Newspaper printing works; Spinning mill	Printing & publishing; Wool	OFIAR-035-053	1	
Birr	Tuck mill (water)	Wool	OFIAR-035-060	1	
Birr	Tuck mill (water)	Wool	OFIAR-035-071	1	
Clara	Bone mill (water); Grain mill (water)	Bone and fat products; Grain milling	OFIAR-008-045	1	
Clara	Chimney	Jute	OFIAR-008-028	1	

	1		1	1 1
Clara	Electricity generating station (water)	Jute	OFIAR-008-028	4
Clara	Electricity generating station (water); Engine house (steam)	Grain milling	OFIAR-008-038	7
Clara	Engine house (steam)	Jute	OFIAR-008-028	5
Clara	Engine house (steam)	Jute	OFIAR-008-028	11
Clara	Engine house (steam); Grain kiln; Grain mill (water; steam)	Grain milling	OFIAR-008-009	1
Clara	Factory canteen	Jute	OFIAR-008-028	3
Clara	Factory garage	Jute	OFIAR-008-028	8
Clara	Factory house	Jute	OFIAR-008-028	9
Clara	Factory house	Jute	OFIAR-008-028	10
Clara	Factory office	Jute	OFIAR-008-028	7
Clara	Grain kiln; Grain mill (water)	Grain milling	OFIAR-008-038	1
Clara	Grain kiln; Grain mill (water)	Grain milling	OFIAR-008-042	1
Clara	Grain silo	Grain milling	OFIAR-008-053	1
Clara	Jute factory (electricity; steam)	Jute	OFIAR-008-028	12
Clara	Jute factory (electricity; steam; water)	Jute	OFIAR-008-028	6
Clara	Jute store	Jute	OFIAR-008-028	2
Clara	Mill building	Grain milling	OFIAR-008-038	2
Clara	Mill building	Grain milling	OFIAR-008-038	5
Clara	Mill building	Grain milling	OFIAR-008-038	6
Clara	Mill building	Grain milling	OFIAR-008-038	9
Clara	Mill building	Grain milling	OFIAR-008-042	2
Clara	Mill chimney	Grain milling	OFIAR-008-038	8
Clara	Mill house	Grain milling	OFIAR-008-038	3
Clara	Mill house	Grain milling	OFIAR-008-038	4
Clara	Mill house	Grain milling	OFIAR-008-064	1
Clara	Railway siding	Grain milling	OFIAR-008-053	2
Clara	Railway siding	Jute	OFIAR-008-028	13
Clara	Weaving factory	Cotton	OFIAR-008-054	1
Clonbulloge	Grain mill (water)	Grain milling	OFIAR-019-010	1
Daingean	Distillery	Distilling	OFIAR-018-024	1
Edenderry	Footwear factory	Footwear manufacture	OFIAR-012-027	2
Edenderry	Grain mill (wind)	Grain milling	OFIAR-012-024	1
Edenderry	Saw mill (steam)	Timber processing & products	OFIAR-012-027	1
Ferbane	Brewery	Brewing	OFIAR-014-039	1
Ferbane	Grain kiln; Grain mill (water)	Grain milling	OFIAR-014-035	1

Kilcormac	Brewery (water)	Brewing	OFIAR-031-011	1
Kilcormac	Distillery	Distilling	OFIAR-031-012	1
Kilcormac	Grain kiln	Grain milling	OFIAR-031-005	2
Kilcormac	Grain kiln; Grain mill (water)	Grain milling	OFIAR-031-005	1
Kilcormac	Grain mill (water)	Grain milling	OFIAR-031-013	1
Kilcormac	Grain store	Grain milling	OFIAR-031-005	3
Kilcormac	Hydraulic ram	Water supply	OFIAR-031-013	2
Kilcormac	Malt house; Malt kiln	Malting	OFIAR-031-012	2
Kilcormac	Mill house	Grain milling	OFIAR-031-005	4
Killeigh	Brewery	Brewing	OFIAR-025-007	1
Portarlington	Grain mill (water)	Grain milling	OFIAR-034-007	1
Portarlington	Malt house	Malting	OFIAR-034-008	1
Shinrone	Brewery	Brewing	OFIAR-042-027	1
Tullamore	Bonded warehouse	Distilling	OFIAR-017-076	1
Tullamore	Bonded warehouse; Distillery (steam); Malt house; Malt kiln; Saw mill (steam)	Distilling; Malting; Timber processing & products	OFIAR-017-049	1
Tullamore	Bottling works	Distilling	OFIAR-017-092	1
Tullamore	Brewery	Brewing	OFIAR-017-072	1
Tullamore	Brewery (water)	Brewing	OFIAR-017-052	1
Tullamore	Brewery; Malt house	Brewing; Malting	OFIAR-017-050	1
Tullamore	Brewery; Malt house	Brewing; Malting	OFIAR-017-053	1
Tullamore	Chop mill	Inland waterway	OFIAR-017-058	1
Tullamore	Distillery office	Distilling	OFIAR-017-091	1
Tullamore	Distillery; Engine house (steam); Grain mill (steam)	Distilling	OFIAR-017-036	1
Tullamore	Grain mill (steam; water)	Grain milling	OFIAR-017-038	1
Tullamore	Grain mill (water)	Grain milling	OFIAR-017-042	1
Tullamore	Grain mill; Malt house	Grain milling; Distilling	OFIAR-017-090	1
Tullamore	Grain store	Distilling	OFIAR-017-062	1
Tullamore	Malt house	Distilling	OFIAR-017-070	2
Tullamore	Malt house	Malting	OFIAR-017-039	1
Tullamore	Malt house	Malting	OFIAR-017-054	2
Tullamore	Malt house	Malting	OFIAR-017-064	1
Tullamore	Malt house	Malting	OFIAR-017-065	1
Tullamore	Malt kiln	Malting	OFIAR-017-064	2
Tullamore	Malt silo	Distilling	OFIAR-017-076	2
Tullamore	Quay	Distilling	OFIAR-017-076	3
Tullamore	Saw mill	Timber processing &	OFIAR-017-037	1

		products		
Tullamore	Saw mill (steam)	Timber processing & products	OFIAR-017-051	1
Tullamore	Spinning mill	Wool	OFIAR-017-085	1
Tullamore	Tannery	Leather products	OFIAR-017-054	1

		4. IRISH GRID		
Easting	Northing	Туре	Site Componen	nt
196152	214256	Grain mill (water); Tuck mill (water)	OFIAR-029-015	1
198530	213054	Grain mill (wind)	OFIAR-029-008	1
199189	185842	Grain kiln; Grain mill (water)	OFIAR-044-007	1
199201	185806	Mill house	OFIAR-044-007	2
200143	179354	Mill weir	OFIAR-046-005	1
200520	215728	Grain mill (steam; water); Malt house; Malt kiln	OFIAR-021-009	1
200748	215462	Malt kiln	OFIAR-021-011	2
200752	215508	Brewery	OFIAR-021-011	1
200762	215482	Malt house	OFIAR-021-011	3
200786	215510	Maltings office	OFIAR-021-011	4
200790	215537	Grain store	OFIAR-021-011	8
200802	215523	Malt house	OFIAR-021-011	5
200817	215551	Malt kiln	OFIAR-021-011	7
200819	215537	Grain store	OFIAR-021-011	6
200823	215557	Brewery house	OFIAR-021-011	9
200913	215614	Distillery	OFIAR-021-012	1
201500	213849	Distillery (steam; water)	OFIAR-029-011	3
201516	213828	Malt kiln	OFIAR-029-011	4
201525	213861	Grain kiln; Grain mill (water)	OFIAR-029-011	1
201529	230469	Grain kiln; Grain mill (water)	OFIAR-005-001	1
201556	213824	Grain store	OFIAR-029-011	5
201561	213861	Grain store	OFIAR-029-011	2
201567	213840	Distillery office	OFIAR-029-011	6
201596	213796	Malt kiln	OFIAR-029-011	7
201618	213849	Malt house	OFIAR-029-011	8
202430	223715	Grain mill (water)	OFIAR-013-006	1
202523	190751	Distillery	OFIAR-041-005	1
202622	191083	Grain kiln; Grain mill (water)	OFIAR-041-004	1
202660	190165	Grain mill (water)	OFIAR-041-007	1
202725	190687	Distillery	OFIAR-041-006	1
203169	212122	Mill (water)	OFIAR-030-002	1
203286	208102	Grain kiln	OFIAR-035-001	2
203289	208044	Grain kiln; Grain mill (water)	OFIAR-035-001	1
204199	220677	Flax mill (water); Grain kiln; Grain mill (water)	OFIAR-022-021	1

				.0.
204514	191253	Grain kiln; Grain mill (water); Saw mill (water)	OFIAR-042-030	1
204620	220933	Grain kiln; Grain mill (water)	OFIAR-022-020	1
204698	192440	Brewery	OFIAR-042-027	1
204805	210205	Grain mill (water)	OFIAR-030-003	1
204835	210209	Grain kiln; Oilseed mill (water)	OFIAR-030-003	2
204898	188895	Grain mill (water)	OFIAR-045-015	1
205139	188313	Mill	OFIAR-045-016	1
205144	185463	Distillery; Grain mill (water); Tuck mill (water)	OFIAR-045-009	1
205256	203456	Grain mill (water)	OFIAR-035-035	1
205651	204866	Tuck mill (water)	OFIAR-035-071	1
205734	204843	Malt house; Malt kiln; Grain mill (water)	OFIAR-035-047	2
205768	204870	Distillery (steam)	OFIAR-035-047	1
205770	204754	Malt store	OFIAR-035-062	1
205796	204834	Malt house; Malt kiln	OFIAR-035-007	1
205817	204867	Brewery	OFIAR-035-029	1
205820	204894	Grain store	OFIAR-035-029	2
205849	194172	Brewery	OFIAR-042-033	1
205850	194195	Grain kiln	OFIAR-042-033	2
205948	204634	Grain mill (water); Saw mill (water)	OFIAR-035-009	1
206044	204560	Distillery	OFIAR-035-010	1
206609	204901	Brewery; Malt kiln	OFIAR-035-046	1
206639	204895	Grain kiln; Grain store	OFIAR-035-046	2
206663	204939	Tuck mill (water)	OFIAR-035-060	1
206666	205025	Bonded warehouse; Distillery; Grain mill (water); Malt house; Malt kiln	OFIAR-035-034	1
206768	217311	Grain kiln; Grain mill (water)	OFIAR-022-017	1
206957	203482	Grain kiln; Grain mill (water)	OFIAR-035-031	1
207081	190570	Grain mill (water)	OFIAR-042-017	1
207105	204534	Newspaper printing works; Spinning mill	OFIAR-035-053	1
207172	222188	Mill building	OFIAR-014-004	9
207187	222168	Mill building	OFIAR-014-004	5
207190	222124	Mill house	OFIAR-014-004	6
207204	222216	Mill building	OFIAR-014-004	4
207213	222131	Grain mill (electric; water)	OFIAR-014-004	2
207218	222174	Grain kiln; Grain mill (water); Oilseed mill (water)	OFIAR-014-004	1
207221	222114	Electricity generating station (water)	OFIAR-014-004	7

207221	222262	Mill house	OFIAR-014-004	3
207243	222090	Electricity generating station (water)	OFIAR-014-004	8
207274	222154	Tuck mill (water)	OFIAR-014-004	10
207577	203156	Grain kiln	OFIAR-035-018	2
207593	203145	Grain kiln; Grain mill (water)	OFIAR-035-018	1
207821	197964	Threshing mill (water)	OFIAR-038-009	1
207906	204650	Grain mill (water); Oilseed mill (water)	OFIAR-035-013	1
208413	194830	Mill?	OFIAR-042-008	1
209190	223222	Grain kiln; Grain mill (water); Tuck mill (water)	OFIAR-014-036	1
209514	209760	Grain kiln; Grain mill (water)	OFIAR-030-004	1
209547	209892	Bleach works (water); Grain mill (water)	OFIAR-030-008	1
210113	192799	Grain mill (water)	OFIAR-042-028	1
210185	191883	Grain kiln; Grain mill (water); Malt house	OFIAR-042-009	1
210213	193165	Mill (water)	OFIAR-042-029	1
210622	191539	Grain mill (water)	OFIAR-042-010	1
210741	191797	Mill	OFIAR-042-042	1
210866	204608	Grain mill (water)	OFIAR-035-033	1
210887	190873	Grain mill (water)	OFIAR-042-026	1
210978	190640	Grain mill (water)	OFIAR-042-011	1
211298	190631	Grain mill (water)	OFIAR-042-012	1
211319	190617	Grain kiln; Grain mill (water); Tuck mill (water)	OFIAR-042-012	2
211479	228031	Grain mill (water)	OFIAR-014-001	1
211513	232142	Grain mill (water)	OFIAR-006-003	1
211516	232131	Tuck mill (water)	OFIAR-006-003	3
211525	232141	Grain kiln	OFIAR-006-003	2
211539	224338	Grain kiln; Grain mill (water)	OFIAR-014-035	1
211561	224431	Brewery	OFIAR-014-039	1
212223	224210	Grain kiln; Grain mill (water)	OFIAR-014-034	1
212390	218982	Mill (water)	OFIAR-022-028	1
212476	204247	Grain mill (water)	OFIAR-035-016	1
213014	199086	Malt house	OFIAR-039-014	1
213336	192588	Grain mill (water); Grain store	OFIAR-043-002	2
213353	192605	Grain mill (water)	OFIAR-043-002	1
213376	192558	Mill house	OFIAR-043-002	3
213771	219296	Grain mill (water)	OFIAR-023-007	1
215333	213277	Grain mill (water)	OFIAR-031-020	1

				0
215349	213277	Grain kiln	OFIAR-031-020	2
216016	199522	Grain kiln; Grain mill (water); Saw mill (water)	OFIAR-039-011	1
216461	201220	Mill house	OFIAR-039-005	2
216474	201168	Grain mill (water)	OFIAR-039-005	1
217470	191658	Grain mill (water)	OFIAR-043-004	1
217471	214807	Mill (water)	OFIAR-031-014	3
217480	214799	Grain kiln	OFIAR-031-014	2
217489	214816	Grain mill (water)	OFIAR-031-014	1
217594	229936	Grain kiln; Grain mill (water)	OFIAR-007-016	1
217841	205714	Starch house	OFIAR-036-019	2
217858	205675	Grain mill (water)	OFIAR-036-019	1
218107	214244	Brewery (water)	OFIAR-031-011	1
218198	214151	Distillery	OFIAR-031-012	1
218221	214112	Malt house; Malt kiln	OFIAR-031-012	2
218285	204212	Grain mill (water)	OFIAR-036-018	1
218353	214139	Grain mill (water)	OFIAR-031-013	1
218353	214139	Hydraulic ram	OFIAR-031-013	2
218692	214089	Grain kiln	OFIAR-031-005	2
218706	214082	Grain store	OFIAR-031-005	3
218706	214082	Mill house	OFIAR-031-005	4
218722	214095	Grain kiln; Grain mill (water)	OFIAR-031-005	1
219560	229493	Grain kiln; Grain mill (water)	OFIAR-007-017	1
220258	230653	Bleach works (water); Grain kiln; Grain mill (water)	OFIAR-007-008	1
220372	213856	Flax mill?	OFIAR-031-019	1
220377	213983	Grain kiln; Grain mill (water); Saw mill (water)	OFIAR-031-007	1
220609	231618	Grain kiln; Grain mill (water)	OFIAR-007-019	1
220741	222006	Grain mill (water); Tuck mill (water)	OFIAR-015-010	1
220925	214202	Grain kiln; Grain mill (water)	OFIAR-031-008	1
220994	230567	Blue mill	OFIAR-007-021	1
221094	230614	Grain mill (water); Tuck mill (water)	OFIAR-007-018	1
221725	238627	Grain mill (water)	OFIAR-001-003	1
221740	229634	Mill	OFIAR-007-032	1
221788	238617	Grain kiln; Grain mill (water)	OFIAR-001-002	1
222023	230359	Grain mill (water)	OFIAR-007-022	1
222173	233639	Grain kiln; Grain mill (water); Tuck mill (water)	OFIAR-008-001	1
222207	220304	Grain mill (water)	OFIAR-024-009	1

				0
222305	213761	Grain mill (water)	OFIAR-032-004	1
222588	213589	Grain kiln; Grain mill (water); Saw mill (water); Tuck mill (water)	OFIAR-032-002	1
222691	208509	Grain mill (water)	OFIAR-037-002	2
222692	208515	Grain kiln; Grain mill (water); Saw mill (water); Weaving factory	OFIAR-037-002	1
222714	208533	Millstone quarry	OFIAR-037-005	1
223344	235657	Mill	OFIAR-002-019	1
223454	221416	Mill	OFIAR-024-013	1
224181	237331	Tuck mill (water)	OFIAR-002-014	1
224937	232215	Chimney	OFIAR-008-028	1
224950	232219	Jute store	OFIAR-008-028	2
224967	232184	Factory house	OFIAR-008-028	9
224979	232223	Factory canteen	OFIAR-008-028	3
224993	232191	Factory house	OFIAR-008-028	10
224995	232233	Electricity generating station (water)	OFIAR-008-028	4
225004	232233	Engine house (steam)	OFIAR-008-028	5
225014	238416	Grain mill (water); Saw mill (water)	OFIAR-002-015	1
225022	232258	Jute factory (electricity; steam; water)	OFIAR-008-028	6
225035	232236	Factory office	OFIAR-008-028	7
225037	232166	Engine house (steam)	OFIAR-008-028	11
225050	232187	Jute factory (electricity; steam)	OFIAR-008-028	12
225077	232261	Factory garage	OFIAR-008-028	8
225180	232103	Railway siding	OFIAR-008-028	13
225416	225821	Grain mill (water); Tuck mill (water)	OFIAR-016-007	1
225635	232458	Mill house	OFIAR-008-038	4
225637	232479	Mill house	OFIAR-008-038	3
225648	232472	Mill building	OFIAR-008-038	2
225651	232448	Mill building	OFIAR-008-038	5
225666	232461	Grain kiln; Grain mill (water)	OFIAR-008-038	1
225669	232387	Grain silo	OFIAR-008-053	1
225674	232488	Mill chimney	OFIAR-008-038	8
225681	232484	Electricity generating station (water); Engine house (steam)	OFIAR-008-038	7
225683	232451	Mill building	OFIAR-008-038	6
225717	232451	Mill building	OFIAR-008-038	9
225737	232318	Railway siding	OFIAR-008-053	2

225742	232473	Bone mill (water); Grain mill (water)	OFIAR-008-045	1
225849	237230	Grain mill (water)	OFIAR-002-017	1
226064	232311	Mill building	OFIAR-008-042	2
226076	232244	Weaving factory	OFIAR-008-054	1
226088	232309	Grain kiln; Grain mill (water)	OFIAR-008-042	1
226103	232336	Mill house	OFIAR-008-064	1
226148	232267	Engine house (steam); Grain kiln; Grain mill (water; steam)	OFIAR-008-009	1
226646	230923	Mill	OFIAR-008-065	1
227175	214200	Grain mill (water)	OFIAR-032-005	1
227187	232302	Bleach works	OFIAR-008-025	1
227523	238255	Grain kiln; Grain mill (water)	OFIAR-002-006	1
227965	224834	Grain kiln; Grain mill (water)	OFIAR-016-040	1
228677	234792	Mill (wind)	OFIAR-002-010	1
228891	233001	Grain mill (water)	OFIAR-008-029	1
229360	233062	Mill race	OFIAR-008-012	1
229876	219029	Grain mill (water)	OFIAR-024-004	1
230256	228981	Grain kiln; Grain mill (water)	OFIAR-008-016	1
230746	222516	Grain mill (water); Tuck mill (water)	OFIAR-016-034	1
231287	223323	Bone mill (water); Saw mill (water); Threshing mill (water); Water pump (water)	OFIAR-016-031	1
231514	227815	Grain kiln; Grain mill (water)	OFIAR-016-002	1
233571	224441	Spinning mill	OFIAR-017-085	1
233579	224890	Grain mill (steam; water)	OFIAR-017-038	1
233626	224868	Grain mill (water)	OFIAR-017-042	1
233682	224959	Saw mill	OFIAR-017-037	1
233695	225040	Distillery; Engine house (steam); Grain mill (steam)	OFIAR-017-036	1
233737	225084	Malt kiln	OFIAR-017-064	2
233765	225078	Malt house	OFIAR-017-064	1
233766	225033	Malt house	OFIAR-017-065	1
233776	224904	Brewery (water)	OFIAR-017-052	1
233802	224982	Brewery	OFIAR-017-072	1
233805	225005	Malt house	OFIAR-017-070	2
233805	225005	Tobacco factory	OFIAR-017-070	1
233816	225070	Grain mill; Malt house	OFIAR-017-090	1
233817	225052	Saw mill (steam)	OFIAR-017-051	1
233844	225343	Malt silo	OFIAR-017-076	2

233851	225118	Distillery office	OFIAR-017-091	1
233856	225147	Bottling works	OFIAR-017-092	1
233871	225347	Bonded warehouse	OFIAR-017-076	1
233872	225355	Quay	OFIAR-017-076	3
233880	225290	Grain store	OFIAR-017-062	1
233985	224891	Malt house	OFIAR-017-039	1
233993	224950	Brewery; Malt house	OFIAR-017-050	1
234023	224834	Malt house	OFIAR-017-054	2
234024	224878	Brewery; Malt house	OFIAR-017-053	1
234034	224817	Tannery	OFIAR-017-054	1
234085	229238	Tuck mill (water)	OFIAR-009-021	1
234165	225095	Bonded warehouse; Distillery (steam); Malt house; Malt kiln; Saw mill (steam)	OFIAR-017-049	1
234176	225244	Chop mill	OFIAR-017-058	1
234464	228906	Distillery	OFIAR-009-005	2
234484	228899	Grain kiln; Grain mill (water)	OFIAR-009-005	1
235945	228909	Grain mill (water)	OFIAR-009-006	1
235970	228890	Grain kiln	OFIAR-009-006	2
236811	218273	Brewery	OFIAR-025-007	1
237013	218614	Grain mill (water)	OFIAR-025-005	1
237532	220793	Grain mill (water)	OFIAR-025-014	1
238248	227276	Grain mill (water)	OFIAR-017-083	1
238303	231579	Grain mill (water)	OFIAR-009-018	1
238827	230620	Grain mill (water)	OFIAR-009-015	1
238852	230624	Grain kiln	OFIAR-009-015	2
239302	224364	Grain mill (water)	OFIAR-017-107	1
239840	222532	Grain mill (water)	OFIAR-017-047	1
240454	220764	Grain mill (water)	OFIAR-025-009	1
244532	222301	Grain mill (water)	OFIAR-018-026	1
244568	222289	Grain kiln	OFIAR-018-026	2
245428	231421	Grain mill (wind)	OFIAR-010-016	1
245684	217153	Grain mill (water)	OFIAR-026-017	1
246368	227418	Mill	OFIAR-018-042	1
246639	226386	Grain mill (water)	OFIAR-018-018	1
247266	227349	Distillery	OFIAR-018-024	1
248052	215478	Brewery	OFIAR-033-008	1

	1			
248142	227843	Grain mill (wind)	OFIAR-018-023	1
248221	231437	Grain mill (water)	OFIAR-010-012	1
248232	231382	Grain kiln; Grain mill (water)	OFIAR-010-014	1
248250	231443	Grain kiln	OFIAR-010-013	1
248514	211296	Mill (water)	OFIAR-033-009	1
249046	231162	Grain kiln; Grain mill (water)	OFIAR-010-010	1
249641	216318	Grain kiln; Grain mill (water)	OFIAR-026-015	1
251257	218229	Grain kiln; Grain mill (water); Tuck mill (water)	OFIAR-026-016	1
251346	226667	Mill	OFIAR-018-035	1
252005	232009	Kiln	OFIAR-011-032	1
252024	223070	Saw mill	OFIAR-019-004	1
252484	233169	Threshing mill (horse)	OFIAR-011-031	1
252860	228651	Grain kiln; Grain mill (water); Saw mill (water)	OFIAR-011-021	1
253050	234124	Threshing mill (horse)	OFIAR-011-030	1
253190	236202	Grain kiln; Grain mill (water)	OFIAR-004-011	1
253574	212449	Malt house	OFIAR-034-008	1
253604	212420	Grain mill (water)	OFIAR-034-007	1
254967	233816	Grain mill (wind)	OFIAR-011-001	1
257618	222773	Grain kiln; Grain mill (water)	OFIAR-019-006	1
259321	234086	Threshing mill (horse)	OFIAR-011-035	1
260026	218531	Grain mill (water)	OFIAR-027-004	1
260912	223506	Grain mill (water)	OFIAR-019-010	1
261207	217696	Grain mill (water)	OFIAR-027-005	1
261207	217696	Smithy	OFIAR-027-005	2
261681	233710	Grain kiln; Grain mill (water)	OFIAR-012-001	1
261737	233449	Grain mill (wind)	OFIAR-012-002	1
262180	232177	Grain mill (wind)	OFIAR-012-024	1
262883	232523	Saw mill (steam)	OFIAR-012-027	1
262907	232456	Footwear factory	OFIAR-012-027	2

		5. TYPE		
Туре	Function	Townland	Site component	Туре
Bleach works	Flax & linen	Kilcoursey	OFIAR-008-025	1
Bleach works (water)	Flax & linen	Ballycumber	OFIAR-007-008	1
Bleach works (water)	Flax & linen	Eglish	OFIAR-030-008	1
Blue mill	Flax & linen	Ballycumber	OFIAR-007-021	1
Bonded warehouse	Distilling	Clonoghil Upper	OFIAR-035-034	1
Bonded warehouse	Distilling	Tullamore	OFIAR-017-049	1
Bonded warehouse	Distilling	Tullamore	OFIAR-017-076	1
Bone mill (water)	Bone and fat products	Charleville Demesne	OFIAR-016-031	1
Bone mill (water)	Bone and fat products	Clara	OFIAR-008-045	1
Bottling works	Distilling	Tullamore	OFIAR-017-092	1
Brewery	Brewing	Clareen	OFIAR-042-033	1
Brewery	Brewing	Clonygowan	OFIAR-033-008	1
Brewery	Brewing	Ferbane	OFIAR-014-039	1
Brewery	Brewing	Killeigh	OFIAR-025-007	1
Brewery	Brewing	Kylebeg or Banagher	OFIAR-021-011	1
Brewery	Brewing	Shinrone	OFIAR-042-027	1
Brewery	Brewing	Townparks (Ballybritt By)	OFIAR-035-029	1
Brewery	Brewing	Townparks (Ballybritt By)	OFIAR-035-046	1
Brewery	Brewing	Tullamore	OFIAR-017-050	1
Brewery	Brewing	Tullamore	OFIAR-017-072	1
Brewery	Distilling	Townparks (Ballybritt By)	OFIAR-035-046	1
Brewery (water)	Brewing	Frankford	OFIAR-031-011	1
Brewery (water)	Brewing	Tullamore	OFIAR-017-052	1
Brewery house	Brewing; Malting	Kylebeg or Banagher	OFIAR-021-011	9
Chimney	Jute	Erry (Armstrong)	OFIAR-008-028	1
Chop mill	Inland waterway	Tullamore	OFIAR-017-058	1
Distillery	Distilling	Acantha	OFIAR-009-005	2
Distillery	Distilling	Ballytoran	OFIAR-041-006	1
Distillery	Distilling	Clonoghil Upper	OFIAR-035-034	1
Distillery	Distilling	Curraghavarna and Portavolla	OFIAR-021-012	1
Distillery	Distilling	Franckfort	OFIAR-045-009	1
Distillery	Distilling	Frankford	OFIAR-031-012	1
Distillery	Distilling	Kilcomin	OFIAR-041-005	1

Distillery	Distilling	Townparks (Ballybritt By)	OFIAR-035-010	1
Distillery	Distilling	Townparks (Lower Philipstown By)	OFIAR-018-024	1
Distillery	Distilling	Tullamore	OFIAR-017-036	1
Distillery (steam)	Distilling	Townparks (Ballybritt By)	OFIAR-035-047	1
Distillery (steam)	Distilling	Tullamore	OFIAR-017-049	1
Distillery (steam; water)	Distilling	Garrycastle	OFIAR-029-011	3
Distillery office	Distilling	Garrycastle	OFIAR-029-011	6
Distillery office	Distilling	Tullamore	OFIAR-017-091	1
Electricity generating station (water)	Electricity	Bellmount or Lisderg	OFIAR-014-004	8
Electricity generating station (water)	Grain milling	Bellmount or Lisderg	OFIAR-014-004	7
Electricity generating station (water)	Grain milling	Erry (Maryborough)	OFIAR-008-038	7
Electricity generating station (water)	Jute	Erry (Armstrong)	OFIAR-008-028	4
Engine house (steam)	Distilling	Tullamore	OFIAR-017-036	1
Engine house (steam)	Grain milling	Erry (Maryborough)	OFIAR-008-038	7
Engine house (steam)	Grain milling	Kilcoursey	OFIAR-008-009	1
Engine house (steam)	Jute	Erry (Armstrong)	OFIAR-008-028	5
Engine house (steam)	Jute	Erry (Armstrong)	OFIAR-008-028	11
Factory canteen	Jute	Erry (Armstrong)	OFIAR-008-028	3
Factory garage	Jute	Erry (Armstrong)	OFIAR-008-028	8
Factory house	Jute	Erry (Armstrong)	OFIAR-008-028	9
Factory house	Jute	Erry (Armstrong)	OFIAR-008-028	10
Factory office	Jute	Erry (Armstrong)	OFIAR-008-028	7
Flax mill (water)	Flax & linen	Moystown Demesne	OFIAR-022-021	1
Flax mill?	Flax & linen	Ballyboy (Ballyboy By)	OFIAR-031-019	1
Footwear factory	Footwear manufacture	Edenderry	OFIAR-012-027	2
Grain kiln	Brewing; Distilling	Townparks (Ballybritt By)	OFIAR-035-046	2
Grain kiln	Grain milling	Acantha	OFIAR-009-005	1
Grain kiln	Grain milling	Aghaboy	OFIAR-014-034	1
Grain kiln	Grain milling	Aghamore (Lower Philipstown By)	OFIAR-010-014	1
Grain kiln	Grain milling	Ballaghanoher	OFIAR-030-003	2
Grain kiln	Grain milling	Ballinree (Ballybritt By)	OFIAR-035-018	1
Grain kiln	Grain milling	Ballinree (Ballybritt By)	OFIAR-035-018	2
Grain kiln	Grain milling	Ballyboy (Ballyboy By)	OFIAR-031-007	1

Grain kiln	Grain milling	Ballycumber	OFIAR-007-008	1
Grain kiln	Grain milling	Ballyduff (Ballycowan By)	OFIAR-016-002	1
Grain kiln	Grain milling	Ballyhugh	OFIAR-011-021	1
Grain kiln	Grain milling	Ballynacarrig	OFIAR-032-002	1
Grain kiln	Grain milling	Ballynaguilsha	OFIAR-030-004	1
Grain kiln	Grain milling	Ballynasrah or Tinnycross	OFIAR-009-006	2
Grain kiln	Grain milling	Ballyoran	OFIAR-031-008	1
Grain kiln	Grain milling	Bellmount or Lisderg	OFIAR-014-004	1
Grain kiln	Grain milling	Bogtown	OFIAR-026-015	1
Grain kiln	Grain milling	Bracklin Big	OFIAR-009-015	2
Grain kiln	Grain milling	Bunrevan	OFIAR-035-001	1
Grain kiln	Grain milling	Bunrevan	OFIAR-035-001	2
Grain kiln	Grain milling	Cadamstown	OFIAR-037-002	1
Grain kiln	Grain milling	Cappydonnell Little	OFIAR-002-006	1
Grain kiln	Grain milling	Castlearmstrong	OFIAR-007-016	1
Grain kiln	Grain milling	Cloghatanny	OFIAR-008-001	1
Grain kiln	Grain milling	Clonavoe	OFIAR-019-006	1
Grain kiln	Grain milling	Clonmacnoise	OFIAR-005-001	1
Grain kiln	Grain milling	Cornafurrish and Corrabeg	OFIAR-007-017	1
Grain kiln	Grain milling	Cranasallagh	OFIAR-007-019	1
Grain kiln	Grain milling	Crinkill	OFIAR-035-031	1
Grain kiln	Grain milling	Croghan Demesne	OFIAR-010-013	1
Grain kiln	Grain milling	Curraghmore (Eglish By)	OFIAR-031-020	2
Grain kiln	Grain milling	Derryiron	OFIAR-004-011	1
Grain kiln	Grain milling	Doon Demesne	OFIAR-006-003	2
Grain kiln	Grain milling	Down (Lower Philipstown By)	OFIAR-010-010	1
Grain kiln	Grain milling	Drumakeenan (Clonlisk By, Ettagh Par)	OFIAR-042-009	1
Grain kiln	Grain milling	Drumakeenan (Clonlisk By, Roscrea Par)	OFIAR-042-012	2
Grain kiln	Grain milling	Enaghan	OFIAR-026-016	1
Grain kiln	Grain milling	Erry (Maryborough)	OFIAR-008-038	1
Grain kiln	Grain milling	Gallen	OFIAR-014-035	1
Grain kiln	Grain milling	Garrycastle	OFIAR-029-011	1
Grain kiln	Grain milling	Gorraun (Clonlisk By)	OFIAR-044-007	1
Grain kiln	Grain milling	Keeloge (Clonlisk By)	OFIAR-042-030	1
Grain kiln	Grain milling	Kilcomin	OFIAR-041-004	1

Grain kiln	Grain milling	Kilcoursey	OFIAR-008-009	1
Grain kiln	Grain milling	Kilcoursey	OFIAR-008-042	1
Grain kiln	Grain milling	Killina	OFIAR-016-040	1
Grain kiln	Grain milling	Kilnagall	OFIAR-031-014	2
Grain kiln	Grain milling	Knockarley	OFIAR-039-011	1
Grain kiln	Grain milling	Loughaun	OFIAR-008-016	1
Grain kiln	Grain milling	Lugmore	OFIAR-018-026	2
Grain kiln	Grain milling	Monasteroris	OFIAR-012-001	1
Grain kiln	Grain milling	Moyally; {Parkwood}	OFIAR-001-002	1
Grain kiln	Grain milling	Moystown Demesne	OFIAR-022-020	1
Grain kiln	Grain milling	Moystown Demesne	OFIAR-022-021	1
Grain kiln	Grain milling	Park (Ballyboy By)	OFIAR-031-005	1
Grain kiln	Grain milling	Park (Ballyboy By)	OFIAR-031-005	2
Grain kiln	Grain milling	Skehanagh	OFIAR-014-036	1
Grain kiln	Grain milling	Tonlemone	OFIAR-022-017	1
Grain kiln	Grain processing	Clareen	OFIAR-042-033	2
Grain mill	Grain milling	Tullamore	OFIAR-017-090	1
Grain mill (electric; water)	Grain milling	Bellmount or Lisderg	OFIAR-014-004	2
Grain mill (steam)	Distilling	Tullamore	OFIAR-017-036	1
Grain mill (steam; water)	Grain milling	Kylebeg or Banagher	OFIAR-021-009	1
Grain mill (steam; water)	Grain milling	Tullamore	OFIAR-017-038	1
Grain mill (water)	Distilling	Clonoghil Upper	OFIAR-035-034	1
Grain mill (water)	Distilling	Townparks (Ballybritt By)	OFIAR-035-047	2
Grain mill (water)	Grain milling	Acantha	OFIAR-009-005	1
Grain mill (water)	Grain milling	Aghaboy	OFIAR-014-034	1
Grain mill (water)	Grain milling	Aghagurty	OFIAR-039-005	1
Grain mill (water)	Grain milling	Aghamore (Lower Philipstown By)	OFIAR-010-014	1
Grain mill (water)	Grain milling	Annaghmore (Garrycastle By)	OFIAR-013-006	1
Grain mill (water)	Grain milling	Ballaghanoher	OFIAR-030-003	1
Grain mill (water)	Grain milling	Ballincur (Ballybritt By)	OFIAR-036-019	1
Grain mill (water)	Grain milling	Ballinree (Ballybritt By)	OFIAR-035-018	1
Grain mill (water)	Grain milling	Ballyboy (Ballyboy By)	OFIAR-031-007	1
Grain mill (water)	Grain milling	Ballycumber	OFIAR-007-008	1
Grain mill (water)	Grain milling	Ballycumber	OFIAR-007-018	1

Grain mill (water)	Grain milling	Ballyduff (Ballybritt By)	OFIAR-043-004	1
Grain mill (water)	Grain milling	Ballyduff (Ballycowan By)	OFIAR-016-002	1
Grain mill (water)	Grain milling	Ballyhugh	OFIAR-011-021	1
Grain mill (water)	Grain milling	Ballykilleen (Kilcoursey By)	OFIAR-002-017	1
Grain mill (water)	Grain milling	Ballynacarrig	OFIAR-032-002	1
Grain mill (water)	Grain milling	Ballynaguilsha	OFIAR-030-004	1
Grain mill (water)	Grain milling	Ballynasrah or Tinnycross	OFIAR-009-006	1
Grain mill (water)	Grain milling	Ballyoran	OFIAR-031-008	1
Grain mill (water)	Grain milling	Ballyshane (Ballybritt By)	OFIAR-036-018	1
Grain mill (water)	Grain milling	Bellmount or Lisderg	OFIAR-014-004	1
Grain mill (water)	Grain milling	Bogtown	OFIAR-026-015	1
Grain mill (water)	Grain milling	Bohernagrisna	OFIAR-007-022	1
Grain mill (water)	Grain milling	Bracklin Big	OFIAR-009-015	1
Grain mill (water)	Grain milling	Bracklin Little	OFIAR-009-018	1
Grain mill (water)	Grain milling	Bracknagh	OFIAR-027-005	1
Grain mill (water)	Grain milling	Bunrevan	OFIAR-035-001	1
Grain mill (water)	Grain milling	Cadamstown	OFIAR-037-002	1
Grain mill (water)	Grain milling	Cadamstown	OFIAR-037-002	2
Grain mill (water)	Grain milling	Cappagowlan	OFIAR-032-004	1
Grain mill (water)	Grain milling	Cappancur	OFIAR-017-107	1
Grain mill (water)	Grain milling	Cappydonnell Little	OFIAR-002-006	1
Grain mill (water)	Grain milling	Castlearmstrong	OFIAR-007-016	1
Grain mill (water)	Grain milling	Clara	OFIAR-008-045	1
Grain mill (water)	Grain milling	Cloghatanny	OFIAR-008-001	1
Grain mill (water)	Grain milling	Clonavoe	OFIAR-019-006	1
Grain mill (water)	Grain milling	Clonbrone (Eglish By)	OFIAR-035-033	1
Grain mill (water)	Grain milling	Clonbulloge	OFIAR-019-010	1
Grain mill (water)	Grain milling	Clonlisik	OFIAR-045-015	1
Grain mill (water)	Grain milling	Clonmacnoise	OFIAR-005-001	1
Grain mill (water)	Grain milling	Clonoghil Upper	OFIAR-035-013	1
Grain mill (water)	Grain milling	Clyduff (Clonlisk By); {Milltown}	OFIAR-042-017	1
Grain mill (water)	Grain milling	Corbane	OFIAR-014-001	1
Grain mill (water)	Grain milling	Cornafurrish and Corrabeg	OFIAR-007-017	1
Grain mill (water)	Grain milling	Cranasallagh	OFIAR-007-019	1
Grain mill (water)	Grain milling	Crinkill OFIAR-035		1
Grain mill (water)	Grain milling	Croghan Demesne	OFIAR-010-012	1

				_
Grain mill (water)	Grain milling	Curraghmore (Eglish By)	OFIAR-031-020	1
Grain mill (water)	Grain milling	Derryiron	OFIAR-004-011	1
Grain mill (water)	Grain milling	Derrymore (Ballyboy By)	OFIAR-024-009	1
Grain mill (water)	Grain milling	Doon Demesne	OFIAR-006-003	1
Grain mill (water)	Grain milling	Down (Lower Philipstown By)	OFIAR-010-010	1
Grain mill (water)	Grain milling	Drumakeenan (Clonlisk By, Ettagh Par)	OFIAR-042-009	1
Grain mill (water)	Grain milling	Drumakeenan (Clonlisk By, Ettagh Par)	OFIAR-042-028	1
Grain mill (water)	Grain milling	Drumakeenan (Clonlisk By, Roscrea Par)	OFIAR-042-010	1
Grain mill (water)	Grain milling	Drumakeenan (Clonlisk By, Roscrea Par)	OFIAR-042-011	1
Grain mill (water)	Grain milling	Drumakeenan (Clonlisk By, Roscrea Par)	OFIAR-042-012	1
Grain mill (water)	Grain milling	Drumakeenan (Clonlisk By, Roscrea Par)	OFIAR-042-012	2
Grain mill (water)	Grain milling	Drumakeenan (Clonlisk By, Roscrea Par)	OFIAR-042-026	1
Grain mill (water)	Grain milling	Eglish	OFIAR-030-008	1
Grain mill (water)	Grain milling	Enaghan	OFIAR-026-016	1
Grain mill (water)	Grain milling	Erry (Maryborough)	OFIAR-008-038	1
Grain mill (water)	Grain milling	Fancroft	OFIAR-043-002	1
Grain mill (water)	Grain milling	Fancroft	OFIAR-043-002	2
Grain mill (water)	Grain milling	Franckfort	OFIAR-045-009	1
Grain mill (water)	Grain milling	Frankford	OFIAR-031-013	1
Grain mill (water)	Grain milling	Gallen	OFIAR-014-035	1
Grain mill (water)	Grain milling	Garrycastle	OFIAR-029-011	1
Grain mill (water)	Grain milling	Gorraun (Clonlisk By)	OFIAR-044-007	1
Grain mill (water)	Grain milling	Gorteenard	OFIAR-026-017	1
Grain mill (water)	Grain milling	Keeloge (Clonlisk By)	OFIAR-042-030	1
Grain mill (water)	Grain milling	Kilcomin	OFIAR-041-004	1
Grain mill (water)	Grain milling	Kilcoursey	OFIAR-008-042	1
Grain mill (water)	Grain milling	Killeenmore	OFIAR-025-014	1
Grain mill (water)	Grain milling	Killina	OFIAR-016-040	1
Grain mill (water)	Grain milling	Killoughy	OFIAR-032-005	1
Grain mill (water)	Grain milling	Killurin	OFIAR-024-004	1
Grain mill (water)	Grain milling	Kilmaine	OFIAR-035-016	1
Grain mill (water)	Grain milling	Kilmalogue	OFIAR-034-007	1

Grain mill (water)	Grain milling	Kilnagall	OFIAR-031-014	1
Grain mill (water)	Grain milling	Knockarley	OFIAR-039-011	1
Grain mill (water)	Grain milling	Lavagh	OFIAR-029-015	1
Grain mill (water)	Grain milling	Lea More	OFIAR-015-010	1
Grain mill (water)	Grain milling	Lehinch	OFIAR-008-029	1
Grain mill (water)	Grain milling	Loughaun	OFIAR-008-016	1
Grain mill (water)	Grain milling	Lugmore	OFIAR-018-026	1
Grain mill (water)	Grain milling	Lumcloon	OFIAR-023-007	1
Grain mill (water)	Grain milling	Meelaghans	OFIAR-017-047	1
Grain mill (water)	Grain milling	Mill Grove	OFIAR-027-004	1
Grain mill (water)	Grain milling	Millbrook	OFIAR-025-005	1
Grain mill (water)	Grain milling	Monasteroris	OFIAR-012-001	1
Grain mill (water)	Grain milling	Moyally; {Parkwood}	OFIAR-001-002	1
Grain mill (water)	Grain milling	Moyally; {Parkwood}	OFIAR-001-003	1
Grain mill (water)	Grain milling	Moystown Demesne	OFIAR-022-020	1
Grain mill (water)	Grain milling	Moystown Demesne	OFIAR-022-021	1
Grain mill (water)	Grain milling	Mucklagh	OFIAR-016-034	1
Grain mill (water)	Grain milling	Newtown (Geashill By)	OFIAR-025-009	1
Grain mill (water)	Grain milling	Newtown (Kilcoursey By, Kilcumreragh Par)	OFIAR-002-015	1
Grain mill (water)	Grain milling	Park (Ballyboy By)	OFIAR-031-005	1
Grain mill (water)	Grain milling	Rahan Demesne	OFIAR-016-007	1
Grain mill (water)	Grain milling	Rusheen	OFIAR-041-007	1
Grain mill (water)	Grain milling	Skehanagh	OFIAR-014-036	1
Grain mill (water)	Grain milling	Tonlemone	OFIAR-022-017	1
Grain mill (water)	Grain milling	Townparks (Ballybritt By)	OFIAR-035-009	1
Grain mill (water)	Grain milling	Townparks (Lower Philipstown By)	OFIAR-018-018	1
Grain mill (water)	Grain milling	Tullamore	OFIAR-017-042	1
Grain mill (water)	Grain milling	Wood of O	OFIAR-017-083	1
Grain mill (water)	Malting	Ballindarra	OFIAR-035-035	1
Grain mill (water; steam)	Grain milling	Kilcoursey OFIAR-008-009		1
Grain mill (wind)	Grain milling	Barnan	OFIAR-010-016	1
Grain mill (wind)	Grain milling	Cloghan Beg	OFIAR-029-008	1
Grain mill (wind)	Grain milling	Edenderry	OFIAR-012-024	1
Grain mill (wind)	Grain milling	Fahy	OFIAR-011-001	1
Grain mill (wind)	Grain milling	Monasteroris	OFIAR-012-002	1

Grain mill (wind)	Grain milling	Townparks (Lower Philipstown By)	OFIAR-018-023	1
Grain silo	Grain milling	Erry (Maryborough)	OFIAR-008-053	1
Grain store	Brewing	Townparks (Ballybritt By)	OFIAR-035-029	2
Grain store	Brewing; Distilling	Townparks (Ballybritt By)	OFIAR-035-046	2
Grain store	Brewing; Malting	Kylebeg or Banagher	OFIAR-021-011	8
Grain store	Distilling	Tullamore	OFIAR-017-062	1
Grain store	Grain milling	Fancroft	OFIAR-043-002	2
Grain store	Grain milling	Garrycastle	OFIAR-029-011	2
Grain store	Grain milling	Garrycastle	OFIAR-029-011	5
Grain store	Grain milling	Park (Ballyboy By)	OFIAR-031-005	3
Grain store	Malting	Kylebeg or Banagher	OFIAR-021-011	6
Hydraulic ram	Water supply	Frankford	OFIAR-031-013	2
Jute factory (electricity; steam)	Jute	Erry (Armstrong)	OFIAR-008-028	12
Jute factory (electricity; steam; water)	Jute	Erry (Armstrong)	OFIAR-008-028	6
Jute store	Jute	Erry (Armstrong)	OFIAR-008-028	2
Kiln	Unknown	Toberdaly	OFIAR-011-032	1
Malt house	Distilling	Clonoghil Upper	OFIAR-035-034	1
Malt house	Distilling	Townparks (Ballybritt By)	OFIAR-035-047	2
Malt house	Distilling	Tullamore	OFIAR-017-070	2
Malt house	Distilling	Tullamore	OFIAR-017-090	1
Malt house	Malting	Ballygaddy (Ballybritt By)	OFIAR-039-014	1
Malt house	Malting	Drumakeenan (Clonlisk By, Ettagh Par)	OFIAR-042-009	1
Malt house	Malting	Frankford	OFIAR-031-012	2
Malt house	Malting	Garrycastle	OFIAR-029-011	8
Malt house	Malting	Kilmalogue	OFIAR-034-008	1
Malt house	Malting	Kylebeg or Banagher	OFIAR-021-009	1
Malt house	Malting	Kylebeg or Banagher	OFIAR-021-011	3
Malt house	Malting	Kylebeg or Banagher	OFIAR-021-011	5
Malt house	Malting	Townparks (Ballybritt By)	OFIAR-035-007	1
Malt house	Malting	Tullamore	OFIAR-017-039	1
Malt house	Malting	Tullamore	OFIAR-017-049	1
Malt house	Malting	Tullamore	OFIAR-017-050	1
Malt house	Malting	Tullamore	OFIAR-017-053	1
Malt house	Malting	Tullamore	OFIAR-017-054	2

Malt house	Malting	Tullamore	OFIAR-017-064	1
Malt house	Malting	Tullamore	OFIAR-017-065	1
Malt kiln	Distilling	Clonoghil Upper	OFIAR-035-034	1
Malt kiln	Distilling	Garrycastle	OFIAR-029-011	4
Malt kiln	Distilling	Garrycastle	OFIAR-029-011	7
Malt kiln	Distilling	Townparks (Ballybritt By)	OFIAR-035-046	1
Malt kiln	Distilling	Townparks (Ballybritt By)	OFIAR-035-047	2
Malt kiln	Malting	Frankford	OFIAR-031-012	2
Malt kiln	Malting	Kylebeg or Banagher	OFIAR-021-009	1
Malt kiln	Malting	Kylebeg or Banagher	OFIAR-021-011	2
Malt kiln	Malting	Kylebeg or Banagher	OFIAR-021-011	7
Malt kiln	Malting	Townparks (Ballybritt By)	OFIAR-035-007	1
Malt kiln	Malting	Tullamore	OFIAR-017-049	1
Malt kiln	Malting	Tullamore	OFIAR-017-064	2
Malt silo	Distilling	Tullamore	OFIAR-017-076	2
Malt store	Malting	Townparks (Ballybritt By)	OFIAR-035-062	1
Maltings office	Malting	Kylebeg or Banagher	OFIAR-021-011	4
Mill	Unknown	Ballybruncullin	OFIAR-007-032	1
Mill	Unknown	Clonlisk	OFIAR-045-016	1
Mill	Unknown	Cully	OFIAR-024-013	1
Mill	Unknown	Drumakeenan (Clonlisk By, Ettagh Par)	OFIAR-042-042	1
Mill	Unknown	Drumcaw or Mountlucas	OFIAR-018-035	1
Mill	Unknown	Erry (Marlborough)	OFIAR-008-065	1
Mill	Unknown	Gorteen (Kilcoursey By)	OFIAR-002-019	1
Mill	Unknown	Townparks (Lower Philipstown By)	OFIAR-018-042	1
Mill (water)	Unknown	Aghadouglas	OFIAR-042-029	1
Mill (water)	Unknown	Garryhinch	OFIAR-033-009	1
Mill (water)	Unknown	Kilnagall	OFIAR-031-014	3
Mill (water)	Unknown	Lumcloon	OFIAR-022-028	1
Mill (water)	Unknown	Milltown (Garrycastle By)	OFIAR-030-002	1
Mill (wind)	Unknown	Ballicknahee	OFIAR-002-010	1
Mill building	Grain milling	Bellmount or Lisderg	OFIAR-014-004	4
Mill building	Grain milling	Bellmount or Lisderg	OFIAR-014-004	5
Mill building	Grain milling	Bellmount or Lisderg	OFIAR-014-004	9
Mill building	Grain milling	Erry (Maryborough)	OFIAR-008-038	2

	1	ı		1
Mill building	Grain milling	Erry (Maryborough)	OFIAR-008-038	5
Mill building	Grain milling	Erry (Maryborough)	OFIAR-008-038	6
Mill building	Grain milling	Erry (Maryborough)	OFIAR-008-038	9
Mill building	Grain milling	Kilcoursey	OFIAR-008-042	2
Mill chimney	Grain milling	Erry (Maryborough)	OFIAR-008-038	8
Mill house	Grain milling	Aghagurty	OFIAR-039-005	2
Mill house	Grain milling	Bellmount or Lisderg	OFIAR-014-004	3
Mill house	Grain milling	Bellmount or Lisderg	OFIAR-014-004	6
Mill house	Grain milling	Erry (Maryborough)	OFIAR-008-038	3
Mill house	Grain milling	Erry (Maryborough)	OFIAR-008-038	4
Mill house	Grain milling	Fancroft	OFIAR-043-002	3
Mill house	Grain milling	Gorraun (Clonlisk By)	OFIAR-044-007	2
Mill house	Grain milling	Kilcoursey	OFIAR-008-064	1
Mill house	Grain milling	Park (Ballyboy By)	OFIAR-031-005	4
Mill race	Flax & linen	Kilclare; Co Westmeath	OFIAR-008-012	1
Mill weir	Grain milling	Ballycormick; Co Tipperary	OFIAR-046-005	1
Mill?	Unknown	Glasderry More	OFIAR-042-008	1
Millstone quarry	Stone	Cadamstown	OFIAR-037-005	1
Newspaper printing works	Printing & publishing	Townparks (Ballybritt By)	OFIAR-035-053	1
Oilseed mill (water)	Oilseed milling	Ballaghanoher	OFIAR-030-003	2
Oilseed mill (water)	Oilseed milling	Bellmount or Lisderg	OFIAR-014-004	1
Oilseed mill (water)	Oilseed milling	Clonoghil Upper	OFIAR-035-013	1
Quay	Distilling	Tullamore	OFIAR-017-076	3
Railway siding	Grain milling	Erry (Maryborough)	OFIAR-008-053	2
Railway siding	Jute	Erry (Armstrong)	OFIAR-008-028	13
Saw mill	Timber processing & products	Scrub or Pigeonpark	OFIAR-019-004	1
Saw mill	Timber processing & products	Tullamore	OFIAR-017-037	1
Saw mill (steam)	Timber processing & products	Edenderry	OFIAR-012-027	1
Saw mill (steam)	Timber processing & products	Tullamore	OFIAR-017-049	1
Saw mill (steam)	Timber processing & products	Tullamore	OFIAR-017-051	1
Saw mill (water)	Timber processing & products	Ballyboy (Ballyboy By)	OFIAR-031-007	1
Saw mill (water)	Timber processing & products	Ballyhugh	OFIAR-011-021	1

Saw mill (water)	Timber processing & products	Ballynacarrig	OFIAR-032-002	1
Saw mill (water)	Timber processing & products	Cadamstown	OFIAR-037-002	1
Saw mill (water)	Timber processing & products	Charleville Demesne	OFIAR-016-031	1
Saw mill (water)	Timber processing & products	Keeloge (Clonlisk By)	OFIAR-042-030	1
Saw mill (water)	Timber processing & products	Knockarley	OFIAR-039-011	1
Saw mill (water)	Timber processing & products	Newtown (Kilcoursey By, Kilcumreragh Par)	OFIAR-002-015	1
Saw mill (water)	Timber processing & products	Townparks (Ballybritt By)	OFIAR-035-009	1
Smithy	Agricultural engineering	Bracknagh	OFIAR-027-005	2
Spinning mill	Wool	Spollanstown	OFIAR-017-085	1
Spinning mill	Wool	Townparks (Ballybritt By)	OFIAR-035-053	1
Starch house	Unknown	Ballincur (Ballybritt By)	OFIAR-036-019	2
Tannery	Leather products	Tullamore	OFIAR-017-054	1
Threshing mill (horse)	Grain processing	Clonin	OFIAR-011-030	1
Threshing mill (horse)	Grain processing	Mountwilson	OFIAR-011-035	1
Threshing mill (horse)	Grain processing	Toberdaly	OFIAR-011-031	1
Threshing mill (water)	Grain processing	Charleville Demesne	OFIAR-016-031	1
Threshing mill (water)	Grain processing	Rath More	OFIAR-038-009	1
Tobacco factory	Tobacco processing & products	Tullamore	OFIAR-017-070	1
Tuck mill (water)	Wool	Acantha	OFIAR-009-021	1
Tuck mill (water)	Wool	Ballycumber	OFIAR-007-018	1
Tuck mill (water)	Wool	Ballynacarrig	OFIAR-032-002	1
Tuck mill (water)	Wool	Bellmount or Lisderg	OFIAR-014-004	10
Tuck mill (water)	Wool	Cloghatanny	OFIAR-008-001	1
Tuck mill (water)	Wool	Clonoghil Upper?; Townparks (Ballybritt By)?	OFIAR-035-060	1
Tuck mill (water)	Wool	Doon Demesne	OFIAR-006-003	3
Tuck mill (water)	Wool	Drumakeenan (Clonlisk By, Roscrea Par)	OFIAR-042-012	2
Tuck mill (water)	Wool	Enaghan	OFIAR-026-016	1
Tuck mill (water)	Wool	Franckfort	OFIAR-045-009	1
Tuck mill (water)	Wool	Lavagh	OFIAR-029-015	1
Tuck mill (water)	Wool	Lea More	OFIAR-015-010	1

Tuck mill (water)	Wool	Mucklagh	OFIAR-016-034	1
Tuck mill (water)	Wool	Rahan Demesne	OFIAR-016-007	1
Tuck mill (water)	Wool	Skehanagh	OFIAR-014-036	1
Tuck mill (water)	Wool	Townparks (Ballybritt By)	OFIAR-035-071	1
Tuck mill (water)	Wool	Tully (Kilcoursey By, Ardarcher or Horseleap Par); {Tully (Kilcoursey By, Kilmanagh Parish)}	OFIAR-002-014	1
Water pump (water)	Water supply	Charleville Demesne	OFIAR-016-031	1
Weaving factory	Cotton	Kilcoursey	OFIAR-008-054	1
Weaving factory	Wool	Cadamstown	OFIAR-037-002	1

6. STATUTORY PROTECTION			
Reg. no	Site no		
Birr RPS 49-301	OFIAR-035-034		
Birr RPS 53-206	OFIAR-035-007		
Birr RPS 53-207	OFIAR-035-047		
Birr RPS 53-324	OFIAR-035-046		
Birr RPS 53-325	OFIAR-035-046		
Birr RPS 53-374	OFIAR-035-053		
Offaly RPS 12-13	OFIAR-008-064		
Offaly RPS 12-18	OFIAR-008-042		
Offaly RPS 12-20	OFIAR-008-054		
Offaly RPS 12-25	OFIAR-008-038		
Offaly RPS 12-26	OFIAR-008-038		
Offaly RPS 12-37	OFIAR-008-028		
Offaly RPS 12-39	OFIAR-008-028		
Offaly RPS 12-40	OFIAR-008-038		
Offaly RPS 12-41	OFIAR-008-038		
Offaly RPS 16-14	OFIAR-011-001		
Offaly RPS 22-08	OFIAR-016-007		
Offaly RPS 23-01	OFIAR-009-005		
Offaly RPS 30-11	OFIAR-014-004		
Offaly RPS 30-12	OFIAR-014-004		
Offaly RPS 30-13	OFIAR-014-004		
Offaly RPS 30-14	OFIAR-014-004		
Offaly RPS 30-15	OFIAR-014-004		
Offaly RPS 30-17	OFIAR-014-004		
Offaly RPS 34-06	OFIAR-025-007		
Offaly RPS 34-07	OFIAR-025-007		
Offaly RPS 39-18	OFIAR-021-011		
Offaly RPS 39-29	OFIAR-021-009		
Offaly RPS 39-43	OFIAR-029-008		
Offaly RPS 41-04	OFIAR-031-012		
Offaly RPS 41-14	OFIAR-031-005		
Offaly RPS 42-01	OFIAR-031-007		
Offaly RPS 42-07	OFIAR-032-002		
Offaly RPS 42-08	OFIAR-032-002		
Offaly RPS 48-03	OFIAR-035-001		

Offaly RPS 51-02	OFIAR-037-002
Offaly RPS 57-07	OFIAR-042-033
Offaly RPS 60-06	OFIAR-041-006
Offaly RPS 60-07	OFIAR-041-006
Offaly RPS 61-14	OFIAR-042-030
Offaly RPS 61-18	OFIAR-042-012
Offaly RPS 62-01	OFIAR-043-002
Offaly RPS 62-02	OFIAR-043-002
Offaly RPS 63-08	OFIAR-044-007
RMP OF002-019	OFIAR-002-017
RMP OF005-067	OFIAR-005-001
RMP OF012-016	OFIAR-012-001
RMP OF026-023	OFIAR-026-017
RMP OF032-00701-	OFIAR-032-002
Tullamore RPS 23-201	OFIAR-017-091
Tullamore RPS 23-202	OFIAR-017-064
Tullamore RPS 23-242	OFIAR-017-085
Tullamore RPS 23-263	OFIAR-017-049
Tullamore RPS 23-275	OFIAR-017-049
Tullamore RPS 23-281	OFIAR-017-036
Tullamore RPS 23-294	OFIAR-017-076
Tullamore RPS 23-295	OFIAR-017-076
Tullamore RPS 23-390	OFIAR-017-038
Tullamore RPS 23-398	OFIAR-017-039
Tullamore RPS 23-403	OFIAR-017-064